

Rules and Regulations

Federal Register

Vol. 81, No. 43

Friday, March 4, 2016

This section of the FEDERAL REGISTER contains regulatory documents having general applicability and legal effect, most of which are keyed to and codified in the Code of Federal Regulations, which is published under 50 titles pursuant to 44 U.S.C. 1510.

The Code of Federal Regulations is sold by the Superintendent of Documents. Prices of new books are listed in the first FEDERAL REGISTER issue of each week.

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2015-2568; Directorate Identifier 2014-SW-026-AD; Amendment 39-18424; AD 2016-05-06]

RIN 2120-AA64

Airworthiness Directives; Airbus Helicopters (Previously Eurocopter France) Helicopters

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: We are superseding Airworthiness Directive (AD) 2014-07-52 for certain Airbus Helicopters (previously Eurocopter France) Model AS350B, AS350BA, AS350B1, AS350B2, AS350B3, AS350C, AS350D, AS350D1, AS355E, AS355F, AS355F1, AS355F2, AS355N, and AS355NP helicopters. AD 2014-07-52 required repetitively inspecting certain reinforcement angles of the rear structure to tailboom junction frame (reinforcement angles) for a crack at 10 hour time-in-service (TIS) intervals, repairing any cracked reinforcement angle, and allowed an optional repetitive inspection with a 165 hour TIS inspection interval as a terminating action for the 10 hour TIS inspections. This AD retains the inspection requirements of AD 2014-07-52 and requires the inspection of the area around each reinforcement angle screw hole as terminating action to the 10 hour TIS inspections. We are issuing this AD to detect a crack in the reinforcement angle, which if not corrected, could result in loss of the tailboom and subsequent loss of control of the helicopter.

DATES: This AD is effective April 8, 2016.

The Director of the Federal Register approved the incorporation by reference of certain documents listed in this AD as of June 25, 2014 (79 FR 33054, June 10, 2014).

ADDRESSES: For service information identified in this final rule, contact Airbus Helicopters, Inc., 2701 N. Forum Drive, Grand Prairie, TX 75052; telephone (972) 641-0000 or (800) 232-0323; fax (972) 641-3775; or at <http://www.airbushelicopters.com/techpub>. You may review the referenced service information at the FAA, Office of the Regional Counsel, Southwest Region, 10101 Hillwood Pkwy., Room 6N-321, Fort Worth, TX 76177.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2015-2568; or in person at the Docket Operations Office between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this AD, the European Aviation Safety Agency (EASA) AD, any incorporated-by-reference service information, the economic evaluation, any comments received, and other information. The street address for the Docket Operations Office (phone: 800-647-5527) is U.S. Department of Transportation, Docket Operations Office, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC 20590.

FOR FURTHER INFORMATION CONTACT: Robert Grant, Aviation Safety Engineer, Safety Management Group, FAA, 10101 Hillwood Pkwy., Fort Worth, TX 76177; telephone (817) 222-5110; email robert.grant@faa.gov.

SUPPLEMENTARY INFORMATION:

Discussion

We issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 to remove AD 2014-07-52, Amendment 39-17858 (79 FR 33054, June 10, 2014) and add a new AD. AD 2014-07-52 applied to Airbus Helicopters Model AS350B, AS350BA, AS350B1, AS350B2, AS350B3, AS350C, AS350D, AS350D1, AS355E, AS355F, AS355F1, AS355F2, AS355N, and AS355NP helicopters with Modification (MOD) 07 3215 or with a reinforcement angle part number (P/N) 350A08.2493.21 or P/N 350A08.2493.23

installed. AD 2014-07-52 required, for helicopters with 640 or more hours TIS, repetitively inspecting each reinforcement angle for a crack every 10 hours TIS. As an optional action, AD 2014-07-52 allowed a repetitive 165 hour TIS inspection of the reinforcement angle under each attaching screw for a crack. AD 2014-07-52 was prompted by Emergency AD No. 2014-0076-E, dated March 25, 2014, issued by EASA, which is the Technical Agent for the Member States of the European Union. EASA advises that during the inspection of several AS355 helicopters, cracks found in the reinforcement angles had initiated on the non-visible surface of the angle, and that this condition, if not corrected, could lead to further crack propagation and subsequent loss of the tailboom, resulting in loss of control of the helicopter. The EASA AD requires repetitive inspections of the reinforcement angles, and states that a terminating action is under investigation.

The NPRM published in the **Federal Register** on July 23, 2015 (80 FR 43645). The NPRM proposed to retain the 10 hour TIS repetitive inspections of the reinforcement angle and require (instead of allow as an option) the 165 hour TIS inspection of the junction frame bores as terminating action for the 10 hour TIS inspections. The NPRM also proposed to revise the applicability to only include helicopters with reinforcement angle P/N 350A08.2493.21 and P/N 350A08.2493.23, and not include helicopters with MOD 07 3215. Since MOD 07 3215 installed reinforcement angle P/N 350A08.2493.21 and P/N 350A08.2493.23, AD 2014-07-52 was written to apply to helicopters with either the reinforcement angle P/Ns or with MOD 07 3215, so that operators could more easily determine whether AD 2014-07-52 applied to their aircraft. Airbus Helicopters then developed MOD 07 3232, which removes reinforcement angle P/N 350A08.2493.21 and P/N 350A08.2493.23. We removed MOD 07 3215 from the applicability because we did not want the AD to apply to a helicopter with both MOD 07 3215 and MOD 07 3232 in its aircraft records, as it would not have reinforcement angle P/N 350A08.2493.21 or P/N 350A08.2493.23 installed. The proposed requirements were intended to detect a

crack in the reinforcement angle, which if not corrected, could result in loss of the tailboom and subsequent loss of control of the helicopter.

Since the NPRM was issued, a group email address has been established for requesting an FAA alternative method of compliance for a helicopter of foreign design. We have revised this contact information in this final rule to reflect the new email address.

Comments

We gave the public the opportunity to participate in developing this AD, but we did not receive any comments on the NPRM (79 FR 33054, June 10, 2014).

FAA's Determination

These helicopters have been approved by the aviation authority of France and are approved for operation in the United States. Pursuant to our bilateral agreement with France, EASA, its technical representative, has notified us of the unsafe condition described in the EASA AD. We are issuing this AD because we evaluated all information provided by EASA and determined the unsafe condition exists and is likely to exist or develop on other helicopters of these same type designs and that air safety and the public interest require adopting the AD requirements as proposed.

Interim Action

We consider this AD to be an interim action. If final action is later identified, we might consider further rulemaking then.

Differences Between This AD and the EASA AD

This AD is not applicable to the AS350BB as that model is not type certificated in the U.S. This AD applies to Airbus Helicopters Model AS350C and AS350D1 helicopters because these helicopters have a similar design. Finally, the EASA AD requires operators to contact Airbus Helicopters if there is a crack, and this AD does not, however it does require repairing the crack before further flight.

Related Service Information Under 14 CFR Part 51

Airbus Helicopters issued Emergency Alert Service Bulletin (EASB) No. 05.00.70 for Model AS350B, BA, BB, Bl, B2, B3, and D helicopters, and EASB No. 05.00.62 for Model AS355E, F, F1, F2, N, and NP helicopters, both Revision 0 and dated March 24, 2014. EASB No. 05.00.70 and EASB No. 05.00.62 describe procedures for inspecting the angle reinforcements for a crack. This service information is

reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the **ADDRESSES** section.

Costs of Compliance

We estimate that this AD affects 822 helicopters of U.S. Registry. We estimate that operators may incur the following costs in order to comply with this AD. At an average labor rate of \$85 per work-hour, inspecting the reinforcement angles for a crack without removing the screws requires 1.0 work-hour, for a cost per helicopter of \$85 and a total cost of \$69,870 for the U.S. fleet, per inspection cycle. Removing the screws and inspecting the reinforcement angle requires 2 work-hours, for a cost per helicopter of \$170 and a total cost of \$139,740 for the U.S. fleet, per inspection cycle. If required, repairing a cracked reinforcement angle requires about 10 work-hours, and required parts cost about \$300, for a total cost per helicopter of \$1,150.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: "General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on helicopters identified in this rulemaking action.

Regulatory Findings

This AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

(1) Is not a "significant regulatory action" under Executive Order 12866;

(2) Is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979);

(3) Will not affect intrastate aviation in Alaska to the extent that it justifies making a regulatory distinction; and

(4) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared an economic evaluation of the estimated costs to comply with this AD and placed it in the AD docket.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

■ 2. The FAA amends § 39.13 by removing Airworthiness Directive (AD) 2014-07-52, Amendment 39-17858 (79 FR 33054, June 10, 2014), and adding the following new AD:

2016-05-06 Airbus Helicopters (previously Eurocopter France): Amendment 39-18424; Docket No. FAA-2015-2568; Directorate Identifier 2014-SW-026-AD.

(a) Applicability

This AD applies to Airbus Helicopters Model AS350B, AS350BA, AS350B1, AS350B2, AS350B3, AS350C, AS350D, AS350D1, AS355E, AS355F, AS355F1, AS355F2, AS355N, and AS355NP helicopters, with a reinforcement angle part number (P/N) 350A08.2493.21 or P/N 350A08.2493.23 installed, certificated in any category.

Note 1 to paragraph (a) of this AD: Helicopters with Modification (MOD) 073232 do not have P/N 350A08.2493.21 or P/N 350A08.2493.23 installed.

(b) Unsafe Condition

This AD defines the unsafe condition as a crack in a rear structure to tailboom junction frame reinforcement angle (reinforcement angle), which if not detected could result in loss of the tail boom and subsequent loss of control of the helicopter.

(c) Affected ADs

This AD supersedes AD 2014-07-52, Amendment 39-17858 (79 FR 33054, June 10, 2014).

(d) Effective Date

This AD becomes effective April 8, 2016.

(e) Compliance

You are responsible for performing each action required by this AD within the specified compliance time unless it has already been accomplished prior to that time.

(f) Required Actions

(1) For helicopters with 640 or more hours time-in-service (TIS) since installation of MOD 073215 or since installation of an applicable reinforcement angle, within 10 hours TIS, and thereafter at intervals not exceeding 10 hours TIS, inspect each reinforcement angle for a crack as depicted in Figure 1 of Airbus Helicopters Emergency Alert Service Bulletin No. 05.00.70 for Model AS350B, AS350BA, AS350B1, AS350B2, AS350B3, AS350C, AS350D, and AS350D1 helicopters and Airbus Helicopters Emergency Alert Service Bulletin No. 05.00.62 for AS355E, AS355F, AS355F1, AS355F2, AS355N, and AS355NP helicopters, both Revision 0 and dated March 24, 2014.

(2) If there is a crack, before further flight, repair the reinforcement angle in a manner approved by the manager listed in paragraph (h)(1) of this AD.

(3) Within 165 hours TIS after the first inspection required by paragraph (f)(1) of this AD, and thereafter at intervals not exceeding 165 hours TIS, remove screw No. 5 from the reinforcement angle, thoroughly clean the area around the hole and inspect the reinforcement angle for a crack. If there is not a crack, reinstall the screw. Sequentially repeat the steps required by this paragraph for screws No. 6 through No. 12. If there is a crack, comply with paragraph (f)(2) of this AD. Accomplishment of the inspection required by this paragraph terminates the repetitive inspections required by paragraph (f)(1) of this AD.

(g) Special Flight Permits

Special flight permits are prohibited.

(h) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Safety Management Group, FAA, may approve AMOCs for this AD. Send your proposal to: Robert Grant, Aviation Safety Engineer, Safety Management Group, FAA, 10101 Hillwood Pkwy, Fort Worth, TX 76177; telephone (817) 222-5110; email 9-ASW-FTW-AMOC-Requests@faa.gov.

(2) For operations conducted under a 14 CFR part 119 operating certificate or under 14 CFR part 91, subpart K, we suggest that you notify your principal inspector, or lacking a principal inspector, the manager of the local flight standards district office or certificate holding district office, before operating any aircraft complying with this AD through an AMOC.

(3) AMOCs approved previously in accordance with AD 2014-07-52, Amendment 39-17858 (79 FR 33054, June 10, 2014) are approved as AMOCs for the corresponding requirements of paragraph (f)(2) of this AD.

(i) Additional Information

The subject of this AD is addressed in European Aviation Safety Agency (EASA) AD 2014-0076-E, dated March 25, 2014. You may view the EASA AD on the Internet at <http://www.regulations.gov> in Docket No. FAA-2015-2568.

(j) Subject

Joint Aircraft Service Component (JASC) Code: 5302: Rotorcraft Tailboom.

(k) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(3) The following service information was approved for IBR on June 25, 2014 (79 FR 33054, June 10, 2014).

(i) Airbus Helicopters Emergency Alert Service Bulletin (EASB) No. 05.00.62, Revision 0, dated March 24, 2014.

(ii) Airbus Helicopters EASB No. 05.00.70, Revision 0, dated March 24, 2014.

Note 2 to paragraph (k)(3): Airbus Helicopters EASB No. 05.00.62 and EASB No. 05.00.70, both Revision 0 and dated March 24, 2014, are co-published as one document along with Airbus Helicopters EASB No. 05.00.45 and EASB No. 05.00.41, both Revision 0 and dated March 24, 2014, which are not incorporated by reference in this AD.

(4) For Airbus Helicopters service information identified in this final rule, contact Airbus Helicopters, Inc., 2701 N. Forum Drive, Grand Prairie, TX 75052; telephone (972) 641-0000 or (800) 232-0323; fax (972) 641-3775; or at <http://www.airbushelicopters.com/techpub>.

(5) You may view this service information at FAA, Office of the Regional Counsel, Southwest Region, 10101 Hillwood Pkwy, Room 6N-321, Fort Worth, TX 76177. For information on the availability of this material at the FAA, call (817) 222-5110.

(6) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call (202) 741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Fort Worth, Texas, on February 25, 2016.

Scott A. Horn,

Acting Manager, Rotorcraft Directorate, Aircraft Certification Service.

[FR Doc. 2016-04678 Filed 3-3-16; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION**Federal Aviation Administration****14 CFR Part 39**

[Docket No. FAA-2015-3607; Directorate Identifier 2015-CE-010-AD; Amendment 39-18398; AD 2016-04-04]

RIN 2120-AA64

Airworthiness Directives; M7 Aerospace LLC Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: We are adopting a new airworthiness directive (AD) for all M7 Aerospace LLC Models SA26-AT, SA226-T(B), SA226-AT, SA226-T, SA226-TC, SA227-AC (C-26A), SA227-AT, SA227-BC (C-26A), SA227-CC, SA227-DC (C-26B), and SA227-TT airplanes. This AD was prompted by information that the airplane flight manual (AFM) does not provide adequate guidance in the handling of engine failures, which may lead to reliance on the negative torque system (NTS) for reducing drag. This condition could lead the pilot to not fully feather the propeller with consequent loss of control. This AD requires inserting updates into the airplane flight manual (AFM) and/or the pilot operating handbook (POH) that will clearly establish that the NTS is not designed to automatically feather the propeller but only to provide drag protection. We are issuing this AD to correct the unsafe condition on these products.

DATES: This AD is effective April 8, 2016.

The Director of the Federal Register approved the incorporation by reference of certain publications listed in this AD as of April 8, 2016.

ADDRESSES: For service information identified in this AD, contact M7 Aerospace LLC, 10823 NE Entrance Road, San Antonio, Texas 78216; phone: (210) 824-9421; fax: (210) 804-7766; Internet: <http://www.elbitsystems-us.com>; email: [MetroTech@M7Aerospace.com](mailto:M7Aerospace.com).

You may view this referenced service information at the FAA, Small Airplane Directorate, 901 Locust, Kansas City, Missouri 64106. For information on the availability of this material at the FAA, call 816-329-4148. It is also available on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2015-3607.