

Proposed Rules

Federal Register

Vol. 81, No. 104

Tuesday, May 31, 2016

This section of the FEDERAL REGISTER contains notices to the public of the proposed issuance of rules and regulations. The purpose of these notices is to give interested persons an opportunity to participate in the rule making prior to the adoption of the final rules.

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2016-6894; Directorate Identifier 2015-NM-120-AD]

RIN 2120-AA64

Airworthiness Directives; Airbus Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: We propose to adopt a new airworthiness directive (AD) for certain Airbus Model A300 F4-600R series airplanes. This proposed AD was prompted by a report of two adjacent frame forks that were found cracked on the aft lower deck cargo door (LDCD) of two Model A300-600F4 airplanes during scheduled maintenance. This proposed AD would require repetitive high frequency eddy current (HFEC) inspections of the aft LDCD frame forks; a one-time check of the LDCD clearances; and a one-time detailed visual inspection of hooks, eccentric bushes, and x-stops; and corrective actions if necessary. We are proposing this AD to detect and correct cracked or ruptured aft LDCD frames, which could allow loads to be transferred to the remaining structural elements. This condition could lead to the rupture of one or more vertical aft LDCD frames, which could result in reduced structural integrity of the aft LDCD.

DATES: We must receive comments on this proposed AD by July 15, 2016.

ADDRESSES: You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal:* Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.
- *Fax:* 202-493-2251.
- *Mail:* U.S. Department of Transportation, Docket Operations, M-

30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC 20590.

- *Hand Delivery:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this NPRM, contact Airbus SAS, Airworthiness Office—EAW, 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France; telephone +33 5 61 93 36 96; fax +33 5 61 93 44 51; email account.airworth-eas@airbus.com; Internet <http://www.airbus.com>. You may view this referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2016-6894; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this proposed AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Operations office (telephone 800-647-5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT: Dan Rodina, Aerospace Engineer, International Branch, ANM-116, Transport Airplane Directorate, FAA, 1601 Lind Avenue SW., Renton, WA 98057-3356; telephone 425-227-2125; fax 425-227-1149.

SUPPLEMENTARY INFORMATION:

Comments Invited

We invite you to send any written relevant data, views, or arguments about this proposed AD. Send your comments to an address listed under the **ADDRESSES** section. Include “Docket No. FAA-2016-6894; Directorate Identifier 2015-NM-120-AD” at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy

aspects of this proposed AD. We will consider all comments received by the closing date and may amend this proposed AD based on those comments.

We will post all comments we receive, without change, to <http://www.regulations.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact we receive about this proposed AD.

Discussion

The European Aviation Safety Agency (EASA), which is the Technical Agent for the Member States of the European Union, has issued EASA Airworthiness Directive 2015-0152, dated July 24, 2015 (referred to after this as the Mandatory Continuing Airworthiness Information, or “the MCAI”), to correct an unsafe condition for all Airbus Model A300 F4-605R and A300 F4-622R. The MCAI states:

During scheduled maintenance at frames (FR) 61 and FR61A on the aft lower deck cargo door (LDCD) of two A300-600F4 aeroplanes, two adjacent frame forks were found cracked.

Subsequent analysis determined that, in case of cracked or ruptured aft cargo door frame(s), loads will be transferred to the remaining structural elements. However, these secondary load paths will be able to sustain the loads for a limited number of flight cycles only.

This condition, if not detected and corrected, could lead to the rupture of one or more vertical aft cargo door frame(s), resulting in reduced structural integrity of the aft cargo door.

To address this unsafe condition, Airbus issued Alert Operators Transmission (AOT) A52W011-15 to provide inspection instructions.

For the reason described above, this [EASA] AD requires repetitive inspections [for cracking] of the aft LDCD frame forks and, depending on findings, the accomplishment of corrective action(s).

This [EASA] AD is considered interim action and further [EASA] AD action may follow.

Required actions include a one-time check of the LDCD clearances; and a one-time detailed visual inspection of hooks, eccentric bushes, x-stops; and corrective actions if necessary. You may examine the MCAI in the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2016-6894.

Related Service Information Under 14 CFR Part 51

Airbus has issued Alert Operators Transmission (AOT) A52W011–15, Revision 00, dated July 23, 2015. The service information describes procedures for repetitive HFEC inspections for cracking of the aft LDCD frame forks; a one-time check of the LDCD clearances; and a one-time detailed visual inspection of hooks, eccentric bushes, and x-stops; and corrective actions if necessary. This service information is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the ADDRESSES section.

FAA's Determination and Requirements of This Proposed AD

This product has been approved by the aviation authority of another country, and is approved for operation in the United States. Pursuant to our bilateral agreement with the State of Design Authority, we have been notified of the unsafe condition described in the MCAI and service information referenced above. We are proposing this AD because we evaluated all pertinent information and determined an unsafe condition exists and is likely to exist or develop on other products of the same type design.

Costs of Compliance

We estimate that this proposed AD affects 58 airplanes of U.S. registry. We also estimate that it would take about 4 work-hours per product to comply with the basic requirements of this proposed AD. The average labor rate is \$85 per work-hour. Required parts would cost about \$0 per product. Based on these figures, we estimate the cost of this proposed AD on U.S. operators to be \$19,720, or \$340 per product.

In addition, we estimate that any necessary follow-on actions would take about 15 work-hours and require parts costing \$10,000, for a cost of \$11,275 per product. We have no way of determining the number of aircraft that might need these actions.

Also, we estimate that the reporting requirement would take about 1 work-hour, for a cost of \$85 per product.

Paperwork Reduction Act

A federal agency may not conduct or sponsor, and a person is not required to respond to, nor shall a person be subject to penalty for failure to comply with a collection of information subject to the requirements of the Paperwork Reduction Act unless that collection of information displays a current valid OMB control number. The control

number for the collection of information required by this proposed AD is 2120–0056. The paperwork cost associated with this proposed AD has been detailed in the Costs of Compliance section of this document and includes time for reviewing instructions, as well as completing and reviewing the collection of information. Therefore, all reporting associated with this proposed AD is mandatory. Comments concerning the accuracy of this burden and suggestions for reducing the burden should be directed to the FAA at 800 Independence Ave. SW., Washington, DC 20591, ATTN: Information Collection Clearance Officer, AES–200.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. "Subtitle VII: Aviation Programs," describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in "Subtitle VII, Part A, Subpart III, Section 44701: General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

1. Is not a "significant regulatory action" under Executive Order 12866;
2. Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979);
3. Will not affect intrastate aviation in Alaska; and
4. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

Airbus: Docket No. FAA–2016–6894; Directorate Identifier 2015–NM–120–AD.

(a) Comments Due Date

We must receive comments by July 15, 2016.

(b) Affected ADs

None.

(c) Applicability

This AD applies to Airbus Model A300 F4–605R and A300 F4–622R airplanes, certificated in any category, on which Airbus Modification 12046 has been embodied in production. Modification 12046 has been embodied in production on manufacturer serial numbers (MSNs) 0805 and above, except MSNs 0836, 0837, and 0838.

(d) Subject

Air Transport Association (ATA) of America Code 52, Doors.

(e) Reason

This AD was prompted by a report of two adjacent frame forks that were found cracked on the aft lower deck cargo door (LDCD) of two Model A300–600F4 airplanes during scheduled maintenance. We are issuing this AD to detect and correct cracked or ruptured aft LDCD frames, which could allow loads to be transferred to the remaining structural elements. This condition could lead to the rupture of one or more vertical aft LDCD frames, which could result in reduced structural integrity of the aft LDCD.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Inspection Requirements

At the applicable time specified in paragraph (h) of this AD, do the actions specified in paragraphs (g)(1), (g)(2), and (g)(3) of this AD, in accordance with Airbus Alert Operators Transmission (AOT) A52W011–15, Revision 00, dated July 23, 2015.

- (1) Do a one-time check of the aft LDCD clearances "U" and "V" between the latching

hooks and the eccentric bush at FR60 through FR64A. If any value outside tolerance is found, adjust the latching hook before further flight.

(2) Do a one-time detailed inspection to detect signs of wear of the hooks, eccentric bushes, and x-stops. If any wear is found, do all applicable corrective actions before further flight.

(3) Do a high frequency eddy current (HFEC) inspection to detect cracking at all frame fork stations of the aft LDCD. If any crack is found, replace the cracked frame fork before further flight. Repeat the HFEC inspection thereafter at intervals not to exceed 600 flight cycles.

(h) Compliance Times

At the later of the times specified in paragraphs (h)(1) and (h)(2) of this AD, do the actions required by paragraph (g) of this AD.

(1) Before the accumulation of 4,500 total flight cycles.

(2) At the applicable time specified by paragraph (h)(2)(i) or (h)(2)(ii) of this AD.

(i) For airplanes that have accumulated 8,000 or more total flight cycles as of the effective date this AD: Within 100 flight cycles after the effective date of this AD.

(ii) For airplanes that have accumulated fewer than 8,000 total flight cycles as of the effective date of this AD: Within 400 flight cycles after the effective date of this AD.

(i) Reporting

At the applicable time specified in paragraph (i)(1) or (i)(2) of this AD, report the findings (both positive and negative) of the clearance check and detailed inspection required by paragraphs (g)(1) and (g)(2) of this AD, and each HFEC inspection required by paragraph (g)(3) of this AD. Send the report to Airbus in accordance with paragraph 7 of Airbus AOT A52W011–15, Revision 00, dated July 23, 2015. The report must include the applicable information specified in Appendix 2 of Airbus AOT A52W011–15, Revision 00, dated July 23, 2015.

(1) If the inspection was done on or after the effective date of this AD: Submit the report within 60 days after the inspection.

(2) If the inspection was done before the effective date of this AD: Submit the report within 60 days after the effective date of this AD.

(j) Post-Repair Provisions

(1) Accomplishment of corrective actions required by this AD does not terminate the repetitive HFEC inspections required by paragraph (g)(3) of this AD.

(2) If all frame forks are replaced at the same time on the aft LDCD of an airplane, the next HFEC inspection required by paragraph (g)(3) of this AD can be deferred up to 4,500 flight cycles after the frame fork replacement.

(k) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs)*: The Manager, International Branch, ANM–116, Transport Airplane Directorate, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19.

In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the International Branch, send it to ATTN: Dan Rodina, Aerospace Engineer, International Branch, ANM–116, Transport Airplane Directorate, FAA, 1601 Lind Avenue SW., Renton, WA 98057–3356; telephone 425–227–2125; fax 425–227–1149. Information may be emailed to: 9-ANM-116-AMOC-REQUESTS@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office. The AMOC approval letter must specifically reference this AD.

(2) *Contacting the Manufacturer*: For any requirement in this AD to obtain corrective actions from a manufacturer, the action must be accomplished using a method approved by the Manager, International Branch, ANM–116, Transport Airplane Directorate, FAA; or the European Aviation Safety Agency (EASA); or Airbus's EASA Design Organization Approval (DOA). If approved by the DOA, the approval must include the DOA-authorized signature.

(3) *Reporting Requirements*: A federal agency may not conduct or sponsor, and a person is not required to respond to, nor shall a person be subject to a penalty for failure to comply with a collection of information subject to the requirements of the Paperwork Reduction Act unless that collection of information displays a current valid OMB Control Number. The OMB Control Number for this information collection is 2120–0056. Public reporting for this collection of information is estimated to be approximately 5 minutes per response, including the time for reviewing instructions, completing and reviewing the collection of information. All responses to this collection of information are mandatory. Comments concerning the accuracy of this burden and suggestions for reducing the burden should be directed to the FAA at: 800 Independence Ave. SW., Washington, DC 20591, Attn: Information Collection Clearance Officer, AES–200.

(l) Related Information

(1) Refer to Mandatory Continuing Airworthiness Information (MCAI) European Airworthiness Directive 2015–0152, dated July 24, 2015, for related information. This MCAI may be found in the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA–2016–6894.

(2) For service information identified in this AD, contact Airbus SAS, Airworthiness Office—EAW, 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France; telephone +33 5 61 93 36 96; fax +33 5 61 93 44 51; email account.airworth-eas@airbus.com; Internet <http://www.airbus.com>. You may view this service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425–227–1221.

Issued in Renton, Washington, on May 18, 2016.

Dionne Palermo,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 2016–12522 Filed 5–27–16; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA–2016–6896; Directorate Identifier 2016–NM–016–AD]

RIN 2120–AA64

Airworthiness Directives; Airbus Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: We propose to adopt a new airworthiness directive (AD) for all Airbus Model A318–111, and –112 airplanes, Model A319–111, –112, –113, –114, and –115 airplanes, Model A320–211, –212 and –214 airplanes, and Model A321–111, –112, –211, –212, and –213 airplanes. This proposed AD was prompted by a report of a production quality deficiency on the inner retainer installed on link assemblies of the engine mount, which could result in failure of the retainer. This proposed AD would require an inspection for, and replacement of, all non-conforming aft engine mount retainers. We are proposing this AD to detect and correct non-conforming retainers of the aft engine mount. This condition could result in the loss of the locking feature of the nuts of the inner and outer pins; loss of the pins will result in the aft mount engine link no longer being secured to the aft engine mount, possibly resulting in damage to the airplane and injury to persons on the ground.

DATES: We must receive comments on this proposed AD by July 15, 2016.

ADDRESSES: You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal*: Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.
- *Fax*: 202–493–2251.
- *Mail*: U.S. Department of

Transportation, Docket Operations, M–30, West Building Ground Floor, Room W12–140, 1200 New Jersey Avenue SE., Washington, DC 20590.