

Proposed Rules

Federal Register

Vol. 81, No. 121

Thursday, June 23, 2016

This section of the FEDERAL REGISTER contains notices to the public of the proposed issuance of rules and regulations. The purpose of these notices is to give interested persons an opportunity to participate in the rule making prior to the adoption of the final rules.

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2016-7271; Directorate Identifier 2015-NM-099-AD]

RIN 2120-AA64

Airworthiness Directives; Fokker Services B.V. Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: We propose to adopt a new airworthiness directive (AD) for all Fokker Services B.V. Model F.28 Mark 0070 and 0100 airplanes. This proposed AD was prompted by heavy corrosion found on the wing rear spar lower girder. This proposed AD would require inspections of the affected areas, modification of the wing trailing edge lower skin panels, and corrective actions if necessary. We are proposing this AD to detect and correct corrosion of the wing rear spar lower girder. This condition could reduce the load-carrying capability of the wing, possibly resulting in structural failure and loss of the airplane.

DATES: We must receive comments on this proposed AD by August 8, 2016.

ADDRESSES: You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal:* Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.
- *Fax:* 202-493-2251.
- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC 20590.
- *Hand Delivery:* Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this NPRM, contact Fokker Services B.V., Technical Services Dept., P.O. Box 1357, 2130 EL Hoofddorp, the Netherlands; telephone +31 (0)88-6280-350; fax +31 (0)88-6280-111; email technicalservices@fokker.com; Internet <http://www.myfokkerfleet.com>. You may view this referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2016-7271; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this proposed AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Operations office (telephone 800-647-5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT: Tom Rodriguez, Aerospace Engineer, International Branch, ANM 116, Transport Airplane Directorate, FAA, 1601 Lind Avenue SW., Renton, WA 98057-3356; telephone 425-227-1137; fax 425-227-1149.

SUPPLEMENTARY INFORMATION:

Comments Invited

We invite you to send any written relevant data, views, or arguments about this proposed AD. Send your comments to an address listed under the **ADDRESSES** section. Include "Docket No. FAA-2016-7271; Directorate Identifier 2015-NM-099-AD" at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this proposed AD. We will consider all comments received by the closing date and may amend this proposed AD based on those comments.

We will post all comments we receive, without change, to <http://www.regulations.gov>, including any personal information you provide. We will also post a report summarizing each

substantive verbal contact we receive about this proposed AD.

Discussion

The European Aviation Safety Agency (EASA), which is the Technical Agent for the Member States of the European Union, has issued EASA Airworthiness Directive 2015-0113, dated June 22, 2015 (referred to after this as the Mandatory Continuing Airworthiness Information, or "the MCAI"), to correct an unsafe condition for all Fokker Services B.V. Model F.28 Mark 0070, and 0100 airplanes. The MCAI states:

On an F28 Mark 0070 aeroplane, heavy corrosion was found on the wing rear spar lower girder. At small spots the effective thickness of the vertical flange of the lower girder was almost lost. Subsequently, a number of inspections were accomplished on other aeroplanes to provide additional information on possible corrosion in this area. Because the rear spar lower girder between Wing Stations (WSTA) 9270 and 11794 is hidden from view by the inboard and outboard aileron balancing plates, it is possible that corrosion in this area remains undetected during the zonal inspections in zone 536 and 636 (MRB tasks 062505-00-01 and 062605-00-01). The heavy corrosion was not only found in the area between WSTA 9270 and 11794, but also in the area where the rear spar lower girder is directly visible.

This condition, if not detected and corrected, reduces the load carrying capability of the wing, possibly resulting in structural failure and loss of the aeroplane.

To address this potential unsafe condition, Fokker Services issued Service Bulletin (SB) SBF100-57-049 to provide instructions to detect and remove corrosion and to modify the wing trailing edge lower skin panels into access panels. SBF100-57-050 was issued to provide repair instructions.

For the reasons described above, this [EASA] AD requires inspections of the affected areas and, depending on findings, accomplishment of applicable corrective action(s). This [EASA] AD also requires modification of the wing trailing edge lower skin panels into access panels [This modification is to provide ease of access for later inspection and repairs in the affected areas.], and reporting of the results of the inspections to Fokker Services.

More information on this subject can be found in Fokker Services All Operators Message AOF100.197.

You may examine the MCAI in the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2016-7271.

Related Service Information Under 1 CFR Part 51

We reviewed Fokker Service Bulletin SBF100–57–049, dated March 24, 2015, which describes procedures for an inspection for corrosion of certain wing rear spar lower girder areas, modification of the wing trailing edge lower skin panels, and corrective actions if necessary. We also reviewed Fokker Service Bulletin SBF100–57–050, Revision 1, dated May 19, 2015, which describes procedures for repair of the wing spar. This service information is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the ADDRESSES section.

FAA's Determination and Requirements of This Proposed AD

This product has been approved by the aviation authority of another country, and is approved for operation in the United States. Pursuant to our bilateral agreement with the State of Design Authority, we have been notified of the unsafe condition described in the MCAI and service information referenced above. We are proposing this AD because we evaluated all pertinent information and determined an unsafe condition exists and is likely to exist or develop on other products of the same type design.

Costs of Compliance

We estimate that this proposed AD affects 8 airplanes of U.S. registry.

We also estimate that it would take about 35 work-hours per product to comply with the basic requirements of this proposed AD. The average labor rate is \$85 per work-hour. Required parts would cost about \$1,680 per product. Based on these figures, we estimate the cost of this proposed AD on U.S. operators to be \$37,240, or \$4,655 per product.

In addition, we estimate that any necessary follow-on actions would take about 372 work-hours and require parts costing \$7,600, for a cost of \$39,220 per product. We have no way of determining the number of aircraft that might need this action.

We also estimate that it would take about 1 work-hour per product for reporting. The average labor rate is \$85 per work-hour. Based on these figures, we estimate the cost of this reporting on U.S. operators to be \$680, or \$85 per product.

Paperwork Reduction Act

A federal agency may not conduct or sponsor, and a person is not required to respond to, nor shall a person be subject

to penalty for failure to comply with a collection of information subject to the requirements of the Paperwork Reduction Act unless that collection of information displays a current valid OMB control number. The control number for the collection of information required by this proposed AD is 2120–0056. The paperwork cost associated with this proposed AD has been detailed in the Costs of Compliance section of this document and includes time for reviewing instructions, as well as completing and reviewing the collection of information. Therefore, all reporting associated with this proposed AD is mandatory. Comments concerning the accuracy of this burden and suggestions for reducing the burden should be directed to the FAA at 800 Independence Ave. SW., Washington, DC 20591, ATTN: Information Collection Clearance Officer, AES–200.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. "Subtitle VII: Aviation Programs," describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in "Subtitle VII, Part A, Subpart III, Section 44701: General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

1. Is not a "significant regulatory action" under Executive Order 12866;
2. Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979);
3. Will not affect intrastate aviation in Alaska; and

4. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

Fokker Services B.V.: Docket No. FAA–2016–7271; Directorate Identifier 2015–NM–099–AD.

(a) Comments Due Date

We must receive comments by August 8, 2016.

(b) Affected ADs

None.

(c) Applicability

This AD applies to all Fokker Services B.V. Model F.28 Mark 0070 and 0100 airplanes, certificated in any category.

(d) Subject

Air Transport Association (ATA) of America Code 57, Wings.

(e) Reason

This AD was prompted by heavy corrosion found on the wing rear spar lower girder. We are issuing this AD to detect and correct corrosion of the wing rear spar lower girder. This condition could reduce the load-carrying capability of the wing, possibly resulting in structural failure and loss of the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Inspection of the Wing Rear Spar Lower Girder From Wing Station (WSTA) 9270 to 11794

Within 1,000 flight cycles or 12 months, whichever occurs first after the effective date of this AD, accomplish a one-time detailed visual inspection for corrosion of the wing rear spar lower girder area from WSTA 9270 to 11794, in accordance with Part 1 of the Accomplishment Instructions of Fokker Service Bulletin SBF100–57–049, dated March 24, 2015.

(h) Modification of Wing Trailing Edge

Within 1,000 flight cycles or 12 months, whichever occurs first after the effective date of this AD, modify the wing trailing edge lower skin panels into access panels, in accordance with Part 1 of the Accomplishment Instructions of Fokker Service Bulletin SBF100–57–049, dated March 24, 2015.

(i) Inspection of the Wing Rear Spar Lower Girder From WSTA 2635 to 8700 and WSTA 11794 to 12975

Within 2,000 flight cycles or 24 months, whichever occurs first after the effective date of this AD, accomplish a one-time detailed visual inspection for corrosion of the wing rear spar lower girder area from WSTA 2635 to 8700 and WSTA 11794 to 12975, in accordance with Part 2 of the Accomplishment Instructions of Fokker Service Bulletin SBF100–57–049, dated March 24, 2015.

(j) Modification of Wing Rear Spar Lower Girder

(1) If during any inspection required by paragraph (g) or (i) of this AD, as applicable, corrosion is found, before further flight, remove the corrosion and determine the remaining thickness at the damaged spots, in accordance with the Accomplishment Instructions of Fokker Service Bulletin SBF100–57–049, dated March 24, 2015. If the remaining thickness at the damaged spots, as determined by this paragraph, is not within the tolerances specified in Fokker Service Bulletin SBF100–57–049, dated March 24, 2015, except as required by paragraph (k)(1) of this AD: Before further flight, accomplish the applicable corrective actions as defined in paragraph (j)(1)(i) or (j)(1)(ii) of this AD, as applicable.

(i) For corrosion damage found outboard of WSTA 8200 only: Repair in accordance with the Accomplishment Instructions of Fokker Service Bulletin SBF100–57–050, Revision 1, dated May 19, 2015.

(ii) Repair using a method approved by the Manager, International Branch, ANM–116, Transport Airplane Directorate, FAA; or the European Aviation Safety Agency (EASA); or Fokker Services B.V.'s EASA Design Organization Approval (DOA).

(2) If during any inspection required by paragraph (g) or (i) of this AD, only damage to the surface protection is found, or if the remaining thickness at the damaged spots, as determined by paragraph (j)(1) of this AD, is within the tolerances specified in Fokker Service Bulletin SBF100–57–049, dated March 24, 2015, except as required by paragraph (k)(1) of this AD: Before further flight, restore the surface protection in accordance with the Accomplishment Instructions of Fokker Service Bulletin SBF100–57–049, dated March 24, 2015, except as required by paragraph (k)(2) of this AD.

(k) Exceptions to Service Information Specifications

(1) Where Fokker Service Bulletin SBF100–57–049, dated March 24, 2015, specifies the acceptability of smaller thickness or customized repairs: Before further flight,

obtain acceptable tolerances, using a method approved by the Manager, International Branch, ANM–116, Transport Airplane Directorate, FAA; or EASA; or Fokker Services B.V.'s EASA DOA.

(2) Where Fokker Service Bulletin SBF100–57–049, dated March 24, 2015, specifies contacting Fokker for a customized repair: Before further flight, repair using a method approved by the Manager, International Branch, ANM–116, Transport Airplane Directorate, FAA; or EASA; or Fokker Services B.V.'s EASA DOA.

(l) Reporting Requirements

Submit a report of the findings both positive and negative of the inspection required by paragraph (g) and (i) of this AD to Fokker Services, in accordance with the Accomplishment Instructions of Fokker Service Bulletin SBF100–57–049, dated March 24, 2015, at the time specified in paragraph (l)(1) or (l)(2) of this AD.

(1) If the inspection was done on or after the effective date of this AD: Submit the report within 30 days after the inspection.

(2) If the inspection was done before the effective date of this AD: Submit the report within 30 days after the effective date of this AD.

(m) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs)*: The Manager, International Branch, ANM–116, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the International Branch, send it to ATTN: Tom Rodriguez, Aerospace Engineer, International Branch, ANM–116, Transport Airplane Directorate, FAA, 1601 Lind Avenue SW., Renton, WA 98057–3356; telephone 425–227–1137; fax 425–227–1149. Information may be emailed to: 9-ANM-116-AMOC-REQUESTS@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office. The AMOC approval letter must specifically reference this AD.

(2) *Contacting the Manufacturer*: For any requirement in this AD to obtain corrective actions from a manufacturer, the action must be accomplished using a method approved by the Manager, International Branch, ANM–116, Transport Airplane Directorate, FAA; or the EASA; or Fokker Service B.V.'s EASA DOA. If approved by the DOA, the approval must include the DOA-authorized signature.

(3) *Reporting Requirements*: A federal agency may not conduct or sponsor, and a person is not required to respond to, nor shall a person be subject to a penalty for failure to comply with a collection of information subject to the requirements of the Paperwork Reduction Act unless that collection of information displays a current valid OMB Control Number. The OMB Control Number for this information

collection is 2120–0056. Public reporting for this collection of information is estimated to be approximately 5 minutes per response, including the time for reviewing instructions, completing and reviewing the collection of information. All responses to this collection of information are mandatory. Comments concerning the accuracy of this burden and suggestions for reducing the burden should be directed to the FAA at: 800 Independence Ave. SW., Washington, DC 20591, Attn: Information Collection Clearance Officer, AES–200.

(n) Related Information

(1) Refer to Mandatory Continuing Airworthiness Information (MCAI) EASA Airworthiness Directive 2015–0113, dated June 22, 2015, for related information. This MCAI may be found in the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA–2016–7271.

(2) For service information identified in this AD, contact Fokker Services B.V., Technical Services Dept., P.O. Box 1357, 2130 EL Hoofddorp, the Netherlands; telephone +31 (0)88–6280–350; fax +31 (0)88–6280–111; email technicalservices@fokker.com; Internet <http://www.myfokkerfleet.com>. You may view this service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425–227–1221.

Issued in Renton, Washington, on June 14, 2016.

Dionne Palermo,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 2016–14754 Filed 6–22–16; 8:45 am]

BILLING CODE 4910–13–P

ENVIRONMENTAL PROTECTION AGENCY**40 CFR Part 52**

[EPA–R07–OAR–2014–0213; FRL–9948–16–Region 7]

Approval and Promulgation of Implementation Plans; State of Iowa; Infrastructure SIP Requirements for the 1997 and 2006 Fine Particulate Matter (PM_{2.5}) National Ambient Air Quality Standards (NAAQS), and the Adoption of the 1997 PM_{2.5} Standard

AGENCY: Environmental Protection Agency (EPA).

ACTION: Proposed rule.

SUMMARY: The Environmental Protection Agency (EPA) is proposing to approve elements of two State Implementation Plan (SIP) submissions from the State of Iowa for the Infrastructure SIP Requirements for the 1997 and 2006 Fine Particulate Matter (PM_{2.5}) National Ambient Air Quality Standards