

(h) Repair

If any crack is found during any inspection required by this AD, and Boeing Alert Service Bulletin 767–53A0266, dated April 20, 2015, specifies to contact Boeing for repair instructions: Before further flight, repair the crack in accordance with the procedures specified in paragraph (j) of this AD. Accomplishing a reinforcing repair terminates the inspections required by paragraph (g) of this AD in the area under the repair only.

(i) Exceptions to the Service Information

Where Boeing Alert Service Bulletin 767–53A0266, dated April 20, 2015, specifies a compliance time “after the original issue date of this service bulletin,” this AD requires compliance within the specified time after the effective date of this AD.

(j) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Seattle Aircraft Certification Office (ACO), FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the ACO, send it to the attention of the person identified in paragraph (k) of this AD. Information may be emailed to: 9-ANM-Seattle-ACO-AMOC-Requests@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(3) An AMOC that provides an acceptable level of safety may be used for any repair required by this AD if it is approved by the Boeing Commercial Airplanes Organization Designation Authorization (ODA) that has been authorized by the Manager, Seattle ACO, to make those findings. For a repair method to be approved, the repair must meet the certification basis of the airplane, and the approval must specifically refer to this AD.

(4) Except as required by paragraph (h) of this AD: For service information that contains steps that are labeled as Required for Compliance (RC), the provisions of paragraphs (j)(4)(i) and (j)(4)(ii) apply.

(i) The steps labeled as RC, including substeps under an RC step and any figures identified in an RC step, must be done to comply with the AD. An AMOC is required for any deviations to RC steps, including substeps and identified figures.

(ii) Steps not labeled as RC may be deviated from using accepted methods in accordance with the operator's maintenance or inspection program without obtaining approval of an AMOC, provided the RC steps, including substeps and identified figures, can still be done as specified, and the airplane can be put back in an airworthy condition.

(k) Related Information

For more information about this AD, contact Wayne Lockett, Aerospace Engineer, Airframe Branch, ANM–120S, FAA, Seattle Aircraft Certification Office (ACO), 1601 Lind

Avenue SW., Renton, WA 98057–3356; phone: 425–917–6447; fax: 425–917–6590; email: wayne.lockett@faa.gov.

(l) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Boeing Alert Service Bulletin 767–53A0266, dated April 20, 2015.

(ii) Reserved.

(3) For service information identified in this AD, contact Boeing Commercial Airplanes, Attention: Data & Services Management, P.O. Box 3707, MC 2H–65, Seattle, WA 98124–2207; telephone 206–544–5000, extension 1; fax 206–766–5680; Internet <https://www.myboeingfleet.com>.

(4) You may view this service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425–227–1221.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202–741–6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on June 14, 2016.

Dionne Palermo,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 2016–14752 Filed 6–24–16; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF TRANSPORTATION**Federal Aviation Administration****14 CFR Part 39**

[Docket No. FAA–2015–8432; Directorate Identifier 2015–NM–100–AD; Amendment 39–18570; AD 2016–13–06]

RIN 2120–AA64

Airworthiness Directives; Saab AB, Saab Aeronautics (Type Certificate Previously Held by Saab AB, Saab Aerosystems) Airplanes

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Final rule.

SUMMARY: We are adopting a new airworthiness directive (AD) for certain Saab AB, Saab Aeronautics Model 340A (SAAB/SF340A) and SAAB 340B airplanes. This AD was prompted by reports of ruptured horizontal stabilizer de-icing boots. This AD requires a

revision of the applicable airplane flight manual (AFM), repetitive inspections of the horizontal stabilizer de-icing boots, and applicable corrective actions. We are issuing this AD to detect and correct damage of the de-icing boot; such damage could lead to a ruptured boot, severe vibrations, and possible reduced control of the airplane.

DATES: This AD is effective August 1, 2016.

The Director of the Federal Register approved the incorporation by reference of certain publications listed in this AD as of August 1, 2016.

ADDRESSES: For service information identified in this final rule, contact Saab AB, Saab Aeronautics, SE–581 88, Linköping, Sweden; telephone +46 13 18 5591; fax +46 13 18 4874; email saab340techsupport@saabgroup.com; Internet <http://www.saabgroup.com>. You may view this referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425–227–1221. It is also available on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA–2015–8432.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA–2015–8432; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Office (telephone 800–647–5527) is Docket Management Facility, U.S. Department of Transportation, Docket Operations, M–30, West Building Ground Floor, Room W12–140, 1200 New Jersey Avenue SE., Washington, DC 20590.

FOR FURTHER INFORMATION CONTACT: Shahram Daneshmandi, Aerospace Engineer, International Branch, ANM–116, Transport Airplane Directorate, FAA, 1601 Lind Avenue SW., Renton, WA 98057–3356; telephone (425) 227–1112; fax (425) 227–1149.

SUPPLEMENTARY INFORMATION:**Discussion**

We issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 by adding an AD that would apply to certain Saab AB, Saab Aeronautics Model 340A (SAAB/SF340A) and SAAB 340B airplanes. The

NPRM published in the **Federal Register** on January 13, 2016 (81 FR 1588) (“the NPRM”). The NPRM was prompted by reports of ruptured horizontal stabilizer de-icing boots. The NPRM proposed to require a revision of the applicable AFM, repetitive inspections of the horizontal stabilizer de-icing boots, and applicable corrective actions. We are issuing this AD to detect and correct damage of the de-icing boot; such damage could lead to a ruptured boot, severe vibrations, and possible reduced control of the airplane.

The European Aviation Safety Agency (EASA), which is the Technical Agent for Member States of the European Union, has issued EASA Airworthiness Directive 2015–0129, dated July 6, 2015 (referred to after this as the Mandatory Continuing Airworthiness Information, or “the MCAI”), to correct an unsafe condition for certain Saab AB, Saab Aeronautics Model 340A (SAAB/SF340A) and SAAB 340B airplanes. The MCAI states:

There have been some reported events of ruptured horizontal stabilizer de-icing boots. In-flight rupture of a de-icing boot will result in complete loss of the de-icing function within its associated zone. In addition, in some of these events, the de-icing boot had formed a large open scoop.

This condition, if not detected and corrected, could lead to severe vibrations, possibly resulting in reduced control of the aeroplane.

To address this potential unsafe condition, SAAB issued Alert Operations Bulletin (AOB) No. 12 and AOB No. 23 as a temporary measure, recommending performing a flap 0 landing in the event of a suspected rupture of the de-icing boot on the horizontal stabilizer.

In addition, SAAB issued SB 340–30–094 to provide instructions to inspect the affected de-icing boots.

For the reasons described above, this [EASA] AD requires an amendment of the applicable Airplane Flight Manual (AFM) and, pending the development of a modification by SAAB, repetitive inspections of the horizontal stabilizer de-icing boots and, depending on findings, accomplishment of applicable corrective action(s).

This [EASA] AD is considered to be an interim action and further AD action may follow.

You may examine the MCAI in the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA–2015–8432.

Comments

We gave the public the opportunity to participate in developing this AD. The following presents the comments received on the NPRM and the FAA’s response to each comment.

Request To Revise Paragraph (g) To Allow Later Approved Revisions of AFMs

Saab AB, Saab Aeronautics requested that we revise paragraph (g) of the proposed AD to state that the use of later-approved revisions of the applicable AFMs is also acceptable for compliance with the proposed AD.

We do not agree. When referring to specific service information in an AD, using the phrase, “or later FAA-approved revisions,” violates Office of the Federal Register regulations for approving materials that are incorporated by reference. However, affected operators may request approval to use a later revision of the referenced service information as an alternative method of compliance, under the provisions of paragraph (i)(1) of this AD. We have not changed this AD in this regard.

Request To Expand Description of Inspection

Saab AB, Saab Aeronautics also requested that we revise paragraph (h) of the proposed AD to explain that the inspection is not only for damage, but also for existing repairs. The commenter stated that the inspection of existing repairs is described in Saab Service Bulletin 340–30–094, dated March 27, 2015, but missing from paragraph (h) of the proposed AD.

We agree with the request. The referenced service information specifies inspecting for damage of the de-icing boots, and a sub-step specifies to “make sure that already made repairs are within specified limits.” That action was not specifically stated in the proposed AD. We have clarified the requirement by changing paragraph (h) of this AD to ensure that de-icing boots as well as existing repairs are within specified limits.

Request To Change the Repetitive Inspection Interval to 600 Flight Hours

PenAir requested a change to the repetitive inspection interval. The commenter requested that the repetitive inspection interval be increased from the proposed 400-flight-hour interval to a 600-flight-hour interval. The commenter also stated that in the event that a 600-flight-hour interval is determined to be unsuitable, then a 450-flight-hour interval should be used. The commenter stated that this change would align with scheduled E-check inspections, alleviate the undue burden of creating maintenance outside of scheduled computerized aircraft maintenance program inspections, and maintain safe operation of the airplane.

We do not agree with the commenter’s request to extend the compliance time. We have determined that the compliance time, as proposed, represents the maximum interval of time allowable for the affected airplanes to continue to operate safely before the next inspection is required. In addition, since maintenance schedules vary among operators, there would be no assurance that a different interval would satisfy all operators’ schedules. However, under the provisions of paragraph (i)(1) of this AD, we will consider requests for approval of an extension of the compliance time if sufficient data are submitted to substantiate that the new compliance time would provide an acceptable level of safety. We have not changed this AD in this regard.

Conclusion

We reviewed the relevant data, considered the comments received, and determined that air safety and the public interest require adopting this AD with the changes described previously and minor editorial changes. We have determined that these minor changes:

- Are consistent with the intent that was proposed in the NPRM for correcting the unsafe condition; and
- Do not add any additional burden upon the public than was already proposed in the NPRM.

We also determined that these changes will not increase the economic burden on any operator or increase the scope of this AD.

Related Service Information Under 1 CFR Part 51

We reviewed Saab Service Bulletin 340–30–094, dated March 27, 2015. The service information describes procedures for repetitive detailed inspections of the de-icing boots installed on the horizontal stabilizers, and repair and replacement of damaged de-icing boots.

We also reviewed the following AFMs, which describe performance limitations and general data:

- Saab AFM 340A 001, Revision 57, dated March 27, 2015.
- Saab AFM 340B 001, Revision 35, dated March 27, 2015.
- Saab AFM 340B 010, Revision 28, dated March 27, 2015.

This service information is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the **ADDRESSES** section.

Costs of Compliance

We estimate that this AD affects 92 airplanes of U.S. registry.

We also estimate that it will take about 6 work-hours per product to comply with the basic requirements of this AD. The average labor rate is \$85 per work-hour. Required parts will cost about \$0 per product. Based on these figures, we estimate the cost of this AD on U.S. operators to be \$46,920, or \$510 per product.

In addition, we estimate that any necessary follow-on actions would take about 6 work-hours and require parts costing \$9,500, for a cost of \$10,010 per product. We have no way of determining the number of aircraft that might need these actions.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. "Subtitle VII: Aviation Programs," describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in "Subtitle VII, Part A, Subpart III, Section 44701: General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We determined that this AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

1. Is not a "significant regulatory action" under Executive Order 12866;
2. Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979);
3. Will not affect intrastate aviation in Alaska; and
4. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

2016–13–06 Saab AB, Saab Aeronautics (Type Certificate Previously Held by Saab AB, Saab Aerosystems): Amendment 39–18570. Docket No. FAA–2015–8432; Directorate Identifier 2015–NM–100–AD.

(a) Effective Date

This AD is effective August 1, 2016.

(b) Affected ADs

None.

(c) Applicability

This AD applies to Saab AB, Saab Aeronautics (Type Certificate Previously Held by Saab AB, Saab Aerosystems) airplanes, certificated in any category, identified in paragraphs (c)(1) and (c)(2) of this AD.

(1) Saab AB, Saab Aeronautics Model 340A (SAAB/SF340A) airplanes, serial numbers (S/Ns) 004 through 138 inclusive, on which Saab Modification 1462 has been embodied in production, or Saab Service Bulletin 340–55–008 has been embodied in service, except those on which Saab Modification 1793 has also been embodied in production, or Saab Service Bulletin 340–55–010 has been embodied in service; and Saab AB, Saab Aeronautics Model 340A (SAAB/SF340A) airplanes, S/Ns 139 through 159 inclusive. Applicable Saab AB, Saab Aeronautics Model 340A (SAAB/SF340A) airplanes S/N 004–138, Post Modification No. 1462 but Pre Modification No. 1793, have a maximum flap setting of 35 degrees instead of 20 degrees, and horizontal stabilizer boots with spanwise tubes instead of chordwise tubes.

(2) Saab AB, Saab Aeronautics Model SAAB 340B airplanes, S/Ns 160 through 459 inclusive.

(d) Subject

Air Transport Association (ATA) of America Code 30, Ice and Rain Protection.

(e) Reason

This AD was prompted by reports of ruptured horizontal stabilizer de-icing boots. We are issuing this AD to detect and correct damage of the de-icing boot; such damage

could lead to a ruptured boot, severe vibrations, and possible reduced control of the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Revision of the Airplane Flight Manual (AFM)

Within 30 days after the effective date of this AD, revise the "Abnormal Procedures" section of the applicable Saab 340 AFM to incorporate the revision specified in paragraphs (g)(1) through (g)(3) of this AD.

(1) For Saab AB, Saab Aeronautics Model 340A (SAAB/SF340A) airplanes, revise AFM 340A 001 by incorporating Revision 57, dated March 27, 2015.

(2) For Saab AB, Saab Aeronautics Model SAAB 340B airplanes, revise AFM 340B 001 by incorporating Revision 35, dated March 27, 2015.

(3) For Saab AB, Saab Aeronautics Model SAAB 340B airplanes with extended wing tips, revise AFM 340B 010 by incorporating Revision 28, dated March 27, 2015.

(h) Inspection/Replacement

Within 400 flight hours or 6 months, whichever occurs first after the effective date of this AD, do a detailed inspection for damage of the horizontal stabilizer de-icing boots, and existing repairs of horizontal stabilizer de-icing boots, in accordance with the Accomplishment Instructions of Saab Service Bulletin 340–30–094, dated March 27, 2015. Repeat the inspection thereafter at intervals not to exceed 400 flight hours. If, during any inspection required by this paragraph, any damage or existing repair outside the limits specified in Saab Service Bulletin 340–30–094, dated March 27, 2015, is found, before further flight, repair or replace the horizontal stabilizer de-icing boots, in accordance with the Accomplishment Instructions of Saab Service Bulletin 340–30–094, dated March 27, 2015. Repair or replacement on an airplane of the horizontal stabilizer de-icing boots, as required by this paragraph, does not constitute terminating action for the repetitive inspections required by this paragraph for that airplane.

(i) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs):* The Manager, International Branch, ANM–116, Transport Airplane Directorate, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the International Branch, send it to ATTN: Shahram Daneshmandi, Aerospace Engineer, International Branch, ANM–116, Transport Airplane Directorate, FAA, 1601 Lind Avenue SW., Renton, WA 98057–3356; telephone 425–227–1112; fax 425–227–1149. Information may be emailed to: 9-ANM-116-AMOC-REQUESTS@faa.gov. Before using

any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office. The AMOC approval letter must specifically reference this AD.

(2) *Contacting the Manufacturer:* For any requirement in this AD to obtain corrective actions from a manufacturer, the action must be accomplished using a method approved by the Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA; or the European Aviation Safety Agency (EASA); or Saab AB, Saab Aeronautics' EASA Design Organization Approval (DOA). If approved by the DOA, the approval must include the DOA-authorized signature.

(j) Related Information

Refer to Mandatory Continuing Airworthiness Information (MCAI) EASA Airworthiness Directive 2015-0129, dated July 6, 2015, for related information. This MCAI may be found in the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2015-8432.

(k) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) Saab Service Bulletin 340-30-094, dated March 27, 2015.

(ii) Saab AFM 340A 001, Revision 57, dated March 27, 2015.

(iii) Saab AFM 340B 001, Revision 35, dated March 27, 2015.

(iv) Saab AFM 340B 010, Revision 28, dated March 27, 2015.

(3) For service information identified in this AD, contact Saab AB, Saab Aeronautics, SE-581 88, Linköping, Sweden; telephone +46 13 18 5591; fax +46 13 18 4874; email saab340techsupport@saabgroup.com; Internet <http://www.saabgroup.com>.

(4) You may view this service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on June 13, 2016.

Dionne Palermo,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 2016-14871 Filed 6-24-16; 8:45 am]

BILLING CODE 4910-13-P

COMMODITY FUTURES TRADING COMMISSION

17 CFR Part 143

RIN 3038-AE45

Adjustment of Civil Monetary Penalties for Inflation

AGENCY: Commodity Futures Trading Commission.

ACTION: Interim final rule.

SUMMARY: The Commodity Futures Trading Commission (Commission) is amending its rule that governs the maximum amount of civil monetary penalties, to adjust for inflation. This rule sets forth the maximum, inflation-adjusted dollar amount for civil monetary penalties (CMPs) assessable for violations of the Commodity Exchange Act (CEA) and Commission rules, regulations and orders thereunder. The rule, as amended, implements the Federal Civil Penalties Inflation Adjustment Act of 1990, as amended.

DATES: Effective Date: This interim final rule is effective August 1, 2016.

FOR FURTHER INFORMATION CONTACT: Edward J. Riccobene, Associate Chief Counsel, Division of Enforcement, at (202) 418-5327 or ericcobene@cftc.gov, Commodity Futures Trading Commission, 1155 21st Street NW., Washington, DC 20581.

SUPPLEMENTARY INFORMATION:

I. Background

The Federal Civil Penalties Inflation Adjustment Act of 1990 (FCPIAA)¹ requires the head of each Federal agency to periodically adjust for inflation the minimum and maximum amount of CMPs provided by law within the jurisdiction of that agency.² On November 2, 2015, the President signed into law the Federal Civil Penalties Inflation Adjustment Act Improvements Act of 2015 (the 2015 Act),³ which further amended the FCPIAA to

¹ The FCPIAA, Public Law 101-410 (1990), as amended, is codified at 28 U.S.C. 2461 note. The FCPIAA states that the purpose of the act is to establish a mechanism that (1) allows for regular adjustment for inflation of civil monetary penalties; (2) maintains the deterrent effect of civil monetary penalties and promote compliance with the law; and (3) improves the collection by the Federal Government of civil monetary penalties.

² For the relevant CMPs within the Commission's jurisdiction, the Act provides only for maximum amounts that can be assessed for each violation of the Act or the rules, regulations and orders promulgated thereunder; the Act does not set forth any minimum penalties. Therefore, the remainder of this release will refer only to CMP maximums.

³ See 2015 Act, Public Law 114-74, 129 Stat. 584 (2015), title VII, Section 701.

improve the effectiveness of civil monetary penalties and to maintain their deterrent effect. The 2015 Act requires agencies to: (1) Adjust the level of civil monetary penalties with an initial "catch-up" adjustment through an interim final rulemaking; and (2) make subsequent annual adjustments for inflation.⁴ Agencies are required to publish interim final rules with the initial penalty adjustment amounts by July 1, 2016, and the new penalty levels must take effect no later than August 1, 2016.⁵

II. Commodity Exchange Act Civil Monetary Penalties

The inflation adjustment requirement applies to any penalty, fine or other sanction that (A) is for a specific monetary amount as provided by Federal law or has a maximum amount provided for by Federal law; (B) is assessed or enforced by an agency pursuant to Federal law; and (C) is assessed or enforced pursuant to an administrative proceeding or a civil action in the Federal courts. 28 U.S.C. 2461 note. The CEA provides for CMPs that meet the above definition and are, therefore, subject to the inflation adjustment in the following instances: Sections 6(c), 6(d), 6b, and 6c of the CEA.⁶

Section 6(c) of the CEA,⁷ as adjusted by the FCPIAA,⁸ currently sets the maximum CMP that may be imposed by the Commission in an administrative proceeding on "any person (other than a registered entity)" for: (1) Each violation of Section 6(c) of the CEA or any other provisions of the Act or of the rules, regulations, or orders of the Commission thereunder to the greater of \$140,000 or triple the monetary gain to the violator; and (2) any manipulation or attempted manipulation in violation of Section 6(c) or 9(a)(2) of the CEA to the greater of \$1,000,000 or triple the monetary gain to the violator.

Section 6(d) of the CEA,⁹ as adjusted by the FCPIAA,¹⁰ currently sets the maximum CMP that may be imposed by the Commission in an administrative proceeding on "any person (other than a registered entity)"¹¹ for violations of

⁴ *Id.*, Section 701(b). Rule 143.8(b) is amended to reflect the change to annual adjustments from "once every four years."

⁵ 2015 Act, Section 701(b).

⁶ 7 U.S.C. 9, 13a, 13a-1, 13b.

⁷ 7 U.S.C. 9.

⁸ See 17 CFR 143.8(a)(1).

⁹ 7 U.S.C. 13b.

¹⁰ See 17 CFR 143.8(a)(2).

¹¹ The term "registered entity" is a defined term under the CEA. Section 1a(40) provides that the term "registered entity" means (A) a board of trade designated as a contract market under section 7 of