

TABLE 1 TO PARAGRAPH (C) OF THIS AD—APPLICABLE ENGINES AND FUEL PUMP HOSE ASSEMBLIES—Continued

Engine	Manufacturer's hose name	Manufacturer's part No. (P/N)	Hose description
LTIO-540-J2BD (left wing)	Hose Assembly—Fuel	Piper 39995-034	Inlet fuel hose to engine fuel pump.

(d) Subject

Joint Aircraft System Component (JASC)/ Air Transport Association (ATA) of America Code 73: Engine Fuel and Control.

(e) Unsafe Condition

This AD was prompted by a report of an engine fire caused by a leak in the fuel pump inlet hose. We are issuing this AD to correct the unsafe condition on these products.

(f) Compliance

Comply with this AD within the compliance times specified in paragraphs (g)(1) through (j)(2) of this AD, unless already done.

(g) Ensure Proper Clearance Between the Fuel Hose Assembly and the Turbocharger Support Assembly

(1) Within the next 60 hours time-in-service (TIS) after the effective date of this AD or within the next 6 months after the effective date of this AD, whichever occurs first, inspect to determine the clearance between the inlet and exit fuel hose assemblies listed in table 1 to paragraph (c) of this AD, and each turbocharger support assembly, Lycoming P/N LW-18302. There should be a minimum $\frac{3}{16}$ -inch clearance. Do the inspection following the INSTRUCTIONS section of Piper Aircraft, Inc. Service Bulletin No. 1257A, dated August 4, 2015.

(2) Before further flight after the inspection required in paragraph (g)(1) of this AD, if the measured clearance is less than $\frac{3}{16}$ -inch, make all necessary adjustments to make the clearance a minimum of $\frac{3}{16}$ -inch between the inlet and exit fuel hose assemblies listed in table 1 to paragraph (c) of this AD and each turbocharger support assembly, Lycoming P/N LW-18302, following the INSTRUCTIONS section of Piper Aircraft, Inc. Service Bulletin No. 1257A, dated August 4, 2015.

(h) Visually Inspect the Fuel Hose Assembly and Replace if Necessary

(1) Within the next 60 hours TIS after the effective date of this AD or within the next 6 months after the effective date of this AD, whichever occurs first, visually inspect the inlet and exit fuel hose assemblies listed in table 1 to paragraph (c) of this AD for evidence of leaking, cracking, chafing, and any other sign of damage. Do the inspection following the INSTRUCTIONS section of Piper Aircraft, Inc. Service Bulletin No. 1257A, dated August 4, 2015.

(2) Before further flight after the inspection required in paragraph (h)(1) of this AD, if any evidence of leaking, cracking, chafing, or any other sign of damage is found in any inlet or exit fuel hose assembly listed in table 1 to paragraph (c) of this AD, replace the fuel hose assembly with a serviceable part. Do the replacement following the INSTRUCTIONS

section of Piper Aircraft, Inc. Service Bulletin No. 1257A, dated August 4, 2015.

(i) Visually Inspect the Turbocharger Support Assembly and Replace if Necessary

(1) Within the next 60 hours TIS after the effective date of this AD or within the next 6 months after the effective date of this AD, whichever occurs first, visually inspect each turbocharger support assembly, Lycoming P/N LW-18302, for evidence of chafing and any other signs of damage. Do the inspection following the INSTRUCTIONS section of Piper Aircraft, Inc. Service Bulletin No. 1257A, dated August 4, 2015.

(2) Before further flight after the inspection required in paragraph (i)(1) of this AD, if any evidence of chafing or any other sign of damage is found on any turbocharger support assembly, replace Lycoming P/N LW-18302 with a serviceable part. Do the replacement following the INSTRUCTIONS section of Piper Aircraft, Inc. Service Bulletin No. 1257A, dated August 4, 2015.

(j) Engine Run-Up

(1) If any fuel line component was adjusted or replaced during any actions required in paragraphs (g)(1) through (i)(2) of this AD, before further flight, perform an engine run-up on the ground to check for leaks. Do the engine run-up following the INSTRUCTIONS section of Piper Aircraft, Inc. Service Bulletin No. 1257A, dated August 4, 2015.

(2) If any leaks found during the engine run-up required in paragraph (j)(1) of this AD emanate from any fuel line component adjusted, repaired, or replaced during any actions required in paragraphs (g)(1) through (i)(2) of this AD, before further flight, take all necessary corrective actions following the INSTRUCTIONS section of Piper Aircraft, Inc. Service Bulletin No. 1257A, dated August 4, 2015.

(k) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Atlanta Aircraft Certification Office (ACO), FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the ACO, send it to the attention of the person identified in the Related Information section of this AD.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(l) Related Information

(1) For more information about this AD, contact Gary Wechsler, Aerospace Engineer,

FAA, Atlanta ACO, 1701 Columbia Avenue, College Park, Georgia 30337; telephone: (404) 474-5575; fax: (404) 474-5606; email: gary.wechsler@faa.gov.

(2) For service information identified in this AD, contact Piper Aircraft, Inc., 926 Piper Drive, Vero Beach, Florida 32960; telephone: (772) 567-4361; fax: (772) 978-6573; Internet: www.piper.com/home/pages/Publications.cfm. You may review copies of the referenced service information at the FAA, Small Airplane Directorate, 901 Locust, Kansas City, Missouri 64106. For information on the availability of this material at the FAA, call (816) 329-4148.

Issued in Kansas City, Missouri, on January 16, 2016.

Melvin Johnson,

Acting Manager, Small Airplane Directorate, Aircraft Certification Service.

[FR Doc. 2016-01380 Filed 1-25-16; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION**Federal Aviation Administration****14 CFR Part 39**

[Docket No. FAA-2016-1363; Directorate Identifier 2015-CE-040-AD]

RIN 2120-AA64

Airworthiness Directives; Mitsubishi Heavy Industries, Ltd. Airplanes

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: We propose to adopt a new airworthiness directive (AD) for certain Mitsubishi Heavy Industries, Ltd. Models MU-2B-30, MU-2B-35, MU-2B-36, MU-2B-36A, and MU-2B-60 airplanes. This proposed AD results from mandatory continuing airworthiness information (MCAI) originated by an aviation authority of another country to identify and correct an unsafe condition on an aviation product. The MCAI describes the unsafe condition as reports of cracks found in the attach fittings of the main landing gear oleo strut. We are issuing this proposed AD to require actions to address the unsafe condition on these products.

DATES: We must receive comments on this proposed AD by March 11, 2016.

ADDRESSES: You may send comments by any of the following methods:

- **Federal eRulemaking Portal:** Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.
- **Fax:** (202) 493-2251.
- **Mail:** U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC 20590.
- **Hand Delivery:** U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC 20590, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this proposed AD, contact Mitsubishi Heavy Industries America, Inc., c/o Turbine Aircraft Services, Inc., 4550 Jimmy Doolittle Drive, Addison, Texas 75001; telephone: (972) 248-3108, ext. 209; fax: (972) 248-3321; Internet: <http://mu-2aircraft.com>. You may review this referenced service information at the FAA, Small Airplane Directorate, 901 Locust, Kansas City, Missouri 64106. For information on the availability of this material at the FAA, call (816) 329-4148.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2016-1363; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this proposed AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Office (telephone (800) 647-5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT: Andrew McAnaul, Aerospace Engineer, FAA, ASW-143 (c/o San Antonio MIDO), 10100 Reunion Place, Suite 650, San Antonio, Texas 78216; phone: (210) 308-3365; fax: (210) 308-3370; email: andrew.mcanaul@faa.gov.

SUPPLEMENTARY INFORMATION:

Comments Invited

We invite you to send any written relevant data, views, or arguments about this proposed AD. Send your comments to an address listed under the **ADDRESSES** section. Include "Docket No. FAA-2016-1363; Directorate Identifier 2015-CE-040-AD" at the beginning of your comments. We specifically invite

comments on the overall regulatory, economic, environmental, and energy aspects of this proposed AD. We will consider all comments received by the closing date and may amend this proposed AD because of those comments.

We will post all comments we receive, without change, to <http://www.regulations.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact we receive about this proposed AD.

Discussion

The Japan Civil Aviation Bureau (JCAB), which is the aviation authority for Japan, has issued AD No. TCD-8595-2015, dated July 1, 2015 (referred to after this as "the MCAI"), to correct an unsafe condition for certain Mitsubishi Heavy Industries, Ltd. (MHI) Models MU-2B-30, MU-2B-35, and MU-2B-36 airplanes. You may examine the MCAI on the Internet at <http://www.regulations.gov> by searching for and locating it in Docket No. FAA-2016-1363.

We have received reports of seven failures of the main landing gear oleo strut attach fitting on certain MHI Models MU-2B-30, MU-2B-35, MU-2B-36, MU-2B-36A, and MU-2B-60 airplanes. Investigation revealed that the failures resulted from improper lubrication and/or hard landings, which caused cracks to develop in the main landing gear oleo strut attach fitting.

Japan is the State of Design for MHI Models MU-2B-30, MU-2B-35, and MU-2B-36, which the MCAI AD applies to, and the United States is the State of Design for MHI Models MU-2B-36A and MU-2B-60 airplanes.

Related Service Information Under 1 CFR Part 51

Mitsubishi Heavy Industries, Ltd. has issued MU-2 Service Bulletin No. 243, dated June 30, 2015, and MU-2 Service Bulletin No. 105/32-017, dated September 29, 2015. These service bulletins describe procedures for visually inspecting the lugs of the oleo attach fittings on both sides for cracks, and if any visible cracks are found, replacing with a new fitting. Mitsubishi Heavy Industries, Ltd. has also issued MU-2 Service News JCAB T.C.: No. 171, FAA T.C.: No. 124/32-011, dated April 27, 2012, and MU-2 Service News JCAB T.C.: No. 176, FAA T.C.: No. 128/32-013, dated July 18, 2013. This service information specifies doing repetitive ultrasound inspections of the main landing gear oleo upper attach fittings for cracks and ensuring proper lubrication of the main landing gear

oleo fitting. All the related service information is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the **ADDRESSES** section of this NPRM.

FAA's Determination and Requirements of the Proposed AD

This product has been approved by the aviation authority of another country, and is approved for operation in the United States. Pursuant to our bilateral agreement with this State of Design Authority, they have notified us of the unsafe condition described in the MCAI and service information referenced above. We are proposing this AD because we evaluated all information and determined the unsafe condition exists and is likely to exist or develop on other products of the same type design.

Differences Between This Proposed AD and the MCAI

We have determined that the repetitive visual inspections specified in the MCAI are not adequate for detecting cracks in the main landing gear oleo strut attach fitting. Repetitive ultrasonic inspections of the main landing gear oleo strut attach fitting have been added into the maintenance requirement manual for these airplanes, which is not considered mandatory in the FAA's airworthiness regulatory system. Therefore, we are proposing to incorporate that requirement through the rulemaking process.

Costs of Compliance

We estimate that this proposed AD will affect 95 products of U.S. registry. We also estimate that it would take about 5 work-hours per product to comply with the visual inspection requirement of this proposed AD. The average labor rate is \$85 per work-hour.

Based on these figures, we estimate the cost of the visual inspection requirements of this proposed AD on U.S. operators to be \$40,375, or \$425 per product.

We also estimate that it would take about 3 work-hours per product to comply with the ultrasound inspection requirements of this proposed AD. The average labor rate is \$85 per work-hour.

Based on these figures, we estimate the cost of the ultrasound inspection requirements of this proposed AD on U.S. operators to be \$24,225, or \$255 per product.

Owner/operators have the option to do an ultrasound inspection in lieu of the required visual inspection.

In addition, we estimate that any necessary follow-on actions would take

about 24 work-hours and require parts costing \$5,220, for a cost of \$7,260 per product to replace the left-hand main landing gear oleo strut. We have no way of determining the number of products that may need this action.

In addition, we also estimate that any necessary follow-on actions would take about 45 work-hours and require parts costing \$5,220, for a cost of \$9,045 per product to replace the right-hand main landing gear oleo strut. We have no way of determining the number of products that may need this action.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. "Subtitle VII: Aviation Programs," describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in "Subtitle VII, Part A, Subpart III, section 44701: General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

- (1) Is not a "significant regulatory action" under Executive Order 12866,
- (2) Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979),
- (3) Will not affect intrastate aviation in Alaska, and
- (4) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 Amended]

- 2. The FAA amends § 39.13 by adding the following new AD:

Mitsubishi Heavy Industries, Ltd.: Docket No. FAA-2016-1363; Directorate Identifier 2015-CE-040-AD.

(a) Comments Due Date

We must receive comments by March 11, 2016.

(b) Affected ADs

None.

(c) Applicability

This AD applies to Mitsubishi Heavy Industries, Ltd. Models MU-2B-30, MU-2B-35, MU-2B-36 airplanes, serial numbers 502 through 696, except 652 and 661, and Models MU-2B-36A and MU-2B-60 airplanes, serial numbers 661SA, and 697SA through 1569SA, certificated in any category.

(d) Subject

Air Transport Association of America (ATA) Code 32: Landing Gear.

(e) Reason

This AD was prompted by mandatory continuing airworthiness information (MCAI) originated by an aviation authority of another country to identify and correct an unsafe condition on an aviation product. The MCAI describes the unsafe condition as reports of cracks found in the fittings of the main landing gear oleo strut. We are issuing this proposed AD to prevent failure of the main landing gear oleo strut attach fitting, which could cause the landing gear to fail and result in loss of control.

(f) Actions and Compliance

Unless already done, do the following actions:

- (1) Within the next 100 hours time-in-service (TIS) after the effective date of this AD or within the next 6 months after the effective date of this AD, whichever occurs first, do a visual inspection of the main landing gear oleo upper attach fittings for cracks. Do the inspection following the INSTRUCTIONS section in Mitsubishi Heavy Industries, Ltd. MU-2 Service Bulletin No. 243, dated June 30, 2015, and the INSTRUCTIONS section in Mitsubishi Heavy

Industries, Ltd. MU-2 Service Bulletin No. 105/32-017, dated September 29, 2015, as applicable.

(2) Before further flight after the inspection required in paragraph (f)(1) of this AD, if no signs of cracks are found, lubricate the pin assembly attached to the main landing gear oleo attach fitting as specified in Mitsubishi Heavy Industries, Ltd. MU-2 Service News JCAB T.C.: No. 171, FAA T.C.: No. 124/32-011, dated April 27, 2012.

(3) Within the next 100 hours TIS after doing the initial visual inspection required in paragraph (f)(1) of this AD or within the next 12 months after doing the initial visual inspection required in paragraph (f)(1) of this AD, whichever occurs first, do an ultrasound inspection of the main landing gear oleo upper attach fittings for cracks as specified in Mitsubishi Heavy Industries, Ltd. MU-2 Service News JCAB T.C.: No. 176, FAA T.C.: No. 128/32-013, dated July 18, 2013. This ultrasound inspection may also be done in place of the visual inspection required in paragraph (f)(1) of this AD if done within the next 100 hours TIS after the effective date of this AD or within the next 6 months after the effective date of this AD, whichever occurs first. Repetitively thereafter inspect every 600 hours TIS or 36 months, whichever occurs first, and any time a hard landing or overweight landing occurs.

(4) Before further flight after any inspection required in paragraph (f)(3) of this AD, if no signs of cracks are found, lubricate the pin assembly attached to the main landing gear oleo attach fitting as specified in Mitsubishi Heavy Industries, Ltd. MU-2 Service News JCAB T.C.: No. 171, FAA T.C.: No. 124/32-011, dated April 27, 2012, and Mitsubishi Heavy Industries, Ltd. MU-2 Service News JCAB T.C.: No. 176, FAA T.C.: No. 128/32-013, dated July 18, 2013.

(5) Before further flight after any inspection required in paragraph (f)(1) and (f)(3) of this AD where cracks are found, replace the main landing gear oleo upper attach fittings following the INSTRUCTIONS section in Mitsubishi Heavy Industries, Ltd. MU-2 Service Bulletin No. 243, dated June 30, 2015, and the INSTRUCTIONS sections in Mitsubishi Heavy Industries, Ltd. MU-2 Service Bulletin No. 105/32-017, dated September 29, 2015, as applicable. After replacement, continue with the repetitive ultrasound inspection requirements of paragraph (f)(3) of this AD.

(g) Other FAA AD Provisions

The following provisions also apply to this AD:

- (1) *Alternative Methods of Compliance (AMOCs):* The Manager, Standards Office, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. Send information to ATTN: Andrew McAnaul, Aerospace Engineer, FAA, ASW-143 (c/o San Antonio MDO), 10100 Reunion Place, Suite 650, San Antonio, Texas 78216; phone: (210) 308-3365; fax: (210) 308-3370; email: andrew.mcanaul@faa.gov. Before using any approved AMOC on any airplane to which the AMOC applies, notify your appropriate principal inspector (PI) in the FAA Flight Standards District Office (FSDO), or lacking a PI, your local FSDO.

(2) *Airworthy Product*: For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they are approved by the State of Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

(h) Related Information

Refer to MCAI Japan Civil Aviation Bureau (JCAB) AD No. TCD-8585-2015, dated July 1, 2015, for related information. You may examine the MCAI on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2016-1363. For service information related to this AD, contact Mitsubishi Heavy Industries America, Inc., c/o Turbine Aircraft Services, Inc., 4550 Jimmy Doolittle Drive, Addison, Texas 75001; telephone: (972) 248-3108, ext. 209; fax: (972) 248-3321; Internet: <http://mu-2aircraft.com>. You may review this referenced service information at the FAA, Small Airplane Directorate, 901 Locust, Kansas City, Missouri 64106. For information on the availability of this material at the FAA, call (816) 329-4148.

Issued in Kansas City, Missouri, on January 16, 2016.

Melvin Johnson,

Acting Manager, Small Airplane Directorate, Aircraft Certification Service.

[FR Doc. 2016-01381 Filed 1-25-16; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 71

[Docket No. FAA-2015-4133; *Airspace Docket No. 15-ANM-27*]

Proposed Revocation of Class D Airspace; Vancouver, WA

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: This action proposes to remove Class D airspace at Pearson Field, Vancouver, WA. FAA Joint Order 7400.2K states that non-towered airports requiring a surface area will be designated Class E. Class E surface area airspace was established on December 10, 2015. The FAA is proposing this action due to the lack of an operating air traffic control tower at Pearson Field Airport, Vancouver, WA.

DATES: Comments must be received on or before March 11, 2016.

ADDRESSES: Send comments on this proposal to the U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor,

Room W12-140, 1200 New Jersey Avenue SE., Washington, DC 20590; telephone (202) 366-9826. You must identify FAA Docket No. FAA-2015-4133; Airspace Docket No. 15-ANM-27, at the beginning of your comments. You may also submit comments through the Internet at <http://www.regulations.gov>. You may review the public docket containing the proposal, any comments received, and any final disposition in person in the Dockets Office between 9:00 a.m. and 5:00 p.m., Monday through Friday, except Federal holidays. The Docket Office (telephone 1-800-647-5527), is on the ground floor of the building at the above address.

FAA Order 7400.9Z, Airspace Designations and Reporting Points, and subsequent amendments can be viewed online at http://www.faa.gov/air_traffic/publications/. For further information, you can contact the Airspace Policy Group, Federal Aviation Administration, 800 Independence Avenue SW., Washington, DC 20591; telephone: 202-267-8783. The Order is also available for inspection at the National Archives and Records Administration (NARA). For information on the availability of FAA Order 7400.9Z at NARA, call 202-741-6030, or go to http://www.archives.gov/federal_register/code_of_federal_regulations/ibr_locations.html.

FAA Order 7400.9, Airspace Designations and Reporting Points, is published yearly and effective on September 15.

FOR FURTHER INFORMATION CONTACT:

Steve Haga, Federal Aviation Administration, Operations Support Group, Western Service Center, 1601 Lind Avenue SW., Renton, WA 98057; telephone (425) 203-4563.

SUPPLEMENTARY INFORMATION:

Authority for This Rulemaking

The FAA's authority to issue rules regarding aviation safety is found in Title 49 of the United States Code. Subtitle I, Section 106 describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the agency's authority. This rulemaking is promulgated under the authority described in Subtitle VII, Part A, Subpart I, Section 40103. Under that section, the FAA is charged with prescribing regulations to assign the use of airspace necessary to ensure the safety of aircraft and the efficient use of airspace. This regulation is within the scope of that authority as it would remove Class D airspace at Pearson Field Airport, Vancouver, WA.

Comments Invited

Interested parties are invited to participate in this proposed rulemaking by submitting such written data, views, or arguments, as they may desire. Comments that provide the factual basis supporting the views and suggestions presented are particularly helpful in developing reasoned regulatory decisions on the proposal. Comments are specifically invited on the overall regulatory, aeronautical, economic, environmental, and energy-related aspects of the proposal. Communications should identify both docket numbers and be submitted in triplicate to the address listed above. Commenters wishing the FAA to acknowledge receipt of their comments on this notice must submit with those comments a self-addressed, stamped postcard on which the following statement is made: "Comments to Docket No. FAA-2015-4133; Airspace Docket No. 15-ANM-27." The postcard will be date/time stamped and returned to the commenter.

Availability of NPRMs

An electronic copy of this document may be downloaded through the Internet at <http://www.regulations.gov>. Recently published rulemaking documents can also be accessed through the FAA's Web page at http://www.faa.gov/airports/airtraffic/air_traffic/publications/airspace_amendments/.

You may review the public docket containing the proposal, any comments received, and any final disposition in person in the Dockets Office (see the **ADDRESSES** section for the address and phone number) between 9:00 a.m. and 5:00 p.m., Monday through Friday, except federal holidays. An informal docket may also be examined during normal business hours at the Northwest Mountain Regional Office of the Federal Aviation Administration, Air Traffic Organization, Western Service Center, Operations Support Group, 1601 Lind Avenue SW., Renton, WA 98057.

Persons interested in being placed on a mailing list for future NPRMs should contact the FAA's Office of Rulemaking, (202) 267-9677, for a copy of Advisory Circular No. 11-2A, Notice of Proposed Rulemaking Distribution System, which describes the application procedure.

Availability and Summary of Documents Proposed for Incorporation by Reference

This document would amend FAA Order 7400.9Z, Airspace Designations and Reporting Points, dated August 6, 2015, and effective September 15, 2015. FAA Order 7400.9Z is publicly available