

**(m) Life Limit for P/N C2CF619A**

As of October 24, 2016 (the effective date of this AD), elevator control rod assemblies, P/N C2CF619A, are life-limited to 15 years and must be replaced with P/N C2CF619A-11, which is not a life-limited part, at the following compliance time:

(1) If, as of October 24, 2016 (the effective date of this AD), the age of the installed P/N C2CF619A is known, it must be replaced before exceeding the life limit or within the next 12 months after October 24, 2016 (the effective date of this AD), whichever occurs later.

(2) If, as of October 24, 2016 (the effective date of this AD), the age of the installed P/N C2CF619A is not known, it must be replaced within the next 12 months after October 24, 2016 (the effective date of this AD).

**(n) Credit for Actions Accomplished in Accordance With Previous Service Information**

Credit will be given for the inspections required in paragraphs (g)(1) through (3) of this AD if they were done before October 24, 2016 (the effective date of this AD) following Viking Air Limited DHC-2 Beaver Service Bulletin Number: V2/0005, Revision 'NC', dated March 26, 2012; Viking Air Limited DHC-2 Beaver Service Bulletin Number: V2/0005, Revision 'A', dated November 7, 2014; or Viking Air Limited DHC-2 Beaver Service Bulletin Number: V2/0005, Revision 'B', dated March 4, 2015.

**(o) Other FAA AD Provisions**

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs)*: The Manager, New York Aircraft Certification Office (ACO), FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. Send information to ATTN: Aziz Ahmed, Aerospace Engineer, FAA, New York ACO, 1600 Stewart Avenue, Suite 410, Westbury, New York 11590; telephone: (516) 228-7329; fax: (516) 794-5531; email: [aziz.ahmed@faa.gov](mailto:aziz.ahmed@faa.gov). Before using any approved AMOC on any airplane to which the AMOC applies, notify your appropriate principal inspector (PI) in the FAA Flight Standards District Office (FSDO), or lacking a PI, your local FSDO.

(2) *Airworthy Product*: For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they are approved by the State of Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

(3) *Reporting Requirements*: For any reporting requirement in this AD, a federal agency may not conduct or sponsor, and a person is not required to respond to, nor shall a person be subject to a penalty for failure to comply with a collection of information subject to the requirements of the Paperwork Reduction Act unless that collection of information displays a current valid OMB Control Number. The OMB Control Number for this information

collection is 2120-0056. Public reporting for this collection of information is estimated to be approximately 5 minutes per response, including the time for reviewing instructions, completing and reviewing the collection of information. All responses to this collection of information are mandatory. Comments concerning the accuracy of this burden and suggestions for reducing the burden should be directed to the FAA at: 800 Independence Ave. SW., Washington, DC 20591, Attn: Information Collection Clearance Officer, AES-200.

**(p) Related Information**

Refer to MCAI Transport Canada AD No. CF-2015-21, dated July 30, 2015; and Viking Air Limited DHC-2 Beaver Service Bulletin Number: V2/0005, Revision 'NC', dated March 26, 2012; Viking Air Limited DHC-2 Beaver Service Bulletin Number: V2/0005, Revision 'A', dated November 7, 2014; or Viking Air Limited DHC-2 Beaver Service Bulletin Number: V2/0005, Revision 'B', dated March 4, 2015, for related information. You may examine the MCAI on the Internet at <https://www.regulations.gov/document?D=FAA-2016-4229-0002>.

**(q) Material Incorporated by Reference**

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Viking DHC-2 Beaver Service Bulletin Number: V2/0005, Revision "C", dated July 17, 2015.

(ii) Item 20A., of Part 3, in Appendix 2 of Temporary Revision No.: 2-38, dated March 4, 2015, into the VIKING PSM NO.: 1-2-2, AIRCRAFT: DHC-2 BEAVER, SERIES: ALL, PUBLICATION: MAINTENANCE MANUAL.

(iii) Item 20A., in Part 4, of Temporary Revision No.: 2T-14, dated March 4, 2015, into VIKING PSM NO.: 1-2T-2, AIRCRAFT: DHC-2 TURBO BEAVER, SERIES: ALL, PUBLICATION: MAINTENANCE MANUAL.

(3) For Viking Air Limited service information identified in this AD, contact Viking Air Limited Technical Support, 1959 De Havilland Way, Sidney, British Columbia, Canada, V8L 5V5; Fax: 250-656-0673; telephone: (North America) (800) 663-8444; email: [technical.support@vikingair.com](mailto:technical.support@vikingair.com); Internet: <http://www.vikingair.com/support/service-bulletins>.

(4) You may view this service information at the FAA, Small Airplane Directorate, 901 Locust, Kansas City, Missouri 64106. For information on the availability of this material at the FAA, call (816) 329-4148. In addition, you can access this service information on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2016-4229.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Kansas City, Missouri, on September 8, 2016.

**Pat Mullen,**

*Acting Manager, Small Airplane Directorate, Aircraft Certification Service.*

[FR Doc. 2016-22183 Filed 9-16-16; 8:45 am]

**BILLING CODE 4910-13-P**

**DEPARTMENT OF TRANSPORTATION****Federal Aviation Administration****14 CFR Part 39**

**[Docket No. FAA-2016-5035; Directorate Identifier 2015-NM-042-AD; Amendment 39-18650; AD 2016-19-01]**

**RIN 2120-AA64**

**Airworthiness Directives; Fokker Services B.V. Airplanes**

**AGENCY:** Federal Aviation Administration (FAA), Department of Transportation (DOT).

**ACTION:** Final rule.

**SUMMARY:** We are adopting a new airworthiness directive (AD) for all Fokker Services B.V. Model F28 Mark 0070 and Mark 0100 airplanes. This AD was prompted by reports of cracking in a certain area of the pressure bulkhead webplate and skin connection angle. This AD requires a one-time inspection of the affected pressure bulkhead webplate and skin connection angle, and corrective actions if necessary. We are issuing this AD to detect and correct cracking of the pressure bulkhead webplate and skin connection angle that could lead to sudden inflight decompression of the airplane, resulting in injury to occupants.

**DATES:** This AD is effective October 24, 2016.

The Director of the Federal Register approved the incorporation by reference of certain publications listed in this AD as of October 24, 2016.

**ADDRESSES:** For service information identified in this final rule, contact Fokker Services B.V., Technical Services Dept., P.O. Box 1357, 2130 EL Hoofddorp, the Netherlands; telephone +31 (0)88-6280-350; fax +31 (0)88-6280-111; email [technicalservices@fokker.com](mailto:technicalservices@fokker.com); Internet <http://www.myfokkerfleet.com>. You may view this referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221. It is also available on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2016-5035.

## Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA–2016–5035; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Office (telephone 800–647–5527) is Docket Management Facility, U.S. Department of Transportation, Docket Operations, M–30, West Building Ground Floor, Room W12–140, 1200 New Jersey Avenue SE., Washington, DC 20590.

**FOR FURTHER INFORMATION CONTACT:** Tom Rodriguez, Aerospace Engineer, International Branch, ANM–116, Transport Airplane Directorate, FAA, 1601 Lind Avenue SW., Renton, WA 98057–3356; telephone 425–227–1137; fax 425–227–1139.

## SUPPLEMENTARY INFORMATION:

### Discussion

We issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 by adding an AD that would apply to all Fokker Services B.V. Model F28 Mark 0070 and Mark 0100 airplanes. The NPRM published in the **Federal Register** on March 29, 2016 (81 FR 17417) (“the NPRM”). The NPRM was prompted by reports of cracking in a certain area of the pressure bulkhead webplate and skin connection angle. The NPRM proposed to require a one-time inspection of the affected pressure bulkhead webplate and skin connection angle, and corrective actions if necessary. We are issuing this AD to detect and correct cracking of the pressure bulkhead webplate and skin connection angle that could lead to sudden inflight decompression of the airplane, resulting in injury to occupants.

The European Aviation Safety Agency (EASA), which is the Technical Agent for the Member States of the European Union, has issued EASA Airworthiness Directive 2015–0024, dated February 19, 2015 (referred to after this as the Mandatory Continuing Airworthiness Information, or “the MCAI”), to correct an unsafe condition for all Fokker Services B.V. Model F28 Mark 0070 and Mark 0100 airplanes. The MCAI states:

Service experience with the Fokker 100 type design has shown that cracking can occur in the pressure bulkhead webplate and skin connection angle on the right hand (RH) side at station 14911 (station 12447 for F28 Mark 0070) at stringer 67 of fuselage section

2, before reaching the existing threshold for inspection per ALS [Airworthiness Limitations Section] task 533016–00–03 (F28 Mark 0100) or task 533016–01–03 (F28 Mark 0070). Any cracks in this area are not visible from the outside (covered by fairing) until they reach a critical length.

This condition, if not detected and corrected, could lead to sudden in-flight decompression of the aeroplane, possibly resulting in injury to occupants.

To address this potential unsafe condition, Fokker Services published Service Bulletin (SB) SBF100–53–128, which provides inspection instructions to detect any crack in the affected area.

For the reasons described above, this [EASA] AD requires a one-time inspection of the affected pressure bulkhead webplate and skin connection angle, and, depending on findings, accomplishment of applicable corrective action(s).

This [EASA] AD is considered to be an interim action and further AD action may follow, possibly to lower the current ALS task threshold, if justified by the inspection results.

Corrective actions include repair of cracking in the skin connection angle and pressure bulkhead webplate, as applicable.

You may examine the MCAI in the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA–2016–5035.

## Comments

We gave the public the opportunity to participate in developing this AD. We received no comments on the NPRM or on the determination of the cost to the public.

## Conclusion

We reviewed the relevant data and determined that air safety and the public interest require adopting this AD as proposed except for minor editorial changes. We have determined that these minor changes:

- Are consistent with the intent that was proposed in the NPRM for correcting the unsafe condition; and
- Do not add any additional burden upon the public than was already proposed in the NPRM.

## Related Service Information Under 1 CFR Part 51

We reviewed Fokker Service Bulletin SBF100–53–128, dated November 12, 2014; and Fokker Service Bulletin SBF100–53–129, dated February 16, 2015. The service information describes procedures for inspection of the affected pressure bulkhead webplate and skin connection angle, and corrective actions if necessary. This service information is reasonably available because the interested parties have access to it

through their normal course of business or by the means identified in the **ADDRESSES** section.

## Costs of Compliance

We estimate that this AD affects 8 airplanes of U.S. registry.

We also estimate that it will take about 1 work-hour per product to comply with the basic requirements of this AD, and 1 work-hour per product for reporting. The average labor rate is \$85 per work-hour. Required parts will cost about \$0 per product. Based on these figures, we estimate the cost of this AD on U.S. operators to be \$1,360, or \$170 per product.

In addition, we estimate that any necessary follow-on actions will take about 46 work-hours and require parts costing \$2,000, for a cost of \$5,910 per product. We have no way of determining the number of aircraft that might need these actions.

## Paperwork Reduction Act

A federal agency may not conduct or sponsor, and a person is not required to respond to, nor shall a person be subject to penalty for failure to comply with a collection of information subject to the requirements of the Paperwork Reduction Act unless that collection of information displays a current valid OMB control number. The control number for the collection of information required by this AD is 2120–0056. The paperwork cost associated with this AD has been detailed in the Costs of Compliance section of this document and includes time for reviewing instructions, as well as completing and reviewing the collection of information. Therefore, all reporting associated with this AD is mandatory. Comments concerning the accuracy of this burden and suggestions for reducing the burden should be directed to the FAA at 800 Independence Ave. SW., Washington, DC 20591, ATTN: Information Collection Clearance Officer, AES–200.

## Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA’s authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. “Subtitle VII: Aviation Programs,” describes in more detail the scope of the Agency’s authority.

We are issuing this rulemaking under the authority described in “Subtitle VII, Part A, Subpart III, Section 44701: General requirements.” Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures

the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

### Regulatory Findings

We determined that this AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

1. Is not a "significant regulatory action" under Executive Order 12866;
2. Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979);
3. Will not affect intrastate aviation in Alaska; and
4. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

### List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

### Adoption of the Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

## PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701.

### § 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

**2016–19–01 Fokker Services B.V.:**  
Amendment 39–18650. Docket No. FAA–2016–5035; Directorate Identifier 2015–NM–042–AD.

#### (a) Effective Date

This AD is effective October 24, 2016.

#### (b) Affected ADs

None.

#### (c) Applicability

This AD applies to Fokker Services B.V. Model F28 Mark 0070 and F28 Mark 0100 airplanes, certificated in any category, all serial numbers.

#### (d) Subject

Air Transport Association (ATA) of America Code 53, Fuselage.

#### (e) Reason

This AD was prompted by reports of cracking in the pressure bulkhead webplate and skin connection angle. We are issuing this AD to detect and correct cracking of the pressure bulkhead webplate and skin connection angle that could lead to sudden inflight decompression of the airplane, resulting in injury to occupants.

#### (f) Compliance

Comply with this AD within the compliance times specified, unless already done.

#### (g) Inspection

At the time specified in paragraph (h) of this AD: Do a detailed inspection of the pressure bulkhead webplate and skin connection angle on the right-hand side at station 14911 (for Model F28 Mark 0100 airplanes) or station 12447 (for Model F28 Mark 0070 airplanes) at stringer 67 of fuselage section 2, as applicable, in accordance with the Accomplishment Instructions of Fokker Service Bulletin SBF100–53–128, dated November 12, 2014. This AD does not require action for airplanes which, as of the effective date of this AD, have accumulated less than 30,000 flight cycles.

(1) If any crack is found in the skin connection angle, before further flight, repair the skin connection angle, in accordance with the Accomplishment Instructions of Fokker Service Bulletin SBF100–53–129, dated February 16, 2015.

(2) If any crack is found in the pressure bulkhead webplate, before further flight, repair the pressure bulkhead webplate, in accordance with the Accomplishment Instructions of Fokker Service Bulletin SBF100–53–129, dated February 16, 2015.

#### (h) Compliance Times

At the applicable time specified in paragraph (h)(1) or (h)(2) of this AD, do the actions required by paragraph (g) of this AD.

(1) For airplanes that have accumulated less than 40,000 total flight cycles as of the effective date of this AD, do the actions in paragraph (g) of this AD within 2,000 flight cycles after the effective date of this AD.

(2) For airplanes that have accumulated 40,000 or more total flight cycles as of the effective date of this AD, do the actions in paragraph (g) of this AD within 750 flight cycles after the effective date of this AD.

#### (i) Reporting

Submit a report of the findings (both positive and negative) of the inspection required by paragraph (g) of this AD to Fokker Services B.V. Engineering, Quality Department P.O. Box 1357, 2130 EL Hoofddorp, the Netherlands; telephone +31 (0)88–6280–350; fax +31 (0)88–6280–111; email [technicalservices@fokker.com](mailto:technicalservices@fokker.com); Internet <http://www.myfokkerfleet.com>, in accordance with the Accomplishment Instructions of Fokker Service Bulletin SBF100–53–128, dated November 12, 2014, at the applicable

time specified in paragraph (i)(1) or (i)(2) of this AD. The report must include the inspection results; the airplane serial number; the total number of flight cycles and flight hours on the airplane; a sketch or photo to show the location of the crack(s) and damaged part(s), if applicable; and the length of each crack, if applicable.

(1) If the inspection was done on or after the effective date of this AD: Submit the report within 30 days after the inspection.

(2) If the inspection was done before the effective date of this AD: Submit the report within 30 days after the effective date of this AD.

#### (j) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs):* The Manager, International Branch, ANM–116, Transport Airplane Directorate, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the International Branch, send it to ATTN: Tom Rodriguez, Aerospace Engineer, International Branch, ANM–116, Transport Airplane Directorate, FAA, 1601 Lind Avenue SW., Renton, WA 98057–3356; telephone 425–227–1137; fax 425–227–1149. Information may be emailed to: [9-ANM-116-AMOC-REQUESTS@faa.gov](mailto:9-ANM-116-AMOC-REQUESTS@faa.gov). Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(2) *Contacting the Manufacturer:* For any requirement in this AD to obtain corrective actions from a manufacturer, the action must be accomplished using a method approved by the Manager, International Branch, ANM–116, Transport Airplane Directorate, FAA; or the European Aviation Safety Agency (EASA); or Fokker B.V. Service's EASA Design Organization Approval (DOA). If approved by the DOA, the approval must include the DOA-authorized signature.

(3) *Reporting Requirements:* A federal agency may not conduct or sponsor, and a person is not required to respond to, nor shall a person be subject to a penalty for failure to comply with a collection of information subject to the requirements of the Paperwork Reduction Act unless that collection of information displays a current valid OMB Control Number. The OMB Control Number for this information collection is 2120–0056. Public reporting for this collection of information is estimated to be approximately 5 minutes per response, including the time for reviewing instructions, completing and reviewing the collection of information. All responses to this collection of information are mandatory. Comments concerning the accuracy of this burden and suggestions for reducing the burden should be directed to the FAA at: 800 Independence Ave. SW., Washington, DC 20591, Attn: Information Collection Clearance Officer, AES–200.

(k) Related Information

Refer to Mandatory Continuing Airworthiness Information (MCAI) EASA Airworthiness Directive 2015–0024, dated February 19, 2015, for related information. This MCAI may be found in the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA–2016–5035.

(l) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) Fokker Service Bulletin SBF100–53–128, dated November 12, 2014.

(ii) Fokker Service Bulletin SBF100–53–129, dated February 16, 2015.

(3) For service information identified in this AD, contact Fokker Services B.V., Technical Services Dept., P.O. Box 1357, 2130 EL Hoofddorp, the Netherlands;

telephone +31 (0)88–6280–350; fax +31 (0)88–6280–111; email [technicalservices@fokker.com](mailto:technicalservices@fokker.com); Internet <http://www.myfokkerfleet.com>.

(4) You may view this service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425–227–1221.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202–741–6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on September 6, 2016.

Michael Kaszycki,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 2016–22186 Filed 9–16–16; 8:45 am]

BILLING CODE 4910–13–P

SOCIAL SECURITY ADMINISTRATION

20 CFR Parts 404 and 416

[Docket No. SSA–2006–0149]

RIN 0960–AF58

Revised Medical Criteria for Evaluating Respiratory System Disorders

Correction

In rule document 2016–13275, appearing on pages 37138–37153, in the issue of Thursday, June 9, 2016, make the following correction:

PART 404—FEDERAL OLD AGE, SURVIVORS AND DISABILITY INSURANCE (1950) [CORRECTED]

■ On page 37147, in the Table titled “TABLE II—FVC CRITERIA FOR 3.02B”, the column headings are corrected to read as set forth below:

Height without shoes (centimeters) < means less than	Height without shoes (inches) < means less than	Table II–A		Table II–B	
		Age 18 to attainment of age 20		Age 20 or older	
		Females FVC less than or equal to (L, BTPS)	Males FVC less than or equal to (L, BTPS)	Females FVC less than or equal to (L, BTPS)	Males FVC less than or equal to (L, BTPS)

[FR Doc. C1–2016–13275 Filed 9–16–16; 8:45 am]

BILLING CODE 1505–01–D

DEPARTMENT OF HEALTH AND HUMAN SERVICES

Food and Drug Administration

21 CFR Parts 117 and 507

[Docket Nos. FDA–2011–N–0920, FDA–2011–N–0922]

Current Good Manufacturing Practice, Hazard Analysis, and Risk-Based Preventive Controls for Human Food and Current Good Manufacturing Practice, Hazard Analysis, and Risk-Based Preventive Controls for Food for Animals; Definition of Qualified Auditor; Announcement of Effective Date

AGENCY: Food and Drug Administration, HHS.

ACTION: Final rule; announcement of effective date.

SUMMARY: The Food and Drug Administration (FDA or we) is announcing the effective date for the

definition of qualified auditor in the two final rules that appeared in the **Federal Register** of September 17, 2015.

DATES: The effective date of paragraph (2) of the definition of qualified auditor in 21 CFR 117.3 and in 21 CFR 507.3, which published in the **Federal Register** of September 17, 2015 (80 FR 55908) and (80 FR 56170), is September 19, 2016.

FOR FURTHER INFORMATION CONTACT: For questions relating to *Current Good Manufacturing Practice, Hazard Analysis and Risk-Based Preventive Controls for Human Food*: Jenny Scott, Center for Food Safety and Applied Nutrition (HFS–300), Food and Drug Administration, 5001 Campus Dr., College Park, MD 20740, 240–402–2166.

For questions relating to *Current Good Manufacturing Practice, Hazard Analysis, and Risk-Based Preventive Controls for Food for Animals*: Jeanette Murphy, Center for Veterinary Medicine (HFV–200), Food and Drug Administration, 7519 Standish Pl., Rockville, MD 20855, 240–402–6246.

SUPPLEMENTARY INFORMATION: In the **Federal Register** of September 17, 2015 (80 FR 55908), we published a final rule

for “Current Good Manufacturing Practices, Hazard Analysis, and Risk-Based Preventive Controls for Human Food” (preventive controls for human food rule). In § 117.3, we included the definition of a qualified auditor. In the definition, we provided examples of qualified auditors. Paragraph 2 of the definition reads “An audit agent of a certification body that is accredited in accordance with regulations in part 1, subpart M of this chapter.” At the time the final rule published, paragraph 2 referred to a provision in a future final rule: “Accreditation of Third-Party Certification Bodies to Conduct Food Safety Audits to Issue Certifications” (third-party certification rule). In the preamble to the preventive controls for human food rule, we stated that we would publish a document in the **Federal Register** announcing the effective date of paragraph (2) once we finalized the third-party certification rule (80 FR 55908 at 55954).

In the **Federal Register** of September 17, 2015 (80 FR 56170), we published a final rule for “Current Good Manufacturing Practices, Hazard Analysis, and Risk-Based Preventive Controls for Food for Animals”