Flight Standards District Office, as appropriate. If sending information directly to the International Branch, send it to ATTN: Shahram Daneshmandi, Aerospace Engineer, International Branch, ANM-116, Transport Airplane Directorate, FAA, 1601 Lind Avenue SW., Renton, WA 98057-3356; telephone: 425-227-1112; fax: 425-227-1149. Information may be emailed to: 9-ANM-116-AMOC-REQUESTS@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/ certificate holding district office.

(2) Contacting the Manufacturer: As of the effective date of this AD, for any requirement in this AD to obtain corrective actions from a manufacturer, the action must be accomplished using a method approved by the Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA; or the European Aviation Safety Agency (EASA); or EADS CASA's EASA Design Organization Approval (DOA). If approved by the DOA, the approval must include the DOA-authorized signature.

#### (l) Related Information

(1) Refer to Mandatory Continuing Airworthiness Information (MCAI) European Aviation Safety Agency (EASA) AD 2016– 0014, dated January 14, 2016, for related information. This MCAI may be found in the AD docket on the Internet at http:// www.regulations.gov by searching for and locating Docket No. FAA-2016-9109.

(2) For service information identified in this AD, contact EADS CASA (Airbus Defense and Space), Services/Engineering Support, Avenida de Aragón 404, 28022 Madrid, Spain; telephone: +34 91 585 55 84; fax: +34 91 585 31 27; email: MTA.TechnicalService@Airbus.com. You may view this service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

Issued in Renton, Washington, on

## September 12, 2016.

#### Michael Kaszycki, Acting Manager, Transport Airplane

Directorate, Aircraft Certification Service.

[FR Doc. 2016-22434 Filed 9-16-16; 8:45 am] BILLING CODE 4910-13-P

## DEPARTMENT OF TRANSPORTATION

## **Federal Aviation Administration**

## 14 CFR Part 39

[Docket No. FAA-2016-9110; Directorate Identifier 2015–NM–196–AD]

## RIN 2120-AA64

## **Airworthiness Directives; Airbus** Airplanes

**AGENCY:** Federal Aviation Administration (FAA), DOT. **ACTION:** Notice of proposed rulemaking (NPRM).

SUMMARY: We propose to adopt a new airworthiness directive (AD) for certain Airbus Model A319–115, A319–132, A320-214, A320-232, A321-211, A321-213, and A321-231 airplanes. This proposed AD was prompted by a report of certain tie rod assemblies installed on the hinged fairing assembly of the main landing gear (MLG) with no cadmium plating on the rod end threads. This proposed AD would require a detailed inspection of certain tie rod assemblies installed on the hinged fairing assembly of the MLG for the presence of cadmium plating, and replacement of tie rod assemblies without cadmium plating. We are proposing this AD to detect and correct the absence of cadmium plating on the rod end threads of the tie rod assemblies. The absence of cadmium plating could lead to galvanic corrosion of the tie rod end threads, resulting in rod end failure, loss of a MLG door, and consequent damage to the airplane. DATES: We must receive comments on this proposed AD by November 3, 2016. ADDRESSES: You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

• Federal eRulemaking Portal: Go to http://www.regulations.gov. Follow the instructions for submitting comments. • Fax: 202–493–2251.

• Mail: U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC 20590.

• Hand Delivery: U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12–140, 1200 New Jersey Avenue SE., Washington, DC, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this NPRM, contact Airbus, Airworthiness Office-EIAS, 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France; telephone +33 5 61 93 36 96; fax +33 5 61 93 44 51; email account.airworth-eas@airbus.com; Internet *http://www.airbus.com*. You may view this referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

## **Examining the AD Docket**

You may examine the AD docket on the Internet at http:// www.regulations.gov by searching for and locating Docket No. FAA-2016-

9110; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this proposed AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Operations office (telephone 800-647-5527) is in the ADDRESSES section. Comments will be available in the AD docket shortly after receipt.

## FOR FURTHER INFORMATION CONTACT:

Sanjay Ralhan, Aerospace Engineer, International Branch, ANM-116, Transport Airplane Directorate, FAA, 1601 Lind Avenue SW., Renton, WA 98057-3356; telephone 425-227-1405; fax 425-227-1149.

## SUPPLEMENTARY INFORMATION:

#### **Comments Invited**

We invite you to send any written relevant data, views, or arguments about this proposed AD. Send your comments to an address listed under the **ADDRESSES** section. Include "Docket No. FAA-2016-9110; Directorate Identifier 2015-NM-196-AD" at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this proposed AD. We will consider all comments received by the closing date and may amend this proposed AD based on those comments.

We will post all comments we receive, without change, to http:// www.regulations.gov, including any personal information you provide. We will also post a report summarizing each substantive verbal contact we receive about this proposed AD.

## Discussion

The European Aviation Safety Agency (EASA), which is the Technical Agent for the Member States of the European Union, has issued EASA Airworthiness Directive 2015–0234, dated December 8, 2015 (referred to after this as the Mandatory Continuing Airworthiness Information, or "the MCAI"), to correct an unsafe condition for certain Airbus Model A319-115, A319-132, A320-214. A320-232, A321-211, A321-213, and A321-231 airplanes. The MCAI states:

A production quality issue was identified concerning tie rod assemblies, having Part Number (P/N) starting with D52840212000 or D52840212002, which are installed on the main landing gear (MLG) hinged fairing assembly. This quality issue affects the cadmium plating surface treatment which was inadvertently omitted from the rod end threads of the assembly. The absence of cadmium plating reduces the corrosion protection scheme.

This condition, if not detected and corrected, could lead to galvanic corrosion of Federal Register/Vol. 81, No. 181/Monday, September 19, 2016/Proposed Rules

64084

the tie rod end threads, possibly resulting in rod end failure, loss of a MLG door, and consequent injury to persons on ground.

To address this unsafe condition, Airbus identified the affected [manufacturer serial number] MSN and issued [service bulletin] SB A320–52–1167 to provide inspection instructions.

For the reason described above, this [EASA] AD requires a one-time inspection of the affected MLG hinged fairing tie rod assemblies [for the presence of cadmium plating], and, depending on findings, replacement of the affected tie rod assembly.

You may examine the MCAI in the AD docket on the Internet at *http://www.regulations.gov* by searching for and locating Docket No. FAA–2016–9110.

## Related Service Information Under 1 CFR Part 51

Airbus has issued Service Bulletin A320–52–1167, dated August 6, 2015. The service information describes procedures for a detailed inspection for the presence of cadmium plating on tie rod assemblies having certain part numbers, and procedures for replacement of tie rod assemblies with no cadmium plating on the rod end threads. This service information is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the **ADDRESSES** section.

# FAA's Determination and Requirements of This Proposed AD

This product has been approved by the aviation authority of another

## ESTIMATED COSTS

ActionLabor costParts costCost per<br/>productCost on U.S.<br/>operatorsInspection ......2 work-hours × \$85 per hour = \$170 ...\$0\$170\$3,400

We estimate the following costs to do any necessary replacements that would

be required based on the results of the proposed inspection. We have no way of determining the number of airplanes that might need these replacements:

country, and is approved for operation

Design Authority, we have been notified

of the unsafe condition described in the

referenced above. We are proposing this

AD because we evaluated all pertinent

information and determined an unsafe

condition exists and is likely to exist or

We estimate that this proposed AD

We estimate the following costs to

affects 20 airplanes of U.S. registry.

comply with this proposed AD:

develop on other products of these same

in the United States. Pursuant to our

bilateral agreement with the State of

MCAI and service information

type designs.

**Costs of Compliance** 

## **ON-CONDITION COSTS**

| Action      | Labor cost                                     | Parts cost    | Cost per<br>product |
|-------------|--|---------------|---------------------|
| Replacement | 13 work-hours $\times$ \$85 per hour = \$1,105 | Not available | \$1,105             |

According to the manufacturer, some of the costs of this proposed AD may be covered under warranty, thereby reducing the cost impact on affected individuals. We do not control warranty coverage for affected individuals. As a result, we have included all available costs in our cost estimate.

## Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. "Subtitle VII: Aviation Programs," describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in "Subtitle VII, Part A, Subpart III, Section 44701: General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

## **Regulatory Findings**

We determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

1. Is not a "significant regulatory action" under Executive Order 12866;

2. Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979);

3. Will not affect intrastate aviation in Alaska; and

4. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

#### List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

#### **The Proposed Amendment**

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

## PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

#### §39.13 [Amended]

■ 2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

Airbus: Docket No. FAA–2016–9110; Directorate Identifier 2015–NM–196–AD.

#### (a) Comments Due Date

We must receive comments by November 3, 2016.

## (b) Affected ADs

None.

## (c) Applicability

This AD applies to Airbus Model A319– 115, A319–132, A320–214, A320–232, A321– 211, A321–213, and A321–231 airplanes, certificated in any category, as identified in Airbus Service Bulletin A320–52–1167, dated August 6, 2015.

#### (d) Subject

Air Transport Association (ATA) of America Code 52, Doors.

#### (e) Reason

This AD was prompted by a report of certain tie rod assemblies installed on the hinged fairing assembly of the main landing gear (MLG) with no cadmium plating on the rod end threads. We are issuing this AD to detect and correct the absence of cadmium plating on the rod end threads of the tie rod assemblies. The absence of cadmium plating could lead to galvanic corrosion of the tie rod end threads, resulting in rod end failure, loss of a MLG door, and consequent damage to the airplane.

#### (f) Compliance

Comply with this AD within the compliance times specified, unless already done.

## (g) Inspection and Corrective Action

Within 80 months after the airplane's first flight, do a detailed inspection of each tie rod assembly having a part number (P/N) D52840212000 or D52840212002 at the MLG hinged fairing for the presence of cadmium plating (gold colored threads), in accordance with the Accomplishment Instructions of Airbus Service Bulletin A320–52–1167, dated August 6, 2015. If during the inspection any tie rod assembly is found that does not have cadmium plating, before further flight, replace the tie rod assembly with a serviceable part having the same part number and cadmium plating, in accordance with the Accomplishment Instructions of Airbus Service Bulletin A320–52–1167, dated August 6, 2015.

## (h) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) Alternative Methods of Compliance (AMOCs): The Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the International Branch, send it to ATTN: Sanjay Ralhan, Aerospace Engineer, International Branch, ANM-116, Transport Airplane Directorate, FAA, 1601 Lind Avenue SW., Renton, WA 98057–3356; telephone 425–227–1405; fax 425–227–1149. Information may be emailed to: *9-ANM-116-AMOC-REQUESTS@faa.gov*. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office. The AMOC approval letter must specifically reference this AD.

(2) Contacting the Manufacturer: For any requirement in this AD to obtain corrective actions from a manufacturer, the action must be accomplished using a method approved by the Manager, International Branch, ANM– 116, Transport Airplane Directorate, FAA; or the European Aviation Safety Agency (EASA); or Airbus's EASA Design Organization Approval (DOA). If approved by the DOA, the approval must include the DOA-authorized signature.

(3) Required for Compliance (RC): If any service information contains procedures or tests that are identified as RC, those procedures and tests must be done to comply with this AD; any procedures or tests that are not identified as RC are recommended. Those procedures and tests that are not identified as RC may be deviated from using accepted methods in accordance with the operator's maintenance or inspection program without obtaining approval of an AMOC, provided the procedures and tests identified as RC can be done and the airplane can be put back in an airworthy condition. Any substitutions or changes to procedures or tests identified as RC require approval of an AMOC.

#### (i) Related Information

(1) Refer to Mandatory Continuing Airworthiness Information (MCAI) EASA Airworthiness Directive 2015–0234, dated December 8, 2015, for related information. This MCAI may be found in the AD docket on the Internet at *http://www.regulations.gov* by searching for and locating Docket No. FAA–2016–9110.

(2) For service information identified in this AD, contact Airbus, Airworthiness Office—EIAS, 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France; telephone +33 5 61 93 36 96; fax +33 5 61 93 44 51; email *account.airworth-eas*@ *airbus.com*; Internet *http://www.airbus.com*. You may view this referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425–227–1221.

Issued in Renton, Washington, on September 12, 2016.

#### Michael Kaszycki,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service. [FR Doc. 2016–22435 Filed 9–16–16; 8:45 am]

## BILLING CODE 4910-13-P

## DEPARTMENT OF TRANSPORTATION

#### **Federal Aviation Administration**

## 14 CFR Part 193

[Docket No. FAA-2006-24855]

## Voluntary Disclosure Reporting Program

**AGENCY:** Federal Aviation Administration (FAA), DOT. **ACTION:** Notice of proposed order designating information as protected from disclosure.

SUMMARY: This notice describes a proposed order through which the Federal Aviation Administration plans to designate a certain category of information as protected from public disclosure pursuant to a Voluntary Disclosure Reporting Program. The Federal Aviation Administration is required to protect the information from disclosure to the public, including disclosure required by statute, such as the Freedom of Information Act, following issuance of an order designating the information as protected. The instant designation is intended to encourage participation in the Voluntary Disclosure Reporting Program.

**DATES:** Comments must be received on or before October 19, 2016.

**ADDRESSES:** Send comments identified by Docket Number FAA–2006–24855 using any of the following methods:

• Federal eRulemaking Portal: Go to http://www.regulations.gov and follow the online instructions for sending your comments electronically.

• *Mail:* Send comments to Docket Operations, M–30; U.S. Department of Transportation (DOT), 1200 New Jersey Avenue SE., Room W12–140, West Building Ground Floor, Washington, DC 20590–0001.

• *Hand Delivery or Courier:* Take comments to Docket Operations in Room W12–140 of the West Building Ground Floor at 1200 New Jersey Avenue SE., Washington, DC, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

• *Fax:* Fax comments to Docket Operations at 202–493–2251.

*Privacy:* In accordance with 5 U.S.C. 553(c), DOT solicits comments from the public to better inform its rulemaking process. DOT posts these comments, without edit, including any personal information the commenter provides, to *www.regulations.gov*, as described in the system of records notice (DOT/ALL–14 FDMS), which can be reviewed at *www.dot.gov/privacy*.