

AD if done before November 4, 2016 (the effective date of this AD), following Pilatus PC-6 SB No. 53-003, dated October 4, 2016. The dye-penetrant or eddy current inspection must still be done following Pilatus PC-6 SB No. 53-003, Revision 1, dated October 13, 2016.

(h) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs)*: The Manager, Standards Office, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. Send information to ATTN: Doug Rudolph, Aerospace Engineer, FAA, Small Airplane Directorate, 901 Locust, Room 301, Kansas City, Missouri 64106; telephone: (816) 329-4059; fax: (816) 329-4090; email: doug.rudolph@faa.gov. Before using any approved AMOC on any airplane to which the AMOC applies, notify your appropriate principal inspector (PI) in the FAA Flight Standards District Office (FSDO), or lacking a PI, your local FSDO.

(2) *Airworthy Product*: For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they are approved by the State of Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

(3) *Reporting Requirements*: For any reporting requirement in this AD, a federal agency may not conduct or sponsor, and a person is not required to respond to, nor shall a person be subject to a penalty for failure to comply with a collection of information subject to the requirements of the Paperwork Reduction Act unless that collection of information displays a current valid OMB Control Number. The OMB Control Number for this information collection is 2120-0056. Public reporting for this collection of information is estimated to be approximately 5 minutes per response, including the time for reviewing instructions, completing and reviewing the collection of information. All responses to this collection of information are mandatory. Comments concerning the accuracy of this burden and suggestions for reducing the burden should be directed to the FAA at: 800 Independence Ave. SW., Washington, DC 20591, Attn: Information Collection Clearance Officer, AES-200.

(i) Related Information

Refer to MCAI European Aviation Safety Agency (EASA) AD No. 2016-0202-E, dated October 7, 2016, and Pilatus Aircraft Ltd. PC-6 Service Bulletin No. 53-003, dated October 4, 2016. You may examine the MCAI on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2016-9356.

(j) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) Pilatus Aircraft Ltd. PC-6 Service Bulletin No. 53-003, Revision 1, dated October 13, 2016.

(ii) Reserved.

(3) For Pilatus Aircraft Ltd. service information identified in this AD, contact Pilatus Aircraft Ltd., Customer Liaison Manager, CH-6371 STANS, Switzerland; telephone: +41 41 619 3333; fax: +41 41 619 7311; Internet: <http://www.pilatus-aircraft.com>.

(4) You may view this service information at the FAA, FAA, Small Airplane Directorate, 901 Locust, Kansas City, Missouri 64106. For information on the availability of this material at the FAA, call (816) 329-4148. It is also available on the Internet at <http://www.regulations.gov> by searching for locating Docket No. FAA-2016-9356.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Kansas City, Missouri on October 27, 2016.

Pat Mullen,

Acting Manager, Small Airplane Directorate, Aircraft Certification Service.

[FR Doc. 2016-26431 Filed 11-3-16; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2016-9306; Directorate Identifier 2016-NM-169-AD; Amendment 39-18707; AD 2016-22-18]

RIN 2120-AA64

Airworthiness Directives; The Boeing Company Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule; request for comments.

SUMMARY: We are adopting a new airworthiness directive (AD) for all The Boeing Company Model MD-90-30 airplanes. This AD requires a detailed inspection of the forward and aft surfaces on the left and right sides at the cant station 1520 bulkhead for any crack in the upper cap and (cap) doubler, webs and doublers, stiffeners, and the lower tee cap between longerons 3 through 11, and repairs if necessary. This AD was prompted by a report of cracking in various structures in the fuselage cant station 1520 bulkhead. We

are issuing this AD to detect and correct cracking in the bulkhead, which could result in reduced structural integrity of the airplane.

DATES: This AD is effective November 21, 2016.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in this AD as of November 21, 2016.

We must receive comments on this AD by December 19, 2016.

ADDRESSES: You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal*: Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.

- *Fax*: 202-493-2251.

- *Mail*: U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC 20590.

- *Hand Delivery*: Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this final rule, contact Boeing Commercial Airplanes, Attention: Contractual & Data Services (C&DS), 2600 Westminister Blvd., MC 110-SK57, Seal Beach, CA 90740-5600; telephone 562-797-1717; Internet <https://www.myboeingfleet.com>. You may view this referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221. It is also available on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2016-9306.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2016-9306; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Office (phone: 800-647-5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT: George Garrido, Aerospace Engineer, Airframe Branch, ANM-120L, FAA, Los Angeles Aircraft Certification Office

(ACO), 3960 Paramount Boulevard, Lakewood, CA 90712-4137; phone: 562-627-5232; fax: 562-627-5210; email: george.garrido@faa.gov.

SUPPLEMENTARY INFORMATION:

Discussion

We have received a report indicating an operator found cracking of various structures in the fuselage cant station 1520 bulkhead on a Model MD-90-30 airplane. The cracks were in the upper left area of the bulkhead, between longerons 5 and 10, in the web, lower tee cap, and the upper cap and (cap) doubler. The affected airplane had accumulated 52,993 total flight hours and 28,718 total flight cycles. Boeing analysis determined that the operational and limit loads cannot duplicate this condition, and the root cause is suspected to be the result of a high load event based on service experience. Cracking of the bulkhead, if not detected and corrected, could result in the inability of the structure to sustain limit loads, and consequent reduced structural integrity of the airplane. We are issuing this AD to correct the unsafe condition on these products.

Related Service Information Under 1 CFR Part 51

We reviewed Boeing Alert Service Bulletin MD90-53A037, dated September 19, 2016. The service information describes procedures for a detailed inspection of the forward and aft surfaces on the left and right sides at cant station 1520 bulkhead for any crack in the upper cap and (cap) doubler, webs and doublers, stiffeners, and the lower tee cap between longerons 3 through 11, and repairs. This service information is reasonably available because the interested parties have access to it through their normal course

of business or by the means identified in the **ADDRESSES** section.

FAA's Determination

We are issuing this AD because we evaluated all the relevant information and determined the unsafe condition described previously is likely to exist or develop in other products of the same type design.

AD Requirements

This AD requires accomplishing the actions specified in the service information described previously, except as discussed under "Differences Between this Proposed AD and the Service Information." For information on the procedures and compliance times, see this service information at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2016-9306.

Differences Between This Proposed AD and the Service Information

Boeing Alert Service Bulletin MD90-53A037, dated September 19, 2016, specifies to contact the manufacturer for certain instructions, but this AD would require accomplishment of repair methods, modification deviations, and alteration deviations in one of the following ways:

- In accordance with a method that we approve; or
- Using data that meet the certification basis of the airplane, and that have been approved by the Boeing Commercial Airplanes Organization Designation Authorization (ODA) whom we have authorized to make those findings.

FAA's Justification and Determination of the Effective Date

An unsafe condition exists that requires the immediate adoption of this

AD. The FAA has found that the risk to the flying public justifies waiving notice and comment prior to adoption of this rule because undetected cracking of the bulkhead may result in the inability of the structure to sustain limit loads, and consequent reduced structural integrity of the airplane. Therefore, we find that notice and opportunity for prior public comment are impracticable and that good cause exists for making this amendment effective in less than 30 days.

Comments Invited

This AD is a final rule that involves requirements affecting flight safety and was not preceded by notice and an opportunity for public comment. However, we invite you to send any written data, views, or arguments about this AD. Send your comments to an address listed under the **ADDRESSES** section. Include the docket number FAA-2016-9306 and Directorate Identifier 2016-NM-169-AD at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this AD. We will consider all comments received by the closing date and may amend this AD because of those comments.

We will post all comments we receive, without change, to <http://www.regulations.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact we receive about this AD.

Costs of Compliance

We estimate that this AD affects 71 airplanes of U.S. registry. We estimate the following costs to comply with this AD:

ESTIMATED COSTS

Action	Labor cost	Parts cost	Cost per product	Cost on U.S. operators
Detailed inspection	2 work-hours × \$85 per hour = \$170	\$0	\$170	\$12,070

We have received no definitive data that would enable us to provide cost estimates for the on-condition actions specified in this AD.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. "Subtitle VII: Aviation Programs" describes in more

detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: "General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation

is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

This AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the

distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

- (1) Is not a "significant regulatory action" under Executive Order 12866,
- (2) Is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979),
- (3) Will not affect intrastate aviation in Alaska, and
- (4) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

2016–22–18 The Boeing Company:
Amendment 39–18707; Docket No. FAA–2016–9306; Directorate Identifier 2016–NM–169–AD.

(a) Effective Date

This AD is effective November 21, 2016.

(b) Affected ADs

None.

(c) Applicability

This AD applies to all The Boeing Company Model MD–90–30 airplanes, certificated in any category.

(d) Subject

Air Transport Association (ATA) of America Code 53, Fuselage.

(e) Unsafe Condition

This AD was prompted by a report of cracking in various structures in the fuselage cant station 1520 bulkhead. We are issuing this AD to detect and correct cracking in the bulkhead, which could result in reduced structural integrity of the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Detailed Inspection of the Cant Station 1520 Bulkhead

At the applicable time specified in paragraph 1.E., "Compliance," of Boeing Alert Service Bulletin MD90–53A037, dated September 19, 2016, except as required by paragraph (j) of this AD: On the left and right sides at the cant station 1520 bulkhead, do a detailed inspection of the forward and aft surfaces, for any crack in the upper cap and (cap) doubler, webs and doublers, stiffeners, and the lower tee cap between longerons 3 through 11, in accordance with the Accomplishment Instructions of Boeing Alert Service Bulletin MD90–53A037, dated September 19, 2016.

(h) Repair of Cracks in the Bulkhead Web or Doubler

If any crack is found in the bulkhead web or doubler, do the repair in accordance with Boeing Alert Service Bulletin MD90–53A037, dated September 19, 2016. Do all repairs before further flight.

(i) Repair of Non-Web or Non-Doubler Cracks in the Bulkhead

If any non-web or non-doubler crack is found in the bulkhead, repair before further flight using a method approved in accordance with the procedures specified in paragraph (l) of this AD.

(j) Service Information Exception

Where paragraph 1.E., "Compliance," of Boeing Alert Service Bulletin MD90–53A037, dated September 19, 2016, specifies a compliance time "after the original issue date of this service bulletin," this AD requires compliance within the specified compliance time after the effective date of this AD.

(k) Special Flight Permit

Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the airplane can be repaired, but if any crack is found as identified in Boeing Alert Service Bulletin MD90–53A037, dated September 19, 2016, concurrence by the Manager, Los Angeles Aircraft Certification Office (ACO), FAA, is required before issuance of the special flight permit.

(l) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Los Angeles ACO, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the ACO, send it to the attention of the person identified in paragraph (m) of this AD. Information may be emailed to: 9-ANM-LACO-AMOC-Requests@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(3) An AMOC that provides an acceptable level of safety may be used for any repair,

modification, or alteration required by this AD if it is approved by the Boeing Commercial Airplanes Organization Designation Authorization (ODA) that has been authorized by the Manager, Los Angeles ACO, to make those findings. To be approved, the repair method, modification deviation, or alteration deviation must meet the certification basis of the airplane, and the approval must specifically refer to this AD.

(4) Except as required by paragraph (j) of this AD: For service information that contains steps that are labeled as Required for Compliance (RC), the provisions of paragraphs (l)(4)(i) and (l)(4)(ii) of this AD apply.

(i) The steps labeled as RC, including substeps under an RC step and any figures identified in an RC step, must be done to comply with the AD. If a step or substep is labeled "RC Exempt," then the RC requirement is removed from that step or substep. An AMOC is required for any deviations to RC steps, including substeps and identified figures.

(ii) Steps not labeled as RC may be deviated from using accepted methods in accordance with the operator's maintenance or inspection program without obtaining approval of an AMOC, provided the RC steps, including substeps and identified figures, can still be done as specified, and the airplane can be put back in an airworthy condition.

(m) Related Information

For more information about this AD, contact George Garrido, Aerospace Engineer, Airframe Branch, ANM–120L, FAA, Los Angeles Aircraft Certification Office (ACO), 3960 Paramount Boulevard, Lakewood, CA 90712–4137; phone: 562–627–5232; fax: 562–627–5210; email: george.garrido@faa.gov.

(n) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Boeing Alert Service Bulletin MD90–53A037, dated September 19, 2016.

(ii) Reserved.

(3) For service information identified in this AD, contact Boeing Commercial Airplanes, Attention: Contractual & Data Services (C&DS), 2600 Westminister Blvd., MC 110–SK57, Seal Beach, CA 90740–5600; telephone 562–797–1717; Internet <https://www.myboeingfleet.com>.

(4) You may view this service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425–227–1221.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202–741–6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on October 26, 2016.

Dionne Palermo,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 2016-26629 Filed 11-3-16; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2016-6669; Directorate Identifier 2015-NM-191-AD; Amendment 39-18698; AD 2016-22-09]

RIN 2120-AA64

Airworthiness Directives; The Boeing Company Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: We are superseding Airworthiness Directive (AD) 2006-20-11 for certain The Boeing Company Model 757-200, -200CB, and -200PF series airplanes. AD 2006-20-11 required initial and repetitive detailed or high frequency eddy current (HFEC) inspections for cracks around the rivets at the upper fastener row of the skin lap splice of the fuselage, and repair of any crack found. This new AD no longer allows the detailed inspections and instead requires repetitive external HFEC inspections for cracking of the skin lap splices of the fuselage, and repair if necessary. This AD was prompted by an evaluation done by the design approval holder (DAH) indicating that the fuselage skin lap splice is subject to widespread fatigue damage (WFD). We are issuing this AD to detect and correct fatigue cracking at certain skin lap splice locations of the fuselage, which could result in reduced structural integrity and rapid decompression of the airplane.

DATES: This AD is effective December 9, 2016.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in this AD as of December 9, 2016.

The Director of the Federal Register approved the incorporation by reference of a certain other publication listed in this AD as of November 8, 2006 (71 FR 58485, October 4, 2006).

ADDRESSES: For service information identified in this final rule, contact Boeing Commercial Airplanes, Attention: Contractual & Data Services (C&DS), 2600 Westminister Blvd., MC

110-SK57, Seal Beach, CA 90740; telephone 562-797-1717; Internet <https://www.myboeingfleet.com>. You may view this referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221. It is also available on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2016-6669.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2016-6669; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this AD, the regulatory evaluation, any comments received, and other information. The address for the Docket Office (phone: 800-647-5527) is Docket Management Facility, U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC 20590.

FOR FURTHER INFORMATION CONTACT: Eric Schrieber, Aerospace Engineer, Airframe Branch, ANM-120L, FAA, Los Angeles Aircraft Certification Office (ACO), 3960 Paramount Boulevard, Lakewood, CA 90712-4137; phone: 562-627-5348; fax: 562-627-5210; email: eric.schrieber@faa.gov.

SUPPLEMENTARY INFORMATION:

Discussion

We issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 to supersede AD 2006-20-11, Amendment 39-14781 (71 FR 58485, October 4, 2006) (“AD 2006-20-11”). AD 2006-20-11 applied to certain The Boeing Company Model 757-200, -200CB, and -200PF series airplanes. The NPRM published in the **Federal Register** on May 12, 2016 (81 FR 29508) (“the NPRM”). The NPRM was prompted by an evaluation done by the DAH indicating that the fuselage skin lap splice is subject to WFD. The NPRM proposed to require repetitive external HFEC inspections for cracking of the skin lap splices of the fuselage, and repair if necessary. We are issuing this AD to detect and correct fatigue cracking at certain skin lap splice locations of the fuselage, which could result in reduced structural integrity and rapid decompression of the airplane.

Comments

We gave the public the opportunity to participate in developing this AD. The following presents the comments received on the NPRM and the FAA’s response to each comment.

Support of the NPRM

FedEx provided comments that supported the intent of the NPRM.

Request To Change Compliance Time

Boeing and United Airlines (UA) asked that we change the compliance time for the repetitive HFEC inspections specified in paragraph (j) of the proposed AD. Boeing learned that some operators began doing inspections long before the 37,500-flight-cycle threshold was attained. Boeing stated that the compliance table in Boeing Special Attention Service Bulletin 757-53-0090, Revision 1, dated November 19, 2015, provided grace periods for doing the HFEC inspections after doing previous inspections, but did not provide for previous inspections being done within the grace period or before the required threshold of 37,500 flight cycles, whichever occurs later. Boeing added that, as written, the service information specifies repetitive inspections within 3,000 flight cycles after any previous detailed inspection and within 12,000 flight cycles after any previous HFEC inspection—even if the interval occurred before the 37,500-flight-cycle threshold.

UA stated that if an operator decided to proactively accomplish either a detailed or HFEC inspection before the specified compliance time in, and in accordance with either Boeing Special Attention Service Bulletin 757-53-0090, dated June 2, 2005 or Boeing Special Attention Service Bulletin 757-53-0090, Revision 1, dated November 19, 2015, then the inspection would have to be repeated within 3,000 or 12,000 flight cycles, depending on which inspection was previously done. UA stated that this compliance time could be much sooner than the intended 37,500 flight cycles. UA noted that it discussed this problem with Boeing and hoped it could be clarified in the NPRM.

We agree with the commenters’ requests to change the compliance time for the repetitive HFEC inspections specified in paragraph (j) of this AD. According to the proposed AD, operators that accomplished the inspections early would be required to do the inspections before reaching the inspection threshold specified in paragraph (j) of the proposed AD. It was not the intent of Boeing or the FAA to require that the airplane be inspected