

DEPARTMENT OF TRANSPORTATION**Federal Aviation Administration****14 CFR Part 39**

[Docket No. FAA-2016-7850; Directorate Identifier 2016-NE-16-AD]

RIN 2120-AA64

Airworthiness Directives; Turbomeca S.A. Turboshift Engines**AGENCY:** Federal Aviation Administration (FAA), DOT.**ACTION:** Notice of proposed rulemaking (NPRM).

SUMMARY: We propose to adopt a new airworthiness directive (AD) for all Turbomeca S.A. Arriel 2B turboshift engines. This proposed AD was prompted by a report of an uncommanded in-flight shutdown (IFSD) on a single-engine helicopter, caused by a low returning spring rate of the needle of the hydro-mechanical metering unit (HMU). This proposed AD would require removing any pre-modification (mod) TU 158 HMU and replacing with a part eligible for installation. We are proposing this AD to prevent failure of the HMU, failure of the engine, IFSD, and loss of the helicopter.

DATES: We must receive comments on this NPRM by December 19, 2016.

ADDRESSES: You may send comments by any of the following methods:

- *Federal eRulemaking Portal:* Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.
- *Mail:* Docket Management Facility, U.S. Department of Transportation, 1200 New Jersey Avenue SE., West Building Ground Floor, Room W12-140, Washington, DC 20590-0001.
- *Hand Delivery:* Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.
- *Fax:* 202-493-2251.

For service information identified in this proposed AD, contact Turbomeca S.A., 40220 Tarnos, France; phone: (33) 05 59 74 40 00; fax: (33) 05 59 74 45 15. You may view this service information at the FAA, Engine & Propeller Directorate, 1200 District Avenue, Burlington, MA. For information on the availability of this material at the FAA, call 781-238-7125. It is also available on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2016-7850.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2016-7850; or in person at the Docket Operations office between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this proposed AD, the mandatory continuing airworthiness information (MCAI), the regulatory evaluation, any comments received, and other information. The address for the Docket Office (phone: 800-647-5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT: Kenneth Steeves, Aerospace Engineer, Engine Certification Office, FAA, Engine & Propeller Directorate, 1200 District Avenue, Burlington, MA 01803; phone: 781-238-7765; fax: 781-238-7199; email: kenneth.steeves@faa.gov.

SUPPLEMENTARY INFORMATION:

Comments Invited

We invite you to send any written relevant data, views, or arguments about this proposed AD. Send your comments to an address listed under the **ADDRESSES** section. Include "Docket No. FAA-2016-7850; Directorate Identifier 2016-NE-16-AD" at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this proposed AD. We will consider all comments received by the closing date and may amend this proposed AD based on those comments.

We will post all comments we receive, without change, to <http://www.regulations.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact with FAA personnel concerning this proposed AD.

Discussion

The European Aviation Safety Agency (EASA), which is the Technical Agent for the Member States of the European Community, has issued EASA AD 2016-0098, dated May 23, 2016 (referred to hereinafter as "the MCAI"), to correct an unsafe condition for the specified products. The MCAI states:

Following a report of an un-commanded in-flight shut-down (IFSD), Turbomeca carried out an engineering investigation. This investigation concluded that the cause of the event was a low returning spring rate of the needle of the hydro-mechanical metering unit (HMU), which enabled needle oscillation during rapid engine deceleration. This condition, if not corrected, could lead to further cases of IFSD, possibly resulting in an emergency landing on single engine.

To address this potential unsafe condition, Turbomeca developed modification (Mod) TU 158, which increases needle return spring rate to prevent oscillation during rapid deceleration, thus preventing the risk of un-commanded IFSD. Turbomeca also published Mandatory Service Bulletin (MSB) 292 73 3158 for embodiment of this modification in service.

You may obtain further information by examining the MCAI in the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2016-7850.

Related Service Information Under 14 CFR Part 39

Turbomeca S.A. has issued MSB No. 292 73 3158, Version A, dated April 7, 2016. The MSB describes procedures for removing the pre-mod TU 158 HMU and replacing with an HMU modified with mod TU 158. This service information is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the **ADDRESSES** section.

Related Service Information Under 14 CFR Part 51

FAA's Determination and Requirements of This Proposed AD

This product has been approved by the aviation authority of France, and is approved for operation in the United States. Pursuant to our bilateral agreement with the European Community, EASA has notified us of the unsafe condition described in the MCAI and service information referenced above. We are proposing this AD because we evaluated all information provided by EASA and determined the unsafe condition exists and is likely to exist or develop on other products of the same type design. This AD would require removing the pre-mod TU 158 HMU and replacing with a part eligible for installation.

Costs of Compliance

We estimate that this proposed AD affects 124 engines installed on helicopters of U.S. registry. We also estimate that it will take about 2.0 hours per engine to comply with this AD. The average labor rate is \$85 per hour. Based on these figures, we estimate the cost of this AD on U.S. operators to be \$21,080.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. "Subtitle VII: Aviation Programs," describes in more detail the scope of the Agency's authority.

Authority for This Rulemaking

We are issuing this rulemaking under the authority described in "Subtitle VII, Authority for This Rulemaking"

We are issuing this rulemaking under the authority described in "Subtitle VII, Authority for This Rulemaking"

Part A, Subpart III, Section 44701: General requirements.” Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

(1) Is not a “significant regulatory action” under Executive Order 12866,

(2) Is not a “significant rule” under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979),

(3) Will not affect intrastate aviation in Alaska to the extent that it justifies making a regulatory distinction, and

(4) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

■ 2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

Turbomeca S.A.: Docket No. FAA-2016-7850; Directorate Identifier 2016-NE-16-AD.

(a) Comments Due Date

We must receive comments by December 19, 2016.

(b) Affected ADs

None.

(c) Applicability

This AD applies to all Turbomeca S.A. Arriel 2B turboshaft engines with a pre-modification (mod) TU 158 hydro-mechanical metering unit (HMU), installed.

(d) Reason

This AD was prompted by a report of an uncommanded in-flight shutdown (IFSD) on a single engine helicopter caused by a low returning spring rate of the needle of the HMU. We are issuing this AD to prevent failure of the HMU, failure of the engine, IFSD and loss of the helicopter.

(e) Actions and Compliance

Comply with this AD within the compliance times specified, unless already done.

(1) For an engine in pre-mod TU 158 configuration, within 200 engine hours, or within 5 months, whichever occurs first after the effective date of this AD, remove the pre-mod TU 158 HMU from service and replace with a part eligible for installation.

(2) Reserved.

(f) Installation Prohibition

After the effective date of the AD, do not install any pre-mod TU 158 HMU into any engine.

(g) Definition

For the purpose of this AD, an HMU eligible for installation is one that incorporates mod TU 158 in accordance with Turbomeca MSB No. 292 73 3158, Version A, dated April 7, 2016, or other FAA approved parts.

(h) Alternative Methods of Compliance (AMOCs)

The Manager, Engine Certification Office, may approve AMOCs for this AD. Use the procedures found in 14 CFR 39.19 to make your request. You may email your request to: ANE-AD-AMOC@faa.gov.

(i) Related Information

(1) For more information about this AD, contact Kenneth Steeves, Aerospace Engineer, Engine Certification Office, FAA, Engine & Propeller Directorate, 1200 District Avenue, Burlington, MA 01803; phone: 781-238-7765; fax: 781-238-7199; email: kenneth.steeves@faa.gov.

(2) Refer to MCAI European Aviation Safety Agency (EASA), AD 2016-0098, dated May 23, 2016, for more information. You may examine the MCAI in the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating it in Docket No. FAA-2016-7850.

(3) Turbomeca Mandatory Service Bulletin MSB No. 292 73 3158, Version A, dated April 7, 2016, can be obtained from Turbomeca S.A., using the contact information in paragraph (i)(4) of this proposed AD.

(4) For service information identified in this proposed AD, contact Turbomeca S.A.,

40220 Tarnos, France; phone: (33) 05 59 74 40 00; fax: (33) 05 59 74 45 15.

(5) You may view this service information at the FAA, Engine & Propeller Directorate, 1200 District Avenue, Burlington, MA. For information on the availability of this material at the FAA, call 781-238-7125.

Issued in Burlington, Massachusetts, on October 25, 2016.

Colleen M. D'Alessandro,

Manager, Engine & Propeller Directorate, Aircraft Certification Service.

[FR Doc. 2016-26335 Filed 11-3-16; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 71

[Docket No. FAA-2016-8163; Airspace Docket No. 16-ANM-2]

Proposed Establishment of Class E Airspace, Thermopolis, WY

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of Proposed Rulemaking (NPRM).

SUMMARY: This action proposes to establish Class E airspace extending upward from 700 feet above the surface at Hot Springs County Airport, Thermopolis, WY, to support the development of Instrument Flight Rules (IFR) operations under standard instrument approach and departure procedures at the airport, for the safety and management of aircraft within the National Airspace System.

DATES: Comments must be received on or before December 19, 2016.

ADDRESSES: Send comments on this proposal to the U.S. Department of Transportation, Docket Operations, 1200 New Jersey Avenue SE., West Building Ground Floor, Room W12-140, Washington, DC 20590; telephone: 1-800-647-5527, or (202) 366-9826. You must identify FAA Docket No. FAA-2016-8163; Airspace Docket No. 16-ANM-2, at the beginning of your comments. You may also submit comments through the Internet at <http://www.regulations.gov>.

FAA Order 7400.11A, Airspace Designations and Reporting Points, and subsequent amendments can be viewed online at http://www.faa.gov/air_traffic/publications/. For further information, you can contact the Airspace Policy Group, Federal Aviation Administration, 800 Independence Avenue SW., Washington, DC 20591; telephone: 202-267-8783. The Order is also available for inspection at the