

## Other Relevant Rulemaking

The FAA previously issued AD 96-01-09, amendment 39-9485 (61 FR 2407, January 26, 1996), which addresses a similar problem found on McDonnell Douglas Model DC-9-80 series airplanes and Model MD-88 airplanes.

## Cost Impact

There are approximately 878 Model DC-9 series airplanes and C-9 (military) airplanes of the affected design in the worldwide fleet. The FAA estimates that 590 airplanes of U.S. registry would be affected by this proposed AD.

To accomplish the proposed replacement would take approximately 5.9 work hours per airplane, at an average labor rate of \$60 per work hour. Required parts would cost approximately \$11,139 per airplane (two assemblies at \$5,569 each). Based on these figures, the cost impact of the proposed replacement action on U.S. operators is estimated to be \$11,492 per airplane.

To accomplish the proposed modification would take approximately 10.9 work hours per airplane, at an average labor rate of \$60 per work hour. Required parts would cost approximately \$2,907 per airplane. Based on these figures, the cost impact of the proposed modification action on U.S. operators is estimated to be \$3,561 per airplane.

Based on the figures discussed above, the cost impact of this proposed AD on the U.S. fleet would be between \$2,100,990 and \$6,780,280. These cost impact figures are based on assumptions that no operator has yet accomplished any of the proposed requirements of this AD action, and that no operator would accomplish those actions in the future if this AD were not adopted.

## Regulatory Impact

The regulations proposed herein would not have substantial direct effects on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, in accordance with Executive Order 12612, it is determined that this proposal would not have sufficient federalism implications to warrant the preparation of a Federalism Assessment.

For the reasons discussed above, I certify that this proposed regulation (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) if

promulgated, will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A copy of the draft regulatory evaluation prepared for this action is contained in the Rules Docket. A copy of it may be obtained by contacting the Rules Docket at the location provided under the caption **ADDRESSES**.

## List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

## The Proposed Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration proposes to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

## PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

### § 39.13 [Amended]

2. Section 39.13 is amended by adding the following new airworthiness directive:

McDonnell Douglas: Docket 96-NM-91-AD.

*Applicability:* Model DC-9-10, -20, -30, -40, and -50 series airplanes, and C-9 (military) airplanes; as listed in McDonnell Douglas Service Bulletin DC9-32-289, dated March 7, 1996; certificated in any category.

Note 1: This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (b) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

*Compliance:* Required as indicated, unless accomplished previously.

To prevent high torsional vibration from occurring, which can damage the main landing gear (MLG) assembly and lead to its collapse, accomplish the following:

(a) Within 24 months after the effective date of this AD, either replace or modify the MLG hydraulic damper assembly, in accordance with the procedures specified as either Option 1 or Option 2, respectively, in McDonnell Douglas Service Bulletin DC9-32-289, dated March 7, 1996.

(b) An alternative method of compliance or adjustment of the compliance time that

provides an acceptable level of safety may be used if approved by the Manager, Los Angeles Aircraft Certification Office (ACO), FAA, Transport Airplane Directorate. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, Los Angeles ACO.

Note 2: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Los Angeles ACO.

(c) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

Issued in Renton, Washington, on July 3, 1996.

Darrell M. Pederson,

*Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.*

[FR Doc. 96-17537 Filed 7-9-96; 8:45 am]

BILLING CODE 4910-13-U

## 14 CFR Part 39

[Docket No. 95-NM-271-AD]

RIN 2120-AA64

## Airworthiness Directives; Jetstream Model 4101 Airplanes

**AGENCY:** Federal Aviation Administration, DOT.

**ACTION:** Notice of proposed rulemaking (NPRM).

**SUMMARY:** This document proposes the adoption of a new airworthiness directive (AD) that is applicable to certain Jetstream Model 4101 series airplanes. This proposal would require a high frequency eddy current inspection to detect cracks of the boundary angle and joint angle of the rear pressure bulkhead, and repair, if necessary. This proposal also would require modification of the rear pressure bulkhead of the fuselage. This proposal is prompted by a report of fatigue cracking in the rear pressure bulkhead of the fuselage. The actions specified by the proposed AD are intended to prevent such fatigue cracking, which could result in reduced structural integrity of the fuselage and, consequently, lead to the rapid decompression of the pressurized area of the airplane.

**DATES:** Comments must be received by August 19, 1996.

**ADDRESSES:** Submit comments in triplicate to the Federal Aviation Administration (FAA), Transport Airplane Directorate, ANM-103,

Attention: Rules Docket No. 95-NM-271-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056. Comments may be inspected at this location between 9:00 a.m. and 3:00 p.m., Monday through Friday, except Federal holidays.

The service information referenced in the proposed rule may be obtained from Jetstream Aircraft, Inc., P.O. Box 16029, Dulles International Airport, Washington, DC 20041-6029. This information may be examined at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington.

**FOR FURTHER INFORMATION CONTACT:** William Schroeder, Aerospace Engineer, Standardization Branch, ANM-113, FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington 98055-4056; telephone (206) 227-2148; fax (206) 227-1149.

#### **SUPPLEMENTARY INFORMATION:**

##### **Comments Invited**

Interested persons are invited to participate in the making of the proposed rule by submitting such written data, views, or arguments as they may desire. Communications shall identify the Rules Docket number and be submitted in triplicate to the address specified above. All communications received on or before the closing date for comments, specified above, will be considered before taking action on the proposed rule. The proposals contained in this notice may be changed in light of the comments received.

Comments are specifically invited on the overall regulatory, economic, environmental, and energy aspects of the proposed rule. All comments submitted will be available, both before and after the closing date for comments, in the Rules Docket for examination by interested persons. A report summarizing each FAA-public contact concerned with the substance of this proposal will be filed in the Rules Docket.

Commenters wishing the FAA to acknowledge receipt of their comments submitted in response to this notice must submit a self-addressed, stamped postcard on which the following statement is made: "Comments to Docket Number 95-NM-271-AD." The postcard will be date stamped and returned to the commenter.

##### **Availability of NPRMs**

Any person may obtain a copy of this NPRM by submitting a request to the FAA, Transport Airplane Directorate, ANM-103, Attention: Rules Docket No.

95-NM-271-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056.

##### **Discussion**

The Civil Aviation Authority (CAA), which is the airworthiness authority for the United Kingdom, recently notified the FAA that an unsafe condition may exist on certain Jetstream Model 4101 airplanes. The CAA advises that, during fatigue tests on a Model 4101 test article, cracking was found in the rear pressure bulkhead of the fuselage. Such cracking is attributed to fatigue-related stress. Fatigue-related cracking in the rear pressure bulkhead, if not detected and correct in a timely manner, could result in reduced structural integrity of fuselage and, consequently, lead to the rapid decompression of the pressurized area of the airplane.

##### **Explanation of Relevant Service Information**

Jetstream has issued Service Bulletin J41-53-020-41382A, dated September 28, 1995, as revised by Erratum No. 1, dated October 11, 1995, which describes procedures for a high frequency eddy current inspection to detect cracks of the boundary angle and joint angle of the rear pressure bulkhead. The service bulletin also describes procedures for modification of the rear pressure bulkhead of the fuselage. The modification involves installing shear cleats, angles, brackets, and stiffeners; and removing and replacing the brackets with new brackets. The CAA classified this service bulletin as mandatory in order to assure the continued airworthiness of these airplanes in the United Kingdom.

##### **FAA's Conclusion**

This airplane model is manufactured in the United Kingdom and is type certificated for operation in the United States under the provisions of section 21.29 of the Federal Aviation Regulations (14 CFR 21.29) and the applicable bilateral airworthiness agreement. Pursuant to this bilateral airworthiness agreement, the CAA has kept the FAA informed of the situation described above. The FAA has examined the findings of the CAA, reviewed all available information, and determined that AD action is necessary for products of this type design that are certificated for operation in the United States.

##### **Explanation of Requirements of Proposed Rule**

Since an unsafe condition has been identified that is likely to exist or develop on other airplanes of the same type design, the proposed AD would

require a high frequency eddy current inspection to detect cracks of the boundary angle and joint angle of the rear pressure bulkhead, and repair, if necessary. The proposed AD also would require modification of the rear pressure bulkhead of the fuselage. The actions would be required to be accomplished in accordance with the service bulletin described previously. If any boundary angle or joint angle is cracked, the repair would be required to be accomplished in accordance with a method approved by the FAA.

##### **Cost Impact**

The FAA estimates that 26 Model 4101 airplanes of U.S. registry would be affected by this proposed AD, that it would take approximately 40 work hours per airplane to accomplish the proposed actions, and that the average labor rate is \$60 per work hour. Required parts would be supplied by the manufacturer at no cost to the operators. Based on these figures, the cost impact of the proposed AD on U.S. operators is estimated to be \$62,400, or \$2,400 per airplane.

The cost impact figure discussed above is based on assumptions that no operator has yet accomplished any of the proposed requirements of this AD action, and that no operator would accomplish those actions in the future if this AD were not adopted.

##### **Regulatory Impact**

The regulations proposed herein would not have substantial direct effects on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, in accordance with Executive Order 12612, it is determined that this proposal would not have sufficient federalism implications to warrant the preparation of a Federalism Assessment.

For the reasons discussed above, I certify that this proposed regulation (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) if promulgated, will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A copy of the draft regulatory evaluation prepared for this action is contained in the Rules Docket. A copy of it may be obtained by contacting the Rules Docket at the location provided under the caption **ADDRESSES**.

## List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

## The Proposed Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration proposes to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

**PART 39—AIRWORTHINESS DIRECTIVES**

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

**39.13 [Amended]**

2. Section 39.13 is amended by adding the following new airworthiness directive:

Jetstream Aircraft Limited: Docket 95–NM–271–AD.

*Applicability:* Model 4101 airplanes, constructors numbers 41004 through 41060 inclusive, certificated in any category.

Note 1: This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been otherwise modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (b) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

Compliance: Required as indicated, unless accomplished previously.

To prevent fatigue-related cracking in the rear pressure bulkhead, which could result in reduced structural integrity of the fuselage and, consequently, lead to the rapid decompression of the pressurized area of the airplane; accomplish the following:

(a) Prior to the accumulation of 10,000 total landings, or within 6 months after the effective date of this AD, whichever occurs later, accomplish paragraphs (a)(1) and (a)(2) of this AD, in accordance with Jetstream Service Bulletin J41–53–020–41382A, dated September 28, 1995, as revised by Erratum No. 1, dated October 11, 1995.

(1) Perform a high frequency eddy current inspection to detect cracks of the boundary angle and joint angle of the rear pressure bulkhead, in accordance with the service bulletin. If any crack is detected, prior to further flight, repair it in accordance with a method approved by the Manager, Standardization Branch, ANM–113, FAA, Transport Airplane Directorate.

(2) Modify the rear pressure bulkhead of the fuselage (Jetstream Modification 41382A), in accordance with the service bulletin.

(b) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, Standardization Branch, ANM–113. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, Standardization Branch, ANM–113.

Note 2: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Standardization Branch, ANM–113.

(c) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

Issued in Renton, Washington, on July 3, 1996.

Darrell M. Pederson,

*Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.*

[FR Doc. 96–17536 Filed 7–9–96; 8:45 am]

**BILLING CODE 4910–13–U**

**14 CFR Part 39**

[Docket No. 96–ANE–08]

**RIN 2120–AA64**

**Airworthiness Directives; AlliedSignal Inc. TFE731 Series Turbofan Engines**

**AGENCY:** Federal Aviation Administration, DOT.

**ACTION:** Notice of proposed rulemaking (NPRM).

**SUMMARY:** This document proposes the adoption of a new airworthiness directive (AD) that is applicable to AlliedSignal Inc. TFE731 series turbofan engines. This proposal would require removal from service of certain low pressure turbine (LPT) seal plates prior to accumulating the new, reduced cyclic life limit, and replacement with serviceable LPT seal plates. This proposal is prompted by a report that the machined LPT seal plate geometry did not meet the design intent due to drawing ambiguity. The actions specified by the proposed AD are intended to prevent fatigue cracking and subsequent uncontained failure of an LPT seal plate.

**DATES:** Comments must be received by September 9, 1996.

**ADDRESSES:** Submit comments in triplicate to the Federal Aviation Administration (FAA), New England Region, Office of the Assistant Chief Counsel, Attention: Rules Docket No. 96–ANE–08, 12 New England Executive Park, Burlington, MA 01803–5299.

Comments may also be submitted to the Rules Docket by using the following Internet address: “epd-adcomments@mail.hq.faa.gov”. Comments may be inspected at this location between 8:00 a.m. and 4:30 p.m., Monday through Friday, except Federal holidays.

The service information referenced in the proposed rule may be obtained from AlliedSignal Aerospace, Attn: Data Distribution, M/S 64–3/2101–201, P.O. Box 29003, Phoenix, AZ 85038–9003; telephone (602) 365–2493, fax (602) 365–5577. This information may be examined at the FAA, New England Region, Office of the Assistant Chief Counsel, 12 New England Executive Park, Burlington, MA.

**FOR FURTHER INFORMATION CONTACT:**

Joseph Costa, Aerospace Engineer, Los Angeles Aircraft Certification Office, FAA, Transport Airplane Directorate, 3960 Paramount Blvd., Lakewood, CA 90712–4137; telephone (310) 627–5246; fax (310) 627–5210.

**SUPPLEMENTARY INFORMATION:**

Comments Invited

Interested persons are invited to participate in the making of the proposed rule by submitting such written data, views, or arguments as they may desire. Communications should identify the Rules Docket number and be submitted in triplicate to the address specified above. All communications received on or before the closing date for comments, specified above, will be considered before taking action on the proposed rule. The proposals contained in this notice may be changed in light of the comments received.

Comments are specifically invited on the overall regulatory, economic, environmental, and energy aspects of the proposed rule. All comments submitted will be available, both before and after the closing date for comments, in the Rules Docket for examination by interested persons. A report summarizing each FAA–public contact concerned with the substance of this proposal will be filed in the Rules Docket.

Commenters wishing the FAA to acknowledge receipt of their comments submitted in response to this notice must submit a self-addressed, stamped postcard on which the following statement is made: “Comments to Docket Number 96–ANE–08.” The postcard will be date stamped and returned to the commenter.