

is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) if promulgated, will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A copy of the draft regulatory evaluation prepared for this action is contained in the Rules Docket. A copy of it may be obtained by contacting the Rules Docket at the location provided under the caption **ADDRESSES**.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

The Proposed Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration proposes to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. Section 39.13 is amended by adding the following new airworthiness directive:

Airbus Industrie: Docket 96–NM–204–AD.

Applicability: Model A320, A321, A330 and A340 series airplanes; equipped with Westland-Sitec fire shutoff valves having part number E03000; certificated in any category.

Note 1: This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been otherwise modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (c) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

Compliance: Required as indicated, unless accomplished previously.

To prevent the flow of hydraulic fluid to the engine in the event of a fire, which would fuel the fire and lead to the loss of fluid in associated hydraulic systems, causing those systems to fail, accomplish the following:

(a) Within six months after the effective date of this AD, perform a functional test (for

A320 and A321 series airplanes) or an operational test (for A330 and A340 series airplanes) on each fire shutoff valve (FSOV) for the left and right engines and immediately follow this test with a check to determine whether the FSOV motor is properly operating, in accordance with Airbus All Operators Telex (AOT) 29–15, dated May 30, 1995.

(1) If an FSOV passes the applicable test and check, repeat the procedures required by paragraph (a) of this AD thereafter at intervals not to exceed 18 months.

(2) If an FSOV fails the applicable test or check, prior to further flight, replace the discrepant FSOV with an FSOV modified in accordance with the service bulletins specified in paragraphs (a)(2)(i), (a)(2)(ii), and (a)(2)(iii), as applicable. Modification of the seal and the electrical actuator for the motor are to be performed at the same time. The accomplishment of these modifications constitutes terminating action for the repetitive testing and checks of this FSOV required by paragraph (a) of AD.

(i) For Airbus A320 and A321 series airplanes: Airbus Service Bulletin A320–29–1071, dated September 21, 1995.

(ii) For Airbus A330 series airplanes: Airbus Service Bulletin A330–29–3018, dated January 17, 1996.

(iii) For Airbus A340 series airplanes: Airbus Service Bulletin A340–29–4018, dated January 17, 1996.

Note 2: The Airbus service bulletins cited in paragraphs (a)(2)(i)–(iii) of this AD refer to Westland-Sitec Service Bulletin No. E030WS–29–1, dated January 12, 1996 (valve modification), and Westland-Sitec Service Bulletin No. A06AWS–24–1, dated January 12, 1996 (electrical actuator modification), as additional sources of procedural information.

(b) Within 4 years after the effective date of this AD, modify the electrical actuator for the motor and the seal of each FSOV, in accordance with the service bulletins specified in paragraphs (b)(2)(i), (b)(2)(ii), and (b)(2)(iii) of this AD, as applicable. The accomplishment of these modifications constitutes terminating action for the repetitive tests and checks required by paragraph (a) of this AD and, thereafter, no further action is required.

(i) For Airbus A320 and A321 series airplanes: Airbus Service Bulletin A320–29–1071, dated September 21, 1995.

(ii) For Airbus A330 series airplanes: Airbus Service Bulletin A330–29–3018, dated January 17, 1996.

(iii) For Airbus A340 series airplanes: Airbus Service Bulletin A340–29–4018, dated January 17, 1996.

(c) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, Standardization Branch, ANM–113, FAA, Transport Airplane Directorate. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, Standardization Branch, ANM–113.

Note 3: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be

obtained from the Standardization Branch, ANM–113.

(d) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

Issued in Renton, Washington, on November 21, 1996.

James V. Devany,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 96–30411 Filed 11–27–96; 8:45 am]

BILLING CODE 4910–13–U

14 CFR Part 39

[Docket No. 96–NM–239–AD]

RIN 2120–AA64

Airworthiness Directives; Boeing Model 747–100, –200, and –300 Series Airplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: This document proposes the adoption of a new airworthiness directive (AD) that is applicable to certain Boeing Model 747–100, –200, and –300 series airplanes. This proposal would require the replacement of certain switches located behind the cabin attendant's panel at one of the airplane's doors with new, improved switches. This proposal is prompted by reports indicating that fires have occurred on some airplanes due to the internal failure of some of these switches. The actions specified by the proposed AD are intended to prevent the installation and use of switches that could short circuit when they fail, and consequently cause fire and smoke aboard the airplane.

DATES: Comments must be received by January 29, 1997.

ADDRESSES: Submit comments in triplicate to the Federal Aviation Administration (FAA), Transport Airplane Directorate, ANM–103, Attention: Rules Docket No. 96–NM–239–AD, 1601 Lind Avenue, SW., Renton, Washington 98055–4056. Comments may be inspected at this location between 9:00 a.m. and 3:00 p.m., Monday through Friday, except Federal holidays.

The service information referenced in the proposed rule may be obtained from Boeing Commercial Airplane Group, P.O. Box 3707, Seattle, Washington 98124–2207. This information may be examined at the FAA, Transport

Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington.

FOR FURTHER INFORMATION CONTACT: Forrest Keller, Senior Aerospace Engineer, Systems and Equipment Branch, ANM-130S, FAA, Seattle Aircraft Certification Office, 1601 Lind Avenue, SW., Renton, Washington; telephone (206) 227-2790; fax (206) 227-1181.

SUPPLEMENTARY INFORMATION:

Comments Invited

Interested persons are invited to participate in the making of the proposed rule by submitting such written data, views, or arguments as they may desire. Communications shall identify the Rules Docket number and be submitted in triplicate to the address specified above. All communications received on or before the closing date for comments, specified above, will be considered before taking action on the proposed rule. The proposals contained in this notice may be changed in light of the comments received.

Comments are specifically invited on the overall regulatory, economic, environmental, and energy aspects of the proposed rule. All comments submitted will be available, both before and after the closing date for comments, in the Rules Docket for examination by interested persons. A report summarizing each FAA-public contact concerned with the substance of this proposal will be filed in the Rules Docket.

Commenters wishing the FAA to acknowledge receipt of their comments submitted in response to this notice must submit a self-addressed, stamped postcard on which the following statement is made: "Comments to Docket Number 96-NM-239-AD." The postcard will be date stamped and returned to the commenter.

Availability of NPRMs

Any person may obtain a copy of this NPRM by submitting a request to the FAA, Transport Airplane Directorate, ANM-103, Attention: Rules Docket No. 96-NM-239-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056.

Discussion

The FAA has received several reports indicating that fires and smoke have occurred aboard Model 747-100 series airplanes behind the cabin attendant's panel at door 4 right. These incidents, reported by four operators, occurred during flight or after landing.

Investigation revealed that the fires were the result of internal failures in switches S4 and/or S5, or switches S7

and S8. These failures caused a short circuit between the switch and its ground. Switches of this type also are found on Model 747-200 and -300 series airplanes. The installation and use of a switch that could short circuit when it fails, if not corrected, could consequently result in fire and smoke aboard the airplane.

Explanation of Relevant Service Information

The FAA has reviewed and approved Boeing Alert Service Bulletin 747-33A2252, dated August 1, 1996, which describes procedures for the replacement of switches S4 and/or S5, or switches S7 and S8 that are installed on the cabin attendant's panel at door 4 right with new, improved switches. In the event that an improved switch fails internally, there will be no short circuit between the switch and its ground; therefore, the potential for fire or smoke to occur is reduced.

Explanation of Requirements of Proposed Rule

Since an unsafe condition has been identified that is likely to exist or develop on other products of this same type design, the proposed AD would require the replacement of switches S4 and/or S5, or switches S7 and S8 that are installed on the cabin attendant's panel at door 4 right with new, improved switches. The actions would be required to be accomplished in accordance with the Boeing alert service bulletin described previously.

Cost Impact

There are approximately 648 Boeing Model 747-100, -200, and -300 series airplanes of the affected design in the worldwide fleet.

The FAA estimates that 167 airplanes of U.S. registry would be affected by this proposed AD. It would take approximately 3 work hours per airplane to accomplish the proposed actions, at an average labor rate of \$60 per work hour. Required parts would cost between \$270 and \$556, depending on the parts kit that is needed. Based on these figures, the cost impact of the proposed AD on U.S. operators is estimated to be between \$75,150 and \$122,912, or between \$450 and \$736 per airplane.

The cost impact figures discussed above are based on assumptions that no operator has yet accomplished any of the proposed requirements of this AD action, and that no operator would accomplish those actions in the future if this AD were not adopted.

Regulatory Impact

The regulations proposed herein would not have substantial direct effects on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, in accordance with Executive Order 12612, it is determined that this proposal would not have sufficient federalism implications to warrant the preparation of a Federalism Assessment.

For the reasons discussed above, I certify that this proposed regulation (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) if promulgated, will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A copy of the draft regulatory evaluation prepared for this action is contained in the Rules Docket. A copy of it may be obtained by contacting the Rules Docket at the location provided under the caption

ADDRESSES.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

The Proposed Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration proposes to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. Section 39.13 is amended by adding the following new airworthiness directive:

Boeing; Docket 96-NM-239-AD.

Applicability: Model 747-100, -200, and -300 series airplanes; as listed in Boeing Alert Service Bulletin 747-33A2252, dated August 1, 1996; certificated in any category.

Note 1: This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been otherwise modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in

accordance with paragraph (c) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

Compliance: Required as indicated, unless accomplished previously.

To prevent the installation and use of switches in the cabin attendant's panel at door 4 right that could short circuit when they fail, and consequently cause fire and smoke aboard the airplane, accomplish the following:

(a) Within 6 months after the effective date of this AD, replace switches S4 and/or S5, or switches S7 and S8 that are installed in the cabin attendant's panel at door 4 right with new switches, in accordance with Boeing Alert Service Bulletin 747-33A2252, dated August 1, 1996.

(b) As of the effective date of this AD, no person shall install at door 4 right of any airplane an attendant's panel having a part number identified in the "Existing Part Number" column of paragraph II.D. of Boeing Alert Service Bulletin 747-33A2252, dated August 1, 1996.

(c) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, Seattle Aircraft Certification Office (ACO), FAA, Transport Airplane Directorate. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, Seattle ACO.

Note 2: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Seattle ACO.

(d) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

Issued in Renton, Washington, on November 21, 1996.

Darrell M. Pederson,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 96-30412 Filed 11-27-96; 8:45 am]

BILLING CODE 4910-13-U

14 CFR Part 71

[Airspace Docket No. 96-AGL-22]

Establishment of Class E Airspace; New Lisbon, WI, Mauston-New Lisbon Union Airport

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking.

SUMMARY: This notice proposes to establish Class E airspace at New Lisbon, WI. A Global Positioning System (GPS) standard instrument

approach procedure (SIAP) to Runway 32 has been developed for Mauston-New Lisbon Union Airport. Controlled airspace extending upward from 700 to 1200 feet above ground level (AGL) is needed to contain aircraft executing the approach. The intended effect of this proposal is to provide segregation of aircraft using instrument approach procedures in instrument conditions from other aircraft operating in visual weather conditions.

DATES: Comments must be received on or before January 7, 1997.

ADDRESSES: Send comments on the proposal in triplicate to: Federal Aviation Administration, Office of the Assistant Chief Counsel, AGL-7, Rules Docket No. 96-AGL-22, 2300 East Devon Avenue, Des Plaines, Illinois 60018.

The official docket may be examined in the Office of the Assistant Chief Counsel, Federal Aviation Administration, 2300 East Devon Avenue, Des Plaines, Illinois. An informal docket may also be examined during normal business hours at the Air Traffic Division, Operations Branch, Federal Aviation Administration, 2300 East Devon Avenue, Des Plaines, Illinois.

FOR FURTHER INFORMATION CONTACT: John A. Clayborn, Air Traffic Division, Operations Branch, AGL-530, Federal Aviation Administration, 2300 East Devon Avenue, Des Plaines, Illinois 60018, telephone (847) 294-7568.

SUPPLEMENTARY INFORMATION:

Comments Invited

Interested parties are invited to participate in this proposed rulemaking by submitting such written data, views, or arguments as they may desire. Comments that provide the factual basis supporting the views and suggestions presented are particularly helpful in developing reasoned regulatory decisions on the proposal. Comments are specifically invited on the overall regulatory, aeronautical, economic, environmental, and energy-related aspects of the proposal.

Communications should identify the airspace docket number and be submitted in triplicate to the address listed above. Commenters wishing the FAA to acknowledge receipt of their comments on this notice must submit with those comments a self-addressed, stamped postcard on which the following statement is made:

"Comments to Airspace Docket No. 96-AGL-22." The postcard will be date/time stamped and returned to the commenter. All communications received on or before the specified

closing date for comments will be considered before taking action on the proposed rule. The proposal contained in this notice may be changed in light of comments received. All comments submitted will be available for examination in the Rules Docket, FAA, Great Lakes Region, Office of the Assistant Chief Counsel, 2300 East Devon Avenue, Des Plaines, Illinois, both before and after the closing date for comments. A report summarizing each substantive public contact with FAA personnel concerned with this rulemaking will be filed in the docket.

Availability of NPRM's

Any person may obtain a copy of the Notice of Proposed Rulemaking (NPRM) by submitting a request to the Federal Aviation Administration, Office of Public Affairs, Attention: Public Inquiry Center, APA-230, 800 Independence Avenue, S.W., Washington, DC 20591, or by calling (202) 267-3484.

Communications must identify the notice number of this NPRM. Persons interested in being placed on a mailing list for future NPRM's should also request a copy of Advisory Circular No. 11-2A, which describes the application procedure.

The Proposal

The FAA is considering an amendment to part 71 of the Federal Aviation Regulations (14 CFR part 71) to establish Class E airspace at New Lisbon, WI; this proposal would provide adequate Class E airspace for operators executing the GPS Runway 32 SIAP at Mauston-New Lisbon Union Airport. Controlled airspace extending upward from 700 to 1200 feet AGL is needed to contain aircraft executing the approach. The intended affect of this action is to provide segregation of aircraft using instrument approach procedures in instrument conditions from other aircraft operating in visual weather conditions. The area would be depicted on appropriate aeronautical charts thereby enabling pilots to circumnavigate the area or otherwise comply with IFR procedures. Class E airspace designations for airspace areas extending upward from 700 feet or more above the surface of the earth are published in paragraph 6005 of FAA Order 7400.9D dated September 4, 1996, and effective September 16, 1996, which is incorporated by reference in 14 CFR 71.1. The Class E airspace designation listed in this document would be published subsequently in the Order.

The FAA has determined that this proposed regulation only involves an established body of technical regulations for which frequent and