

5 SB No. 72-541, dated July 27, 1998, as follows:

(1) For seals that have accumulated less than 3,000 CSN on the effective date of this AD, remove the seal from service prior to accumulating 7,700 CSN.

(2) For seals that have accumulated 3,000 CSN or more, but less than 7,700 CSN on the effective date of this AD, accomplish the following:

(i) For engines that have an ESV prior to the seal accumulating 7,700 CSN, remove the seal from service prior to the seal accumulating 7,700 CSN.

(ii) For engines that do not have an ESV prior to the seal accumulating 7,700 CSN after the effective date of the AD, remove the seal from service prior to the seal accumulating 4,700 CIS after the effective date of this AD, or prior to the seal accumulating 13,000 CSN, whichever occurs first.

(3) For seals that have accumulated 7,700 CSN or more on the effective date of this AD, remove the seal from service at the next ESV, or prior to the seal accumulating 13,000 CSN, whichever occurs first.

(c) For CFM56-5A4, -5A4/F, -5A5, and -5A5/F HPTR front air seals, P/N 1319M11P05, 1319M11P06, 1319M11P07, 1319M11P08, and 1319M11P09, that have previously operated in CFM56-5-A1, -5-A1/F, or -5A3 engine models, recalculate the HPTR front air seal total cycles remaining using 11,000 cycles for the CFM56-5-A1 and CFM56-5-A1/F engine models, and 7,700 cycles for the CFM56-5A3 engine model, in

accordance with CFM56-5 SB No. 72-541, dated July 27, 1998, within 750 CIS after the effective date of this AD.

Note 2: The current HPTR front air seal retirement life for the CFM56-5A4, -5A4/F, -5A5, and -5A5/F engine models is 9,100 cycles, and is not affected by this AD.

Note 3: For additional information on recalculating the HPTR front air seal total cycles remaining see Chapter 05, Section 05-11-00, of the CFM56-5 series Engine Shop Manual, CFMI-TP.SM.7.

(d) This AD establishes new LCF retirement lives of 11,000 cycles for CFM56-5-A1 and -5-A1/F HPTR front air seals, and 7,700 cycles for CFM56-5A3 HPTR front air seals, which is published in Chapter 05, Section 05-11-03, of the CFM56-5 series Engine Shop Manual, CFMI-TP.SM.7. The following conditions also apply:

(1) Except as provided in paragraph (g) of this AD, no alternative retirement lives may be approved for the CFM56-5-A1, -5-A1/F, and -5A3 HPTR front air seals.

(2) After the effective date of this AD, no CFM56-5-A1 and -5-A1/F HPTR front air seals may be installed or reinstalled on an engine if the seals have accumulated more than 11,000 CSN.

(3) After the effective date of this AD, no CFM56-5A3 HPTR front air seals may be installed or reinstalled on an engine if the seals have accumulated more than 7,700 CSN.

(e) For the purpose of this AD, an "engine shop visit" is defined as the induction of an

engine into the shop for maintenance involving the separation of any major mating engine flanges, or the removal of a disk or spool, except that the separation of engine flanges solely for the purposes of transportation without subsequent engine maintenance does not constitute an engine shop visit.

(f) For the purpose of this AD, a "serviceable part" is defined as one that has not exceeded its respective new retirement life as set out in this AD.

(g) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, Engine Certification Office. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, Engine Certification Office.

Note 4: Information concerning the existence of approved alternative methods of compliance with this airworthiness directive, if any, may be obtained from the Engine Certification Office.

(h) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the aircraft to a location where the requirements of this AD can be accomplished.

(i) The actions required by this AD shall be done in accordance with the following CFM International SB:

Document No.	Pages	Date
CFM56-5 SB No. 72-541 Total Pages: 8.	1-8	July 27, 1998.

This incorporation by reference was approved by the Director of the Federal Register in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Copies may be obtained from CFM International, Technical Publications Department, 1 Neumann Way, Cincinnati, OH 45215; telephone (513) 552-2981, fax (513) 552-2816. Copies may be inspected at the FAA, New England Region, Office of the Regional Counsel, 12 New England Executive Park, Burlington, MA; or at the Office of the Federal Register, 800 North Capitol Street NW, suite 700, Washington, DC.

(j) This amendment becomes effective on April 21, 1999.

Issued in Burlington, Massachusetts, on March 11, 1999.

David A. Downey,

Assistant Manager, Engine and Propeller Directorate, Aircraft Certification Service.
[FR Doc. 99-6555 Filed 3-19-99; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 96-NM-171-AD; Amendment 39-11082; AD 99-06-18]

RIN 2120-AA64

Airworthiness Directives; Boeing Model 747-400, -400D, and -400F Series Airplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Final rule.

SUMMARY: This amendment adopts a new airworthiness directive (AD), applicable to certain Boeing Model 747-400, -400D, and -400F series airplanes, that requires modification of the P212 and P213 panels of the cabin pressure control system. For certain airplanes, this amendment also requires modification of the P5, P6, and P7 panels, and the W4701, W4703, and W4908 wire bundles, as applicable. This amendment is prompted by a report of

in-flight loss of cabin pressurization control due to a single failure of the auxiliary power unit (APU) battery. The actions specified by this AD are intended to prevent loss of control of the cabin pressurization system, which could result in rapid depressurization of the airplane. Such rapid depressurization could result in deleterious physiological effects on the passengers and crew; and airplane diversions, which represent an increased risk to the airplane, passengers, and crew.

DATES: Effective April 26, 1999.

The incorporation by reference of certain publications listed in the regulations is approved by the Director of the Federal Register as of April 26, 1999.

ADDRESSES: The service information referenced in this AD may be obtained from Boeing Commercial Airplane Group, P.O. Box 3707, Seattle, Washington 98124-2207. This information may be examined at the Federal Aviation Administration (FAA), Transport Airplane Directorate, Rules

Docket, 1601 Lind Avenue, SW., Renton, Washington; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

FOR FURTHER INFORMATION CONTACT:

Clayton R. Morris, Jr., Aerospace Engineer, Systems and Equipment Branch, ANM-130S, FAA, Seattle Aircraft Certification Office, 1601 Lind Avenue, SW., Renton, Washington; telephone (425) 227-2794; fax (425) 227-1181.

SUPPLEMENTARY INFORMATION: A proposal to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) to include an airworthiness directive (AD) that is applicable to certain Boeing Model 747-400, -400D, and -400F series airplanes was published as a supplemental notice of proposed rulemaking (NPRM) in the **Federal Register** on May 12, 1998 (63 FR 26100). That action proposed to require modification of the P212 and P213 panels of the cabin pressure control system. For certain airplanes, that action also proposed to require modification of the P5, P6, and P7 panels, and the W4701, W4703, and W4908 wire bundles, as applicable.

Comments

Interested persons have been afforded an opportunity to participate in the making of this amendment. Due consideration has been given to the comments received.

Support for the Proposal

One commenter supports the proposed rule. Another commenter offers no comments to the proposed rule, because it does not own or operate the subject airplanes.

Requests To Extend Compliance Time

One commenter requests that the FAA extend the proposed compliance time for the modification from 180 days after the effective date of this AD to 18 months after the effective date of this AD, to reduce the impact on its operations and the cost associated with accomplishment of the proposed actions. The commenter states that the proposed 180-day compliance time would make it necessary to schedule approximately five of its airplanes for special maintenance visits, which the commenter estimates would cost \$60,000 per airplane. The commenter states that an 18-month compliance time would allow the modifications proposed in the supplemental NPRM to be accomplished during a regularly scheduled "C" check.

The FAA partially concurs with the commenter's request to extend the compliance time. The FAA has

determined that the compliance time may be extended somewhat. The FAA finds that extending the compliance time from 180 days after the effective date of this AD to 12 months after the effective date of this AD will not adversely affect safety and will allow the modifications to be performed, in the majority of cases, during a regularly scheduled maintenance visit. Therefore, paragraphs (a) and (b) of the final rule have been revised to specify a compliance time of 12 months after the effective date of this AD. However, with regard to the commenter's cost estimate, the FAA points out that operators may take advantage of special maintenance visits to accomplish other deferred maintenance tasks, which would reduce the time necessary to accomplish those deferred tasks during regularly scheduled checks. The commenter's estimate of additional costs associated with special visits does not take this into account.

Another commenter also requests that the FAA extend the proposed compliance time for accomplishment of the actions to 18 months after the effective date of this AD. The commenter states that Boeing Service Bulletin 747-21-2268 should be accomplished prior to the accomplishment of Boeing Alert Service Bulletin 747-21A2381, dated June 27, 1996 (which was referenced as an appropriate source of service information in the supplemental NPRM). The commenter states that Boeing Alert Service Bulletin 747-21A2381 can be accomplished within the 180-day compliance time proposed in the supplemental NPRM only if Boeing Service Bulletin 747-21-2268 has already been accomplished. The commenter requests that the compliance time be extended to provide for accomplishment of both Boeing Service Bulletin 747-21-2268 and Boeing Alert Service Bulletin 747-21A2381.

The FAA does not concur that Boeing Service Bulletin 747-21-2268 must be accomplished prior to accomplishment of Boeing Alert Service Bulletin 747-21A2381. The FAA has determined that Boeing Alert Service Bulletin 747-21A2381 provides specific instructions on how to accomplish the actions specified in the alert service bulletin both with and without prior incorporation of the actions specified in Boeing Service Bulletin 747-21-2268. In addition, the FAA does not require accomplishment of Boeing Service Bulletin 747-21-2268. Therefore, the FAA finds that it is not necessary to extend the compliance time to allow for accomplishment of Boeing Service Bulletin 747-21-2268. However, as

stated previously, the compliance time for the actions required by this final rule has been extended to 12 months after the effective date of this AD to allow for accomplishment of the required actions during regularly scheduled maintenance visits.

Conclusion

After careful review of the available data, including the comments noted above, the FAA has determined that air safety and the public interest require the adoption of the rule with the changes described previously. The FAA has determined that these changes will neither increase the economic burden on any operator nor increase the scope of the AD.

Cost Impact

There are approximately 351 Model 747-400, -400D, and -400F series airplanes of the affected design in the worldwide fleet. The FAA estimates that 43 airplanes of U.S. registry will be affected by this AD.

For all airplanes, it will take approximately 8 work hours per airplane to accomplish the required modification of the P212 and P213 panels, at an average labor rate of \$60 per work hour. Required parts will cost approximately \$389 per airplane. Based on these figures, the cost impact of this modification required by this AD on U.S. operators is estimated to be \$37,367, or \$869 per airplane.

For certain airplanes, it will take approximately 47 work hours per airplane to accomplish the required modification of the P5, P6, and P7 panels, and the W4701, W4703, and W4908 wire bundles, at an average labor rate of \$60 per work hour. Required parts will cost approximately \$1,529 per airplane. Based on these figures, the cost impact of this modification required by this AD on U.S. operators is estimated to be \$4,349 per airplane.

The cost impact figures discussed above are based on assumptions that no operator has yet accomplished any of the requirements of this AD action, and that no operator would accomplish those actions in the future if this AD were not adopted.

Regulatory Impact

The regulations adopted herein will not have substantial direct effects on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, in accordance with Executive Order 12612, it is determined that this final rule does not have sufficient federalism

implications to warrant the preparation of a Federalism Assessment.

For the reasons discussed above, I certify that this action (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A final evaluation has been prepared for this action and it is contained in the Rules Docket. A copy of it may be obtained from the Rules Docket at the location provided under the caption ADDRESSES.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration amends part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. Section 39.13 is amended by adding the following new airworthiness directive:

99-06-18 Boeing: Amendment 39-11082, Docket 96-NM-171-AD.

Applicability: Model 747-400, -400D, and -400F series airplanes; as identified in Boeing Alert Service Bulletin 747-21A2381, dated June 27, 1996; certificated in any category.

Note 1: This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (c) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

Compliance: Required as indicated, unless accomplished previously.

To prevent loss of control of the cabin pressurization system, which could result in

rapid depressurization of the airplane and consequent deleterious physiological effects on the passengers and crew; and airplane diversions, which represent an increased risk to the airplane, passengers, and crew, accomplish the following:

(a) Within 12 months after the effective date of this AD: Modify the P212 and P213 panels of the cabin pressure control system as specified in paragraph (a)(1) or (a)(2) of this AD, as applicable, in accordance with Boeing Alert Service Bulletin 747-21A2381, dated June 27, 1996.

(1) For Groups 1 through 7 airplanes, as identified in the alert service bulletin: Change the wiring in the P212 and P213 panels; replace the existing two-pole relays with new four-pole relays; and perform a test of both panels.

(2) For Group 8 airplanes, as identified in the alert service bulletin: Change the wiring in the P212 panel; replace the existing two-pole relays with new four-pole relays; replace the existing P213 panel with a new P213 panel; and perform a test of both panels.

(b) For airplanes having line positions 696 through 1021 inclusive: Within 12 months after the effective date of this AD, accomplish paragraphs (b)(1) and (b)(2), as applicable, of this AD: in accordance with Boeing Service Bulletin 747-24-2193, dated January 26, 1995; as revised by Notices of Status Change (NSC) 747-24-2193 NSC 1, dated April 13, 1995, 747-24-2193 NSC 2, dated October 5, 1995, 747-24-2193 NSC 3, dated November 22, 1995, 747-24-2193 NSC 4, dated December 21, 1995, 747-24-2193 NSC 5, dated May 2, 1996, and 747-24-2193 NSC 6, dated March 13, 1997; or Alert Service Bulletin 747-24A2193, Revision 1, dated June 19, 1997.

(1) For all airplanes: Modify the wiring of the P5, P6, and P7 panels; modify the wiring in the W4701 and W4908 wire bundles; and install diodes in the P6 panel.

(2) For Groups 1 and 2 airplanes identified in paragraph I. of the Accomplishment Instructions of the service bulletin or alert service bulletin: Modify the wiring in the W4703 wire bundle.

(c) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, Seattle Aircraft Certification Office (ACO), FAA, Transport Airplane Directorate. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, Seattle ACO.

Note 2: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Seattle ACO.

(d) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

(e) The actions shall be done in accordance with Boeing Alert Service Bulletin 747-21A2381, dated June 27, 1996; and Boeing Service Bulletin 747-24-2193, dated January 26, 1995; as revised by Notices of Status Change (NSC) 747-24-2193 NSC 1, dated

April 13, 1995, 747-24-2193 NSC 2, dated October 5, 1995, 747-24-2193 NSC 3, dated November 22, 1995, 747-24-2193 NSC 4, dated December 21, 1995, 747-24-2193 NSC 5, dated May 2, 1996, and 747-24-2193 NSC 6, dated March 13, 1997; or Boeing Alert Service Bulletin 747-24A2193, Revision 1, dated June 19, 1997. This incorporation by reference was approved by the Director of the Federal Register in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Copies may be obtained from Boeing Commercial Airplane Group, P.O. Box 3707, Seattle, Washington 98124-2207. Copies may be inspected at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

(f) This amendment becomes effective on April 26, 1999.

Issued in Renton, Washington, on March 12, 1999.

Darrell M. Pederson,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 99-6714 Filed 3-19-99; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 71

[Airspace Docket No. 98-ANM-19]

Establishment of Class D Airspace and Modification of Class E Airspace; Bozeman, MT

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: This action establishes Class D surface airspace and modifies Class E surface airspace at Gallatin Field, Bozeman, MT. The Class D surface area is established to accommodate the procedures associated with the operation of a new Airport Traffic Control Tower (ATCT) at the airport. The modification of the Class E surface area amends the effective hours from continuous to part-time, the effective hours coinciding with the hours that the tower is closed. The effect of this action is to clarify when two-way radio communication with the ATCT is required and to provide adequate Class D airspace for procedures when the tower is open.

EFFECTIVE DATE: 0901 UTC, May 20, 1999.

FOR FURTHER INFORMATION CONTACT: Dennis Ripley, ANM-520.6, Federal Aviation Administration, Docket No. 98-ANM-19, 1601 Lind Avenue S.W., Renton, Washington, 98055-4056; telephone number: (425) 227-2527.