

The regulations adopted herein will not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, it is determined that this final rule does not have federalism implications under Executive Order 13132.

The FAA has determined that this regulation is an emergency regulation that must be issued immediately to correct an unsafe condition in aircraft, and that it is not a "significant regulatory action" under Executive Order 12866. It has been determined further that this action involves an emergency regulation under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979). If it is determined that this emergency regulation otherwise would be significant under DOT Regulatory Policies and Procedures, a final regulatory evaluation will be prepared and placed in the Rules Docket. A copy of it, if filed, may be obtained from the Rules Docket at the location provided under the caption **ADDRESSES**.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

Adoption of the Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration amends part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. Section 39.13 is amended by adding a new airworthiness directive to read as follows:

AD 2000-06-05 Eurocopter France:
Amendment 39-11645. Docket No. 2000-SW-06-AD.

Applicability: SA330F, SA330G, SA330J, AS332C, AS332L, AS332L1, and AS332L2 helicopters, certificated in any category.

Note 1: This AD applies to each helicopter identified in the preceding applicability provision, regardless of whether it has been otherwise modified, altered, or repaired in the area subject to the requirements of this AD. For helicopters that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in

accordance with paragraph (b) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

Compliance: Required before further flight after April 30, 2000, unless accomplished previously.

To prevent failure of a tail rotor blade due to a lightning strike and subsequent loss of control of the helicopter, accomplish the following:

(a) Remove from service any tail rotor blade with a following part number (P/N), including all dash numbers for each P/N:

332A-12-0010
332A-12-0020
332A-12-0030
332A-12-0035
332A-12-0045

Replace with an airworthy tail rotor blade with a following P/N:

332A-12-0050-01 or
332A-12-0055-01

Note 2: Eurocopter France Service Bulletins 01.57 for the Models SA330 and 01.00.59 for the Models AS332, both dated November 23, 1999, pertain to the subject of this AD.

(b) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, Regulations Group, Rotorcraft Directorate, FAA. Operators shall submit their requests through an FAA Principal Maintenance Inspector who may concur or comment and then send it to the Manager, Regulations Group.

Note 3: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Regulations Group.

(c) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the helicopter to a location where the requirements of this AD can be accomplished.

(d) This amendment becomes effective on April 10, 2000.

Note 4: The subject of this AD is addressed in Direction Generale De L'Aviation Civile (France) AD's 2000-002-081(A) and 2000-003-075(A), both dated January 12, 2000.

Issued in Fort Worth, Texas, on March 15, 2000.

Eric Bries,

*Acting Manager, Rotorcraft Directorate,
Aircraft Certification Service.*

[FR Doc. 00-7111 Filed 3-23-00; 8:45 am]

BILLING CODE 4910-13-U

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 98-SW-77-AD; Amendment 39-11647; AD 2000-06-07]

RIN 2120-AA64

Airworthiness Directives; Eurocopter Deutschland GMBH Model MBB-BK 117 Helicopters

AGENCY: Federal Aviation Administration, DOT.

ACTION: Final rule.

SUMMARY: This amendment adopts a new airworthiness directive (AD), applicable to Eurocopter Deutschland GMBH (ECD) Model MBB-BK 117 helicopters, that requires changing the retirement life for the tail rotor (output) drive bevel gear (bevel gear). This amendment is prompted by a fatigue analysis of the bevel gear conducted by the manufacturer due to installation of different tail rotor blades. The actions specified by this AD are intended to prevent fatigue failure of the bevel gear, loss of tail rotor drive, and subsequent loss of control of the helicopter.

EFFECTIVE DATE: April 28, 2000.

FOR FURTHER INFORMATION CONTACT: Shep Blackman, Aerospace Engineer, FAA, Rotorcraft Directorate, Rotorcraft Standards Staff, 2601 Meacham Blvd., Fort Worth, Texas 76137, telephone (817) 222-5296, fax (817) 222-5961.

SUPPLEMENTARY INFORMATION: A proposal to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) to include an airworthiness directive (AD) that is applicable to ECD Model MBB-BK 117 helicopters was published in the **Federal Register** on December 10, 1999 (64 FR 69208). That action proposed to require changing the retirement life for the bevel gear.

Interested persons have been afforded an opportunity to participate in the making of this amendment. No comments were received on the proposal or the FAA's determination of the cost to the public. The FAA has determined that air safety and the public interest require the adoption of the rule as proposed except that the part number of the affected bevel gear has been added to the applicability paragraph and the limitations paragraph to more specifically identify the affected part. The FAA has determined that these changes will neither increase the economic burden on any operator nor increase the scope of the AD.

The FAA estimates that 130 helicopters of U.S. registry will be

affected by this AD, that it will take approximately 0.5 work hour per helicopter to change the retirement life in the records, and 36 work hours to replace the bevel gear. Required parts will cost approximately \$14,092 per helicopter. Based on these figures, the total cost impact of the AD on U.S. operators is estimated to be \$2,116,660 to change the retirement life entry and to replace the bevel gear upon reaching 18,500 hours TIS for the entire fleet.

The regulations adopted herein will not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, it is determined that this final rule does not have federalism implications under Executive Order 13132.

For the reasons discussed above, I certify that this action (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A final evaluation has been prepared for this action and it is contained in the Rules Docket. A copy of it may be obtained from the Rules Docket at the FAA, Office of the Regional Counsel, Southwest Region, 2601 Meacham Blvd., Room 663, Fort Worth, Texas.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

Adoption of the Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration amends part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. Section 39.13 is amended by adding a new airworthiness directive to read as follows:

AD 2000-06-07 Eurocopter Deutschland:
Amendment 39-11647. Docket No. 98-SW-77-AD.

Applicability: Model MBB-BK 117 helicopters, serial numbers 7001 through 7250 and 7500 through 7509, with tail rotor (output) drive bevel gear (bevel gear), part number (P/N) 117-12215-01, installed, certificated in any category.

Note 1: This AD applies to each helicopter identified in the preceding applicability provision, regardless of whether it has been otherwise modified, altered, or repaired in the area subject to the requirements of this AD. For helicopters that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (d) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

Compliance: Required as indicated, unless accomplished previously.

To prevent fatigue failure of the bevel gear, loss of tail rotor drive, and subsequent loss of control of the helicopter, accomplish the following:

(a) Within 100 hours time-in-service (TIS):

(1) Record in the accessory replacement record and historical record "Main Transmission" section the retirement life of 18,500 hours TIS for the bevel gear.

(2) Determine the total hours TIS of the bevel gear. If the total hours TIS cannot be determined, use the operating time of the main transmission.

(b) If the bevel gear's total hours TIS is equal to or greater than 18,400 hours TIS, remove the bevel gear within the next 100 hours TIS and replace it with an airworthy bevel gear. If the bevel gear's total hours TIS is less than 18,400 hours TIS, remove the bevel gear on or before 18,500 hours TIS and replace it with an airworthy bevel gear.

(c) This AD revises the helicopter Airworthiness Limitations section of the maintenance manual by establishing a new retirement life for the bevel gear, P/N 117-12215-01, of 18,500 hours TIS.

(d) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, Regulations Group, Rotorcraft Directorate, FAA. Operators shall submit their requests through an FAA Principal Maintenance Inspector, who may concur or comment and then send it to the Manager, Regulations Group.

Note 2: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Regulations Group.

(e) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the helicopter to a location where the requirements of this AD can be accomplished.

(f) This amendment becomes effective on April 28, 2000.

Note 3: The subject of this AD is addressed in Luftfahrt-Bundesamt (Federal Republic of Germany) AD No. 97-350, dated December 18, 1997.

Issued in Fort Worth, Texas, on March 17, 2000.

Eric Bries,

*Acting Manager, Rotorcraft Directorate,
Aircraft Certification Service.*

[FR Doc. 00-7336 Filed 3-23-00; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 71

[Airspace Docket No. 99-ASW-32]

Revision of Class D Airspace; Hobbs, NM

AGENCY: Federal Aviation Administration (FAA), DOT

ACTION: Direct final rule; confirmation of effective date.

SUMMARY: This notice confirms the effective date of a direct final rule which revises Class D airspace at Hobbs, NM.

EFFECTIVE DATE: The direct final rule published at 65 FR 2537 is effective 0901 UTC, April 20, 2000.

FOR FURTHER INFORMATION CONTACT: Donald J. Day, Airspace Branch, Air Traffic Division, Southwest Region, Federal Aviation Administration, Fort Worth, TX 76193-0520, telephone: 817-222-5593.

SUPPLEMENTARY INFORMATION: The FAA published this direct final rule with a request for comments in the **Federal Register** on January 18, 2000, (65 FR 2537). The FAA uses the direct final rulemaking procedure for a noncontroversial rule where the FAA believes that there will be no adverse public comment. This direct final rule advised the public that no adverse comments were anticipated, and that unless a written adverse comment, or a written notice of intent to submit such an adverse comment, were received within the comment period, the regulation would become effective on April 20, 2000. No adverse comments were received, and, thus, this action confirms that this direct final rule will be effective on that date.

Issued in Fort Worth, TX, on March 16, 2000.

JoEllen Casilio,

*Assistant Manager, Air Traffic Division,
Southwest Region.*

[FR Doc. 00-7344 Filed 3-23-00; 8:45 am]

BILLING CODE 4910-13-M