

Issued in Renton, Washington, on May 30, 2001.

**Vi L. Lipski,**

*Manager, Transport Airplane Directorate,  
Aircraft Certification Service.*

[FR Doc. 01-14043 Filed 6-4-01; 8:45 am]

BILLING CODE 4910-13-U

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. 2000-NM-19-AD]

RIN 2120-AA64

#### **Airworthiness Directives; Boeing Model 767 Series Airplanes Powered by Pratt & Whitney Model PW4000 Series Engines**

**AGENCY:** Federal Aviation Administration, DOT.

**ACTION:** Supplemental notice of proposed rulemaking; reopening of comment period.

**SUMMARY:** This document revises an earlier proposed airworthiness directive (AD), applicable to certain Boeing Model 767 series airplanes, that would have required a one-time detailed visual inspection of certain wire bundles located in the aft section of the strut forward fairing panel of both engine struts to detect chafing damage, and repair or replacement of wiring, if necessary. This new action revises the proposed rule by adding replacement of wires repaired by splicing and damaged wires that require splicing, and replacement of the support brackets of the existing wire bundles with new brackets and clamps, which would terminate the existing requirements. The actions specified by this new proposed AD are intended to prevent the potential for dual wire faults from grounded, separated, or shorted wires; which could result in inadvertent takeoff thrust overboost, in-flight loss of thrust, or engine shutdown.

**DATES:** Comments must be received by July 2, 2001.

**ADDRESSES:** Submit comments in triplicate to the Federal Aviation Administration (FAA), Transport Airplane Directorate, ANM-114, Attention: Rules Docket No. 2000-NM-19-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056. Comments may be inspected at this location between 9 a.m. and 3 p.m., Monday through Friday, except Federal holidays. Comments may be submitted via fax to (425) 227-1232. Comments may also be sent via the Internet using

the following address: 9-anm-nprmcment@faa.gov. Comments sent via fax or the Internet must contain "Docket No. 2000-NM-19-AD" in the subject line and need not be submitted in triplicate. Comments sent via the Internet as attached electronic files must be formatted in Microsoft Word 97 for Windows or ASCII text.

The service information referenced in the proposed rule may be obtained from Boeing Commercial Airplane Group, P.O. Box 3707, Seattle, Washington 98124-2207. This information may be examined at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington.

**FOR FURTHER INFORMATION CONTACT:** Dennis Kammers, Aerospace Engineer, Propulsion Branch, ANM-140S, FAA, Seattle Aircraft Certification Office, 1601 Lind Avenue, SW., Renton, Washington 98055-4056; telephone (425) 227-2956; fax (425) 227-1181.

#### **SUPPLEMENTARY INFORMATION:**

##### **Comments Invited**

Interested persons are invited to participate in the making of the proposed rule by submitting such written data, views, or arguments as they may desire. Communications shall identify the Rules Docket number and be submitted in triplicate to the address specified above. All communications received on or before the closing date for comments, specified above, will be considered before taking action on the proposed rule. The proposals contained in this action may be changed in light of the comments received.

Submit comments using the following format:

- Organize comments issue-by-issue. For example, discuss a request to change the compliance time and a request to change the service bulletin reference as two separate issues.
- For each issue, state what specific change to the proposed AD is being requested.
- Include justification (e.g., reasons or data) for each request.

Comments are specifically invited on the overall regulatory, economic, environmental, and energy aspects of the proposed rule. All comments submitted will be available, both before and after the closing date for comments, in the Rules Docket for examination by interested persons. A report summarizing each FAA-public contact concerned with the substance of this proposal will be filed in the Rules Docket.

Commenters wishing the FAA to acknowledge receipt of their comments submitted in response to this action

must submit a self-addressed, stamped postcard on which the following statement is made: "Comments to Docket Number 2000-NM-19-AD." The postcard will be date stamped and returned to the commenter.

#### **Availability of NPRMs**

Any person may obtain a copy of this NPRM by submitting a request to the FAA, Transport Airplane Directorate, ANM-114, Attention: Rules Docket No. 2000-NM-19-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056.

#### **Discussion**

A proposal to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) to add an airworthiness directive (AD), applicable to certain Boeing Model 767 series airplanes, was published as a notice of proposed rulemaking (NPRM) in the **Federal Register** on September 18, 2000 (65 FR 56264). That NPRM would have required a one-time detailed visual inspection of certain wire bundles located in the aft section of the strut forward fairing panel of both engine struts to detect chafing damage, and repair or replacement of wiring, if necessary. That NPRM was prompted by reports indicating several incidents of severe wire chafing of certain wire bundles in both engine struts. That condition, if not corrected, could result in the potential for dual wire faults from grounded, separated, or shorted wires; and consequent inadvertent takeoff thrust overboost, in-flight loss of thrust, or engine shutdown.

#### **Actions Since Issuance of Notice of Proposed Rulemaking (NPRM)**

Since issuance of the NPRM, the FAA has reviewed and approved Boeing Service Bulletin 767-73A0049, Revision 3, dated December 20, 2000, which contained certain changes from Revision 2 of the service bulletin (referenced as the appropriate source of service information for accomplishment of the actions specified in the proposed rule). Revision 3 adds airplanes that have been manufactured since the issuance of the NPRM; updates warranty information; corrects a wire part number, and clarifies repair/splice instructions for fire zone wiring. Revision 3 has been added as a revised source of service information for accomplishment of the specified actions, and the references to Revision 2 have been removed from the supplemental NPRM. Additionally, paragraph (a)(2) of the NPRM has been revised. The reference to the repair of the wires as specified in the wiring practices manual has been removed

from paragraph (a)(2) because Revision 3 corrects the errors contained in Revision 2 describing repair/splice instructions for wires installed in the fire zone. Paragraph (a)(3) has been changed to a new (b)(1), which specifies the replacement of any wires that are damaged and require a splice repair.

The FAA also has reviewed and approved Boeing Service Bulletin 767-73A0049, Revision 4, dated April 5, 2001. Revision 4 is essentially the same as Revision 3 (above), but eliminates one airplane that was inadvertently included in the effectivity section of Revision 3. Revision 4 has been added to the supplemental NPRM as an additional source of service information for accomplishment of the specified actions.

#### Comments

Due consideration has been given to the comments received in response to the NPRM. Certain comments have resulted in changes to the NPRM.

#### Terminating Action

One commenter asks that Boeing Service Bulletin 767-73-0051, dated December 20, 2000, replace Boeing Service Bulletin 767-73A0049, which was referenced as the appropriate source of service information for accomplishment of the actions specified in the NPRM. The commenter states that the new service bulletin would provide final corrective action for the unsafe condition, and would eliminate the need for further rulemaking. Another commenter states that the action specified in the NPRM was interim action and asks that the manufacturer's final action be included in the supplemental NPRM.

The FAA partially concurs with the commenters. Since the issuance of the NPRM, the FAA has reviewed and approved Boeing Service Bulletin 767-73-0051. The service bulletin describes procedures for replacement of the support brackets of the existing wire bundle with a new bridge bracket, support bracket, and wire bundle clamps. Accomplishment of the replacement eliminates the need for the inspection and corrective action required by the NPRM, and as the final action, addresses the unsafe condition. Additionally, the applicability in the NPRM has been changed to the same effectivity listed in the service bulletin, because airplanes having line number 822 and after have been delivered with the new bracket installed. A new paragraph (b) has been added to include the replacement as terminating action, and a spares paragraph has been added to ensure that existing parts are not used

for the replacement. However, the new service bulletin (above) will not replace the service bulletin referenced in the NPRM because the existing actions will continue to be required until accomplishment of the terminating action.

#### Conclusion

Since these changes expand the scope of the originally proposed rule, the FAA has determined that it is necessary to reopen the comment period to provide additional opportunity for public comment.

#### Differences Between Service Bulletin and Proposed Rule

Boeing Service Bulletin 767-73-0049 recommends that damaged wires repaired by splicing, as specified in paragraph (a)(2) of the NPRM, be replaced at the next scheduled strut system maintenance check. This supplemental NPRM would require that any wires repaired by splicing, and any damaged wires that need to be spliced, be replaced concurrent with the incorporation of the terminating action specified in Boeing Service Bulletin 767-73-0051.

Although Boeing Service Bulletin 767-73-0051 recommends doing the replacement at the next convenient opportunity where facilities and manpower are available, the FAA has determined that this compliance time may not ensure that the identified unsafe condition is addressed in a timely manner. In developing an appropriate compliance time for this proposed AD, the FAA considered not only the manufacturer's recommendation, but the degree of urgency associated with addressing the subject unsafe condition, the average utilization of the affected fleet, and the time necessary to perform the proposed AD. In light of all of these factors, the FAA finds a compliance time of within 6,000 flight hours or 18 months after the effective date of this AD, whichever occurs later, to be warranted, in that it represents an appropriate interval of time allowable for affected airplanes to continue to operate without compromising safety.

#### Cost Impact

There are approximately 185 airplanes of the affected design in the worldwide fleet. The FAA estimates that 79 airplanes of U.S. registry would be affected by this proposed AD.

It would take approximately 2 work hours per airplane to accomplish the proposed inspection, at an average labor rate of \$60 per work hour. Based on these figures, the cost impact of the

inspection proposed by this AD on U.S. operators is estimated to be \$9,480, or \$120 per airplane.

It would take approximately 3 work hours per airplane to accomplish the proposed replacement, at an average labor rate of \$60 per work hour. Required parts would cost approximately \$1,570 per airplane. Based on these figures, the cost impact of the replacement proposed by this AD on U.S. operators is estimated to be \$138,250, or \$1,750 per airplane.

The cost impact figures discussed above are based on assumptions that no operator has yet accomplished any of the proposed requirements of this AD action, and that no operator would accomplish those actions in the future if this AD were not adopted. The cost impact figures discussed in AD rulemaking actions represent only the time necessary to perform the specific actions actually required by the AD. These figures typically do not include incidental costs, such as the time required to gain access and close up, planning time, or time necessitated by other administrative actions.

#### Regulatory Impact

The regulations proposed herein would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, it is determined that this proposal would not have federalism implications under Executive Order 13132.

For the reasons discussed above, I certify that this proposed regulation (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) if promulgated, will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A copy of the draft regulatory evaluation prepared for this action is contained in the Rules Docket. A copy of it may be obtained by contacting the Rules Docket at the location provided under the caption **ADDRESSES**.

#### List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

#### The Proposed Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration proposes to amend part

39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

### PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701.

#### § 39.13 [Amended]

2. Section 39.13 is amended by adding the following new airworthiness directive:

**Boeing:** Docket 2000–NM–19–AD.

*Applicability:* Model 767 series airplanes as listed in Boeing Service Bulletin 767–73–0051, dated December 20, 2000, certificated in any category.

**Note 1:** This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance per paragraph (e) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

*Compliance:* Required as indicated, unless accomplished previously.

To prevent the potential for dual wire faults from grounded, separated, or shorted wires; which could result in inadvertent takeoff thrust overboost, in-flight loss of thrust, or engine shutdown, accomplish the following:

#### Detailed Visual Inspection

(a) Prior to the accumulation of 10,000 hours time-in-service or within 180 days after the effective date of this AD, whichever occurs later: Do a one-time detailed visual inspection of the wire bundles located in the aft section of the strut forward fairing panel of both engine struts to detect chafing damage, per Boeing Service Bulletin 767–73A0049, Revision 3, dated December 20, 2000, or Revision 4, dated April 5, 2001.

**Note 2:** For the purposes of this AD, a detailed visual inspection is defined as: “An intensive visual examination of a specific structural area, system, installation, or assembly to detect damage, failure, or irregularity. Available lighting is normally supplemented with a direct source of good lighting at intensity deemed appropriate by the inspector. Inspection aids such as mirror, magnifying lenses, etc., may be used. Surface cleaning and elaborate access procedures may be required.”

#### Corrective Action

(1) If any chafing damage of any wire bundle is detected: Before further flight, repair the wire bundle per the service bulletin, except as provided by paragraph (a)(2) of this AD.

(2) Replace all spliced wires with new wires per the service bulletin, concurrent with accomplishment of the terminating action required by paragraph (b)(2) of this AD.

#### Terminating Action

(b) Within 6,000 flight hours or 18 months after the effective date of this AD, whichever occurs later, do the actions specified in paragraphs (b)(1) and (b)(2) of this AD per the Accomplishment Instructions of Boeing Service Bulletin 767–73–0051, dated December 20, 2000.

(1) Do a detailed visual inspection of the wire bundles to detect chafing damage; if any damaged wires are found, replace the wires that require a splice repair with new wires concurrent with accomplishment of the terminating action specified in paragraph (b)(2) of this AD.

(2) Replace the existing support bracket of the wire bundle with a new bridge bracket, support bracket, and wire bundle clamps. Accomplishment of this replacement terminates the requirements of this AD.

#### Report Inspection Results

(c) Following accomplishment of paragraph (a) or (b) of this AD: Report inspection results, as described in Boeing Service Bulletin 767–73A0049, Revision 3, dated December 20, 2000, or Revision 4, dated April 5, 2001, to Boeing Commercial Airplane Group, P.O. Box 3707, Seattle, Washington 98124–2207.

#### Spares

(d) As of the effective date of this AD, no person shall install on any airplane any bracket identified in the “Existing Part Number” column of Paragraph 2.E. of Boeing Service Bulletin 767–73–0051, dated December 20, 2000.

#### Alternative Methods of Compliance

(e) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, Seattle Aircraft Certification Office (ACO), FAA. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, Seattle ACO.

**Note 3:** Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Seattle ACO.

#### Special Flight Permit

(f) Special flight permits may be issued per §§ 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

Issued in Renton, Washington, on May 30, 2001.

**Vi L. Lipski,**

*Manager, Transport Airplane Directorate, Aircraft Certification Service.*

[FR Doc. 01–14041 Filed 6–4–01; 8:45 am]

**BILLING CODE 4910–13–U**

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. 2000–NM–146–AD]

RIN 2120–AA64

#### Airworthiness Directives; Boeing Model 737 Series Airplanes

**AGENCY:** Federal Aviation Administration, DOT.

**ACTION:** Supplemental notice of proposed rulemaking; reopening of comment period.

**SUMMARY:** This document revises an earlier proposed airworthiness directive (AD), applicable to certain Boeing Model 737–100, –200, –300, –400, and –500 series airplanes, that would have required inspection of wire bundles in two junction boxes in the main wheel well to detect chafing or damage, and follow-on actions. This new action revises the proposed rule by expanding the applicability to include additional airplanes and models, and by adding new inspections for chafing or damage of two additional junction boxes in the main wheel well and follow-on actions for those boxes. This action is necessary to prevent wire damage, which could result in arcing and consequent fire in the main wheel well or passenger cabin, or inability to stop the flow of fuel to an engine or to the auxiliary power unit in the event of a fire. This action is intended to address the identified unsafe condition.

**DATES:** Comments must be received by July 10, 2001.

**ADDRESSES:** Submit comments in triplicate to the Federal Aviation Administration (FAA), Transport Airplane Directorate, ANM–114, Attention: Rules Docket No. 2000–NM–146–AD, 1601 Lind Avenue, SW., Renton, Washington 98055–4056. Comments may be inspected at this location between 9:00 a.m. and 3:00 p.m., Monday through Friday, except Federal holidays. Comments may be submitted via fax to (425) 227–1232. Comments may also be sent via the Internet using the following address: 9-anm-nprmcomment@faa.gov. Comments sent via fax or the Internet must contain “Docket No. 2000–NM–146–AD” in the subject line and need not be submitted in triplicate. Comments sent via the Internet as attached electronic files must be formatted in Microsoft Word 97 for Windows or ASCII text.

The service information referenced in the proposed rule may be obtained from Boeing Commercial Airplane Group,