

placard, in accordance with Boeing Service Bulletin 767-28-0063, dated December 20, 2000; or accomplishment of equivalent actions during production; are approved means of compliance with paragraph (i) of this AD.

#### Terminating Action

(j) Accomplishment of the requirements of paragraph (e) of this AD constitutes terminating action for the requirements of AD 94-11-05, amendment 39-8921 (59 FR 27970, May 31, 1994).

(k) Accomplishment of the requirements of paragraph (i) of this AD constitutes terminating action for the requirements of paragraphs (a), (b), (c), (d), (e), (g), and (h) of this AD, and the requirements of AD 94-11-05, amendment 39-8921.

#### Spares

(l) As of the effective date of this AD, no person shall install on any airplane a fuel pump having part number S343T002-5, -8, -12, or -15, unless that pump has been inspected and corrective actions have been performed in accordance with the requirements of either paragraph (b) or (c), and paragraph (e), of this AD.

(m) As of the effective date of this AD, no person shall install on any airplane a fuel pump having part number S343T002-23, -51, -81, or -121.

#### Alternative Methods of Compliance

(n)(1) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, Seattle ACO. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, Seattle ACO.

(2) Alternative methods of compliance, approved previously in accordance with AD 97-19-15, amendment 39-10136, are approved as alternative methods of compliance when performing the requirements of paragraphs (b) and (c) of this AD.

**Note 5:** Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Seattle ACO.

#### Special Flight Permits

(o) Special flight permits may be issued in accordance with §§ 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

#### Incorporation by Reference

(p) Except as provided by paragraphs (a), (b), (c), (d), (f), (g)(2), (h)(2), and (i) of this AD; the actions shall be done in accordance with Boeing Alert Service Bulletin 767-28A0050, dated December 18, 1997, or Boeing Service Bulletin 767-28A0050, Revision 1, dated December 22, 1999; Boeing Alert Service Bulletin 767-28A0057, dated November 18, 1999; or Boeing Service Bulletin 767-28-0059, dated December 22, 1999; as applicable. This incorporation by

reference was approved by the Director of the Federal Register in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Copies may be obtained from Boeing Commercial Airplane Group, P.O. Box 3707, Seattle, Washington 98124-2207. Copies may be inspected at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

#### Effective Date

(q) This amendment becomes effective on September 4, 2001.

Issued in Renton, Washington, on July 19, 2001.

**Donald L. Riggin,**

*Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.*

[FR Doc. 01-18471 Filed 7-30-01; 8:45 am]

**BILLING CODE 4910-13-U**

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. 2000-NM-421-AD; Amendment 39-12350; AD 2001-15-16]

**RIN 2120-AA64**

#### Airworthiness Directives; Airbus Model A319, A320, and A321 Series Airplanes

**AGENCY:** Federal Aviation Administration, DOT.

**ACTION:** Final rule.

**SUMMARY:** This amendment adopts a new airworthiness directive (AD), applicable to certain Airbus Model A319, A320, and A321 series airplanes, that requires performing a general visual inspection of the outer handle flap mechanisms of the passenger doors for the presence of corrosion inhibitor and for correct operation; cleaning, if necessary; and greasing. The actions specified by this AD are intended to prevent blockage of the outer handle flap in an intermediate pushed-in position, which may prevent a passenger door from opening from the inside of the airplane, thereby delaying an emergency evacuation. This action is intended to address the identified unsafe condition.

**DATES:** Effective September 4, 2001.

The incorporation by reference of certain publications listed in the regulations is approved by the Director of the Federal Register as of September 4, 2001.

**ADDRESSES:** The service information referenced in this AD may be obtained from Airbus Industrie, 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex,

France. This information may be examined at the Federal Aviation Administration (FAA), Transport Airplane Directorate, Rules Docket, 1601 Lind Avenue, SW., Renton, Washington; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

**FOR FURTHER INFORMATION CONTACT:** Dan Rodina, Aerospace Engineer, International Branch, ANM-116, FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington 98055-4056; telephone (425) 227-2125; fax (425) 227-1149.

**SUPPLEMENTARY INFORMATION:** A proposal to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) to include an airworthiness directive (AD) that is applicable to certain Airbus Model A319, A320, and A321 series airplanes was published in the **Federal Register** on April 26, 2001 (66 FR 20952). That action proposed to require performing a general visual inspection of the outer handle flap mechanisms of the passenger doors for the presence of corrosion inhibitor and for correct operation; cleaning, if necessary; and greasing.

#### Comments

Interested persons have been afforded an opportunity to participate in the making of this amendment. Due consideration has been given to the single comment received.

The commenter generally supports the proposed rule, but requests changing an incorrect reference cited in the proposed AD for the All-Operator Telex (AOT). The FAA concurs with this request and has changed paragraph (a) of this AD to cite AOT A320-52A1106, instead of AOT A320-54A1106.

#### Conclusion

After careful review of the available data, including the comment noted above, the FAA has determined that air safety and the public interest require the adoption of the rule with the change described previously. The FAA has determined that this change will neither increase the economic burden on any operator nor increase the scope of the AD.

#### Cost Impact

The FAA estimates that 63 Model A319, A320, and A321 series airplanes of U.S. registry will be affected by this AD, that it will take approximately 1 work hour per airplane to accomplish the required actions, and that the average labor rate is \$60 per work hour. Based on these figures, the cost impact of the AD on U.S. operators is estimated to be \$3,780, or \$60 per airplane.

The cost impact figure discussed above is based on assumptions that no operator has yet accomplished any of the requirements of this AD action, and that no operator would accomplish those actions in the future if this AD were not adopted. The cost impact figures discussed in AD rulemaking actions represent only the time necessary to perform the specific actions actually required by the AD. These figures typically do not include incidental costs, such as the time required to gain access and close up, planning time, or time necessitated by other administrative actions.

### Regulatory Impact

The regulations adopted herein will not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, it is determined that this final rule does not have federalism implications under Executive Order 13132.

For the reasons discussed above, I certify that this action (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A final evaluation has been prepared for this action and it is contained in the Rules Docket. A copy of it may be obtained from the Rules Docket at the location provided under the caption ADDRESSES.

### List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

### Adoption of the Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration amends part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

### PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701.

### § 39.13 [Amended]

2. Section 39.13 is amended by adding the following new airworthiness directive:

**2001-15-16 Airbus Industrie:** Amendment 39-12350. Docket 2000-NM-421-AD.

**Applicability:** Model A319, A320, and A321 series airplanes, up to and including manufacturer's serial number (MSN) 1261, certificated in any category.

**Note 1:** This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (b) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

**Compliance:** Required as indicated, unless accomplished previously.

To prevent blockage of the outer door handle flap in an intermediate pushed-in position, which may prevent a passenger door from opening from the inside of the airplane, thereby delaying an emergency evacuation, accomplish the following:

#### Inspection and Corrective Action

(a) Within 500 flight hours after the effective date of this AD, perform a one-time general visual inspection of the outer handle flap mechanisms of the passenger doors for the presence of corrosion inhibitor and for correct operation; remove any corrosion inhibitor, grease the doors, and check that the flap comes back correctly, flush with the door skin, when the handle is in the closed position; in accordance with Airbus All Operators Telex (AOT) A320-52A1106, dated September 28, 2000.

**Note 2:** For the purposes of this AD, a general visual inspection is defined as: "A visual examination of an interior or exterior area, installation, or assembly to detect obvious damage, failure, or irregularity. This level of inspection is made under normally available lighting conditions such as daylight, hangar lighting, flashlight, or drop-light, and may require removal or opening of access panels or doors. Stands, ladders, or platforms may be required to gain proximity to the area being checked."

#### Alternative Methods of Compliance

(b) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, International Branch, ANM-116.

**Note 3:** Information concerning the existence of other approved alternative

methods of compliance with this AD, if any, may be obtained from the International Branch, ANM-116.

### Special Flight Permits

(c) Special flight permits may be issued in accordance with §§ 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

### Incorporation by Reference

(d) The actions shall be done in accordance with Airbus All Operators Telex A320-52A1106, dated September 28, 2000. This incorporation by reference was approved by the Director of the Federal Register in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Copies may be obtained from Airbus Industrie, 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France. Copies may be inspected at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

**Note 4:** The subject of this AD is addressed in French airworthiness directive 2000-519-158(B), dated December 13, 2000.

### Effective Date

(e) This amendment becomes effective on September 4, 2001.

Issued in Renton, Washington, on July 19, 2001.

**Donald L. Riggan,**

*Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.*

[FR Doc. 01-18470 Filed 7-30-01; 8:45 am]

**BILLING CODE 4910-13-U**

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

### 14 CFR Part 39

[Docket No. 2000-NM-271-AD; Amendment 39-12349; AD 2001-15-15]

**RIN 2120-AA64**

### Airworthiness Directives; Boeing Model 747 Series Airplanes Powered By Pratt & Whitney JT9D-7 Series Engines

**AGENCY:** Federal Aviation Administration, DOT.

**ACTION:** Final rule.

**SUMMARY:** This amendment supersedes an existing airworthiness directive (AD), applicable to certain Boeing Model 747 series airplanes powered by Pratt & Whitney JT9D-7 series engines, that currently requires detailed visual inspections of the lugs on the bulkhead fitting of the rear engine mount, and corrective action, if necessary. The existing AD also specifies optional