

Actions	Compliance	Procedures
(1) Inspect for understrength rivets on the elevator torque tube and rudder hinge.	Within the next 10 hours time-in-service after December 17, 2001 (the effective date of this AD).	For Model SR 20 airplanes, follow the ACCOMPLISHMENT INSTRUCTIONS section in Cirrus Design Service Bulletin SB 20-55-06, issued November 27, 2001. For Model SR 22 airplanes, follow the ACCOMPLISHMENT INSTRUCTIONS section in Cirrus Design Service Bulletin SB 22-55-03, issued November 27, 2001.
(2) If an understrength rivet is found, replace it with a new rivet, part number MS20470AD4, or FAA-approved equivalent part number.	Before further flight after the inspection referenced in paragraph (d)(1) of this AD.	For Model SR 20 airplanes, follow the ACCOMPLISHMENT INSTRUCTIONS section in Cirrus Design Service Bulletin SB 20-55-06, issued November 27, 2001. For Model SR 22 airplanes, follow the ACCOMPLISHMENT INSTRUCTIONS section in Cirrus Design Service Bulletin SB 22-55-03, issued November 27, 2001.
(3) Do not install part number MS20470A4 rivet	As of December 17, 2001 (the effective date of this AD).	Not Applicable.

(e) *Can I comply with this AD in any other way?* You may use an alternative method of compliance or adjust the compliance time if:

(1) Your alternative method of compliance provides an equivalent level of safety; and

(2) The Manager, Chicago ACO, approves your alternative. Submit your request through an FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, Chicago ACO.

Note: This AD applies to each airplane identified in paragraph (a) of this AD, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (e) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if you have not eliminated the unsafe condition, specific actions you propose to address it.

(f) *Where can I get information about any already-approved alternative methods of compliance?* Contact Gregory J. Michalik, Aerospace Engineer, FAA, Chicago Aircraft Certification Office, 2300 E. Devon Avenue, Room 107, Des Plaines, IL 60018 telephone: (847) 294-7135; facsimile: (847) 294-7834.

(g) *What if I need to fly the airplane to another location to comply with this AD?* The FAA can issue a special flight permit under sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate your airplane to a location where you can accomplish the requirements of this AD.

(h) *Are any service bulletins incorporated into this AD by reference?* Actions required by this AD must be done in accordance with Cirrus Design Service Bulletin No. SB 20-55-06, issued November 27, 2001, and Cirrus Design Service Bulletin No. SB 22-55-03, issued November 27, 2001. The Director of the Federal Register approved this incorporation by reference under 5 U.S.C. 552(a) and 1 CFR part 51. You can get copies from Cirrus Design Corporation, 4515 Taylor Circle, Duluth, MN 55811, telephone: (218)

529-7202, facsimile: (218) 727-2148. You may view this information at FAA, Central Region, Office of the Regional Counsel, 901 Locust, Room 506, Kansas City, Missouri, or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

(i) *When does this amendment become effective?* This amendment becomes effective on December 17, 2001.

Issued in Kansas City, Missouri, on December 4, 2001.

Dorenda Baker,

Acting Manager, Small Airplane Directorate, Aircraft Certification Service.

[FR Doc. 01-30423 Filed 12-10-01; 8:45 am]

BILLING CODE 4910-13-U

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 2001-SW-27-AD; Amendment 39-12554; AD 2001-25-02]

RIN 2120-AA64

Airworthiness Directives; Enstrom Helicopter Corporation Model TH-28 and 480 Helicopters

AGENCY: Federal Aviation Administration, DOT.

ACTION: Final rule.

SUMMARY: This amendment adopts a new airworthiness directive (AD) for Enstrom Helicopter Corporation (EHC) Model TH-28 and 480 helicopters. This AD requires establishing a life limit for certain upper and lower main rotor hub plates of 5000 hours time-in-service (TIS), creating a component history card or equivalent record, and replacing each main rotor hub plate (hub plate) having 5000 or more hours TIS with an airworthy hub plate. This AD is prompted by a recent reliability-based

stress analysis that indicates a 5000-hour TIS life limit should be imposed on certain hub plates. The actions specified by this AD are intended to prevent failure of a hub plate, loss of control of the main rotor, and subsequent loss of control of the helicopter.

EFFECTIVE DATE: January 15, 2002.

FOR FURTHER INFORMATION CONTACT:

Joseph McGarvey, Fatigue Specialist, FAA, Chicago Aircraft Certification Office, Airframe and Administrative Branch, 2300 East Devon Ave., Des Plaines, Illinois 60018, telephone (847) 294-7136, fax (847) 294-7834.

SUPPLEMENTARY INFORMATION:

A proposal to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) to include an AD for EHC Model TH-28 and 480 helicopters was published in the **Federal Register** on September 18, 2001 (66 FR 48102). That action proposed establishing a life limit of 5000 hours TIS for both upper and lower hub plates, part number (P/N) 28-14280-1 and 28-14281-1. Also proposed was replacing hub plates, P/N 28-14280-1 and 28-14281-1, having 5000 or more hours TIS with airworthy hub plates.

Interested persons have been afforded an opportunity to participate in the making of this amendment. No comments were received on the proposal or the FAA's determination of the cost to the public. The FAA has determined that air safety and the public interest require the adoption of the rule as proposed.

The FAA estimates that 4 helicopters of U.S. registry will be affected by this AD, that it will take approximately 10 work hours per helicopter to replace the hub plates, and that the average labor rate is \$60 per work hour. Creating a component history or equivalent record

would take approximately 2 hours. Required parts will cost approximately \$5350 to install hub plates, P/N 28-14280-3 and 28-14281-3 and \$5000 to install hub plates, P/N 28-14280-5 and 28-14281-5, per helicopter. Based on these figures, the total cost impact of this AD on U.S. operators is estimated to be \$24,280 maximum, assuming that all hub plates are replaced and that hub plates, P/N 28-14280-3 and 28-14281-3, are installed.

The regulations adopted herein will not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, it is determined that this final rule does not have federalism implications under Executive Order 13132.

For the reasons discussed above, I certify that this action (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A final evaluation has been prepared for this action and it is contained in the Rules Docket. A copy of it may be obtained from the Rules Docket at the FAA, Office of the Regional Counsel, Southwest Region, 2601 Meacham Blvd., Room 663, Fort Worth, Texas.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

Adoption of the Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration amends part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. Section 39.13 is amended by adding a new airworthiness directive to read as follows:

2001-25-02 Enstrom Helicopter Corporation: Amendment 39-12554. Docket No. 2001-SW-27-AD.

Applicability: Model TH-28 and 480 helicopters, with upper hub plate, part number (P/N) 28-14280-1, and lower hub plate, P/N 28-14281-1, installed, certificated in any category.

Note 1: This AD applies to each helicopter identified in the preceding applicability provision, regardless of whether it has been otherwise modified, altered, or repaired in the area subject to the requirements of this AD. For helicopters that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (c) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

Compliance: Required as indicated, unless accomplished previously.

To prevent failure of a hub plate, loss of control of the main rotor, and subsequent loss of control of the helicopter, accomplish the following:

(a) Within 30 days after the effective date of this AD, for upper hub plate, P/N 28-14280-1, and for lower hub plate, P/N 28-14281-1, create a component history card or equivalent record, and determine the total hours time-in-service (TIS). Thereafter, record the hours TIS for each hub plate and replace each hub plate having 5000 or more hours TIS as follows:

(1) Install hub plates, P/N 28-14280-3 and 28-14281-3, on helicopters with main rotor damper, P/N 28-14375-8.

(2) Install hub plates, P/N 28-14280-5 and 28-14281-5, on helicopters with main rotor damper, P/N 28-14375-10.

(b) This AD revises the Limitations section of the applicable maintenance manual by establishing a life limit of 5000 hours TIS for the upper hub plate, P/N 28-14280-1, and for the lower hub plate, P/N 28-14281-1.

(c) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, Chicago Aircraft Certification Office (ACO), FAA. Operators shall submit their requests through an FAA Principal Maintenance Inspector, who may concur or comment and then send it to the Manager, Chicago ACO.

Note 2: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Chicago ACO.

(d) Special flight permits may be issued in accordance with 14 CFR 21.197 and 21.199 to operate the helicopter to a location where the requirements of this AD can be accomplished.

(e) This amendment becomes effective on January 15, 2002.

Issued in Fort Worth, Texas, on November 30, 2001.

David A. Downey,
Manager, Rotorcraft Directorate, Aircraft Certification Service.

[FR Doc. 01-30499 Filed 12-10-01; 8:45 am]

BILLING CODE 4910-13-U

DEPARTMENT OF COMMERCE

Bureau of Economic Analysis

15 CFR Part 801

[Docket No. 010607148-1277-02]

RIN 0691-AA42

International Services Surveys: BE-48, Annual Survey of Reinsurance and Other Insurance Transactions by U.S. Insurance Companies With Foreign Persons

AGENCY: Bureau of Economic Analysis, Commerce.

ACTION: Final rule.

SUMMARY: This final rule revises regulations for the BE-48, Annual Survey of Reinsurance and Other Insurance Transactions by U.S. Insurance Companies with Foreign Persons.

The BE-48 survey is conducted by the Bureau of Economic Analysis (BEA), U.S. Department of Commerce, under the International Investment and Trade in Services Survey Act. The data are needed to support U.S. trade policy initiatives; compile the U.S. international transactions, national income and product, and input-output accounts; assess U.S. competitiveness in international trade in services; and improve the ability of U.S. businesses to identify and evaluate market opportunities.

The revised rule raises the exemption level for the 2001 annual survey to \$2 million in either reinsurance premiums, received or paid; reinsurance losses, paid or recovered; primary insurance premiums received; or primary insurance losses paid, from \$1 million on the previous (2000) survey. Raising the exemption level will reduce respondent burden, particularly for small companies.

EFFECTIVE DATE: This final rule will be effective January 10, 2002.

FOR FURTHER INFORMATION CONTACT: R. David Belli, Chief, International Investment Division (BE-50), Bureau of Economic Analysis, U.S. Department of Commerce, Washington, DC 20230; phone (202) 606-9800.

SUPPLEMENTARY INFORMATION: In the September 5, 2001, **Federal Register**, volume 66, No. 172, 66 FR 46407-46408, BEA published a notice of proposed rulemaking setting forth revised reporting requirements for the BE-48, Annual Survey of Reinsurance and Other Insurance Transactions by U.S. Insurance Companies with Foreign Persons. No comments on the proposed