

**Compliance:** Required as indicated, unless accomplished previously.

To prevent chafing of certain electrical wire bundles located behind the flight engineer's panel, which could result in smoke in the cockpit, and uncommanded discharge of fire extinguishing bottles for the No. 4 engine and consequent reduction of the ability to fight a fire in the No. 4 engine, accomplish the following:

#### One-Time Inspection and Modification

(a) Within 12 months after the effective date of this AD, perform a one-time detailed visual inspection for chafing of wire bundles in the area of the forward upper corner of the P4 flight engineer's panel, outboard of the drip shield. Pay particular attention to wire bundles W528 and W530.

(1) If any chafing is found, before further flight, repair the chafed wire bundles according to Section 20-10-13 of the Boeing Standard Wiring Practices Manual, and do paragraph (a)(2) of this AD.

(2) If no chafing is found, or after chafing has been repaired, before further flight, modify the airplane by rerouting electrical wire bundle W530 to ensure sufficient clearance between that wire bundle and an adjacent flood light support bracket and installing a caterpillar grommet on the flood light supports, according to Boeing Alert Service Bulletin 747-25A2407, Revision 1, dated September 23, 1999.

**Note 2:** For the purposes of this AD, a detailed visual inspection is defined as: "An intensive visual examination of a specific structural area, system, installation, or assembly to detect damage, failure, or irregularity. Available lighting is normally supplemented with a direct source of good lighting at intensity deemed appropriate by the inspector. Inspection aids such as mirror, magnifying lenses, etc., may be used. Surface cleaning and elaborate access procedures may be required."

**Note 3:** Modifications accomplished prior to the effective date of this AD according to Boeing Service Bulletin 747-25-2407, dated November 18, 1977, are considered acceptable for compliance with paragraph (a)(2) of this AD. However, the detailed visual inspection required by paragraph (a) and any applicable corrective actions required by paragraph (a)(1) of this AD must still be accomplished.

#### Operator's Equivalent Procedure

(b) Where Boeing Alert Service Bulletin 747-25A2407, Revision 1, dated September 23, 1999, specifies that installation of a caterpillar grommet may be accomplished per "your equivalent procedure," the procedures must be accomplished per the applicable chapter of the Boeing 747 Overhaul Manual specified in the service bulletin.

#### Alternative Methods of Compliance

(c) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, Seattle Aircraft Certification Office (ACO), FAA. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, Seattle ACO.

**Note 4:** Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Seattle ACO.

#### Special Flight Permits

(d) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

#### Incorporation by Reference

(e) The modification required in paragraph (a)(2) of this AD shall be done in accordance with Boeing Alert Service Bulletin 747-25A2407, Revision 1, dated September 23, 1999. This incorporation by reference was approved by the Director of the Federal Register in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Copies may be obtained from Boeing Commercial Airplane Group, P.O. Box 3707, Seattle, Washington 98124-2207. Copies may be inspected at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

#### Effective Date

(f) This amendment becomes effective on January 16, 2002.

Issued in Renton, Washington, on November 28, 2001.

**Vi L. Lipski,**

*Manager, Transport Airplane Directorate,  
Aircraft Certification Service.*

[FR Doc. 01-30208 Filed 12-11-01; 8:45 am]

**BILLING CODE 4910-13-P**

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. 2001-NM-219-AD; Amendment 39-12548; AD 2001-24-31]

**RIN 2120-AA64**

#### Airworthiness Directives; Boeing Model 747 Series Airplanes

**AGENCY:** Federal Aviation Administration, DOT.

**ACTION:** Final rule.

**SUMMARY:** This amendment adopts a new airworthiness directive (AD), applicable to certain Boeing Model 747

series airplanes, that requires performing a one-time inspection for chafing of certain electrical wire bundles behind the flight engineer's panel in the cockpit; repairing any chafed wire bundles, if necessary; and installing Teflon sleeving over the inspected wire bundles and rerouting them. This action is necessary to prevent burning of electrical wires, which could result in smoke in the cockpit and loss of function of several airplane systems. This action is intended to address the identified unsafe condition.

**DATES:** Effective January 16, 2002.

The incorporation by reference of certain publications listed in the regulations is approved by the Director of the Federal Register as of January 16, 2002.

**ADDRESSES:** The service information referenced in this AD may be obtained from Boeing Commercial Airplane Group, P.O. Box 3707, Seattle, Washington 98124-2207. This information may be examined at the Federal Aviation Administration (FAA), Transport Airplane Directorate, Rules Docket, 1601 Lind Avenue, SW., Renton, Washington; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

**FOR FURTHER INFORMATION CONTACT:** Stephen Oshiro, Aerospace Engineer, Systems and Equipment Branch, ANM-130S, FAA, Seattle Aircraft Certification Office, 1601 Lind Avenue, SW., Renton, Washington 98055-4056; telephone (425) 227-2793; fax (425) 227-1181.

**SUPPLEMENTARY INFORMATION:** A proposal to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) to include an airworthiness directive (AD) that is applicable to certain Boeing Model 747 series airplanes was published in the **Federal Register** on July 23, 2001 (66 FR 38211). That action proposed to require performing a one-time inspection for chafing of certain electrical wire bundles behind the flight engineer's panel in the cockpit; repairing any chafed wire bundles, if necessary; and installing Teflon sleeving over the inspected wire bundles and rerouting them.

#### Comments

Interested persons have been afforded an opportunity to participate in the making of this amendment. Due consideration has been given to the single comment received.

#### Request To Allow Use of Other Service Information

The commenter requests that the FAA revise the proposed AD to specify that

accomplishment of the necessary actions according to Boeing Alert Service Bulletin 747-24A2118, Revision 3, dated June 24, 1999, OR EARLIER REVISIONS, is acceptable for compliance. The commenter states that it has done the actions on its airplanes according to revisions of the service bulletin prior to Revision 3 and believes that this meets the intent of the proposed AD.

The FAA concurs and has added Note 3 to this final rule (and reordered subsequent notes accordingly) to state that inspections and follow-on actions accomplished before the effective date of this AD according to Boeing Service Bulletin 747-24-2118, dated February 9, 1989; Revision 1, dated May 11, 1989; or Revision 2, dated December 21, 1989; are acceptable for compliance with the corresponding actions required by this AD.

### Conclusion

After careful review of the available data, including the comment noted above, the FAA has determined that air safety and the public interest require the adoption of the rule with the changes previously described. The FAA has determined that these changes will neither increase the economic burden on any operator nor increase the scope of the AD.

### Cost Impact

There are approximately 443 Model 747 series airplanes of the affected design in the worldwide fleet. The FAA estimates that 164 airplanes of U.S. registry will be affected by this AD, that it will take approximately 3 work hours per airplane to accomplish the required actions, and that the average labor rate is \$60 per work hour. The cost of required parts per airplane will be negligible. Based on these figures, the cost impact of this AD on U.S. operators is estimated to be \$29,520, or \$180 per airplane.

The cost impact figure discussed above is based on assumptions that no operator has yet accomplished any of the requirements of this AD action, and that no operator would accomplish those actions in the future if this AD were not adopted. The cost impact figures discussed in AD rulemaking actions represent only the time necessary to perform the specific actions actually required by the AD. These figures typically do not include incidental costs, such as the time required to gain access and close up, planning time, or time necessitated by other administrative actions.

### Regulatory Impact

The regulations adopted herein will not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, it is determined that this final rule does not have federalism implications under Executive Order 13132.

For the reasons discussed above, I certify that this action (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A final evaluation has been prepared for this action and it is contained in the Rules Docket. A copy of it may be obtained from the Rules Docket at the location provided under the caption **ADDRESSES**.

### List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

### Adoption of the Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration amends part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

### PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701.

#### **§ 39.13 [Amended]**

2. Section 39.13 is amended by adding the following new airworthiness directive:

**2001-24-31 Boeing:** Amendment 39-12548. Docket 2001-NM-219-AD.

**Applicability:** Model 747 series airplanes, as listed in Boeing Alert Service Bulletin 747-24A2118, Revision 3, dated June 24, 1999; certificated in any category.

**Note 1:** This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in

accordance with paragraph (c) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

**Compliance:** Required as indicated, unless accomplished previously.

To prevent chafing and burning of electrical wires, which could result in smoke in the cockpit and loss of function of several airplane systems, accomplish the following:

### One-Time Inspection and Follow-On Actions

(a) Within 12 months after the effective date of this AD, do a one-time detailed visual inspection for chafing of certain electrical wire bundles behind the P4 flight engineer's panel in the cockpit, according to Boeing Alert Service Bulletin 747-24A2118, Revision 3, dated June 24, 1999. If any chafing is found, before further flight, repair the chafed wire bundles according to the service bulletin. Before further flight following the inspection and repair, as applicable, wrap the electrical wire bundles with Teflon sleeving and reroute them, according to the service bulletin.

**Note 2:** For the purposes of this AD, a detailed visual inspection is defined as: "An intensive visual examination of a specific structural area, system, installation, or assembly to detect damage, failure, or irregularity. Available lighting is normally supplemented with a direct source of good lighting at intensity deemed appropriate by the inspector. Inspection aids such as mirror, magnifying lenses, etc., may be used. Surface cleaning and elaborate access procedures may be required."

**Note 3:** Inspections and follow-on actions accomplished before the effective date of this AD according to Boeing Service Bulletin 747-24-2118, dated February 9, 1989; Revision 1, dated May 11, 1989; or Revision 2, dated December 21, 1989; are acceptable for compliance with the corresponding actions required by this AD.

### Operator's Comparable Procedure

(b) Where Boeing Alert Service Bulletin 747-24A2118, Revision 3, dated June 24, 1999, specifies that certain procedures may be accomplished per an "operator's comparable procedure," the procedures must be accomplished per the applicable chapter of the Boeing 747 Airplane Maintenance Manual (AMM) specified in the service bulletin.

### Alternative Methods of Compliance

(c) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, Seattle Aircraft Certification Office (ACO), FAA. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, Seattle ACO.

**Note 4:** Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Seattle ACO.

**Special Flight Permits**

(d) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

**Incorporation by Reference**

(e) Except as required by paragraph (b) of this AD, the actions shall be done in accordance with Boeing Alert Service Bulletin 747-24A2118, Revision 3, dated June 24, 1999. This incorporation by reference was approved by the Director of the Federal Register in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Copies may be obtained from Boeing Commercial Airplane Group, P.O. Box 3707, Seattle, Washington 98124-2207. Copies may be inspected at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

**Effective Date**

(f) This amendment becomes effective on January 16, 2002.

Issued in Renton, Washington, on November 28, 2001.

**Vi L. Lipski,**

*Manager, Transport Airplane Directorate,  
Aircraft Certification Service.*

[FR Doc. 01-30207 Filed 12-11-01; 8:45 am]

**BILLING CODE 4910-13-P**

**DEPARTMENT OF TRANSPORTATION****Federal Aviation Administration****14 CFR Part 39**

[Docket No. 2001-NM-218-AD; Amendment 39-12547; AD 2001-24-30]

**RIN 2120-AA64**

**Airworthiness Directives; Boeing  
Model 747-200C and -200F Series  
Airplanes**

**AGENCY:** Federal Aviation  
Administration, DOT.

**ACTION:** Final rule.

**SUMMARY:** This amendment adopts a new airworthiness directive (AD), applicable to certain Boeing Model 747-200C and -200F series airplanes, that requires installation of drip shields over certain shelves in the main equipment bay. This action is necessary to prevent water from dripping through floor panels of the main deck cargo bay onto wire bundles and electronic components, which could lead to the loss of function of multiple electronic components and, consequently, could reduce the flight crew's ability to operate in adverse conditions. This

action is intended to address the identified unsafe condition.

**DATES:** Effective January 16, 2002.

The incorporation by reference of certain publications listed in the regulations is approved by the Director of the Federal Register as of January 16, 2002.

**ADDRESSES:** The service information referenced in this AD may be obtained from Boeing Commercial Airplane Group, P.O. Box 3707, Seattle, Washington 98124-2207. This information may be examined at the Federal Aviation Administration (FAA), Transport Airplane Directorate, Rules Docket, 1601 Lind Avenue, SW., Renton, Washington; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

**FOR FURTHER INFORMATION CONTACT:**

Stephen Oshiro, Aerospace Engineer, Systems and Equipment Branch, ANM-130S, FAA, Seattle Aircraft Certification Office, 1601 Lind Avenue, SW., Renton, Washington 98055-4056; telephone (425) 227-2793; fax (425) 227-1181.

**SUPPLEMENTARY INFORMATION:**

A proposal to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) to include an airworthiness directive (AD) that is applicable to certain Boeing Model 747-200C and -200F series airplanes was published in the **Federal Register** on July 23, 2001 (66 FR 38209). That action proposed to require installation of drip shields over certain shelves in the main equipment bay.

**Comments**

Interested persons have been afforded an opportunity to participate in the making of this amendment. Due consideration has been given to the single comment received.

The commenter supports the proposed rule, including the proposed 18-month compliance time. The commenter states that this is the minimum compliance time that will allow sufficient time for the proposed installation to be accomplished on affected airplanes.

**Explanation of Changes to Proposed Rule**

Note 2 of this final rule has been revised to correct an error in the reference to Boeing Service Bulletin 747-38-2073.

Also, the statement of unsafe condition in the "Summary" section and preceding the requirements of this AD have been revised to clarify that this AD concerns floor panels of the main deck cargo bay.

**Conclusion**

After careful review of the available data, including the comment noted above, the FAA has determined that air safety and the public interest require the adoption of the rule with the changes described previously. The FAA has determined that these changes will neither increase the economic burden on any operator nor increase the scope of the AD.

**Cost Impact**

There are approximately 59 Model 747-200C and -200F series airplanes of the affected design in the worldwide fleet. The FAA estimates that 21 airplanes of U.S. registry will be affected by this AD, that it will take approximately 32 work hours per airplane to accomplish the required actions, and that the average labor rate is \$60 per work hour. Required parts will cost approximately \$4,497 per airplane. Based on these figures, the cost impact of this AD on U.S. operators is estimated to be \$134,757, or \$6,417 per airplane.

The cost impact figure discussed above is based on assumptions that no operator has yet accomplished any of the requirements of this AD action, and that no operator would accomplish those actions in the future if this AD were not adopted. The cost impact figures discussed in AD rulemaking actions represent only the time necessary to perform the specific actions actually required by the AD. These figures typically do not include incidental costs, such as the time required to gain access and close up, planning time, or time necessitated by other administrative actions.

**Regulatory Impact**

The regulations adopted herein will not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, it is determined that this final rule does not have federalism implications under Executive Order 13132.

For the reasons discussed above, I certify that this action (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A final evaluation has