

SMALL BUSINESS ADMINISTRATION**13 CFR Part 120**

RIN 3245-AE68

Business Loans and Development Company Loans

AGENCY: Small Business Administration (SBA).

ACTION: Withdrawal of direct final rule.

SUMMARY: The SBA is withdrawing the direct final rule published on November 14, 2001 (66 FR 56985) implementing various changes in the Business Loan Program enacted by the Small Business Reauthorization Act of 2000. Pending further evaluation SBA will publish a new rule.

DATES: The direct final rule published at 66 FR 56985, November 14, 2001 is withdrawn, as of December 14, 2001.

FOR FURTHER INFORMATION CONTACT: James W. Hammersley, Director, Office of Loan Programs, Office of Financial Assistance, (202) 205-6490.

SUPPLEMENTARY INFORMATION: The SBA published a direct final rule on November 14, 2001, (66 FR 56985), which incorporated changes to SBA rules concerning loan guaranty and loan amounts, minimum guaranteed dollar amount of 7(a) loans, percentages of financing which can be guaranteed by SBA, guarantee fees paid by lenders, real estate occupancy rules, and borrower prepayment penalties. Subsequent to the publication of the direct final rule, SBA has decided to withdraw it and reconsider portions of the rule. After such reconsideration, SBA will publish a new rule at an early date.

List of Subjects in 13 CFR Part 120

Loan program—business, Small businesses.

Authority: 15 U.S.C. 634(b)(6), 636(a) and (h), 696(3), and 697(a)(2).

Hector V. Barreto,
Administrator.

[FR Doc. 01-30842 Filed 12-13-01; 8:45 am]

BILLING CODE 8025-01-P

DEPARTMENT OF TRANSPORTATION**Federal Aviation Administration****14 CFR Part 39**

[Docket No. 2000-NM-68-AD; Amendment 39-12488; AD 2001-22-09]

RIN 2120-AA64

Airworthiness Directives; Bombardier Model CL-600-2B19 Series Airplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Final rule; correction.

SUMMARY: This document corrects information in an existing airworthiness directive (AD) that applies to certain Bombardier Model CL-600-2B19 series airplanes. That AD currently requires repetitive eddy current inspections for cracking of the main landing gear (MLG) main fittings, and replacement with a new or serviceable MLG, if necessary. That AD also requires servicing the MLG shock struts; inspecting the MLG shock struts for nitrogen pressure, visible chrome dimension, and oil leakage; and performing corrective actions, if necessary. This document corrects an error that resulted in the omission of the AD and amendment numbers in the "Product Identification" section of the AD. This correction is necessary to ensure that the correct AD and amendment numbers are specified.

DATES: Effective December 4, 2001.

The incorporation by reference of certain publications listed in the regulations was approved previously by the Director of the Federal Register as of December 4, 2001, (66 FR 54658, October 30, 2001).

FOR FURTHER INFORMATION CONTACT: Serge Napoleon, Aerospace Engineer, ANE-171, FAA, New York Aircraft Certification Office, 10 Fifth Street, Third Floor, Valley Stream, New York 11581; telephone (516) 256-7512; fax (516) 568-2716.

SUPPLEMENTARY INFORMATION: On October 22, 2001, the Federal Aviation Administration (FAA) issued airworthiness directive (AD) 2001-22-09, amendment 39-12488 (66 FR 54658, October 30, 2001), which applies to certain Bombardier Model CL-600-2B19 series airplanes. A correction of the rule was published in the **Federal Register** on November 26, 2001 (66 FR 58931). That AD requires repetitive eddy current inspections for cracking of the main landing gear (MLG) main fittings, and replacement with a new or serviceable MLG, if necessary. That AD also requires servicing the MLG shock struts; inspecting the MLG shock struts

for nitrogen pressure, visible chrome dimension, and oil leakage; and performing corrective actions, if necessary. The actions specified by that AD are intended to prevent failure of the MLG main fitting, which could result in collapse of the MLG upon landing. The actions are intended to address the identified unsafe condition.

Need for the Correction

The FAA inadvertently omitted the AD and amendment numbers from the "Product Identification" section of the AD. As a result, we have determined that a correction to AD 2001-22-09 is necessary. The correction will correctly add the AD and amendment numbers in the "Product Identification" section of the AD.

Correction of Publication

This document corrects the error and correctly adds the AD as an amendment to section 39.13 of the Federal Aviation Regulations (14 CFR 39.13).

The AD is reprinted in its entirety for the convenience of affected operators. The effective date of the AD remains December 4, 2001.

Since this action only adds the omitted AD and amendment numbers, it has no adverse economic impact and imposes no additional burden on any person. Therefore, the FAA has determined that notice and public procedures are unnecessary.

List of Subject in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Correction

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration amends part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Corrected]

2. Section 39.13 is amended by correctly adding the following airworthiness directive (AD):

2001-22-09 Bombardier: Amendment 39-12488. Docket 2000-NM-68-AD.

Applicability: Model CL-600-2B19 series airplanes, certificated in any category, having serial numbers 7003 and subsequent, and equipped with a main landing gear (MLG) main fitting having part number (P/N)

17064–101, 17064–102, 17064–103, or 17064–104.

Note 1: This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (g) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

Compliance: Required as indicated, unless accomplished previously.

To prevent failure of MLG main fitting, which could result in collapse of the MLG upon landing, accomplish the following:

Inspection and Replacement

(a) Prior to the accumulation of 1,500 total flight cycles, or within 150 flight cycles after December 4, 2001, the effective date of this AD, whichever occurs later: Perform an eddy current inspection to detect cracking of the MLG main fittings, in accordance with Part B of the Accomplishment Instructions of Bombardier Alert Service Bulletin A601R–32–079, Revision D, dated December 1, 2000. If any cracking is found, prior to further flight, replace the cracked fitting with a new or serviceable fitting in accordance with the alert service bulletin. Repeat the inspection thereafter at intervals not to exceed 500 flight cycles.

Servicing the Shock Struts

(b) Prior to the accumulation of 1,500 total flight cycles since the date of manufacture, or within 500 flight cycles after the effective date of this AD, whichever occurs later: Perform a servicing (Oil and Nitrogen) of the MLG shock struts (left and right main landing shock struts), in accordance with Part C (for airplanes on the ground) or Part D (for airplanes on jacks) of the Accomplishment Instructions of Bombardier Alert Service Bulletin A601R–32–079, Revision D, dated December 1, 2000.

Other Inspections

(c) Within 500 flight cycles after completing the actions required by paragraph (b) of this AD: Perform an inspection of the MLG left and right shock struts for nitrogen pressure, visible chrome dimension, and oil leakage, in accordance with Part E of the Accomplishment Instructions of Bombardier Alert Service Bulletin A601R–32–079, Revision D, dated December 1, 2000. Thereafter, repeat the inspection at intervals not to exceed 500 flight cycles.

Corrective Actions for Certain Inspections

(d) If the chrome extension dimension of the shock strut pressure reading is outside the limits specified in the Airplane Maintenance Manual, Task 32–11–05–220–801, or any oil leakage is found: Prior to further flight, service the MLG shock strut in

accordance with Part C (for airplanes on the ground) or Part D (for airplanes on jacks) of the Accomplishment Instructions of Bombardier Alert Service Bulletin A601R–32–079, Revision D, dated December 1, 2000.

Extension of the Repetitive Interval

(e) After the effective date of this AD: After a total of five consecutive inspections of the MLG shock struts that verify that the shock struts are serviced properly, and a total of five consecutive eddy current inspections of the MLG main fitting has been accomplished that verify there is no cracking of the main fitting, in accordance with Bombardier Alert Service Bulletin A601R–32–079, Revision D, dated December 1, 2000, the repetitive interval for the eddy current inspections required by paragraph (a) of this AD may be extended from every 500 flight cycles to every 1,000 flight cycles.

Reporting Requirement

(f) Within 30 days after each inspection and servicing required by paragraphs (a), (b), and (c) of this AD, report all findings, positive or negative, to: Bombardier Aerospace, Regional Aircraft, CRJ Action Desk, fax number 514–855–8501. Information collection requirements contained in this AD have been approved by the Office of Management and Budget (OMB) under the provisions of the Paperwork Reduction Act of 1980 (44 U.S.C. 3501 *et seq.*) and have been assigned OMB Control Number 2120–0056.

Alternative Methods of Compliance

(g) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, New York Aircraft Certification Office (ACO), FAA. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, New York ACO.

Note 2: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the New York ACO.

Special Flight Permits

(h) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

Incorporation by Reference

(i) The actions shall be done in accordance with Bombardier Alert Service Bulletin A601R–32–079, Revision D, dated December 1, 2000. This incorporation by reference was approved previously by the Director of the Federal Register as of December 4, 2001 (66 FR 54658, October 30, 2001). Copies may be obtained from Bombardier, Inc., Canadair, Aerospace Group, P.O. Box 6087, Station Centre-ville, Montreal, Quebec H3C 3G9, Canada. Copies may be inspected at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the FAA, New York Aircraft Certification Office, 10 Fifth Street, Third Floor, Valley Stream, New York; or at the Office of the Federal

Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

Note 3: The subject of this AD is addressed in Canadian airworthiness directive CF–1999–32R1, dated January 22, 2001.

Effective Date

(j) The effective date of this amendment remains December 4, 2001.

Issued in Renton, Washington, on December 7, 2001.

Kalene C. Yanamura,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 01–30863 Filed 12–13–01; 8:45 am]

BILLING CODE 4910–13–U

DEPARTMENT OF THE TREASURY

Internal Revenue Service

26 CFR Part 301

[TD 8969]

RIN 1545–AW37

Payment by Credit Card and Debit Card

AGENCY: Internal Revenue Service (IRS), Treasury.

ACTION: Final regulations and removal of temporary regulations.

SUMMARY: This document contains final regulations authorizing the Commissioner to accept payment of internal revenue taxes by credit card or debit card and limit the use and disclosure of information relating to payment of taxes by credit card and debit card. Additionally, the final regulations provide that payments of tax by check or money order should be made payable to the United States Treasury. The final regulations reflect changes to the law made by the Taxpayer Relief Act of 1997 and affect persons who pay their tax liabilities by credit card, debit card, check, or money order.

DATES: *Effective Date:* These final regulations are effective December 14, 2001.

Applicability Date: For dates of applicability, see § 301.6311–2(h).

FOR FURTHER INFORMATION CONTACT: Brinton Warren, (202) 622–4940 (not a toll-free number).

SUPPLEMENTARY INFORMATION:

Background

This document contains final regulations amending the Procedure and Administration Regulations (26 CFR part 301) under sections 6103 and 6311 of the Internal Revenue Code (Code). The final regulations reflect the