establishment during a period when the establishment is not operating or is not engaged in producing products for exportation to the United States;

Done in Washington, DC, on August 12, 2004.

#### Barbara J. Masters,

Acting Administrator.

[FR Doc. 04-18889 Filed 8-17-04; 8:45 am]

#### BILLING CODE 3410-DM-P

# **DEPARTMENT OF TRANSPORTATION**

#### **Federal Aviation Administration**

#### 14 CFR Part 39

[Docket No. 98-ANE-43-AD]

#### RIN 2120-AA64

Airworthiness Directives; Pratt & Whitney JT8D-209, -217, -217A, -217C, and -219 Turbofan Engines

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Notice of proposed rulemaking

(NPRM).

**SUMMARY:** The FAA proposes to supersede an existing airworthiness directive (AD) for Pratt & Whitney (PW) JT8D-209, -217, -217A, -217C, and –219 turbofan engines. That AD currently requires revisions to the engine manufacturer's time limits section (TLS) to include enhanced inspection of selected critical lifelimited parts at each piece-part opportunity. This proposed AD would modify the airworthiness limitations section of the manufacturer's manual and an air carrier's approved continuous airworthiness maintenance program to incorporate additional inspection requirements. An FAA study of inservice events involving uncontained failures of critical rotating engine parts has indicated the need for mandatory inspections. The mandatory inspections are needed to identify those critical rotating parts with conditions, which if allowed to continue in service, could result in uncontained failures. We are proposing this AD to prevent critical life-limited rotating engine part failure, which could result in an uncontained engine failure and damage to the airplane.

DATES: We must receive any comments on this proposed AD by October 18, 2004.

**ADDRESSES:** Use one of the following addresses to submit comments on this proposed AD:

• By mail: Federal Aviation Administration (FAA), New England Region, Office of the Regional Counsel, Attention: Rules Docket No. 98-ANE-43-AD, 12 New England Executive Park, Burlington, MA 01803-5299.

By fax: (781) 238-7055.

By e-mail: 9-ane-

adcomment@faa.gov.

You may examine the AD docket at the FAA, New England Region, Office of the Regional Counsel, 12 New England Executive Park, Burlington, MA.

# FOR FURTHER INFORMATION CONTACT: Keith Lardie, Aerospace Engineer, Engine Certification Office, FAA, Engine and Propeller Directorate, 12 New

England Executive Park, Burlington, MA 01803-5299; telephone (781) 238-7189, fax (781) 238-7199.

# SUPPLEMENTARY INFORMATION:

#### Comments Invited

We invite you to submit any written relevant data, views, or arguments regarding this proposal. Send your comments to an address listed under ADDRESSES. Include "AD Docket No. 98-ANE-43-AD" in the subject line of your comments. If you want us to acknowledge receipt of your mailed comments, send us a self-addressed, stamped postcard with the docket number written on it; we will datestamp your postcard and mail it back to you. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of the proposed AD. If a person contacts us verbally, and that contact relates to a substantive part of this proposed AD, we will summarize the contact and place the summary in the docket. We will consider all comments received by the closing date and may amend the proposed AD in light of those comments.

We are reviewing the writing style we currently use in regulatory documents. We are interested in your comments on whether the style of this document is clear, and your suggestions to improve the clarity of our communications that affect you. You may get more information about plain language at http://www.faa.gov/language and http:// www.plainlanguage.gov.

#### **Examining the AD Docket**

You may examine the AD Docket (including any comments and service information), by appointment, between 8 a.m. and 4:30 p.m., Monday through Friday, except Federal holidays. See ADDRESSES for the location.

#### Discussion

On June 18, 2002, the FAA issued airworthiness directive (AD) 2002-13-

09, Amendment 39-12797 (67 FR 44527, July 3, 2002), to require revisions to the TLS of the manufacturer's Engine Manuals (EMs) for these engines to include required enhanced inspection of selected critical life-limited parts at each piece-part opportunity.

## **New Inspection Procedures**

Since the issuance of that AD, an FAA study of in-service events involving uncontained failures of critical rotating engine parts has indicated the need for additional mandatory inspections. The mandatory inspections are needed to identify those critical rotating parts with conditions, which if allowed to continue in service, could result in uncontained failures. This proposal would modify the time limitations section of the manufacturer's manual and an air carrier's approved continuous airworthiness maintenance program to incorporate the additional inspection requirements.

# FAA's Determination of an Unsafe **Condition and Proposed Actions**

Since an unsafe condition has been identified that is likely to exist or develop on other PW JT8D-209, -217, –217A, –217C, and –219 turbofan engines of the same type design, the proposed AD would supersede AD 2002-13-09 to add additional critical life-limited parts for enhanced inspection at each piece-part opportunity.

# **Costs of Compliance**

There are about 2,345 Pratt & Whitney JT8D-209, -217, -217A, -217C, and -219 turbofan engines of the affected design in the worldwide fleet. We estimate that 1,143 engines installed on airplanes of U.S. registry would be affected by this proposed AD. We also estimate that it would take about 8 work hours per engine to perform the proposed inspections, and that the average labor rate is \$65 per work hour. Since this is an added inspection requirement, included as part of the normal maintenance cycle, no additional part costs are involved. Based on these figures, the total cost of the proposed AD on U.S. operators is estimated to be \$594,360.

#### **Regulatory Findings**

We have determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and

responsibilities among the various levels of government.

For the reasons discussed above, I certify that this proposed regulation:

- 1. Is not a "significant regulatory action" under Executive Order 12866; 2. Is not a "significant rule" under the
- 2. Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and
- 3. Would not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared a summary of the costs to comply with this proposal and placed it in the AD Docket. You may get a copy of this summary by sending a request to us at the address listed under ADDRESSES. Include "AD Docket No. 98—

## List of Subjects in 14 CFR Part 39

ANE-43-AD" in your request.

Air transportation, Aircraft, Aviation safety, Safety.

#### The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the Federal Aviation Administration proposes to amend 14 CFR part 39 as follows:

# PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

#### § 39.13 [Amended]

2. The FAA amends § 39.13 by removing Amendment 39–12797 (67 FR 44527 July 3, 2002), and by adding a new airworthiness directive to read as follows:

Pratt & Whitney: Docket No. 98–ANE–43– AD. Supersedes AD 2002–13–09, Amendment 39–12797.

#### **Comments Due Date**

(a) The Federal Aviation Administration (FAA) must receive comments on this airworthiness directive (AD) action by October 18, 2004.

#### Affected ADs

(b) This AD supersedes AD 2002-13-09.

#### Applicability

(c) This AD applies to Pratt & Whitney (PW) JT8D–209, –217, –217A, –217C, and –219 turbofan engines. These engines are installed on, but not limited to Boeing 727 and McDonnell Douglas MD–80 series airplanes.

#### **Unsafe Condition**

(d) This AD results from the need to require enhanced inspection of selected critical life-limited parts of JT8D–209, –217, –217A, –217C, and –219 turbofan engines. We are issuing this AD to prevent critical life-limited rotating engine part failure, which could result in an uncontained engine failure and damage to the airplane.

#### Compliance

(e) You are responsible for having the actions required by this AD performed within

the compliance times specified unless the actions have already been done.

(f) Within the next 30 days after the effective date of this AD, (1) revise the Time Limits section (TLS) of the manufacturer's Engine Manual, Part Number 773128, as appropriate for PW JT8D–209, –217, –217A, –217C, and –219 turbofan engines, and (2) for air carriers, revise the approved mandatory inspections section of the continuous airworthiness maintenance program, by adding the following:

#### "Critical Life Limited Part Inspection

#### A. Inspection Requirements

- (1) This section contains the definitions for individual engine piece-parts and the inspection procedures, which are necessary, when these parts are removed from the engine.
- (2) It is necessary to do the inspection procedures of the piece-parts in Paragraph B when:
- (a) The part is removed from the engine and disassembled to the level specified in paragraph B and
- (b) The part has accumulated more than 100 cycles since the last piece part inspection, provided that the part is not damaged or related to the cause of its removal from the engine.
- (3) The inspections specified in this section do not replace or make unnecessary other recommended inspections for these parts or other parts.

#### B. Parts Requiring Inspection

**Note:** Piece part is defined as any of the listed parts with all the blades removed.

Description	Section	Inspection No.
Hub (Disk), 1st Stage Compressor:		
Hub Detail—All P/Ns	72-33-31	-02, -03, -04.
Hub Assembly—All P/Ns	72-33-31	-02, -03, -04.
Disk, 13th Stage Compressor—All P/Ns	72-36-47	-02.
HP Turbine, First Stage:		
Rotor Assembly—All P/Ns	72-52-02	-04.
Disk—All P/Ns	72-52-02	-03.
Disk, 2nd Stage Turbine—All P/Ns	72-53-16	-02.
Disk, 3rd Stage Turbine—All P/Ns	72-53-17	-02.
Disk, 4th Stage Turbine—All P/Ns	72–53–18	-02."

# **Alternative Methods of Compliance**

- (g) You must perform these mandatory inspections using the TLS and the applicable Engine Manual unless you receive approval to use an alternative method of compliance under paragraph (h) of this AD. Section 43.16 of the Federal Aviation Regulations (14 CFR 43.16) may not be used to approve alternative methods of compliance or adjustments to the times in which these inspections must be performed.
- (h) The Manager, Engine Certification Office, has the authority to approve alternative methods of compliance for this AD if requested using the procedures found in 14 CFR 39.19.

# **Maintaining Records of the Mandatory Inspections**

(i) You have met the requirements of this AD by using a TLS of the manufacturer's engine manual changed as specified in paragraph (f) of this AD, and, for air carriers operating under part 121 of the Federal Aviation Regulations (14 CFR part 121), by modifying your continuous airworthiness maintenance plan to reflect those changes. You must maintain records of the mandatory inspections that result from those changes to the TLS according to the regulations governing your operation. You do not need to record each piece-part inspection as compliance to this AD. For air carriers operating under part 121, you may use either the system established to comply with

- section 121.369 or use an alternative system that your principal maintenance inspector has accepted if that alternative system:
- (1) Includes a method for preserving and retrieving the records of the inspections resulting from this AD; and
- (2) Meets the requirements of section 121.369(c); and
- (3) Maintains the records either indefinitely or until the work is repeated.
- (j) These recordkeeping requirements apply only to the records used to document the mandatory inspections required as a result of revising the TLS as specified in paragraph (f) of this AD, and do not alter or amend the recordkeeping requirements for any other AD or regulatory requirement.

#### **Related Information**

(k) None.

Issued in Burlington, Massachusetts, on August 12, 2004.

#### Ann Mollica,

Acting Manager, Engine and Propeller Directorate, Aircraft Certification Service. [FR Doc. 04–18921 Filed 8–17–04; 8:45 am] BILLING CODE 4910–13–P

#### **DEPARTMENT OF TRANSPORTATION**

#### **Federal Aviation Administration**

14 CFR Part 39

[Docket No. 98-ANE-61-AD]

RIN 2120-AA64

# Airworthiness Directives; Pratt & Whitney PW2000 Series Turbofan Engines

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Notice of proposed rulemaking

(NPRM).

**SUMMARY:** The FAA proposes to supersede an existing airworthiness directive (AD) for Pratt & Whitney (PW) PW2000 series turbofan engines. That AD currently requires revisions to the engine manufacturer's time limits section (TLS) to include enhanced inspection of selected critical lifelimited parts at each piece-part opportunity. This proposed AD would modify the airworthiness limitations section of the manufacturer's manual and an air carrier's approved continuous airworthiness maintenance program to incorporate additional inspection requirements. An FAA study of inservice events involving uncontained failures of critical rotating engine parts has indicated the need for mandatory inspections. The mandatory inspections are needed to identify those critical rotating parts with conditions, which if allowed to continue in service, could result in uncontained failures. We are proposing this AD to prevent critical life-limited rotating engine part failure, which could result in an uncontained engine failure and damage to the airplane.

**DATES:** We must receive any comments on this proposed AD by October 18, 2004.

**ADDRESSES:** Use one of the following addresses to submit comments on this proposed AD:

• By mail: Federal Aviation Administration (FAA), New England Region, Office of the Regional Counsel, Attention: Rules Docket No. 98–ANE– 61–AD, 12 New England Executive Park, Burlington, MA 01803–5299.

• By fax: (781) 238–7055.

• By e-mail: 9-ane-adcomment@faa.gov.

You may examine the AD docket at the FAA, New England Region, Office of the Regional Counsel, 12 New England Executive Park, Burlington, MA.

#### FOR FURTHER INFORMATION CONTACT:

Mark Riley, Aerospace Engineer, Engine Certification Office, FAA, Engine and Propeller Directorate, 12 New England Executive Park, Burlington, MA 01803–5299; telephone (781) 238–7758, fax (781) 238–7199.

#### SUPPLEMENTARY INFORMATION:

#### **Comments Invited**

We invite you to submit any written relevant data, views, or arguments regarding this proposal. Send your comments to an address listed under ADDRESSES. Include "AD Docket No. 98-ANE-61-AD" in the subject line of your comments. If you want us to acknowledge receipt of your mailed comments, send us a self-addressed, stamped postcard with the docket number written on it; we will datestamp your postcard and mail it back to you. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of the proposed AD. If a person contacts us verbally, and that contact relates to a substantive part of this proposed AD, we will summarize the contact and place the summary in the docket. We will consider all comments received by the closing date and may amend the proposed AD in light of those comments.

We are reviewing the writing style we currently use in regulatory documents. We are interested in your comments on whether the style of this document is clear, and your suggestions to improve the clarity of our communications that affect you. You may get more information about plain language at <a href="http://www.faa.gov/language">http://www.faa.gov/language</a> and <a href="http://www.plainlanguage.gov">http://www.plainlanguage.gov</a>.

# **Examining the AD Docket**

You may examine the AD Docket (including any comments and service information), by appointment, between 8 a.m. and 4:30 p.m., Monday through Friday, except Federal holidays. See ADDRESSES for the location.

#### Discussion

On June 4, 2002, the FAA issued airworthiness directive (AD) 2002–12–06, Amendment 39–12778 (67 FR 40143, June 12, 2002), to require revisions to the Time Limits Section (TLS) of the PW2000 Turbofan Engine

Manual to include required enhanced inspection of selected critical lifelimited parts at each piece-part opportunity.

#### **New Inspection Procedures**

Since the issuance of that AD, an FAA study of in-service events involving uncontained failures of critical rotating engine parts has indicated the need for additional mandatory inspections. The mandatory inspections are needed to identify those critical rotating parts with conditions, which if allowed to continue in service, could result in uncontained failures. This proposal would modify the TLS of the manufacturer's manual and an air carrier's approved continuous airworthiness maintenance program to incorporate the additional inspection requirements.

## FAA's Determination of an Unsafe Condition and Proposed Actions

Since an unsafe condition has been identified that is likely to exist or develop on other PW2000 series turbofan engines of the same type design, the proposed AD would supersede AD 2002–12–06 to add additional inspection requirements for critical life-limited parts for enhanced inspection at each piece-part opportunity.

#### **Costs of Compliance**

There are about 938 Pratt & Whitney PW2000 series turbofan engines of the affected design in the worldwide fleet. We estimate that 777 engines installed on airplanes of U.S. registry would be affected by this proposed AD. We also estimate that it would take about 4 work hours per engine to perform the proposed inspections, and that the average labor rate is \$65 per work hour. Since this is an added inspection requirement, included as part of the normal maintenance cycle, no additional part costs are involved. Based on these figures, the total additional cost per engine per shop visit is estimated to be \$260. Based on the current PW2000 engine shop visit rate, the total additional cost for the PW2000 fleet is estimated to be \$80,860 per year.

# **Regulatory Findings**

We have determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.