

Instructions of Hamilton Sundstrand ASB No. ASB-4504112-49-22, Revision 2, dated October 4, 2004 to inspect and adjust the gap.

Optional Terminating Action for APU Model T-62T-40C14 (APS 500R)

(j) For APU Model T-62T-40C14 (APS 500R), installation of a part number fuel filter assembly that is not listed in this AD constitutes optional terminating action to the requirements of this AD.

Alternative Methods of Compliance

(k) The Manager, Los Angeles Aircraft Certification Office, has the authority to approve alternative methods of compliance for this AD if requested using the procedures found in 14 CFR 39.19.

Material Incorporated by Reference

(l) You must use the Alert Service Bulletins listed in Table 1 of this AD to perform the bracket installations required by this AD. The Director of the Federal Register approved the incorporation by reference of the documents listed in Table 1 of this AD in accordance

with 5 U.S.C. 552(a) and 1 CFR part 51. You can get a copy from Hamilton Sundstrand Technical Publications Department, P.O. Box 7002, Rockford, IL 61125-7002, U.S.A. You can review copies at the FAA, New England Region, Office of the Regional Counsel, 12 New England Executive Park, Burlington, MA; or at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: http://www.archives.gov/federal_register/code_of_federal_regulations/ibr_locations.html. Table 1 follows:

TABLE 1.—INCORPORATION BY REFERENCE

Alert service bulletin No.	Page number(s) shown on the page	Revision level shown on the page	Date shown on the page
Hamilton Sundstrand ASB-4503067-49-9	All	Original	December 2, 2003.
Hamilton Sundstrand ASB-4504112-49-22	All	2	October 4, 2004.

Related Information

(m) None.

Issued in Burlington, Massachusetts, on November 15, 2004.

Jay J. Pardee,

Manager, Engine and Propeller Directorate, Aircraft Certification Service.

[FR Doc. 04-25792 Filed 11-24-04; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 2003-NE-23-AD; Amendment 39-13880; AD 2004-24-04]

RIN 2120-AA64

Airworthiness Directives; Rolls-Royce Corporation (Formerly Allison Engine Company, Allison Gas Turbine Division, and Detroit Diesel Allison) (RRC) Models 250-C30R/3, -C30R/3M, -C47B, and -C47M Turboshaft Engines

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: The FAA is superseding an existing airworthiness directive (AD) for RRC models 250-C30R/3, -C30R/3M, -C47B, and -C47M turboshaft engines. That AD currently requires initial and repetitive electrical signal inspections of the hydromechanical unit (HMU) Power Lever Angle (PLA) potentiometer. This ad continues to require those inspections and adds replacement of the existing HMU with a new design HMU as a mandatory terminating action to the repetitive inspection requirements. This AD results from the manufacturer

releasing a redesigned HMU that has a dual-element potentiometer. We are issuing this AD to prevent uncommanded and sudden changes in engine power.

DATES: This AD becomes effective January 3, 2005. The Director of the Federal Register approved the incorporation by reference of certain publications listed in the regulations as of January 3, 2005.

ADDRESSES: You can get the service information identified in this AD from Rolls-Royce Corporation, P.O. Box 420, Indianapolis, IN 46206-0420; telephone (317) 230-6400; fax (317) 230-4243.

You may examine the AD docket at the FAA, New England Region, Office of the Regional Counsel, 12 New England Executive Park, Burlington, MA. You may examine the service information, at the FAA, New England Region, Office of the Regional Counsel, 12 New England Executive Park, Burlington, MA; or at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: http://www.archives.gov/federal_register/code_of_federal_regulations/ibr_locations.html.

FOR FURTHER INFORMATION CONTACT: Khailaa Hosny, Aerospace Engineer, Chicago Aircraft Certification Office, FAA, 2300 East Devon Avenue, Des Plaines, IL 60018-4696; telephone (847) 294-7134; fax (847) 294-7834.

SUPPLEMENTARY INFORMATION: The FAA proposed to amend 14 CFR part 39 with a proposed AD. The proposed AD applies to RRC models 250-C30R/3, -C30R/3M, -C47B, and -C47M turboshaft engines. We published the proposed AD in the **Federal Register** on

June 9, 2004 (69 FR 32287). That action proposed to require initial and repetitive electrical signal inspections of the HMU PLA potentiometer and replacement of the existing HMU with a new design HMU as a mandatory terminating action to the repetitive inspection requirements.

Examining the AD Docket

You may examine the AD Docket (including any comments and service information), by appointment, between 8 a.m. and 4:30 p.m., Monday through Friday, except Federal holidays. See **ADDRESSES** for the location.

Comments

We provided the public the opportunity to participate in the development of this AD. We received no comments on the proposal or on the determination of the cost to the public.

Conclusion

We have carefully reviewed the available data and determined that air safety and the public interest require adopting the AD as proposed.

Costs of Compliance

We estimate that 700 engines installed on helicopters of U.S. registry will be affected by this AD. We estimate that it will take about 4 work hours per engine to replace a single-element HMU with a dual-element HMU. We also estimate that 12 percent of the single-element HMUs will fail the required inspection and require replacing the HMU. The average labor rate is \$65 per work hour. Required parts cost about \$615 per engine. Based on these figures, we estimate the total cost of the AD to U.S. operators to be \$686,000.

Regulatory Findings

We have determined that this AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

- (1) Is not a "significant regulatory action" under Executive Order 12866;
- (2) Is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and
- (3) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared a summary of the costs to comply with this AD and placed it in the AD Docket. You may get a copy of this summary by sending a request to us at the address listed under ADDRESSES. Include "AD Docket No. 2003-NE-23-AD" in your request.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

■ Accordingly, under the authority delegated to me by the Administrator, the Federal Aviation Administration amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:
Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

■ 2. The FAA amends § 39.13 by removing Amendment 39-13210 (68 FR 38590, June 30, 2003) and by adding a new airworthiness directive,

Amendment 39-13880, to read as follows:

2004-24-04 Rolls-Royce Corporation (formerly Allison Engine Company, Allison Gas Turbine Division, and Detroit Diesel Allison): Amendment 39-13880. Docket No. 2003-NE-23-AD. Supersedes AD 2003-13-10, Amendment 39-13210.

Effective Date

(a) This AD becomes effective January 3, 2005.

Affected ADs

(b) This AD supersedes AD 2003-13-10.

Applicability

(c) This AD applies to Rolls-Royce Corporation (formerly Allison Engine Company, Allison Gas Turbine Division, and Detroit Diesel Allison) (RRC) models 250-C30R/3, -C30R/3M, -C47B, and -C47M turboshaft engines that have a hydromechanical unit (HMU) with a part number (P/N) listed in 1.A. Group A of RRC Alert Commercial Engine Bulletins (ACEB) No. CEB A-73-3103, Revision 4, dated December 2, 2003; and No. CEB A-73-6030, Revision 4, dated December 2, 2003. These engines are installed on, but not limited to, Bell OH-58D, Bell Helicopter Textron 407, Boeing AH/MH-6M, and MD Helicopters Inc. 600N helicopters.

Unsafe Condition

(d) This AD results from the manufacturer releasing a redesigned HMU that has a dual-element potentiometer. The actions specified in this AD are intended to prevent uncommanded and sudden changes in engine power.

Compliance

(e) Compliance with this AD is required as indicated, unless already done.

Initial Inspection

(f) Perform an initial electrical signal inspection of the HMU Power Lever Angle (PLA) potentiometer, within 300 flight hours (FH) after the effective date of this AD. Use paragraphs 2.B. through 2.B.(8) and 2.B.(10) of the Accomplishment Instructions of RRC ACEB No. CEB A-73-3103, Revision 4, dated December 2, 2003; or No. CEB A-73-6030, Revision 4, dated December 2, 2003; to perform the inspection.

(g) Replace the HMU before further flight if the electrical signal inspection result is unacceptable.

Repetitive Inspections

(h) Thereafter, perform repetitive electrical signal inspections of the HMU PLA potentiometer within 300 FH of the last inspection. Use paragraphs 2.B. through 2.B.(8) and 2.B.(10) of the Accomplishment Instructions of RRC ACEB No. CEB A-73-3103, Revision 4, dated December 2, 2003; or No. CEB A-73-6030, Revision 4, dated December 2, 2003; to perform the inspection.

(i) Replace the HMU before further flight if the electrical signal inspection result is unacceptable.

Mandatory Terminating Action

(j) Replace the HMU with an HMU that has a P/N not specified in this AD within 600 FH after the effective date of this AD, or January 31, 2005, whichever occurs earlier. Replacing the HMU with an HMU that has a P/N not specified in this AD terminates the repetitive inspection requirement specified in paragraph (h) of this AD.

Alternative Methods of Compliance

(k) Alternative methods of compliance must be requested in accordance with 14 CFR part 39.19, and must be approved by the Manager, Chicago Aircraft Certification Office, FAA.

Material Incorporated by Reference

(l) You must use the Rolls-Royce Corporation Alert Commercial Engine Bulletins (ACEBs) listed in Table 1 of this AD to perform the inspections required by this AD. The Director of the Federal Register approved the incorporation by reference of the documents listed in Table 1 of this AD in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. You can get a copy from Rolls-Royce Corporation, P.O. Box 420, Indianapolis, IN 46206-0420; telephone (317) 230-6400; fax (317) 230-4243. You can review copies at the FAA, New England Region, Office of the Regional Counsel, 12 New England Executive Park, Burlington, MA; or at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: http://www.archives.gov/federal_register/code_of_federal_regulations/ibr_locations.html. Table 1 follows:

TABLE 1.—INCORPORATION BY REFERENCE

Service bulletin	Page number(s) shown on the page	Revision level shown on the page	Date shown on the page
CEB A-73-3103, Total Pages: 20	All	4	December 2, 2003.
CEB A-73-6030, Total Pages: 20	All	4	December 2, 2003.

Related Information

(m) None.

Issued in Burlington, Massachusetts, on November 15, 2004.

Jay J. Pardee,

Manager, Engine and Propeller Directorate, Aircraft Certification Service.

[FR Doc. 04-25791 Filed 11-24-04; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 2003-CE-67-AD; Amendment 39-13878; AD 2004-24-02]

RIN 2120-AA64

Airworthiness Directives; Ostmecklenburgische Flugzeugbau GmbH Model OMF-100-160 Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: The FAA adopts a new airworthiness directive (AD) for certain Ostmecklenburgische Flugzeugbau GmbH (OMF) Model OMF-100-160 airplanes. This AD requires you to inspect the outside tube (cage) that supports the main landing gear leg for cracks, repair if cracks are found, and inspect the thickness of the tube if no cracks were found and reinforce the tube as necessary. This AD results from mandatory continuing airworthiness information (MCAI) issued by the airworthiness authority for Germany. We are issuing this AD to detect, correct, and prevent future cracks in the outside tube of the main landing gear leg, which could result in structural failure of the fuselage tubing assembly. This failure could lead to loss of control of the airplane.

DATES: This AD becomes effective on December 28, 2004.

As of December 28, 2004, the Director of the **Federal Register** approved the incorporation by reference of certain publications listed in the regulation.

ADDRESSES: To get the service information identified in this AD, contact Ostmecklenburgische

Flugzeugbau GmbH, Flughafenstrasse, 17039 Trollenhagen, Federal Republic of Germany; telephone: 011 49 395 42560-0; facsimile: 011 49 395 42560-20. To review this service information, go to the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, go to: http://www.archives.gov/federal_register/code_of_federal_regulations/ibr_locations.html or call (202) 741-6030.

To view the AD docket, go to the Docket Management Facility; U.S. Department of Transportation, 400 Seventh Street, SW., Nassif Building, Room PL-401, Washington, DC 20590-001 or on the Internet at <http://dms.dot.gov>. The docket number is 2003-CE-67-AD.

FOR FURTHER INFORMATION CONTACT: Karl Schletzbaum, Aerospace Engineer, ACE-112, Small Airplane Directorate, 901 Locust, Room 301, Kansas City, Missouri, 64106; telephone: (816) 329-4146; facsimile: (816) 329-4149.

SUPPLEMENTARY INFORMATION:

Discussion

What events have caused this AD? The Luftfahrt-Bundesamt (LBA), which is the airworthiness authority for Germany, recently notified the FAA that an unsafe condition may exist on certain OMF Model OMF-100-160 airplanes. The LBA reports that the manufacturer received a report of cracks in the outside fuselage tube that supports the main landing gear leg. Further investigation revealed that one manufacturer of fuselage tubes used out-of-design dimensions for the tube elements.

What is the potential impact if FAA took no action? Cracks in the outside tube of the main landing gear leg, if not detected, corrected, and prevented, could result in structural failure of the fuselage tubing assembly. This failure could lead to loss of control of the airplane.

Has FAA taken any action to this point? We issued a proposal to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) to include an AD that would apply to certain OMF Model OMF-100-160 airplanes. This proposal was published in the **Federal Register** as a notice of proposed

rulemaking (NPRM) on August 18, 2004, (69 FR 51206). The NPRM proposed to detect, correct, and prevent future cracks in the outside tube of the main landing gear leg. These cracks could result in structural failure of the fuselage tubing assembly and lead to loss of control of the airplane.

Comments

Was the public invited to comment? We provided the public the opportunity to participate in developing this AD. We received no comments on the proposal or on the determination of the cost to the public.

Conclusion

What is FAA's final determination on this issue? We have carefully reviewed the available data and determined that air safety and the public interest require adopting the AD as proposed except for minor editorial corrections. We have determined that these minor corrections:

- Are consistent with the intent that was proposed in the NPRM for correcting the unsafe condition; and
- Do not add any additional burden upon the public than was already proposed in the NPRM.

Changes to 14 CFR Part 39—Effect on the AD

How does the revision to 14 CFR part 39 affect this AD? On July 10, 2002, the FAA published a new version of 14 CFR part 39 (67 FR 47997, July 22, 2002), which governs the FAA's AD system. This regulation now includes material that relates to altered products, special flight permits, and alternative methods of compliance. This material previously was included in each individual AD. Since this material is included in 14 CFR part 39, we will not include it in future AD actions.

Costs of Compliance

How many airplanes does this AD impact? We estimate that this AD affects 11 airplanes in the U.S. registry.

What is the cost impact of this AD on owners/operators of the affected airplanes? We estimate the following costs to accomplish the inspections:

Labor cost	Parts cost	Total cost per airplane	Total cost on U.S. operators
Inspection for cracks—2 workhours est. \$65 per hour = \$130	N/A	\$130	\$1,430.
Inspection for inadequate thickness of tubing that supports the main landing gear leg—2 workhours est. \$65 per hour = \$130.	N/A	130	OMF will cover the cost for the special inspection.