

Contact Turbomeca S.A., 40220 Tarnos, France; telephone 33 05 59 74 40 00, fax 33 05 59 74 45 15, for a copy of this service information. You may review copies at the Docket Management Facility; U.S.

Department of Transportation, 400 Seventh Street, SW., Nassif Building, Room PL-401, Washington, DC 20590-0001, on the internet at <http://dms.dot.gov>; or at the National Archives and Records Administration

(NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: http://www.archives.gov/federal_register/code_of_federal_regulations/ibr_locations.html.

TABLE 2.—INCORPORATION BY REFERENCE

Mandatory service bulletin No.	Page	Revision	Date
319 73 2080 Total Pages—6	ALL ...	1	February 13, 2004.
319 73 2081 Total Pages—6	ALL ...	1	February 13, 2004.
319 73 2082 Total Pages—6	ALL ...	1	February 13, 2004.
319 73 2090 Total Pages—7	ALL ...	Original ..	February 13, 2004.

Related Information

(i) DGAC airworthiness directive F-2004-017 R1, dated March 3, 2004, also addresses the subject of this AD.

Issued in Burlington, Massachusetts, on June 6, 2005.

Jay J. Pardee,

Manager, Engine and Propeller Directorate, Aircraft Certification Service.

[FR Doc. 05-11611 Filed 6-13-05; 8:45 am]

BILLING CODE 4910-13-U

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 93-ANE-07-AD; Amendment 39-14122; AD 2005-12-06]

RIN 2120-AA64

Airworthiness Directives; Teledyne Continental Motors (Formerly Bendix) S-20, S-1200, D-2000, and D-3000 Series Magnetos

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: The FAA is superseding an existing airworthiness directive (AD) for Teledyne Continental Motors (TCM) (formerly Bendix) S-20, S-1200, D-2000, and D-3000 series magnetos equipped with impulse coupling assemblies. That AD currently requires replacing riveted-impulse coupling assemblies and snap-ring coupling assemblies, which are worn beyond limits, with serviceable riveted-impulse coupling assemblies or snap-ring impulse coupling assemblies. This ad requires a reduced inspection interval for magnetos with riveted-impulse coupling assemblies installed on certain Lycoming engine models. This AD does not lower the inspection interval for magnetos with snap-ring impulse

coupling assemblies. This AD also limits the applicability to certain Lycoming engine models. This AD results from data provided by the manufacturer that shows a need to reduce the inspection intervals for riveted-impulse coupling assemblies used on certain Lycoming engine models. We are issuing this AD to prevent failure of the magneto impulse coupling assembly and possible engine failure.

DATES: This AD becomes effective July 19, 2005. The Director of the Federal Register previously approved the incorporation by reference of certain publications as listed in the regulations as of July 18, 1996 (61 FR 29934, June 13, 1996).

ADDRESSES: You can get the service information identified in this AD from Teledyne Continental Motors, P.O. Box 90, Mobile, AL 36601; telephone (334) 438-3411. For the Teledyne Continental Motors Web site: Go to <http://www.TCMLINK.com>.

You may examine the AD docket at the FAA, New England Region, Office of the Regional Counsel, 12 New England Executive Park, Burlington, MA. You may examine the service information, at the FAA, New England Region, Office of the Regional Counsel, 12 New England Executive Park, Burlington, MA; or at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: http://www.archives.gov/federal_register/code_of_federal_regulations/ibr_locations.html.

FOR FURTHER INFORMATION CONTACT: Jerry Robinette, Senior Aerospace Engineer, Propulsion, Atlanta Aircraft Certification Office, FAA, Small Airplane Directorate, 1 Crown Center, 1895 Phoenix Blvd., Suite 450, Atlanta,

GA, 30349; telephone (770) 703-6096, fax (770) 703-6097.

SUPPLEMENTARY INFORMATION: The FAA proposed to amend 14 CFR part 39 with a proposed airworthiness directive (AD). The proposed AD applies to TCM S-20, S-1200, D-2000, and D-3000 series magnetos equipped with impulse coupling assemblies. We published the proposed AD in the **Federal Register** on December 22, 2004 (69 FR 76632). That action proposed to require:

- An initial visual inspection of riveted-impulse coupling assemblies that have 100 or more hours time-since-new (TSN) or time-since-last-inspection (TSLI) on the effective date of the proposed AD, within 10 hours time-in-service (TIS) after the effective date of this AD, or
- An initial visual inspection of riveted-impulse coupling assemblies that have fewer than 100 hours TSN or TSLI on the effective date of the proposed AD, before accumulating 100 hours TSN or TSLI, and
- Repetitive inspections of riveted-impulse coupling assemblies within intervals of 100 hours TSLI.
- An initial visual inspection of snap-ring impulse coupling assemblies that have 450 or more hours TSN or TSLI on the effective date of the proposed AD, within 50 hours TIS after the effective date of the AD, or
- An initial visual inspection of snap-ring impulse coupling assemblies that have fewer than 450 hours TSN or TSLI before accumulating 500 hours TSN or TSLI, and
- Repetitive inspections of snap-ring impulse coupling assemblies within intervals of 500 hours TSLI.
- Replacing impulse coupling assemblies that fail the inspection.

Examining the AD Docket

You may examine the AD Docket (including any comments and service information), by appointment, between

8 a.m. and 4:30 p.m., Monday through Friday, except Federal holidays. See **ADDRESSES** for the location.

Comments

We provided the public the opportunity to participate in the development of this AD. We have considered the comments received.

Request To Not Change the Eligibility From the Current AD

One commenter requests that we not change the eligibility from the current AD. The commenter states that experience has shown that the current AD is preventing failures and there is no difference between the wear or reliability of the impulse coupling assemblies installed on one make and model of engine, or another.

We do not agree. Responses we received to the Airworthiness Concern Sheet and Special Airworthiness Information Bulletin from owners and operators, and the manufacturer's data, indicate that there is a significant difference in the wear and reliability of magnetos installed on Lycoming 540 series engines as compared with other engines. Based on these responses, we have appropriately reduced the inspection interval for magnetos with riveted-impulse coupling assemblies installed on Lycoming 540 series engines.

Request To Not Change From the Current AD

One commenter states that without the current AD, owners and operators will not have the manufacturer's recommended maintenance performed, and safety will suffer.

We do not agree. While a small percentage of operators may not voluntarily comply with the manufacturer's recommended maintenance, we anticipate virtually all will comply. The response to the Airworthiness Concern Sheet, Special Airworthiness Information Bulletin, and manufacturer's data, indicates the AD is only needed for the Lycoming 540 series engines. This action does not negate the 500-hour inspection recommended by TCM. That inspection is part of the total inspection program to ensure the continued airworthiness of the engine. Therefore, we anticipate that safety will not suffer.

Addition of Description of Magneto Model Numbering System

To assist owners and operators, we have added the description of the magneto numbering system used for TCM S-20, S-1200, D-2000, and D-

3000 series magnetos to the compliance section of the AD.

Conclusion

We have carefully reviewed the available data, including the comments received, and determined that air safety and the public interest require adopting the AD with the changes described previously. We have determined that these changes will neither increase the economic burden on any operator nor increase the scope of the AD.

Costs of Compliance

We estimate that this AD will affect about 4,200 magnetos installed on airplanes of U.S. registry. We also estimate that it will take about 1 work hour per magneto to perform the actions, and that the average labor rate is \$65 per work hour. The reduced inspection interval will require doing the inspections about four times more often. Based on these figures, we estimate the total cost of the AD to U.S. operators to be \$1,092,000.

Special Flight Permits Paragraph Removed

Paragraph (d) of the current AD, AD 96-12-07, contains a paragraph pertaining to special flight permits. Even though this final rule does not contain a similar paragraph, we have made no changes with regard to the use of special flight permits to operate the airplane to a repair facility to do the work required by this AD. In July 2002, we published a new 14 CFR part 39 that contains a general authority regarding special flight permits and airworthiness directives; see Docket No. FAA-2004-8460, Amendment 39-9474 (69 FR 47998, July 22, 2002). Thus, when we now supersede ADs we will not include a specific paragraph on special flight permits unless we want to limit the use of that general authority granted in section 39.23.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in subtitle VII, part A, subpart III, section 44701, "General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for

safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We have determined that this AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

- (1) Is not a "significant regulatory action" under Executive Order 12866;
- (2) Is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and
- (3) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared a summary of the costs to comply with this AD and placed it in the AD Docket. You may get a copy of this summary by sending a request to us at the address listed under **ADDRESSES**. Include "AD Docket No. 93-ANE-07-AD" in your request.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

- Accordingly, under the authority delegated to me by the Administrator, the Federal Aviation Administration amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by removing Amendment 39-9649 (61 FR 29934, June 13, 1996) and by adding a new airworthiness directive, Amendment 39-14122, to read as follows:

2005-12-06 Teledyne Continental Motors:
Amendment 39-14122. Docket No. 93-ANE-07-AD.

Effective Date

- (a) This AD becomes effective July 19, 2005.

Affected ADs

(b) This AD supersedes AD 96-12-07, Amendment 39-9649.

Applicability: (c) This AD applies to Teledyne Continental Motors (TCM) (formerly Bendix) magnetos that have a magneto part number (P/N) listed in Table 1 of TCM Mandatory Service Bulletin (MSB) No. MSB645, dated April 4, 1994, installed on Lycoming AEIO-540, HIO-540, IO-540, O-540, and TIO-540 series engines. These engines are installed on, but not limited to, airplanes manufactured by the Cessna Aircraft Company, Maule Aerospace Technology Corporation, Mooney Aircraft Corporation, The New Piper Aircraft Inc.,

and Raytheon Aircraft Company (Formerly Beech Aircraft Company).

Unsafe Condition

(d) This AD results from data provided by the manufacturer that indicates a need to reduce the inspection intervals for riveted-impulse coupling assemblies used on certain Lycoming engine models. We are issuing this AD to prevent failure of the magneto impulse coupling assembly and possible engine failure.

Compliance: (e) You are responsible for having the actions required by this AD performed within the compliance times specified unless the actions have already been done.

Initial Inspections of Impulse Coupling Assemblies

(f) For all magnetos that have a P/N listed in Table 1 of TCM MSB No. MSB645, dated April 4, 1994, that have never been inspected, perform an initial inspection of the impulse coupling assembly for wear using paragraphs 1.2 through 1.4.5 of the Detailed Instructions of TCM MSB No. MSB645, dated April 4, 1994. Use the following Table 1 for the compliance times. Snap-ring impulse coupling assemblies will have an "A" stamped in the lower-right quarter of the magneto data plate.

TABLE 1.—INITIAL INSPECTION COMPLIANCE TIMES

Engine Model	Type of impulse coupling assembly	Time on impulse coupling assembly on the effective date of this AD	Inspect
Lycoming AEIO-540, HIO-540, IO-540, O-540, and TIO-540 series engines.	(1) Riveted	(i) 100 or more hours time-since-new or overhaul (TSN) or if the TSN is unknown. (ii) Fewer than 100 hours TSN	Within 10 hours time-in-service (TIS) after the effective date of this AD. Before accumulating 100 hours TSN.
	(2) Snap ring	(i) 450 or more hours TSN	Within 50 hours TIS after the effective date of this AD. Before accumulating 500 hours TSN.

(g) Replace any impulse coupling assembly that fails the inspection with a serviceable riveted or snap-ring impulse coupling assembly. Paragraphs 2 through 2.6 of the Detailed Instructions of TCM MSB No. MSB645, dated April 4, 1994 contain information on replacing the impulse coupling assembly.

(h) If you replace a snap-ring impulse coupling assembly with a riveted-impulse

coupling assembly, strike out the "A" on the magneto data plate.

Repetitive Inspections of Impulse Coupling Assemblies

(i) For all magnetos that have a P/N listed in Table 1 of TCM MSB No. MSB645, dated April 4, 1994, that have had an initial inspection as specified in paragraph (f) of this AD, perform repetitive inspections of the

impulse coupling assembly for wear using paragraphs 1.2 through 1.4.5 of the Detailed Instructions of TCM MSB No. MSB645, dated April 4, 1994. Use the following Table 2 for the compliance times. Snap-ring impulse coupling assemblies will have an "A" stamped in the lower-right quarter of the magneto data plate.

TABLE 2.—REPETITIVE INSPECTION COMPLIANCE TIMES

Engine model	Type of impulse coupling assembly	Inspect
Lycoming AEIO-540, HIO-540, IO-540, O-540, and TIO-540 series engines..	(1) Riveted	Within 100 hours time-since-last inspection (TSLI).
	(2) Snap ring	Within 500 hours TSLI.

(j) Replace any impulse coupling assembly that fails the inspection with a serviceable riveted or snap-ring impulse coupling assembly. Paragraphs 2 through 2.6 of the Detailed Instructions of TCM MSB No. MSB645, dated April 4, 1994 contain information on replacing the impulse coupling assembly.

(k) If you replace a snap-ring impulse coupling assembly with a riveted-impulse

coupling assembly, strike out the "A" on the magneto data plate.

Optional Terminating Action

(l) Installing a "Shower-of-Sparks" ignition system in place of a magneto system that has a riveted-impulse coupling assembly or a snap-ring impulse coupling assembly ends the repetitive inspection requirements specified in paragraph (i) of this AD. You can find more information on installing a

"Shower-of-Sparks" ignition system in TCM Service Information Letter No. SIL648, dated October 18, 1994.

Description of Magneto Model Numbering System

(m) To assist owners and operators, the description of the magneto numbering system used for TCM S-20, S-1200, D-2000, and D-3000 series magnetos is in the following Table 3:

TABLE 3.—MAGNETO NUMBERING SYSTEM

Code:	Signifies:
S or D	Ignition Type (Single or Dual)
6	Number of Cylinders
L or R	Direction of Rotation (Left-hand or Right-hand)
N (Not used on SC Models)	Manufacturer Designation

TABLE 3.—MAGNETO NUMBERING SYSTEM—Continued

Code:	Signifies:
SC (if applicable) –25, –1209, or –3200	Short Cover Configuration Magneto Series
Examples:	Description:
S6LN–1209	Single type ignition, 6-cylinder engine, left-hand rotation, TCM (formerly Bendix), S–1200 series
D6RN–3200	Dual type ignition, 6-cylinder engine, right-hand rotation, TCM (formerly Bendix), D–3000 series
S6LSC–25	Single type ignition, 6-cylinder engine, left-hand rotation, short cover configuration, S–20 series

Alternative Methods of Compliance

(n) The Manager, Atlanta Aircraft Certification Office, has the authority to approve alternative methods of compliance for this AD if requested using the procedures found in 14 CFR 39.19.

Related Information

(o) TCM SB No. 639, dated March 1993, contains additional information for replacing impulse coupling assemblies on a TCM magneto. TCM Service Information Letter No. SIL648, dated October 18, 1994, contains information for converting an engine to a “Shower-of-Sparks” ignition system.

Material Incorporated by Reference

(p) You must use Teledyne Continental Motors Mandatory Service Bulletin No. MSB645, dated April 4, 1994 to perform the inspections and replacements required by this AD. The Director of the Federal Register approved the incorporation by reference of this service bulletin as of July 18, 1996 (61 FR 29934, June 13, 1996). You can get a copy from Teledyne Continental Motors, P.O. Box 90, Mobile, AL 36601; telephone (334) 438–3411. For the Teledyne Continental Motors Web site: Go to <http://www.TCMLINK.com>. You can review copies at the FAA, New England Region, Office of the Regional Counsel, 12 New England Executive Park, Burlington, MA; or at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202–741–6030, or go to: http://www.archives.gov/federal_register/code_of_federal_regulations/ibr_locations.html.

Issued in Burlington, Massachusetts, on June 6, 2005.

Jay J. Pardee,

Manager, Engine and Propeller Directorate, Aircraft Certification Service.

[FR Doc. 05–11610 Filed 6–13–05; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF TRANSPORTATION**Federal Aviation Administration****14 CFR Part 71**

[Docket FAA 2003–16460; Airspace Docket 02–ANM–16]

Amendment to Class E Airspace; Wray, CO

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: This final rule will revise Class E airspace at Wray, CO. New Area Navigation (RNAV) Global Positioning System (GPS) Standard Instrument Approach Procedures (SIAPs) have been developed at Wray Municipal Airport. Additional Class E airspace extending upward from 700 feet above the surface is necessary for the safety of instrument flight rules (IFR) aircraft executing these new SIAPs and transitioning between the terminal and en route environment.

DATES: 0901 UTC May 12, 2005.

FOR FURTHER INFORMATION CONTACT: Ed Haesecker, Federal Aviation Administration, Air Traffic Organization, Western En Route and Oceanic Area Office, Airspace Branch, 1601 Lind Avenue, SW., Renton, WA 98055–4056; telephone (425) 227–2527.

SUPPLEMENTARY INFORMATION:**History**

On October 21, 2003, the FAA published in the **Federal Register** a notice of proposed rule making to modify Class E airspace at Wray, CO (69 FR 32295). New RNAV GPS SIAPs at Wray Municipal Airport, Wray, CO, make it necessary to increase the controlled airspace.

Interested parties were invited to participate on this rule making proceeding by submitting written comments on the proposal to the FAA. No comments were received. Class E airspace designations are published in paragraph 6005 of FAA Order 7400.9M

dated August 30, 2004, and effective September 16, 2004, which is incorporated by reference in 14 CFR part 71.1. The Class E airspace designations listed in this document will be published subsequently in that order.

The Rule

This amendment to 14 CFR part 71 revises Class E airspace at Wray Municipal Airport, Wray, CO. New RNAV GPS SIAPs at Wray Municipal Airport make it necessary to increase the Class E airspace. This additional controlled airspace extending upward from 700 feet or more above the surface of the earth is for the containment and safety of IFR aircraft transitioning to/ from the en route environment and executing these RNAV GPS SIAP procedures.

The FAA has determined that this regulation only involved an established body of technical regulations for which frequent and routine amendments are necessary to keep them operationally current. Therefore, this regulation: (1) Is not a “significant regulatory action” under Executive Order 12866; (2) is not a “significant rule” under DOT Regulatory Policies and Procedures (44 FR 11034; February 26, 1979); and (3) does not warrant preparation of a regulatory evaluation as the anticipated impact is so minimal. Since this is a routine matter that will only affect air traffic procedures and air navigation, it is certified that this rule, when promulgated, will not have a significant economic impact on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 71

Airspace, Incorporation by reference, Navigation (air).

Adoption of the Amendment

■ In consideration of the foregoing, the Federal Aviation Administration amends 14 CFR part 71 as follows: