

Compliance

(e) You are responsible for having the actions required by this AD performed within the compliance times specified, unless the actions have already been done.

Inspections

(f) At the applicable "Inspection Threshold" in the table in Part 1.E. "Compliance" of Boeing Alert Service Bulletin 737-53A1248, dated September 9, 2004, or within 18 months after the effective date of this AD, whichever occurs later, and thereafter at intervals not to exceed the applicable "Inspection Repeat Interval" in that table: Do the inspections (i.e., detailed inspection and either high- or low-frequency eddy current inspections) of the aft pressure bulkhead web for fatigue cracks, crack indications, discrepant holes, and corrosion, in accordance with the Accomplishment Instructions of the service bulletin.

Corrective Action Difference

(g) If any fatigue crack, crack indication, discrepant hole, or corrosion is found during any inspection required by this AD, before further flight, repair the fatigue crack, crack indication, discrepant hole, and corrosion according to a method approved by the Manager, Seattle Aircraft Certification Office (ACO), FAA; or using a method approved in accordance with the procedures specified in paragraph (i) of this AD.

No Reporting

(h) Although the service bulletin references a reporting requirement in the Accomplishment Instructions, that reporting is not required by this AD.

Alternative Methods of Compliance (AMOCs)

(i)(1) The Manager, Seattle ACO, FAA, has the authority to approve AMOCs for this AD, if requested in accordance with the procedures found in 14 CFR 39.19.

(2) An AMOC that provides an acceptable level of safety may be used for corrective actions, if it is approved by an Authorized Representative for the Boeing Commercial Airplanes Delegation Option Authorization Organization who has been authorized by the Manager, Seattle ACO, to make those findings. For a repair method to be approved, the repair must meet the certification basis of the airplane, and the approval must specifically refer to this AD.

(3) Before using any AMOC approved in accordance with § 39.19 on any airplane to which the AMOC applies, notify the appropriate principal inspector in the FAA Flight Standards Certificate Holding District Office.

Material Incorporated by Reference

(j) You must use Boeing Alert Service Bulletin 737-53A1248, dated September 9, 2004, to perform the actions that are required by this AD, unless the AD specifies otherwise. The Director of the Federal Register approved the incorporation by reference of this document in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Contact Boeing Commercial Airplanes, P.O. Box 3707, Seattle, Washington 98124-2207,

for a copy of this service information. You may review copies at the Docket Management Facility, U.S. Department of Transportation, 400 Seventh Street, SW., room PL-401, Nassif Building, Washington, DC; on the Internet at <http://dms.dot.gov>; or at the National Archives and Records Administration (NARA). For information on the availability of this material at the NARA, call (202) 741-6030, or go to http://www.archives.gov/federal_register/code_of_federal_regulations/ibr_locations.html.

Issued in Renton, Washington, on October 13, 2005.

Kalene C. Yanamura,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 05-20966 Filed 10-20-05; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION**Federal Aviation Administration****14 CFR Part 39**

[Docket No. 2000-NE-48-AD; Amendment 39-14343; AD 2005-21-05]

RIN 2120-AA64

Airworthiness Directives; Rolls-Royce Deutschland Ltd & Co KG (Formerly Rolls-Royce Deutschland GmbH, formerly BMW Rolls-Royce GmbH) Models BR700-710A1-10 and BR700-710A2-20 Turbofan Engines

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: The FAA is superseding an existing airworthiness directive (AD) for Rolls-Royce Deutschland Ltd & Co KG (RRD) (formerly Rolls-Royce Deutschland GmbH, formerly BMW Rolls-Royce GmbH) models BR700-710A1-10 and BR700-710A2-20 turbofan engines. That AD currently requires initial and repetitive visual and ultrasonic inspections of fan discs, part numbers (P/Ns) BRR18803, BRR19248, and BRR20791 for cracks, and if necessary, replacement with serviceable parts. This ad requires those same inspections for discs having old design P/N fan blades installed, and extends the inspection interval for fan discs having new design P/N fan blades installed. Also, this AD adds as optional terminating action to the inspections, installation of certain P/N new fan discs, certain P/N new fan blades, and engine fan speed (N1) Keep Out Zone software. This AD results from a revised RRD service bulletin (SB) that introduces relaxed inspection intervals for certain P/N combinations of fan

discs and fan blades, and introduces improved design fan discs and fan blades.

DATES: This AD becomes effective November 25, 2005. The Director of the Federal Register approved the incorporation by reference of certain publications listed in the regulations as of November 25, 2005. The Director of the Federal Register previously approved the incorporation by reference of certain other publications as listed in the regulations as of April 28, 2003 (68 FR 17727, April 11, 2003).

ADDRESSES: Contact Rolls-Royce Deutschland Ltd & Co KG, Eschenweg 11, 15827 Blankenfelde-Mahlow, Germany, telephone: 011 49 (0) 33-7086-1768, fax: 011 49 (0) 33-7086-3356, for the service information identified in this AD.

You may examine the AD docket at the FAA, New England Region, Office of the Regional Counsel, 12 New England Executive Park, Burlington, MA. You may examine the service information, at the FAA, New England Region, Office of the Regional Counsel, 12 New England Executive Park, Burlington, MA.

FOR FURTHER INFORMATION CONTACT: Jason Yang, Aerospace Engineer, Engine Certification Office, FAA, Engine and Propeller Directorate, 12 New England Executive Park, Burlington, MA 01803-5299; telephone: (781) 238-7747, fax: (781) 238-7199.

SUPPLEMENTARY INFORMATION: The FAA proposed to amend 14 CFR part 39 with a proposed AD. The proposed AD applies to Rolls-Royce Deutschland Ltd & Co KG (RRD) (formerly Rolls-Royce Deutschland GmbH, formerly BMW Rolls-Royce GmbH) models BR700-710A1-10 and BR700-710A2-20 turbofan engines. We published the proposed AD in the **Federal Register** on July 5, 2005 (70 FR 38627). That action proposed to require initial and repetitive inspections for cracks in fan discs P/Ns BRR18803, BRR19248, BRR20791, BRR24829, and FW33929. That action also proposed as optional terminating action to the repetitive inspection requirements, installation of a new fan disc P/N FW33927, new fan blades P/N FW33513 or P/N FW33980, and N1 Keep Out Zone software.

Examining the AD Docket

You may examine the AD Docket (including any comments and service information), by appointment, between 8 a.m. and 4:30 p.m., Monday through Friday, except Federal holidays. See **ADDRESSES** for the location.

Comments

We provided the public the opportunity to participate in the development of this AD. We have considered the comments received.

Request To Cancel Inspections

One commenter, RRD, requests we cancel the inspections in paragraphs (f)(1), (g)(1), (f)(3), and (g)(3), as these inspections have been conducted on all hardware in service, and are no longer needed. We disagree. Mandatory actions that published in the superseded AD need to be carried forward in the superseding AD. The operator can then determine if the affected engine is in compliance with all mandatory actions.

Add Applicable Fan Blade Part Numbers to Paragraph (h)

The same commenter requests that we add the applicable fan blade part numbers in paragraph (h), for clarity, as we did in paragraph (g). We agree and have added fan blades P/N BRR20677 and BRR23178 to paragraph (h).

Request To Cover Engines That Had a New Disc Installed on, or After, January 1, 2002

The same commenter requests that we cover engines that had a new production fan disc installed on or after January 1, 2002, in a new paragraph in the compliance section. The commenter states that these fan discs already had a visual and ultrasonic inspection before delivery and installation, and only require initial inspection at 150 flight cycles-since-new. These engines are not appropriately covered by the proposed AD. We agree and have added a paragraph to the compliance section to cover these engines.

Request To Directly Identify Requirements

The same commenter requests that we clarify paragraphs (i) and (j) by directly identifying the requirements, instead of referring to other paragraphs. We agree and have changed paragraphs (i) and (j) to identify the requirements.

Request To Change Repetitive Inspection Interval

The same commenter requests that in paragraphs (k)(1) and (k)(2), we change the inspection interval time requirement from flight hours, to A-Check. The commenter states that the proposed AD does not reflect the requirements of RRD SB No. SB-BR700-72-900229, Revision 6, dated February 23, 2005. The visual and ultrasonic inspections were always aligned with the scheduled airplane maintenance A-Check. The commenter further states that the A-Check occurs

every 500-to-550 flight hours. We partially agree. We consider the A-Check to occur at an indefinite interval that can vary from operator to operator. However, in this case, we have changed the compliance in paragraph (k)(1) to perform a visual and ultrasonic inspection before accumulating 550 flight hours-since-new. We also changed paragraph (k)(2) to perform a visual and ultrasonic inspection at every A-Check but not to exceed 550 hours-since-the last visual and ultrasonic inspection.

Request To Remove Inspection Requirements From the AD and Reference the Time Limits Manual

The same commenter requests that we remove the inspection requirements from paragraph (l) of the proposed AD, which is for engines with fan disc P/N BRR20791, BRR24829, or FW33929 installed, and fan blades P/N FW33513, FW33980, FW33925, FW34114, or FW34776 installed. The commenter requests that we refer to the applicable RRD Time Limits Manual that mandates the inspections for these fan disc-and-blade-engine configurations. We agree and have changed that paragraph in the AD.

Request To Clarify the Optional Terminating Action

The same commenter requests that in the optional terminating action paragraph, we change the phrase "is optional terminating action to the repetitive inspections required by this AD" to "is optional terminating action to any inspection required by this AD". The commenter states that once the parts and the Keep Out Zone software referenced in the optional terminating action paragraph are installed, none of the inspections in the AD are required. We agree and have made that change in the AD.

Request To Reference the Latest Service Bulletin

The same commenter requests that we reference the latest service bulletin in the Inspection Reporting Requirements paragraph, which is RRD SB No. SB-BR700-72-900229, Revision 6, dated February 23, 2005. We agree and have made that change in the AD.

Conclusion

We have carefully reviewed the available data, including the comments received, and determined that air safety and the public interest require adopting the AD with the changes described previously. We have determined that these changes will neither increase the economic burden on any operator nor increase the scope of the AD.

Costs of Compliance

There are about 500 RRD models BR700-710A1-10 and BR700-710A2-20 turbofan engines of the affected design in the worldwide fleet. We estimate that 400 engines installed on airplanes of U.S. registry are affected by this AD. We also estimate that it will take about 7 work hours per engine to perform the inspections, and that the average labor rate is \$65 per work hour. We estimate the total labor cost for performing one inspection of the U.S. fleet to be \$182,000. New design fan discs and fan blades will cost about \$150,000 per engine. Based on these figures, the total cost of the AD on U.S. operators is estimated to be \$60,182,000. The manufacturer has stated that it may provide the new fan disc and new fan blades at no cost to operators.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, Section 106, describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701, "General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We have determined that this AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

- (1) Is not a "significant regulatory action" under Executive Order 12866;
- (2) Is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and
- (3) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared a summary of the costs to comply with this AD and placed it in the AD Docket. You may get a copy of this summary by sending a request to us at the address listed under **ADDRESSES**. Include "AD Docket No. 2000-NE-48-AD" in your request.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

Accordingly, under the authority delegated to me by the Administrator, the Federal Aviation Administration amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. The FAA amends § 39.13 by removing Amendment 39-13107 (68 FR 17727, April 11, 2003) and by adding a new airworthiness directive, Amendment 39-14343, to read as follows:

2005-21-05 Rolls-Royce Deutschland Ltd & Co KG (formerly Rolls-Royce Deutschland GmbH, formerly BMW Rolls-Royce GmbH): Amendment 39-14343. Docket No. 2000-NE-48-AD.

Effective Date

(a) This AD becomes effective November 25, 2005.

Affected ADs

(b) This AD supersedes AD 2003-07-11, Amendment 39-13107.

Applicability

(c) This AD applies to Rolls-Royce Deutschland Ltd & Co KG (RRD) (formerly Rolls-Royce Deutschland GmbH, formerly BMW Rolls-Royce GmbH) models BR700-710A1-10 and BR700-710A2-20 turbofan engines. These engines are installed on, but not limited to, Bombardier Inc. BD-700-1A10, BD-700-1A11, and Gulfstream Aerospace Corp. G-V series airplanes.

Unsafe Condition

(d) This AD results from a revised RRD service bulletin (SB) that introduces relaxed inspection intervals for certain P/N combinations of fan discs and fan blades, and introduces improved design fan discs and fan blades. The actions specified in this AD are intended to detect and prevent cracks in the fan disc that could result in an uncontained engine failure and damage to the airplane.

Compliance

(e) You are responsible for having the actions required by this AD performed within the compliance times specified unless the actions have already been done.

Initial Inspection

Engines With Fan Disc P/N BRR18803 or BRR19248 Installed and Fan Blades P/N BRR20677 or BRR23178 Installed

(f) For engines with fan disc P/N BRR18803 or BRR19248 installed, and fan blades P/N BRR20677 or BRR23178 installed, do the following:

(1) If the last fan disc inspection was a visual inspection performed using RRD SB No. SB-BR700-72-900229, Revision 3, dated July 12, 2001; Revision 4, dated December 20, 2001; Revision 5, dated January 8, 2003; or Revision 6, dated February 23, 2005, visually or ultrasonically inspect fan disc within 25 flight cycles-since-last inspection (CSLI). Use paragraphs A. through F. of the applicable Part 1 or Part 2 of the Accomplishment Instructions of RRD SB No. SB-BR700-72-900229, Revision 6, dated February 23, 2005 to do the inspection.

(2) If the last fan disc inspection was an ultrasonic inspection performed using RRD SB No. SB-BR700-72-900229, Revision 3, dated July 12, 2001; Revision 4, dated December 20, 2001; Revision 5, dated January 8, 2003; or Revision 6, dated February 23, 2005, visually or ultrasonically inspect fan disc within 75 CSLI. Use paragraphs A. through F. of the applicable Part 1 or Part 2 of the Accomplishment Instructions of RRD SB No. SB-BR700-72-900229, Revision 6, dated February 23, 2005 to do the inspection.

(3) For engines that have not yet been inspected, visually or ultrasonically inspect fan disc within 25 flight cycles after the effective date of this AD. Use paragraphs A. through F. of the applicable Part 1 or Part 2 of the Accomplishment Instructions of RRD SB No. SB-BR700-72-900229, Revision 6, dated February 23, 2005 to do the inspection.

(4) If any cracks are found, remove the disc from service and replace with a serviceable disc.

Engines With Fan Disc P/N BRR20791 Installed, and Fan Blades P/N BRR20677 or BRR23178 Installed

(g) For BR700-710A1-10 engines with serial numbers (SNs) 11452 and lower, and BR700-710A2-20 engines with SNs 12352 and lower, with fan disc P/N BRR20791 installed, and fan blades P/N BRR20677 or BRR23178 installed, do the following:

(1) If the last fan disc inspection was a visual inspection performed using RRD SB No. SB-BR700-72-900229, Revision 3, dated July 12, 2001; Revision 4, dated December 20, 2001; Revision 5, dated January 8, 2003; or Revision 6, dated February 23, 2005, visually or ultrasonically inspect fan disc within 25 CSLI. Use paragraphs A. through F. of the applicable Part 1 or Part 2 of the Accomplishment Instructions of RRD SB No. SB-BR700-72-900229, Revision 6, dated February 23, 2005 to do the inspection.

(2) If the last fan disc inspection was an ultrasonic inspection performed using RRD SB No. SB-BR700-72-900229, Revision 3, dated July 12, 2001; Revision 4, dated December 20, 2001; Revision 5, dated January 8, 2003; or Revision 6, dated February 23, 2005, visually or ultrasonically inspect fan disc within 150 CSLI. Use paragraphs A. through F. of the applicable Part 1 or Part 2

of the Accomplishment Instructions of RRD SB No. SB-BR700-72-900229, Revision 6, dated February 23, 2005 to do the inspection.

(3) For engines that have not yet been inspected, visually or ultrasonically inspect fan disc within 25 flight cycles after the effective date of this AD. Use paragraphs A. through F. of the applicable Part 1 or Part 2 of the Accomplishment Instructions of RRD SB No. SB-BR700-72-900229, Revision 6, dated February 23, 2005 to do the inspection.

(4) If any cracks are found, remove the disc from service and replace with a serviceable disc.

(h) For BR700-710A1-10 engines with SNs 11453 and higher, and BR700-710A2-20 engines with SNs 12353 and higher with fan discs P/N BRR20791 installed, and fan blades P/N BRR20677 or BRR23178 installed, do the following:

(1) Visually or ultrasonically inspect fan discs within 150 flight cycles-since-new (CSN). Use paragraphs A. through F. of the applicable Part 1 or Part 2 of the Accomplishment Instructions of RRD SB No. SB-BR700-72-900229, Revision 5, dated January 8, 2003; or Revision 6, dated February 23, 2005 to do the inspection.

(2) If any cracks are found, remove the disc from service and replace with a serviceable disc.

Engines With New Production Fan Discs

(i) For engines with new production fan discs P/N BRR20791 installed on or after January 1, 2002, and fan blades P/Ns BRR20677 or BRR23178 installed, do the following:

(1) Visually or ultrasonically inspect fan discs within 150 flight CSN. Use paragraphs A. through F. of the applicable Part 1 or Part 2 of the Accomplishment Instructions of RRD SB No. SB-BR700-72-900229, Revision 5, dated January 8, 2003; or Revision 6, dated February 23, 2005 to do the inspection.

(2) If any cracks are found, remove the disc from service and replace with a serviceable disc.

Repetitive Inspections

Engines With Fan Disc P/N BRR18803 or BRR19248 Installed, and Fan Blades P/N BRR20677 or BRR23178 Installed

(j) For engines with fan disc P/N BRR18803 or BRR19248 installed, and fan blades P/N BRR20677 or BRR23178 installed, do the following:

(1) Perform repetitive visual or ultrasonic inspections within every 75 CSLI. Use paragraphs A. through F. of the applicable Part 1 or Part 2 of the Accomplishment Instructions of RRD SB No. SB-BR700-72-900229, Revision 5, dated January 8, 2003; or Revision 6, dated February 23, 2005 to do the inspection.

(2) Perform a visual and ultrasonic inspection before accumulating 550 flight hours-since-new. Use paragraphs A. through F. of the applicable Part 1 or Part 2 of the Accomplishment Instructions of RRD SB No. SB-BR700-72-900229, Revision 5, dated January 8, 2003, or Revision 6, dated February 23, 2005 to do the inspection.

(3) Thereafter, perform a visual and an ultrasonic inspection at every A-Check but not to exceed 550 flight hours-since-the last visual and ultrasonic inspection.

Engines With Fan Disc P/N BRR20791 Installed, and Fan Blades P/N BRR20677 or BRR23178 Installed

(k) For engines with fan disc P/N BRR20791 installed, and fan blades P/N BRR20677 or BRR23178 installed, do the following:

(1) Perform repetitive visual or ultrasonic inspections within every 150 CSLI. Use paragraphs A. through F. of the applicable Part 1 or Part 2 of the Accomplishment Instructions of RRD SB No. SB-BR700-72-900229, Revision 5, dated January 8, 2003; or Revision 6, dated February 23, 2005 to do the inspection.

(2) Perform a visual and ultrasonic inspection before accumulating 550 flight hours-since-new. Use paragraphs A. through F. of the applicable Part 1 or Part 2 of the Accomplishment Instructions of RRD SB No. SB-BR700-72-900229, Revision 5, dated January 8, 2003, or Revision 6, dated February 23, 2005 to do the inspection.

(3) Thereafter, perform a visual and an ultrasonic inspection at every A-Check but not to exceed 550 flight hours-since-the last visual and ultrasonic inspection.

Engines With Fan Disc P/N BRR20791, BRR24829, or FW33929 Installed, and Fan Blades P/N FW33513, FW33980, FW33925, FW34114, or FW34776 Installed

(l) For engines with fan disc P/N BRR20791, BRR24829, or FW33929 installed, and fan blades P/N FW33513, FW33980, FW33925, FW34114, or FW34776 installed, initial and repetitive inspections are mandated in RRD Time Limits Manual T-710-1BR, Chapter 05-10-01 (BR700-710A1-10), and RRD Time Limits Manual T-710-2BR, Chapter 05-10-01 (BR700-710A2-20).

Optional Terminating Action

(m) Installation of a new fan disc P/N FW33927, new fan blades, P/N FW33513, or P/N FW33980, and N1 Keep Out Zone software with EEC P/Ns 1501KDC02-010, or 1501KDC03-010, or 1501KDC05-010, or 1520KDC05-010, or 1520KDC05R-010, or 1520KDC07-010, or 1520KDC08-010, is optional terminating action to any inspection required by this AD.

Inspection Reporting Requirements

(n) Report defects in accordance with the applicable Part 1 or Part 2 of RRD SB No. SB-BR700-72-900229, Revision 5, dated January 8, 2003; or Revision 6, dated February 23, 2005. Reporting requirements have been approved by the Office of Management and Budget (OMB) and assigned OMB control number 2120-0056.

Alternative Methods of Compliance

(o) The Manager, Engine Certification Office, has the authority to approve alternative methods of compliance for this AD if requested using the procedures found in 14 CFR 39.19.

Related Information

(p) LBA airworthiness directive 2000-348, Revision 6, dated March 31, 2005, also addresses the subject of this AD.

Material Incorporated by Reference

(q) You must use Rolls-Royce Deutschland Ltd & Co KG Service Bulletin No. SB-BR700-72-900229, Revision 5, dated January 8, 2003; or Revision 6, dated February 23, 2005, to perform the actions required by this AD. The Director of the Federal Register approved the incorporation by reference of Revision 6 of this service bulletin in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. The Director of the Federal Register approved the incorporation by reference of Revision 5 of this service bulletin as of April 28, 2003 (68 FR 17727, April 11, 2003). Contact Rolls-Royce Deutschland Ltd & Co KG, Eschenweg 11, 15827 Blankenfelde-Mahlow, Germany, telephone: 011 (0) 33-7086-1768, fax: 011 49 (0) 33-7086-3356, for a copy of the service information. You can review copies at the FAA, New England Region, Office of the Regional Counsel, 12 New England Executive Park, Burlington, MA; or at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Burlington, Massachusetts, on October 11, 2005.

Ann C. Mollica,

Acting Manager, Engine and Propeller Directorate, Aircraft Certification Service.

[FR Doc. 05-20780 Filed 10-20-05; 8:45 am]

BILLING CODE 4910-13-P

ENVIRONMENTAL PROTECTION AGENCY

40 CFR Part 52 and 81

[R04-OAR-2005-KY-0001-200521(w); FRL-7985-9]

Approval and Promulgation of Implementation Plans and Designation of Areas for Air Quality Planning Purposes; Kentucky; Redesignation of the Clarksville, Kentucky Portion of the Clarksville-Hopkinsville 8-Hour Ozone Nonattainment Area to Attainment for Ozone; Withdrawal of Direct Final Rule

AGENCY: Environmental Protection Agency (EPA).

ACTION: Withdrawal of direct final rule.

SUMMARY: Due to adverse comment, EPA is withdrawing the direct final rule published September 22, 2005, (70 FR 55550) approving the redesignation of the Clarksville-Hopkinsville 8-Hour Ozone Nonattainment Area to Attainment for Ozone. EPA stated in the direct final rule that if EPA received adverse comment by October 24, 2005, the rule would be withdrawn and not take effect. EPA subsequently received adverse comment. EPA will address the comment in a subsequent final action based upon the proposed action also

published on September 22, 2005 (70 FR 55613). EPA will not institute a second comment period on this action.

DATES: The direct final rule is withdrawn as of October 21, 2005.

FOR FURTHER INFORMATION CONTACT: Stacy DiFrank, Air Planning Branch, U.S. Environmental Protection Agency Region 4, 61 Forsyth Street, SW., Atlanta, Georgia 30303-8960. Ms. DiFrank can be reached via phone at (404) 562-9042 or via electronic mail at difrank.stacy@epa.gov.

List of Subjects in 40 CFR Part 52

Environmental protection, Air pollution control, Intergovernmental relations, Ozone, Reporting and recordkeeping requirements, Volatile organic compounds.

Dated: October 4, 2005.

A. Stanley Meiburg,

Acting Regional Administrator, Region 4.

Accordingly, the amendments to 40 CFR 52.919 and 52.920 (which published in the **Federal Register** on September 22, 2005, at 70 FR 55550) is withdrawn as of October 21, 2005.

[FR Doc. 05-20982 Filed 10-20-05; 8:45 am]

BILLING CODE 6560-50-P

ENVIRONMENTAL PROTECTION AGENCY

40 CFR Part 166

[OPP-2004-0038; FRL-7739-6]

RIN 2070-AD36

Pesticides; Emergency Exemption Process Revisions; Notification to the Secretary of Agriculture

AGENCY: Environmental Protection Agency (EPA).

ACTION: Notification to the Secretary of Agriculture.

SUMMARY: This document notifies the public that the Administrator of EPA has forwarded to the Secretary of Agriculture a draft final rule as required by section 25(a) of the Federal Insecticide, Fungicide, and Rodenticide Act (FIFRA). As described in the Agency's semi-annual Regulatory Agenda, the draft final rule will make several improvements to the pesticide emergency exemption process under section 18 of FIFRA. EPA has established regulations under section 18 of FIFRA which allow a Federal or State agency to apply for an emergency exemption to allow an unregistered use of a pesticide for a limited time when such use is necessary to alleviate an emergency condition.