

Issued in Renton, Washington, on April 19, 2007.

Ali Bahrami,

Manager, Transport Airplane Directorate,  
Aircraft Certification Service.

[FR Doc. E7-7979 Filed 4-25-07; 8:45 am]

BILLING CODE 4910-13-P

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. FAA-2007-27680; Directorate Identifier 2007-CE-026-AD]

RIN 2120-AA64

#### Airworthiness Directives; AEROTECHNIC Vertriebs-u. Service GmbH Honeywell CAS67A ACAS II Systems Appliances

**AGENCY:** Federal Aviation Administration (FAA), Department of Transportation (DOT).

**ACTION:** Notice of proposed rulemaking (NPRM).

**SUMMARY:** We propose to adopt a new airworthiness directive (AD) for the products listed above. This proposed AD results from mandatory continuing airworthiness information (MCAI) originated by an aviation authority of another country to identify and correct an unsafe condition on an aviation product. The MCAI describes the unsafe condition as:

It was detected by the STC holder that in earlier installations of the ACASII system there were no isolation diodes installed in the Heading and Attitude Valid lines. The absence of an isolation diode in the valid lines can prevent the valid flag to come up even if a gyro fault exists. The problem has only been detected for Heading Valid lines but could equally affect the Altitude Valid lines.

With installation of the ACASII, the heading and attitude valid lines have to be connected to the TPU67A. On valid state, the signals are +28VDC. On invalid, the signals are open. This condition of direct connection (without an isolation diode installed) of the valid lines to the TPU67A, if not corrected, could cause the TPU67A to feed current into the open stated valid lines. This prevents the flag to appear even if the gyro is invalid, providing the flight crew with erroneous navigation information.

The proposed AD would require actions that are intended to address the unsafe condition described in the MCAI.

**DATES:** We must receive comments on this proposed AD by May 29, 2007.

**ADDRESSES:** You may send comments by any of the following methods:

- **DOT Docket Web Site:** Go to <http://dms.dot.gov> and follow the instructions

for sending your comments electronically.

- **Fax:** (202) 493-2251.
- **Mail:** Docket Management Facility, U.S. Department of Transportation, 400 Seventh Street, SW., Nassif Building, Room PL-401, Washington, DC 20590-0001.
- **Hand Delivery:** Room PL-401 on the plaza level of the Nassif Building, 400 Seventh Street, SW., Washington, DC, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.
- **Federal eRulemaking Portal:** Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.

#### Examining the AD Docket

You may examine the AD docket on the Internet at <http://dms.dot.gov>; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this proposed AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Office (telephone (800) 647-5227) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

**FOR FURTHER INFORMATION CONTACT:** Karl Schletzbaum, Aerospace Engineer, FAA, Small Airplane Directorate, 901 Locust, Room 301, Kansas City, Missouri 64106; telephone: (816) 329-4146; fax: (816) 329-4090.

#### SUPPLEMENTARY INFORMATION:

##### Streamlined Issuance of AD

The FAA is implementing a new process for streamlining the issuance of ADs related to MCAI. This streamlined process will allow us to adopt MCAI safety requirements in a more efficient manner and will reduce safety risks to the public. This process continues to follow all FAA AD issuance processes to meet legal, economic, Administrative Procedure Act, and **Federal Register** requirements. We also continue to meet our technical decision-making responsibilities to identify and correct unsafe conditions on U.S.-certificated products.

This proposed AD references the MCAI and related service information that we considered in forming the engineering basis to correct the unsafe condition. The proposed AD contains text copied from the MCAI and for this reason might not follow our plain language principles.

#### Comments Invited

We invite you to send any written relevant data, views, or arguments about this proposed AD. Send your comments to an address listed under the

**ADDRESSES** section. Include "Docket No. FAA-2007-27680; Directorate Identifier 2007-CE-026-AD" at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this proposed AD. We will consider all comments received by the closing date and may amend this proposed AD because of those comments.

We will post all comments we receive, without change, to <http://dms.dot.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact we receive about this proposed AD.

#### Discussion

The European Aviation Safety Agency (EASA), which is the Technical Agent for the Member States of the European Community, has issued EASA AD No. 2007-0059 dated March 5, 2007 (referred to after this as "the MCAI"), to correct an unsafe condition for the specified products.

The MCAI states:

It was detected by the STC holder that in earlier installations of the ACASII system there were no isolation diodes installed in the Heading and Attitude Valid lines. The absence of an isolation diode in the valid lines can prevent the valid flag to come up even if a gyro fault exists. The problem has only been detected for Heading Valid lines but could equally affect the Attitude Valid lines.

With installation of the ACASII, the heading and attitude valid lines have to be connected to the TPU67A. On valid state, the signals are +28VDC. On invalid, the signals are open. This condition of direct connection (without an isolation diode installed) of the valid lines to the TPU67A, if not corrected, could cause the TPU67A to feed current into the open stated valid lines. This prevents the flag to appear even if the gyro is invalid, providing the flight crew with erroneous navigation information.

For the reasons stated above, this Airworthiness Directive (AD) requires the installation of isolation diodes into the signal lines to the TPU67A to prevent reverse feed of the valid lines.

You may obtain further information by examining the MCAI in the AD docket.

#### Relevant Service Information

Aerotechnic Vertiebs -u. Service GmbH has issued Service Bulletin No. DO228-119780-0104, Revision 2, dated December 21, 2006. The actions described in this service information are intended to correct the unsafe condition identified in the MCAI.

## FAA's Determination and Requirements of the Proposed AD

This product has been approved by the aviation authority of another country, and is approved for operation in the United States. Pursuant to our bilateral agreement with this State of Design Authority, they have notified us of the unsafe condition described in the MCAI and service information referenced above. We are proposing this AD because we evaluated all information and determined the unsafe condition exists and is likely to exist or develop on other products of the same type design.

## Differences Between This Proposed AD and the MCAI or Service Information

We have reviewed the MCAI and related service information and, in general, agree with their substance. But we might have found it necessary to use different words from those in the MCAI to ensure the AD is clear for U.S. operators and is enforceable. In making these changes, we do not intend to differ substantively from the information provided in the MCAI and related service information.

We might also have proposed different actions in this AD from those in the MCAI in order to follow FAA policies. Any such differences are highlighted in a NOTE within the proposed AD.

## Costs of Compliance

The FAA is not aware of any airplanes on the U.S. Registry that have the affected equipment installed. All airplanes with this equipment included in the applicability of this rule currently are operated by non-U.S. operators under foreign registry; therefore, they are not directly affected by this AD action at this time. However, the FAA considers this rule necessary to ensure that the unsafe condition is addressed in the event that any of these subject airplanes are imported and placed on the U.S. Registry.

Should an affected airplane be imported and placed on the U.S. Registry, accomplishment of the required action would take approximately 8 work-hours at an average labor rate of \$80 per work-hour. Required parts would cost about \$50 per product. Where the service information lists required parts costs that are covered under warranty, we have assumed that there will be no charge for these costs. As we do not control warranty coverage for affected parties, some parties may incur costs higher than estimated here.

Based on these figures, the total cost impact of this AD would be \$690 per airplane.

## Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. "Subtitle VII: Aviation Programs," describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in "Subtitle VII, Part A, Subpart III, Section 44701: General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

## Regulatory Findings

We determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

1. Is not a "significant regulatory action" under Executive Order 12866;
2. Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and
3. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared a regulatory evaluation of the estimated costs to comply with this proposed AD and placed it in the AD docket.

## List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

## The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

## PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701.

### § 39.13 [Amended]

2. The FAA amends § 39.13 by adding the following new AD:

**AEROTECHNIC Vertriebs-u. Service GmbH:**  
Docket No. FAA-2007-27680;  
Directorate Identifier 2007-CE-026-AD.

### Comments Due Date

(a) We must receive comments by May 29, 2007.

### Affected ADs

(b) None.

### Applicability

(c) This AD applies to Honeywell CAS67A ACAS II systems that are installed on, but not limited to, DORNIER LUFTFAHRT GmbH Models Dornier 228-100, Dornier 228-101, Dornier 228-200, Dornier 228-201, and Dornier 228-212 airplanes that:

- (1) Had Supplemental Type Certificate No. SA1310 installed prior to January 31, 2005; and
- (2) Are certificated in any category.

### Subject

(d) Air Transport Association of America (ATA) Code 34: Navigation.

### Reason

(e) The mandatory continuing airworthiness information (MCAI) states:

It was detected by the STC holder that in earlier installations of the ACAS II system there were no isolation diodes installed in the Heading and Attitude Valid lines. The absence of an isolation diode in the valid lines can prevent the valid flag to come up even if a gyro fault exists. The problem has only been detected for Heading Valid lines but could equally affect the Attitude Valid lines.

With installation of the ACAS II, the heading and attitude valid lines have to be connected to the TPU67A. On valid state, the signals are +28VDC. On invalid, the signals are open. This condition of direct connection (without an isolation diode installed) of the valid lines to the TPU67A, if not corrected, could cause the TPU67A to feed current into the open stated valid lines. This prevents the flag to appear even if the gyro is invalid, providing the flight crew with erroneous navigation information.

For the reasons stated above, this Airworthiness Directive (AD) requires the installation of isolation diodes into the signal lines to the TPU67A to prevent reverse feed of the valid lines.

### Actions and Compliance

(f) Unless already done, within 100 flight hours time-in-service (TIS) after the effective date of this AD, modify the Honeywell CAS67A ACAS II System Installation following Aerotechnic Service Bulletin No. DO228-119780-0104, Revision 2, dated December 21, 2006.

**FAA AD Differences**

**Note:** This AD differs from the MCAI and/or service information as follows: No differences.

**Other FAA AD Provisions**

(g) The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs):* The Manager, Standards Staff, FAA, ATTN: Karl Schletzbaum, Aerospace Engineer, FAA, Small Airplane Directorate, 901 Locust, Room 301, Kansas City, Missouri 64106; telephone: (816) 329-4146; fax: (816) 329-4090, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. Before using any approved AMOC on any airplane to which the AMOC applies, notify your appropriate principal inspector (PI) in the FAA Flight Standards District Office (FSDO), or lacking a PI, your local FSDO.

(2) *Airworthy Product:* For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they are approved by the State of Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

(3) *Reporting Requirements:* For any reporting requirement in this AD, under the provisions of the Paperwork Reduction Act (44 U.S.C. 3501 et seq.), the Office of Management and Budget (OMB) has approved the information collection requirements and has assigned OMB Control Number 2120-0056.

**Related Information**

(h) Refer to MCAI European Aviation Safety Agency (EASA) AD No. 2007-0059, dated March 5, 2007; and Service Bulletin No. DO228-119780-0104 Revision 2, dated December 21, 2006, for related information.

Issued in Kansas City, Missouri, on April 20, 2007.

**Charles L. Smalley,**

*Acting Manager, Small Airplane Directorate, Aircraft Certification Service.*

[FR Doc. E7-7993 Filed 4-25-07; 8:45 am]

**BILLING CODE 4910-13-P**

**DEPARTMENT OF TRANSPORTATION****Federal Aviation Administration****14 CFR Part 39**

[Docket No. FAA-2007-28015; Directorate Identifier 2006-NM-210-AD]

**RIN 2120-AA64**

**Airworthiness Directives; Boeing Model 747-100, 747-100B, 747-100B SUD, 747-200B, 747-200C, 747-300, 747-400, 747-400D, and 747SR Series Airplanes**

**AGENCY:** Federal Aviation Administration (FAA), Department of Transportation (DOT).

**ACTION:** Notice of proposed rulemaking (NPRM).

**SUMMARY:** The FAA proposes to supersede an existing airworthiness directive (AD) that applies to all Boeing Model 747-100, 747-100B, 747-100B SUD, 747-200B, 747-200C, 747-300, 747-400, 747-400D, and 747SR series airplanes. The existing AD currently requires repetitive inspections for cracking of the station 800 frame assembly, and repair if necessary. This proposed AD would revise certain applicabilities and compliance times in the existing AD. This proposed AD results from several reports of cracks of the station 800 frame assembly on airplanes that had accumulated fewer total flight cycles than the initial inspection threshold in the original AD. We are proposing this AD to detect and correct fatigue cracks that could extend and fully sever the frame, which could result in development of skin cracks that could lead to rapid depressurization of the airplane.

**DATES:** We must receive comments on this proposed AD by June 11, 2007.

**ADDRESSES:** Use one of the following addresses to submit comments on this proposed AD.

- *DOT Docket Web site:* Go to <http://dms.dot.gov> and follow the instructions for sending your comments electronically.

- *Government-wide rulemaking Web site:* Go to <http://www.regulations.gov> and follow the instructions for sending your comments electronically.

- *Mail:* Docket Management Facility; U.S. Department of Transportation, 400 Seventh Street, SW., Nassif Building, Room PL-401, Washington, DC 20590.

- *Fax:* (202) 493-2251.

- *Hand Delivery:* Room PL-401 on the plaza level of the Nassif Building, 400 Seventh Street, SW., Washington, DC, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

Contact Boeing Commercial Airplanes, P.O. Box 3707, Seattle, Washington 98124-2207, for service information identified in this proposed AD.

**FOR FURTHER INFORMATION CONTACT:** Ivan Li, Aerospace Engineer, Airframe Branch, ANM-120S, FAA, Seattle Aircraft Certification Office, 1601 Lind Avenue, SW., Renton, Washington 98057-3356; telephone (425) 917-6437; fax (425) 917-6590.

**SUPPLEMENTARY INFORMATION:****Comments Invited**

We invite you to submit any relevant written data, views, or arguments regarding this proposed AD. Send your

comments to an address listed in the **ADDRESSES** section. Include the docket number "Docket No. FAA-2007-28015; Directorate Identifier 2006-NM-210-AD" at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of the proposed AD. We will consider all comments received by the closing date and may amend the proposed AD in light of those comments.

We will post all comments we receive, without change, to <http://dms.dot.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact with FAA personnel concerning this proposed AD. Using the search function of that Web site, anyone can find and read the comments in any of our dockets, including the name of the individual who sent the comment (or signed the comment on behalf of an association, business, labor union, etc.). You may review the DOT's complete Privacy Act Statement in the **Federal Register** published on April 11, 2000 (65 FR 19477-78), or may can visit <http://dms.dot.gov>.

**Examining the Docket**

You may examine the AD docket on the Internet at <http://dms.dot.gov>, or in person at the Docket Management Facility office between 9 a.m. and 5 p.m. Monday through Friday, except Federal holidays. The Docket Management Facility office (telephone (800) 647-5227) is located on the plaza level of the Nassif Building at the DOT street address stated in the **ADDRESSES** section. Comments will be available in the AD docket shortly after the Docket Management System receives them.

**Discussion**

On May 31, 2006, we issued AD 2006-12-12, amendment 39-14638 (71 FR 33595, June 12, 2006), for all Boeing Model 747-100, 747-100B, 747-100B SUD, 747-200B, 747-200C, 747-300, 747-400, 747-400D, and 747SR series airplanes. That AD requires repetitive inspections for cracking of the station 800 frame assembly, and repair if necessary. That AD resulted from several reports of cracks of the station 800 frame assembly on airplanes that had accumulated fewer total flight cycles than the initial inspection threshold in an existing AD that AD 2006-12-12 superseded. We issued AD 2006-12-12 to detect and correct fatigue cracks that could extend and fully sever the frame, which could result in development of skin cracks that could