

Subject

(g) Air Transport Association of America (ATA) Code: 2913 Hydraulic Pump.

Other Information

(h) The Manager, Safety Management Group, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. Send information to ATTN: Uday Garadi, Aviation Safety Engineer, Rotorcraft Directorate, Regulations and Guidance Group, Fort Worth, Texas 76193-0110, telephone (817) 222-5123, fax (817) 222-5961.

Related Information

(i) MCAI Airworthiness Directive No. F-2007-010, dated September 12, 2007, contains related information.

Material Incorporated by Reference

(j) You must use the specified portions of Eurocopter France Emergency Alert Service Bulletin 01.00.73, dated August 23, 2007, to do the actions required.

(1) The Director of the Federal Register approved the incorporation by reference of this service information under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) For service information identified in this AD, contact American Eurocopter Corporation, 2701 Forum Drive, Grand Prairie, TX 75053-4005, telephone (972) 641-3460, fax (972) 641-3527, or at <http://www.eurocopter.com>.

(3) You may review copies at the FAA, Rotorcraft Directorate, Fort Worth, Texas 76193-0112; or at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call (202) 741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Fort Worth, Texas, on September 30, 2008.

Scott A. Horn,

Acting Manager, Rotorcraft Directorate, Aircraft Certification Service.

[FR Doc. E8-24987 Filed 10-30-08; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION**Federal Aviation Administration****14 CFR Part 39**

[Docket No. FAA-2008-0623; Directorate Identifier 2008-NM-089-AD; Amendment 39-15699; AD 2008-22-04]

RIN 2120-AA64

Airworthiness Directives; Bombardier Model CL-600-2C10 (Regional Jet Series 700, 701, & 702), CL-600-2D15 (Regional Jet Series 705), and CL-600-2D24 (Regional Jet Series 900) Airplanes

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Final rule.

SUMMARY: We are superseding an existing airworthiness directive (AD) for the products listed above. This AD results from mandatory continuing airworthiness information (MCAI) originated by an aviation authority of another country to identify and correct an unsafe condition on an aviation product. The MCAI describes the unsafe condition as:

Bombardier Aerospace has completed a system safety review of the aircraft fuel system against fuel tank safety standards * * *.

[A]ssessment showed that supplemental maintenance tasks [for the fuel tank wiring harness installation, and the hydraulic system No. 3 temperature transducer, among other items] are required to prevent potential ignition sources inside the fuel system, which could result in a fuel tank explosion. * * *

We are issuing this AD to require actions to correct the unsafe condition on these products.

DATES: This AD becomes effective December 5, 2008.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in this AD as of December 5, 2008.

The Director of the Federal Register approved the incorporation by reference of Section 3, "Fuel System Limitations," of Part 2 of Bombardier CL-600-2C10, CL-600-2D15, and CL-600-2D24 Maintenance Requirements Manual CSP B-053, Revision 9, dated July 20, 2007, listed in this AD, as of April 16, 2008 (73 FR 13098, March 12, 2008).

ADDRESSES: You may examine the AD docket on the Internet at <http://www.regulations.gov> or in person at the U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue, SE., Washington, DC.

FOR FURTHER INFORMATION CONTACT:

Rocco Viselli, Aerospace Engineer, Airframe and Propulsion Branch, ANE-171, FAA, New York Aircraft Certification Office, 1600 Stewart Avenue, Suite 410, Westbury, New York 11590; telephone (516) 228-7331; fax (516) 794-5531.

SUPPLEMENTARY INFORMATION:**Discussion**

We issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 to include an AD that would apply to the specified products. That NPRM was published in the **Federal Register** on June 9, 2008 (73 FR 32486) and proposed to supersede AD 2008-06-01, Amendment 39-15413 (73 FR

13098, March 12, 2008). That NPRM proposed to correct an unsafe condition for the specified products. The MCAI states:

Bombardier Aerospace has completed a system safety review of the aircraft fuel system against fuel tank safety standards introduced in Chapter 525 of the Airworthiness Manual through Notice of Proposed Amendment (NPA) 2002-043. The identified non-compliances were then assessed using Transport Canada Policy Letter No. 525-001, to determine if mandatory corrective action is required.

The assessment showed that supplemental maintenance tasks [for the fuel tank wiring harness installation, and the hydraulic system No. 3 temperature transducer, among other items] are required to prevent potential ignition sources inside the fuel system, which could result in a fuel tank explosion. Revision has been made to Canadair Regional Jet Models CL-600-2C10, CL-600-2D15 and CL-600-2D24 Maintenance Requirements Manual, CSP B-053, Part 2, Section 3 "Fuel System Limitations" to introduce the required maintenance tasks.

The corrective action is revising the Airworthiness Limitations Section (ALS) of the Instructions for Continued Airworthiness to incorporate new limitations for fuel tank systems. You may obtain further information by examining the MCAI in the AD docket.

Comments

We gave the public the opportunity to participate in developing this AD. We received no comments on the NPRM or on the determination of the cost to the public.

Remove References to Later Revisions

We removed the references to "later revisions" of the applicable service information in paragraphs (f) and (g)(2) of this AD to be consistent with FAA policy and Office of the Federal Register regulations. We may consider approving the use of later revisions of the service information as an alternative method of compliance with this AD, as provided by paragraph (h)(1) of this AD.

New Service Information

We received Revision 10, dated March 20, 2008, of Section 3, "Fuel System Limitations," of Part 2 of Bombardier CL-600-2C10, CL-600-2D15, and CL-600-2D24 maintenance requirements manual CSP B-053. The tasks specified in Revision 10 of the Maintenance Requirements Manual (MRM) are essentially the same as those in the previous revision of the MRM cited in the NPRM. We have revised paragraphs (f) and (g)(1) of the AD to reference Revisions 9 and 10 of the MRM.

Conclusion

We reviewed the available data, and determined that air safety and the public interest require adopting the AD with the changes described previously. We determined that these changes will not increase the economic burden on any operator or increase the scope of the AD.

Differences Between This AD and the MCAI or Service Information

We have reviewed the MCAI and related service information and, in general, agree with their substance. But we might have found it necessary to use different words from those in the MCAI to ensure the AD is clear for U.S. operators and is enforceable. In making these changes, we do not intend to differ substantively from the information provided in the MCAI and related service information.

We might also have required different actions in this AD from those in the MCAI in order to follow our FAA policies. Any such differences are highlighted in a Note within the AD.

Costs of Compliance

We estimate that this AD will affect about 289 products of U.S. registry. We also estimate that it will take about 1 work-hour per product to comply with the basic requirements of this AD. The average labor rate is \$80 per work-hour. Based on these figures, we estimate the cost of this AD to the U.S. operators to be \$23,120, or \$80 per product.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. "Subtitle VII: Aviation Programs," describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in "Subtitle VII, Part A, Subpart III, Section 44701: General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We determined that this AD will not have federalism implications under Executive Order 13132. This AD will

not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this AD:

1. Is not a "significant regulatory action" under Executive Order 12866;
2. Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and
3. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared a regulatory evaluation of the estimated costs to comply with this AD and placed it in the AD docket.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov>; or in person at the Docket Operations office between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains the NPRM, the regulatory evaluation, any comments received, and other information. The street address for the Docket Operations office (telephone (800) 647-5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

■ Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

■ 2. The FAA amends § 39.13 by removing Amendment 39-15413 (73 FR 13098, March 12, 2008) and adding the following new AD:

2008-22-04 Bombardier, Inc. (Formerly Canadair): Amendment 39-15699. Docket No. FAA-2008-0623; Directorate Identifier 2008-NM-089-AD.

Effective Date

(a) This airworthiness directive (AD) becomes effective December 5, 2008.

Affected ADs

(b) This AD supersedes AD 2008-06-01, Amendment 39-15413.

Applicability

(c) This AD applies to all Bombardier Model CL-600-2C10 (Regional Jet Series 700, 701, & 702), CL-600-2D15 (Regional Jet Series 705), and CL-600-2D24 (Regional Jet Series 900) airplanes, certificated in any category, all serial numbers.

Note 1: This AD requires revisions to certain operator maintenance documents to include new inspections. Compliance with these inspections is required by 14 CFR 91.403(c). For airplanes that have been previously modified, altered, or repaired in the areas addressed by these inspections, the operator may not be able to accomplish the inspections described in the revisions. In this situation, to comply with 14 CFR 91.403(c), the operator must request approval for an alternative method of compliance according to paragraph (h)(1) of this AD. The request should include a description of changes to the required inspections that will ensure the continued operational safety of the airplane.

Subject

(d) Air Transport Association (ATA) of America Code 28: Fuel.

Reason

(e) The mandatory continuing airworthiness information (MCAI) states:

Bombardier Aerospace has completed a system safety review of the aircraft fuel system against fuel tank safety standards introduced in Chapter 525 of the Airworthiness Manual through Notice of Proposed Amendment (NPA) 2002-043. The identified non-compliances were then assessed using Transport Canada Policy Letter No. 525-001, to determine if mandatory corrective action is required.

The assessment showed that supplemental maintenance tasks [for the fuel tank wiring harness installation, and the hydraulic system No. 3 temperature transducer, among other items] are required to prevent potential ignition sources inside the fuel system, which could result in a fuel tank explosion. Revision has been made to Canadair Regional Jet Models CL-600-2C10, CL-600-2D15 and CL-600-2D24 Maintenance Requirements Manual, CSP B-053, Part 2, Section 3 "Fuel System Limitations" to introduce the required maintenance tasks.

The corrective action is revising the Airworthiness Limitations Section (ALS) of the Instructions for Continued Airworthiness to incorporate new limitations for fuel tank systems.

Restatement of Certain Requirements of AD 2008-06-01

(f) Unless already done, within 60 days after April 16, 2008 (the effective date of AD 2008-06-01), revise the ALS of the Instructions for Continued Airworthiness to incorporate the inspection requirements in Section 3, "Fuel System Limitations," of Part 2 of Bombardier CL-600-2C10, CL-600-2D15, and CL-600-2D24 Maintenance Requirements Manual CSP B-053, Revision

9, dated July 20, 2007; or Revision 10, dated March 20, 2008.

New Requirements of This AD: Actions and Compliance

(g) Unless already done, do the following actions.

(1) For task numbers 24–90–00–601, 24–90–00–602, 28–00–00–601, 28–11–23–601, 28–11–23–602, 28–12–13–601, 29–30–00–

601, and 29–30–00–602 identified in Section 3, “Fuel System Limitations,” of Part 2 of Bombardier CL–600–2C10, CL–600–2D15, and CL–600–2D24 Maintenance Requirements Manual CSP B–053, Revision 9, dated July 20, 2007; or Revision 10, dated March 20, 2008: The initial compliance times start at the later of the applicable “Threshold” and “Grace Period” times specified in Table 1 of this AD, and the

repetitive limitation tasks must be accomplished thereafter at the applicable interval specified in Revision 9 or Revision 10 of the Bombardier CL–600–2C10, CL–600–2D15, and CL–600–2D24 Maintenance Requirements Manual CSP B–053, except as provided by paragraph (g)(2) and (h)(1) of this AD.

TABLE 1—INITIAL INSPECTIONS

Description	Compliance time (whichever occurs later)	
	Threshold	Grace period
Tasks with limiting intervals of 8,000 flight hours.	Before the accumulation of 8,000 total flight hours.	Within 2,000 flight hours after the effective date of this AD.
Tasks with limiting intervals of 20,000 flight hours.	Before the accumulation of 20,000 total flight hours.	Within 6,000 flight hours after the effective date of this AD.
Tasks with limiting intervals of 30,000 flight hours.	Before the accumulation of 30,000 total flight hours.	Within 6,000 flight hours after the effective date of this AD.

(2) After accomplishing the actions specified in paragraph (g)(1) of this AD, no alternative inspections/limitation tasks or inspection/limitation task intervals may be used unless the inspection/limitation task or inspection/limitation task interval is approved as an alternative method of compliance (AMOC) in accordance with the procedures specified in paragraph (h)(1) of this AD.

FAA AD Differences

Note 2: This AD differs from the MCAI and/or service information as follows: No differences.

Other FAA AD Provisions

(h) The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs):* The Manager, New York Aircraft Certification Office, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. Send information to ATTN: Rocco Viselli, Aerospace Engineer, Airframe and Propulsion Branch, ANE–171, FAA, New York ACO, 1600 Stewart Avenue, Suite 410, Westbury, New York 11590; telephone (516) 228–7331; fax (516) 794–5531. Before using any approved AMOC on any airplane to which the AMOC applies, notify your appropriate principal inspector (PI) in the FAA Flight Standards District Office (FSDO), or lacking a PI, your local FSDO.

(2) *Airworthy Product:* For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they are approved by the State of Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

(3) *Reporting Requirements:* For any reporting requirement in this AD, under the provisions of the Paperwork Reduction Act, the Office of Management and Budget (OMB) has approved the information collection requirements and has assigned OMB Control Number 2120–0056.

Related Information

(i) Refer to MCAI Canadian Airworthiness Directive CF–2007–28, dated November 22, 2007; and Section 3, “Fuel System Limitations,” of Part 2 of Bombardier CL–600–2C10, CL–600–2D15, and CL–600–2D24 Maintenance Requirements Manual CSP B–053, Revision 9, dated July 20, 2007; or Revision 10, dated March 20, 2008; for related information.

Material Incorporated by Reference

(j) You must use Section 3, “Fuel System Limitations,” of Part 2 of Bombardier CL–600–2C10, CL–600–2D15, and CL–600–2D24 Maintenance Requirements Manual CSP B–053, Revision 9, dated July 20, 2007; or Section 3, “Fuel System Limitations,” of Part 2 of Bombardier CL–600–2C10, CL–600–2D15, and CL–600–2D24 Maintenance Requirements Manual CSP B–053, Revision 10, dated March 20, 2008; to do the actions required by this AD, unless the AD specifies otherwise.

(1) The Director of the Federal Register approved the incorporation by reference of Section 3, “Fuel System Limitations,” of Part 2 of Bombardier CL–600–2C10, CL–600–2D15, and CL–600–2D24 Maintenance Requirements Manual CSP B–053, Revision 10, dated March 20, 2008, under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) The Director of the Federal Register previously approved the incorporation by reference of Section 3, “Fuel System Limitations,” of Part 2 of Bombardier CL–600–2C10, CL–600–2D15, and CL–600–2D24 Maintenance Requirements Manual CSP B–053, Revision 9, dated July 20, 2007, on April 16, 2008 (73 FR 13098, March 12, 2008).

(3) For service information identified in this AD, contact Bombardier, Inc., 400 Côte-Vertu Road West, Dorval, Québec H4S 1Y9, Canada; telephone 514–855–5000; fax 514–855–7401; e-mail thd.crj@aero.bombardier.com; Internet <http://www.bombardier.com>.

(4) You may review copies at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the National Archives and Records

Administration (NARA). For information on the availability of this material at NARA, call (202) 741–6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on October 9, 2008.

Ali Bahrami,

Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. E8–25302 Filed 10–30–08; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA–2007–27628; Directorate Identifier 2007–CE–025–AD; Amendment 39–15713; AD 2007–07–06 R1]

RIN 2120–AA64

Airworthiness Directives; Cessna Aircraft Company (Type Certificate Previously Held by Columbia Aircraft Manufacturing) Models LC40–550FG, LC41–550FG, and LC42–550FG Airplanes

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Final rule.

SUMMARY: We are adopting a new airworthiness directive (AD) to revise AD 2007–07–06, which applies to certain Cessna Aircraft Company (type certificate previously held by Columbia Aircraft Manufacturing) (Cessna) Models LC40–550FG, LC41–550FG, and LC42–550FG airplanes. AD 2007–07–06 currently requires the following: Adding information to the limitations section of