

availability of this material at the FAA, call 425–227–1221.

Issued in Renton, Washington, on March 1, 2012.

**Jeffrey E. Duven,**

*Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.*

[FR Doc. 2012–6470 Filed 3–15–12; 8:45 am]

**BILLING CODE 4910–13–P**

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. FAA–2012–0192; Directorate Identifier 2011–NM–225–AD]

**RIN 2120–AA64**

#### Airworthiness Directives; Airbus Airplanes

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Notice of proposed rulemaking (NPRM).

**SUMMARY:** We propose to adopt a new airworthiness directive (AD) for certain Airbus Model A330–200 and –200 freighter series airplanes; and Model A340–200, –300, –500, and –600 series airplanes. This proposed AD was prompted by fuel system reviews conducted by the manufacturer. This proposed AD would require modification of the control circuit for the fuel pumps for the center fuel tanks for certain airplanes, and center and rear fuel tanks for certain other airplanes. We are proposing this AD to prevent the potential of ignition sources inside fuel tanks, which, in combination with flammable fuel vapors, could result in fuel tank explosions and consequent loss of the airplane.

**DATES:** We must receive comments on this proposed AD by April 30, 2012.

**ADDRESSES:** You may send comments by any of the following methods:

- *Federal eRulemaking Portal:* Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.

- *Fax:* (202) 493–2251.

- *Mail:* U.S. Department of Transportation, Docket Operations, M–30, West Building Ground Floor, Room W12–140, 1200 New Jersey Avenue SE., Washington, DC 20590.

- *Hand Delivery:* U.S. Department of Transportation, Docket Operations, M–30, West Building Ground Floor, Room W12–140, 1200 New Jersey Avenue SE., Washington, DC, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this proposed AD, contact Airbus SAS—Airworthiness Office—EAL, 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France; telephone +33 5 61 93 36 96; fax +33 5 61 93 45 80; email [airworthiness.A330-A340@airbus.com](mailto:airworthiness.A330-A340@airbus.com); Internet <http://www.airbus.com>. You may review copies of the referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, Washington. For information on the availability of this material at the FAA, call 425–227–1221.

#### Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov>; or in person at the Docket Operations office between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this proposed AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Operations office (telephone (800) 647–5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

#### FOR FURTHER INFORMATION CONTACT:

Vladimir Ulyanov, Aerospace Engineer, International Branch, ANM–116, Transport Airplane Directorate, FAA, 1601 Lind Avenue SW., Renton, Washington 98057–3356; telephone 425–227–1138; fax 425–227–1149.

#### SUPPLEMENTARY INFORMATION:

##### Comments Invited

We invite you to send any written relevant data, views, or arguments about this proposed AD. Send your comments to an address listed under the **ADDRESSES** section. Include “Docket No. FAA–2012–0192; Directorate Identifier 2011–NM–225–AD” at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this proposed AD. We will consider all comments received by the closing date and may amend this proposed AD based on those comments.

We will post all comments we receive, without change, to <http://www.regulations.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact we receive about this proposed AD.

#### Discussion

The European Aviation Safety Agency (EASA), which is the Technical Agent for the Member States of the European Community, has issued EASA Airworthiness Directive 2011–0196,

dated October 7, 2011 (referred to after this as “the MCAI”), to correct an unsafe condition for the specified products. The MCAI states:

\* \* \* [T]he FAA issued a set of new rules related to Fuel Tank Safety including Special Federal Aviation Regulation (SFAR) 88. In line with SFAR88, the JAA [Joint Aviation Authorities] issued policy JAA INT/POL 25/12 and recommended to the National Aviation Authorities (NAA) the application of a similar regulation.

To ensure compliance with the requirements set by SFAR88 and JAA INT/POL 25/12, this [EASA] AD requires that Ground Fault Interrupters (GFI) are installed into the electrical power supply circuits of fuel pumps for which the canisters become uncovered during normal operation, taking into account normal fuel reserve or the fuel level, triggering the low fuel level warning.

The function of this additional system protection is to electrically isolate the pump if a ground fault condition occurs downstream of the GFI. The GFI gives additional earth leakage protection to the downstream circuit.

The unsafe condition is the potential of ignition sources inside fuel tanks, which, in combination with flammable fuel vapors, could result in fuel tank explosions and consequent loss of the airplane. The corrective action is modifying the control circuits of the fuel pump for the rear and center fuel tanks. You may obtain further information by examining the MCAI in the AD docket.

The FAA has examined the underlying safety issues involved in fuel tank explosions on several large transport airplanes, including the adequacy of existing regulations, the service history of airplanes subject to those regulations, and existing maintenance practices for fuel tank systems. As a result of those findings, we issued a regulation titled “Transport Airplane Fuel Tank System Design Review, Flammability Reduction and Maintenance and Inspection Requirements” (66 FR 23086, May 7, 2001). In addition to new airworthiness standards for transport airplanes and new maintenance requirements, this rule included Special Federal Aviation Regulation No. 88 (“SFAR 88,” Amendment 21–78, and subsequent Amendments 21–82 and 21–83).

Among other actions, SFAR 88 (66 FR 23086, May 7, 2001) requires certain type design (i.e., type certificate (TC) and supplemental type certificate (STC)) holders to substantiate that their fuel tank systems can prevent ignition sources in the fuel tanks. This requirement applies to type design holders for large turbine-powered transport airplanes and for subsequent modifications to those airplanes. It requires them to perform design reviews

and to develop design changes and maintenance procedures if their designs do not meet the new fuel tank safety standards. As explained in the preamble to the rule, we intended to adopt airworthiness directives to mandate any changes found necessary to address unsafe conditions identified as a result of these reviews.

In evaluating these design reviews, we have established four criteria intended to define the unsafe conditions associated with fuel tank systems that require corrective actions. The percentage of operating time during which fuel tanks are exposed to flammable conditions is one of these criteria. The other three criteria address the failure types under evaluation: single failures, single failures in combination with a latent condition(s), and in-service failure experience. For all four criteria, the evaluations included consideration of previous actions taken that may mitigate the need for further action.

The Joint Aviation Authorities (JAA) has issued a regulation that is similar to SFAR 88 (66 FR 23086, May 7, 2001). (The JAA is an associated body of the European Civil Aviation Conference (ECAC) representing the civil aviation regulatory authorities of a number of European States who have agreed to co-operate in developing and implementing common safety regulatory standards and procedures.) Under this regulation, the JAA stated that all members of the ECAC that hold type certificates for transport category airplanes are required to conduct a design review against explosion risks.

We have determined that the actions identified in this proposed AD are necessary to reduce the potential of ignition sources inside fuel tanks, which, in combination with flammable fuel vapors, could result in fuel tank explosions and consequent loss of the airplane.

#### Relevant Service Information

Airbus has issued the following mandatory service bulletins. The actions described in this service information are intended to correct the unsafe condition identified in the MCAI.

- Airbus Mandatory Service Bulletin A330–28–3113, dated July 19, 2011 (for Model A330–200 and –200 freighter series airplanes).
- Airbus Mandatory Service Bulletin A340–28–4129, dated July 19, 2011 (for Model A340–200 and –300 series airplanes).
- Airbus Mandatory Service Bulletin A340–28–5051, dated September 1, 2011 (for Model A340–500 and –600 series airplanes).

#### FAA's Determination and Requirements of This Proposed AD

This product has been approved by the aviation authority of another country, and is approved for operation in the United States. Pursuant to our bilateral agreement with the State of Design Authority, we have been notified of the unsafe condition described in the MCAI and service information referenced above. We are proposing this AD because we evaluated all pertinent information and determined an unsafe condition exists and is likely to exist or develop on other products of the same type design.

#### Costs of Compliance

Based on the service information, we estimate that this proposed AD would affect about 29 products of U.S. registry. We also estimate that it would take about 10 work-hours per product to comply with the basic requirements of this proposed AD. The average labor rate is \$85 per work-hour. Required parts would cost about \$3,480 per product. Where the service information lists required parts costs that are covered under warranty, we have assumed that there will be no charge for these parts. As we do not control warranty coverage for affected parties, some parties may incur costs higher than estimated here. Based on these figures, we estimate the cost of the proposed AD on U.S. operators to be \$125,570, or \$4,330 per product.

#### Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. "Subtitle VII: Aviation Programs," describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in "Subtitle VII, Part A, Subpart III, Section 44701: General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

#### Regulatory Findings

We determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a

substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

*For the reasons discussed above, I certify this proposed regulation:*

1. Is not a "significant regulatory action" under Executive Order 12866;
2. Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979);
3. Will not affect intrastate aviation in Alaska; and
4. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared a regulatory evaluation of the estimated costs to comply with this proposed AD and placed it in the AD docket.

#### List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

#### The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

#### PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701.

#### § 39.13 [Amended]

2. The FAA amends § 39.13 by adding the following new AD:

**Airbus:** Docket No. FAA–2012–0192; Directorate Identifier 2011–NM–225–AD.

#### (a) Comments Due Date

We must receive comments by April 30, 2012.

#### (b) Affected ADs

None.

#### (c) Applicability

This AD applies to the airplanes specified in paragraphs (c)(1), (c)(2), and (c)(3) of this AD, certificated in any category.

(1) Airbus Model A330–201, –202, –203, –223, and –243 airplanes; all serial numbers; except those on which Airbus modification 200242 has been accomplished in production.

(2) Airbus Model A330–223F and –243F airplanes; all serial numbers; except airplanes on which Airbus modification 58623 has been accomplished in production and on which Airbus modification 200281 has not been accomplished in production; and airplanes on which modification 200242 has been accomplished in production.

(3) Airbus Model A340–211, –212, –213, –311, –312, –313, –541, and –642 airplanes; all serial numbers; except airplanes on which Airbus modification 200242 has been accomplished in production.

**(d) Subject**

Air Transport Association (ATA) of America Code 28: Fuel.

**(e) Reason**

This AD was prompted by fuel system reviews conducted by the manufacturer. We are issuing this AD to prevent the potential of ignition sources inside fuel tanks, which, in combination with flammable fuel vapors, could result in fuel tank explosions and consequent loss of the airplane.

**(f) Compliance**

You are responsible for having the actions required by this AD performed within the compliance times specified, unless the actions have already been done.

**(g) Actions**

Within 48 months after the effective date of this AD, do the actions specified in paragraph (g)(1) or (g)(2) of this AD, as applicable.

(1) For Model A330–200 and –200F series airplanes, and Model A340–200 and –300 series airplanes: Modify the control circuit for the fuel pump for the center fuel tank, in accordance with the Accomplishment Instructions of Airbus Mandatory Service Bulletin A330–28–3113, dated July 19, 2011 (for Model A330–200 and –200 freighter series airplanes); or A340–28–4129, dated July 19, 2011 (for Model A340–200 and –300 series airplanes).

(2) For Model A340–500 and –600 series airplanes: Modify the control circuit for the fuel pump for the rear and/or center fuel tanks, in accordance with the Accomplishment Instructions of Airbus Mandatory Service Bulletin A340–28–5051, dated September 1, 2011.

**(h) Other FAA AD Provisions**

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs)*: The Manager, International Branch, ANM–116, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the International Branch, send it to ATTN: Vladimir Ulyanov, Aerospace Engineer, International Branch, ANM–116, Transport Airplane Directorate, FAA, 1601 Lind Avenue SW., Renton, Washington 98057–3356; telephone 425–227–1138; fax 425–227–1149. Information may be emailed to: 9-ANM-116-AMOC-REQUESTS@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or

lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office. The AMOC approval letter must specifically reference this AD.

(2) *Airworthy Product*: For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they are approved by the State of Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

**(i) Related Information**

Refer to MCAI European Aviation Safety Agency (EASA) Airworthiness Directive 2011–0196, dated October 7, 2011, and the service bulletins specified in paragraphs (i)(1), (i)(2), and (i)(3) of this AD, for related information.

(1) Airbus Mandatory Service Bulletin A330–28–3113, dated July 19, 2011.

(2) Airbus Mandatory Service Bulletin A340–28–4129, dated July 19, 2011.

(3) Airbus Mandatory Service Bulletin A340–28–5051, dated September 1, 2011.

Issued in Renton, Washington, on March 1, 2012.

**Jeffrey E. Duven,**

*Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.*

[FR Doc. 2012–6461 Filed 3–15–12; 8:45 am]

**BILLING CODE 4910–13–P**

## DEPARTMENT OF THE TREASURY

### Internal Revenue Service

#### 26 CFR Part 1

[REG–168745–03]

RIN 1545–BE18

#### Guidance Regarding Deduction and Capitalization of Expenditures Related to Tangible Property; Hearing

**AGENCY:** Internal Revenue Service (IRS), Treasury.

**ACTION:** Change date of public hearing on proposed rulemaking.

**SUMMARY:** This document changes the date of a public hearing on proposed regulations relating to the deduction and capitalization of expenditures related to tangible property.

**DATES:** The public hearing originally scheduled for Wednesday, April 25, 2012, at 10 a.m. is rescheduled for Wednesday, May 9, 2012, at 10 a.m. Written or electronically submitted public comments along with requests to

speak and outlines of topics to be discussed at the public hearing must be received by Tuesday, April 17, 2012.

**ADDRESSES:** The public hearing is being held in the auditorium of the Internal Revenue Service Building, 1111 Constitution Avenue NW., Washington, DC 20224.

Due to building security procedures, visitors must enter at the Constitution Avenue entrance. Send submissions to: CC:PA:LPD:PR (REG–168745–03); Room 5203, Internal Revenue Service, POB 7604, Ben Franklin Station, Washington, DC. Submissions may be hand delivered Monday through Friday between the hours of 8 a.m. and 4 p.m. to CC:PA:LPD:PR (REG–168745–03) Courier's Desk, Internal Revenue Service, 1111 Constitution Avenue NW., Washington, DC. Alternatively, comments may be transmitted electronically via the Federal eRulemaking Portal at [www.regulations.gov](http://www.regulations.gov). (IRS–REG–168745–03).

**FOR FURTHER INFORMATION CONTACT:** Funmi Taylor of the Publications and Regulations Branch, Legal Processing Division, Associate Chief Counsel (Procedures and Administration), at (202) 622–7180 (not a toll-free number).

**SUPPLEMENTARY INFORMATION:** A notice of change date of public hearing on proposed rulemaking appearing in the *Federal Register* on Monday, January 23, 2012 (77 FR 3210), announced that a public hearing relating to the deduction and capitalization of expenditures related to tangible property, would be held on Wednesday, April 25, 2012 at 10 a.m., in the auditorium of the Internal Revenue Service Building, 1111 Constitution Avenue NW., Washington, DC.

The date of the public hearing has been changed. The hearing is now scheduled for Wednesday, May 9, 2012, beginning at 10 a.m. in the auditorium of the Internal Revenue Service Building at 1111 Constitution Avenue NW., Washington, DC. Requests to speak and outlines of topics to be discussed at the public hearing must be received by Tuesday, April 17, 2012.

**LaNita Van Dyke,**

*Chief, Publications and Regulations Branch, Legal Processing Division, Associate Chief Counsel, (Procedures and Administration).*

[FR Doc. 2012–6371 Filed 3–15–12; 8:45 am]

**BILLING CODE 4830–01–P**