that the prescribed acceptance criteria will not be met—finds that those acceptance criteria will be met, and the Commission or the appropriate director thereafter is able to make the finding that those acceptance criteria are met; and

(4) Notwithstanding the pendency of a petition for reconsideration under 10 CFR 2.345, a petition for review under 10 CFR 2.341, or a motion for stay under 10 CFR 2.342, or the filing of a petition under 10 CFR 2.206.

PART 52—LICENSES, CERTIFICATIONS, AND APPROVALS FOR NUCLEAR POWER PLANTS

■ 3. The authority citation for part 52 continues to read as follows:

Authority: Atomic Energy Act secs. 103, 104, 147, 149, 161, 181, 182, 183, 185, 186, 189, 223, 234 (42 U.S.C. 2133, 2201, 2167, 2169, 2232, 2233, 2235, 2236, 2239, 2282); Energy Reorganization Act secs. 201, 202, 206, 211 (42 U.S.C. 5841, 5842, 5846, 5851); Government Paperwork Elimination Act sec. 1704 (44 U.S.C. 3504 note); Energy Policy Act of 2005, Pub. L. 109–58, 119 Stat. 594 (2005).

■ 4. Revise § 52.99 to read as follows:

§ 52.99 Inspection during construction; ITAAC schedules and notifications; NRC notices

(a) Licensee schedule for completing inspections, tests, or analyses. The licensee shall submit to the NRC, no later than 1 year after issuance of the combined license or at the start of construction as defined at 10 CFR 50.10(a), whichever is later, its schedule for completing the inspections, tests, or analyses in the ITAAC. The licensee shall submit updates to the ITAAC schedules every 6 months thereafter and, within 1 year of its scheduled date for initial loading of fuel, the licensee shall submit updates to the ITAAC schedule every 30 days until the final notification is provided to the NRC under paragraph (c)(1) of this section.

(b) Licensee and applicant conduct of activities subject to ITAAC. With respect to activities subject to an ITAAC, an applicant for a combined license may proceed at its own risk with design and procurement activities, and a licensee may proceed at its own risk with design, procurement, construction, and preoperational activities, even though the NRC may not have found that any one of the prescribed acceptance criteria are met.

(c) Licensee notifications—(1) ITAAC closure notification. The licensee shall notify the NRC that prescribed inspections tests and analyses have

inspections, tests, and analyses have been performed and that the prescribed acceptance criteria are met. The notification must contain sufficient information to demonstrate that the prescribed inspections, tests, and analyses have been performed and that the prescribed acceptance criteria are met

(2) ITAAC post-closure notifications. Following the licensee's ITAAC closure notifications under paragraph (c)(1) of this section until the Commission makes the finding under 10 CFR 52.103(g), the licensee shall notify the NRC, in a timely manner, of new information that materially alters the basis for determining that either inspections, tests, or analyses were performed as required, or that acceptance criteria are met. The notification must contain sufficient information to demonstrate that, notwithstanding the new information, the prescribed inspections, tests, or analyses have been performed as required, and the prescribed acceptance criteria are met.

(3) Uncompleted ITAAC notification. If the licensee has not provided, by the date 225 days before the scheduled date for initial loading of fuel, the notification required by paragraph (c)(1) of this section for all ITAAC, then the licensee shall notify the NRC that the prescribed inspections, tests, or analyses for all uncompleted ITAAC will be performed and that the prescribed acceptance criteria will be met prior to operation. The notification must be provided no later than the date 225 days before the scheduled date for initial loading of fuel, and must provide sufficient information to demonstrate that the prescribed inspections, tests, or analyses will be performed and the prescribed acceptance criteria for the uncompleted ITAAC will be met, including, but not limited to, a description of the specific procedures and analytical methods to be used for performing the prescribed inspections, tests, and analyses and determining that the prescribed acceptance criteria are

met.
(4) All ITAAC complete notification.
The licensee shall notify the NRC that all ITAAC are complete.

(d) Licensee determination of non-compliance with ITAAC. (1) In the event that an activity is subject to an ITAAC derived from a referenced standard design certification and the licensee has not demonstrated that the prescribed acceptance criteria are met, the licensee may take corrective actions to successfully complete that ITAAC or request an exemption from the standard design certification ITAAC, as applicable.

A request for an exemption must also be accompanied by a request for a license amendment under 10 CFR 52.98(f).

(2) In the event that an activity is subject to an ITAAC not derived from a referenced standard design certification and the licensee has not demonstrated that the prescribed acceptance criteria are met, the licensee may take corrective actions to successfully complete that ITAAC or request a license amendment under 10 CFR 52.98(f).

(e) NRC inspection, publication of notices, and availability of licensee notifications. The NRC shall ensure that the prescribed inspections, tests, and analyses in the ITAAC are performed.

(1) At appropriate intervals until the last date for submission of requests for hearing under 10 CFR 52.103(a), the NRC shall publish notices in the **Federal Register** of the NRC staff's determination of the successful completion of inspections, tests, and analyses.

(2) The NRC shall make publicly available the licensee notifications under paragraph (c) of this section. The NRC shall, no later than the date of publication of the notice of intended operation required by 10 CFR 52.103(a), make publicly available those licensee notifications under paragraph (c) of this section that have been submitted to the NRC at least seven (7) days before that notice.

Dated at Rockville, Maryland, this 22nd day of August, 2012.

For the Nuclear Regulatory Commission.

Annette L. Vietti-Cook,

Secretary of the Commission. [FR Doc. 2012–21207 Filed 8–27–12; 8:45 am]

BILLING CODE 7590-01-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2011-1045; Directorate Identifier 2011-NE-32-AD; Amendment 39-17168; AD 2012-17-05]

RIN 2120-AA64

Airworthiness Directives; Honeywell International Inc. Turbofan Engines

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: We are adopting a new airworthiness directive (AD) for certain Honeywell International Inc. models TFE731–4, –4R, –5, –5R, –5AR, and –5BR series turbofan engines. This AD was prompted by a report of a rim/web separation of a first stage low-pressure

turbine (LPT1) rotor assembly. This AD requires replacing affected LPT1 rotor assemblies with assemblies eligible for installation. We are issuing this AD to prevent uncontained disk separation, engine failure, and damage to the airplane.

DATES: This AD is effective October 2, 2012.

ADDRESSES: For service information identified in this AD, contact Honeywell International Inc., 111 S. 34th Street, Phoenix, AZ 85034–2802; Web site: http://portal.honeywell.com; or call Honeywell toll free at phone: 800–601–3099 (U.S./Canada) or 602–365–3099 (International Direct). You may view this service information at the FAA, Engine & Propeller Directorate, 12 New England Executive Park, Burlington, MA. For information on the availability of this material at the FAA, call 781–238–7125.

Examining the AD Docket

You may examine the AD docket on the Internet at http:// www.regulations.gov; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this AD, the regulatory evaluation, any comments received, and other information. The address for the Docket Office (phone: 800-647-5527) is Document Management Facility, U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC 20590.

FOR FURTHER INFORMATION CONTACT:

Joseph Costa, Aerospace Engineer, Los Angeles Aircraft Certification Office, FAA, Transport Airplane Directorate, 3960 Paramount Blvd., Lakewood, CA 90712–4137; phone: 562–627–5246; fax: 562–627–5210: email: joseph.costa@faa.gov.

SUPPLEMENTARY INFORMATION:

Discussion

We issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 to include an AD that would apply to the specified products. That NPRM published in the **Federal Register** on February 21, 2012 (77 FR 9868). That NPRM proposed to require replacing affected LPT1 rotor assemblies with LPT1 rotor assemblies eligible for installation.

Comments

We gave the public the opportunity to participate in developing this AD. The following presents the one comment received on the proposal and the FAA's response to the comment.

Request To Clarify Definition Paragraph

One commenter requested we change a term in paragraph (h) of the proposed AD. The commenter requested that "tie rod" be changed to "tie shaft." The commenter said that making this change would allow a level of disassembly to access the inlet total temperature harness and other hardware without affecting the low-pressure turbine (LPT) module.

We do not agree. Mandating access to the LPT module in the AD and suspect disks when the tie rod is unstretched is consistent in achieving AD compliance sooner for the Falcon 20 and CASA 101 airplanes. LPT disk separations in these airplanes have been determined to be higher risk than for engines in other applications. We did not change the AD.

Conclusion

We reviewed the relevant data, considered the comment received, and determined that air safety and the public interest require adopting the AD as proposed except for minor editorial changes. We have determined that these minor changes:

- Are consistent with the intent that was proposed in the NPRM (77 FR 9868, February 21, 2012) for correcting the unsafe condition; and
- Do not add any additional burden upon the public than was already proposed in the NPRM (77 FR 9868, February 21, 2012).

We also determined that these changes will not increase the economic burden on any operator or increase the scope of the AD.

Costs of Compliance

We estimate that this AD will affect 1,550 engines installed on airplanes of U.S. registry. We also estimate that it will take about 1 work-hour per engine to perform the actions at next access and 165 work-hours per unscheduled engine disassembly, and that the average labor rate is \$85 per work-hour. Replacement parts will cost about \$175,000 per engine. Based on these figures, we estimate the total cost of the AD to U.S. operators to be \$35,195,488 per year.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: "General Requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

This AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

- (1) Is not a "significant regulatory action" under Executive Order 12866,
- (2) Is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979),
- (3) Will not affect intrastate aviation in Alaska, and
- (4) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

■ 2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

2012–17–05 Honeywell International Inc. (formerly AlliedSignal Inc., formerly Garret Turbine Engine Company):
Amendment 39–17168; Docket No. FAA–2011–1045; Directorate Identifier 2011–NE–32–AD.

(a) Effective Date

This AD is effective October 2, 2012.

(b) Affected ADs

None.

(c) Applicability

This AD applies to Honeywell International Inc.:

- (1) Model TFE731–5 series turbofan engines, with a first stage low-pressure turbine (LPT1) rotor assembly, part number (P/N) 3075184–2, 3075184–3, or 3075184–4, installed, and
- (2) Models TFE731–5AR and –5BR series turbofan engines, with a first stage LPT1 rotor assembly, P/N 3075447–1, 3075447–2, 3075447–4, 3075713–1, 3075713–2, 3075713–3, or 3074748–5, installed, and
- (3) Models TFE731–4, –4R, –5AR, –5BR, and –5R series turbofan engines, with an LPT1 rotor assembly, P/N 3074748–4, 3074748–5, 3075447–1, 3075447–2, 3075447–4, 3075713–1, 3075713–2, or 3075713–3, installed.

(d) Unsafe Condition

This AD was prompted by a report of a rim/web separation of an LPT1 rotor assembly. We are issuing this AD to prevent uncontained disk separation, engine failure, and damage to the airplane.

(e) Compliance

Comply with this AD within the compliance times specified, unless already done.

(f) Engines Installed in Dassault-Aviation Falcon 20 and Construcciones Aeronauticas, S.A. (CASA) 101 Airplanes

- (1) Remove the LPT1 rotor assembly at the next access to the LPT1 rotor assembly or at the next major periodic inspection, not to exceed 2,600 hours-in-service since last major periodic inspection, or 8 years after the effective date of this AD, whichever occurs first
- (2) Install an LPT1 rotor assembly that is eligible for installation.

(g) Engines Not Installed in Dassault-Aviation Falcon 20 or CASA 101 Airplanes

- (1) Remove the LPT1 rotor assembly at the next core zone inspection, not to exceed 5,100 hours-in-service since last core zone inspection, or at the next time the LPT1 rotor disc is removed for cause, or 8 years after the effective date of this AD, whichever occurs first
- (2) Install an LPT1 rotor assembly that is eligible for installation.

(h) Definitions

- (1) For the purpose of this AD, "next access" is when the low-pressure tie rod is unstretched.
- (2) For the purpose of this AD, an LPT1 rotor assembly "eligible for installation" is an LPT1 rotor assembly not having a P/N listed in this AD.

(i) Installation Prohibition

After the effective date of this AD, do not install any LPT1 rotor assembly listed by P/N in paragraphs (c)(1), (c)(2), and (c)(3) of this AD, into any engine.

(j) Alternative Methods of Compliance (AMOCs)

The Manager, Los Angeles Aircraft Certification Office, FAA, may approve AMOCs for this AD. Use the procedures in 14 CFR 39.19 to request an AMOC.

(k) Related Information

- (1) For more information about this AD, contact Joseph Costa, Aerospace Engineer, Los Angeles Aircraft Certification Office, FAA, Transport Airplane Directorate, 3960 Paramount Blvd., Lakewood, CA 90712–4137; phone: 562–627–5246; fax: 562–627–5210: email: joseph.costa@faa.gov.
- (2) Honeywell International Inc. Service Bulletin (SB) No. TFE731–72–3768; SB No. TFE731–72–3769; and SB No. TFE731–72– 3770, pertain to the subject of this AD.
- (3) For service information identified in this AD, contact Honeywell International Inc., 111 S. 34th Street, Phoenix, AZ 85034–2802; Web site: http://portal.honeywell.com; or call Honeywell toll free at phone: 800–601–3099 (U.S./Canada) or 602–365–3099 (International Direct).

(l) Material Incorporated by Reference

None

Issued in Burlington, Massachusetts, on August 14, 2012.

Robert G. Mann.

Acting Manager, Engine & Propeller Directorate, Aircraft Certification Service. [FR Doc. 2012–21010 Filed 8–27–12; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 97

[Docket No. 30857; Amdt. No. 3492]

Standard Instrument Approach Procedures, and Takeoff Minimums and Obstacle Departure Procedures; Miscellaneous Amendments

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: This rule establishes, amends, suspends, or revokes Standard Instrument Approach Procedures (SIAPs) and associated Takeoff Minimums and Obstacle Departure Procedures for operations at certain airports. These regulatory actions are needed because of the adoption of new or revised criteria, or because of changes occurring in the National Airspace System, such as the commissioning of new navigational facilities, adding new obstacles, or changing air traffic requirements. These changes are designed to provide safe and efficient use of the navigable airspace and to promote safe flight operations under

instrument flight rules at the affected airports.

DATES: This rule is effective August 28, 2012. The compliance date for each SIAP, associated Takeoff Minimums, and ODP is specified in the amendatory provisions.

The incorporation by reference of certain publications listed in the regulations is approved by the Director of the **Federal Register** as of August 28, 2012.

ADDRESSES: Availability of matters incorporated by reference in the amendment is as follows:

For Examination—

- 1. FAA Rules Docket, FAA Headquarters Building, 800 Independence Avenue SW., Washington, DC 20591;
- 2. The FAA Regional Office of the region in which the affected airport is located:
- 3. The National Flight Procedures Office, 6500 South MacArthur Blvd., Oklahoma City, OK 73169 or,
- 4. The National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202–741–6030, or go to: http://www.archives.gov/federal_register/code_of_federal_regulations/ibr_locations.html.

Āvailability—All SIAPs and Takeoff Minimums and ODPs are available online free of charge. Visit http:// www.nfdc.faa.gov to register. Additionally, individual SIAP and Takeoff Minimums and ODP copies may be obtained from:

- 1. FAA Public Inquiry Center (APA–200), FAA Headquarters Building, 800 Independence Avenue SW., Washington, DC 20591; or
- 2. The FAA Regional Office of the region in which the affected airport is located.

FOR FURTHER INFORMATION CONTACT:

Richard A. Dunham III, Flight Procedure Standards Branch (AFS–420), Flight Technologies and Programs Divisions, Flight Standards Service, Federal Aviation Administration, Mike Monroney Aeronautical Center, 6500 South MacArthur Blvd., Oklahoma City, OK 73169 (Mail Address: P.O. Box 25082, Oklahoma City, OK 73125) Telephone: (405) 954–4164.

SUPPLEMENTARY INFORMATION: This rule amends Title 14 of the Code of Federal Regulations, Part 97 (14 CFR part 97), by establishing, amending, suspending, or revoking SIAPS, Takeoff Minimums and/or ODPS. The complete regulators description of each SIAP and its associated Takeoff Minimums or ODP