

comments received, and other information. The street address for the Docket Operations office (telephone (800) 647-5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new AD:

2012-17-11 BAE SYSTEMS (Operations) Limited: Amendment 39-17174. Docket No. FAA-2012-0489; Directorate Identifier 2011-NM-229-AD.

(a) Effective Date

This airworthiness directive (AD) becomes effective October 11, 2012.

(b) Affected ADs

None.

(c) Applicability

This AD applies to BAE SYSTEMS (Operations) Limited Model 4101 airplanes, certificated in any category, all serial numbers.

(d) Subject

Air Transport Association (ATA) of America Code 26, Fire Protection.

(e) Reason

This AD was prompted by reports that the fire extinguisher of the toilet vanity unit needs to be mounted vertically, rather than horizontally. We are issuing this AD to detect and correct the orientation of the fire extinguisher bottle in the toilet vanity unit to the vertical position, which if not corrected, could result in a toilet waste bin fire spreading, and consequent damage to the airplane and injury to its occupants.

(f) Compliance

You are responsible for having the actions required by this AD performed within the compliance times specified, unless the actions have already been done.

(g) Actions

Within 2 months after the effective date of this AD, determine from the table specified in paragraph 2.A.(1) of BAE SYSTEMS (Operations) Limited Service Bulletin J41-26-008, Revision 2, dated September 20,

2011, if fire extinguisher bottle part number (P/N) BA20509AM-4 is fitted to the airplane. If a fire extinguisher bottle P/N BA20509AM-4 is fitted, before further flight, reposition the fire extinguisher bottle, in accordance with the Accomplishment Instructions of BAE SYSTEMS (Operations) Limited Service Bulletin J41-26-008, Revision 2, dated September 20, 2011.

(h) Credit for Previous Actions

This paragraph provides credit for the actions required by paragraph (g) of this AD, if those actions were performed before the effective date of this AD using BAE SYSTEMS (Operations) Limited Service Bulletin J41-26-008, dated October 5, 2010; or BAE SYSTEMS (Operations) Limited Service Bulletin J41-26-008, Revision 1, dated April 12, 2011.

(i) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs):* The Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the International Branch, send it to ATTN: Todd Thompson, Aerospace Engineer, International Branch, ANM-116, Transport Airplane Directorate, FAA, 1601 Lind Avenue SW., Renton, WA 98057-3356; telephone: (425) 227-1175; fax: (425) 227-1149.

Information may be emailed to: 9-ANM-116-AMOC-REQUESTS@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office. The AMOC approval letter must specifically reference this AD.

(2) *Airworthy Product:* For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they are approved by the State of Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

(j) Related Information

Refer to MCAI European Aviation Safety Agency (EASA) Airworthiness Directive 2011-0194, dated October 6, 2011; and BAE SYSTEMS (Operations) Limited Service Bulletin J41-26-008, Revision 2, dated September 20, 2011; for related information.

(k) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) BAE SYSTEMS (Operations) Limited Service Bulletin J41-26-008, Revision 2, dated September 20, 2011.

(ii) Reserved.

(3) For service information identified in this AD, contact BAE SYSTEMS (Operations) Limited, Customer Information Department, Prestwick International Airport, Ayrshire, KA9 2RW, Scotland, United Kingdom; telephone +44 1292 675207; fax +44 1292 675704; email RApublications@baesystems.com; Internet <http://www.baesystems.com/Businesses/RegionalAircraft/index.htm>.

(4) You may review copies of the service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

(5) You may also review copies of the service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at an NARA facility, call 202-741-6030, or go to http://www.archives.gov/federal_register/code_of_federal_regulations/ibr_locations.html.

Issued in Renton, Washington, on August 22, 2012.

Ali Bahrami,

Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 2012-21288 Filed 9-5-12; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 71

[Docket No. FAA-2012-0456; Airspace Docket No. 12-AEA-9]

Amendment of Class D and Class E Airspace; Lakehurst, NJ; Correction

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule; technical amendment, correction.

SUMMARY: This action corrects the geographic coordinates in the airspace description of a final rule, published in the **Federal Register** on July 10, 2012, amending controlled airspace at Lakehurst Naval Support Activity/Maxfield Field (Joint Base McGuire-Dix-Lakehurst).

DATES: Effective date: 0901 UTC. September 20, 2012. The Director of the Federal Register approves this incorporation by reference action under title 1, Code of Federal Regulations, part 51, subject to the annual revision of FAA Order 7400.9 and publication of conforming amendments.

FOR FURTHER INFORMATION CONTACT: John Fornito, Operations Support Group,

Eastern Service Center, Federal Aviation Administration, P.O. Box 20636, Atlanta, Georgia 30320; telephone (404) 305-6364.

SUPPLEMENTARY INFORMATION:

History

On July 10, 2012, the FAA published a final rule, in the **Federal Register** changing the name of the airport associated with the Class D and E airspace at Lakehurst, NJ, to Lakehurst Naval Support Activity/Maxfield Field (Joint Base McGuire-Dix-Lakehurst) (77 FR 40488). After publication, the FAA found that the geographic coordinates of the airport and Lakehurst (Navy) NDB navigation aid need to be adjusted to be in concert with the FAA's aeronautical database. This action makes the administrative adjustment that does not affect the altitude, boundaries, or operating requirements of the airspace. Therefore, notice and public procedures under 5 U.S.C. 553(b) are unnecessary.

The Class D and E airspace designations are published in Paragraphs 5000 and 6004 respectively of FAA order 7400.9V, dated August 9, 2011, and effective September 15, 2011, which is incorporated by reference in 14 CFR 71.1. The Class D and E airspace designations listed in this document will be published subsequently in the Order.

Correction to Final Rule

Accordingly, pursuant to the authority delegated to me, the geographic coordinates listed in the airspace designation of the Class D and Class E airspace areas for Lakehurst Naval Support Activity/Maxfield Field (Joint Base McGuire-Dix-Lakehurst), and the Lakehurst (Navy) NDB, Lakehurst, NJ, as published in the **Federal Register** of July 10, 2012, (77 FR 40488), FR Doc. 2012-16674, are corrected as follows:

* * * * *

AEA NJ D Lakehurst, NJ [Corrected]

Lakehurst Naval Support Activity/Maxfield Field, NJ (Joint Base McGuire-Dix-Lakehurst)

On page 40488, column 3, line 27, remove, "lat. 40°02'00" N., long. 74°21'13" W", and insert "lat. 40°02'09" N., long. 74°21'05" W".

* * * * *

AEA NJ E4 Lakehurst, NJ [Corrected]

Lakehurst Naval Support Activity/Maxfield Field, NJ (Joint Base McGuire-Dix-Lakehurst)

On page 40488, column 3, line 45, remove "lat. 40°02'00" N., long. 74°21'13" W", and insert "lat. 40°02'09" N., long. 74°21'05" W", and on page 40488, column 3, line 47, under Lakehurst (Navy) NDB, remove "lat. 40°02'41" N., long. 74°20'09" W" and insert "lat. 40°02'42" N., long. 74°20'08" W"

Issued in College Park, Georgia, on August 24, 2012.

Barry A. Knight,

Manager, Operations Support Group, Eastern Service Center, Air Traffic Organization.

[FR Doc. 2012-21830 Filed 9-5-12; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 71

[Docket No. FAA-2012-0749; Airspace Docket No. 11-ANM-29]

RIN 2120-AA66

Revocation of Jet Route J-528; WA

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: This action removes Jet Route J-528 because the route is too short to serve a useful navigation or air traffic control purpose and is causing flight plan rejections in the air traffic control automation system.

DATES: Effective date 0901 UTC, November 15, 2012. The Director of the Federal Register approves this incorporation by reference action under 1 CFR part 51, subject to the annual revision of FAA Order 7400.9 and publication of conforming amendments.

FOR FURTHER INFORMATION CONTACT: Paul Gallant, Airspace, Regulations and ATC Procedures Group, Office of Airspace Services, Federal Aviation Administration, 800 Independence Avenue SW., Washington, DC 20591; telephone: (202) 267-8783.

SUPPLEMENTARY INFORMATION:

Background

Jet Route J-528 is currently depicted on United States High Altitude En Route Navigation charts as a three-mile long segment that extends between the Whatcom, WA, VORTAC and the United States/Canadian border. J-528 is described in FAA Order 7400.9V as extending from Whatcom, WA, to Williams Lake, BC, Canada, excluding the airspace within Canada. The current FAA air traffic control automation system does not recognize J-528 beyond the Seattle Air Route Traffic Control Center and Vancouver Area Control Center boundary. This results in numerous rejected international flight plans and additional air traffic controller workload. Since J-528 parallels another existing Jet Route, J-534 that originates in U.S. airspace and proceeds to Williams Lake, BC, Canada,

removing J-528 will not adversely affect NAS operations. In addition, NavCanada has advised that the designator J-528 is used for a route that exists entirely within Canadian airspace.

The Rule

The FAA is amending Title 14 Code of Federal Regulations (14 CFR) part 71 by removing Jet Route J-528 in Washington state. Due to its short length, the route serves no useful navigation or air traffic control purpose and causes flight plan error problems for the air traffic control automation system. Another Jet Route, J-534, that already exists through the same area, provides routing into Canada; therefore, removing J-528 will not result in any adverse impact to the NAS.

Because this action removes a redundant route segment that does not serve a useful navigation purpose, but causes problems for the air traffic control automation system, I find that notice and public procedures under 5 U.S.C. 553(b) are impractical and contrary to the public interest.

The FAA has determined that this regulation only involves an established body of technical regulations for which frequent and routine amendments are necessary to keep them operationally current. Therefore, this regulation: (1) Is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under Department of Transportation (DOT) Regulatory Policies and Procedures (44 FR 11034; February 26, 1979); and (3) does not warrant preparation of a regulatory evaluation as the anticipated impact is so minimal. Since this is a routine matter that will only affect air traffic procedures and air navigation, it is certified that this rule, when promulgated, will not have a significant economic impact on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

The FAA's authority to issue rules regarding aviation safety is found in Title 49 of the United States Code. Subtitle I, Section 106 describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the agency's authority.

This rulemaking is promulgated under the authority described in Subtitle VII, Part A, Subpart I, Section 40103. Under that section, the FAA is charged with prescribing regulations to assign the use of the airspace necessary to ensure the safety of aircraft and the efficient use of airspace. This regulation is within the scope of that authority as