

Proposed Rules

Federal Register

Vol. 77, No. 205

Tuesday, October 23, 2012

This section of the FEDERAL REGISTER contains notices to the public of the proposed issuance of rules and regulations. The purpose of these notices is to give interested persons an opportunity to participate in the rule making prior to the adoption of the final rules.

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2012-1134; Directorate Identifier 2012-CE-034-AD]

RIN 2120-AA64

Airworthiness Directives; Lindstrand Hot Air Balloons Ltd Appliances

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: We propose to adopt a new airworthiness directive (AD) for certain Lindstrand Hot Air Balloons Ltd female ACME threaded hose connectors, part numbers HS6139 and HS6144, installed on balloons. This proposed AD results from mandatory continuing airworthiness information (MCAI) originated by an aviation authority of another country to identify and correct an unsafe condition on an aviation product. The MCAI describes the unsafe condition as insufficient tightness of the threaded hose connector in the assembly area that could result in fuel leakage. We are issuing this proposed AD to require actions to address the unsafe condition on these products.

DATES: We must receive comments on this proposed AD by December 7, 2012.

ADDRESSES: You may send comments by any of the following methods:

- Federal eRulemaking Portal: Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.
- Fax: (202) 493-2251.
- Mail: U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.
- Hand Delivery: U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC 20590, between 9 a.m.

and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this proposed AD, contact Lindstrand Hot Air Balloons Ltd., Maesbury Road, Oswestry, Shropshire SY10 8ZZ, The United Kingdom; telephone: +44 (0) 1691-671717; fax: +44 (0) 1691-671122; email: simon@lindstrand.co.uk; Internet: <http://www.lindstrand.co.uk/>. You may review copies of the referenced service information at the FAA, Small Airplane Directorate, 901 Locust, Kansas City, Missouri 64106. For information on the availability of this material at the FAA, call (816) 329-4148.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov>; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this proposed AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Office (telephone (800) 647-5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT: Taylor Martin, Aerospace Engineer, FAA, Small Airplane Directorate, 901 Locust, Room 301, Kansas City, Missouri 64106; telephone: (816) 329-4138; fax: (816) 329-4090; email: taylor.martin@faa.gov.

SUPPLEMENTARY INFORMATION:

Comments Invited

We invite you to send any written relevant data, views, or arguments about this proposed AD. Send your comments to an address listed under the **ADDRESSES** section. Include "Docket No. FAA-2012-1134; Directorate Identifier 2012-CE-034-AD" at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this proposed AD. We will consider all comments received by the closing date and may amend this proposed AD because of those comments.

We will post all comments we receive, without change, to <http://www.regulations.gov>, including any personal information you provide. We will also

post a report summarizing each substantive verbal contact we receive about this proposed AD.

Discussion

The European Aviation Safety Agency (EASA), which is the Technical Agent for the Member States of the European Community, has issued EASA AD No.: 2012-0142R1, dated September 14, 2012 (referred to after this as "the MCAI"), to correct an unsafe condition for the specified products. The MCAI states:

Three incidents were reported where the female ACME threaded connectors (Rego type) was leaking when connected to the gas cylinder with the cylinder valve turned on.

The results of the technical investigations revealed the possibility that other similar connectors produced between 01 January 2011 and 01 September 2011 might not have been assembled with sufficient tightness. A list of potentially affected connectors has been drawn up Table 1 of this AD. A list of burners and manifolds on which it is already known that an affected connector has been installed is provided in Table 2 of this AD.

This condition, if not detected and corrected, could result, in case of an ignition source, in a fire hazard that could damage the balloon and its envelope, ultimately leading to a forced emergency landing, during which balloon occupants and persons on the ground could be injured.

To address this potential unsafe condition, Lindstrand Hot Air Balloons Ltd. (who manufactured the hose assemblies) issued Service Bulletin (SB) N°12, which, for the affected parts, requires accomplishment of an inspection of the female ACME thread hose connectors.

For the reasons described above, EASA issued AD 2012-0142, to require an inspection of the female ACME thread hose connectors for leakage, and, depending on findings, to re-torque the connectors using correct values.

Since that AD was issued, it has been determined that the pilot-owner of the balloon can accomplish the inspection of the affected parts to identify the leak. In addition, the risk assessment has been reconsidered, which has led to the conclusion that the compliance time for the inspection can be extended to 60 days after the effective date of the date at original issue. Similarly, as most of the parts have now been inspected and, depending on findings, corrected, it was possible to delete paragraph (3) from the AD, dealing with spare parts.

You may obtain further information by examining the MCAI in the AD docket.

Although the European Aviation Safety Agency (EASA) MCAI allows the pilot-owner to do the inspection and

correction required in paragraphs (f)(1), (f)(2), and (f)(3) of this AD, the U.S. regulatory system requires all actions of this AD be done by a certified mechanic.

Relevant Service Information

Lindstrand Hot Air Balloons Ltd has issued Service Bulletin No. 12, Issue 2, dated May 10, 2012. The actions described in this service information are intended to correct the unsafe condition identified in the MCAI.

FAA's Determination and Requirements of the Proposed AD

This product has been approved by the aviation authority of another country, and is approved for operation in the United States. Pursuant to our bilateral agreement with this State of Design Authority, they have notified us of the unsafe condition described in the MCAI and service information referenced above. We are proposing this AD because we evaluated all information and determined the unsafe condition exists and is likely to exist or develop on other products of the same type design.

Costs of Compliance

We estimate that this proposed AD will affect 2,170 products of U.S. registry. We also estimate that it would take about .5 work-hour per product to comply with the basic requirements of this proposed AD. The average labor rate is \$42.50 per work-hour.

Based on these figures, we estimate the cost of the proposed AD on U.S. operators to be \$92,225, or \$42.50 per product.

In addition, we estimate that any necessary follow-on actions would take about .5 work-hour. We have no way of determining the number of products that may need these actions.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. "Subtitle VII: Aviation Programs," describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in "Subtitle VII, Part A, Subpart III, Section 44701: General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition

that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

- (1) Is not a "significant regulatory action" under Executive Order 12866,
- (2) Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979),
- (3) Will not affect intrastate aviation in Alaska, and
- (4) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. The FAA amends § 39.13 by adding the following new AD:

Lindstrand Hot Air Balloons LTD: Docket No. FAA-2012-1134; Directorate Identifier 2012-CE-034-AD.

(a) Comments Due Date

We must receive comments by December 7, 2012.

(b) Affected ADs

None.

(c) Applicability

This AD applies to all hot air balloons, certificated in any category, equipped with Lindstrand Hot Air Balloons Ltd female ACME threaded hose connectors, part numbers (P/Ns) HS6139 and HS6144, all serial numbers.

(d) Subject

Air Transport Association of America (ATA) Code 14: Hardware.

(e) Reason

This AD was prompted by mandatory continuing airworthiness information (MCAI) originated by an aviation authority of another country to identify and correct an unsafe condition on an aviation product. The MCAI describes the unsafe condition as insufficient tightness of the threaded hose connector in the assembly area that could result in fuel leakage. We are issuing this AD to detect and correct insufficient tightness of the threaded hose connector in the assembly area. This condition, if not corrected, could result in fuel leakage and lead to an inflight fire.

(f) Actions and Compliance

Unless already done, do the following actions:

- (1) Within the next 60 days after the effective date of this AD, inspect the female ACME threaded hose connectors, (P/Ns) HS6139 and HS6144, for leaking in accordance with the instructions of Lindstrand Hot Air Balloons Ltd Service Bulletin No. 12, dated May 10, 2012.
- (2) If fuel leakage is detected in the inspection required in paragraph (f)(1) of this AD, before further flight, tighten the threaded hose connector to the correct torque following Lindstrand Hot Air Balloons Ltd Service Bulletin No. 12, dated May 10, 2012.
- (3) If, after the effective date of this AD, you install on any balloon an ACME threaded hose connector, (P/Ns) HS6139 or HS6144, manufactured by Lindstrand Hot Air Balloons Ltd. and supplied as a spare part between January 1, 2011, and September 1, 2011, before further flight, you must comply with the actions of this AD.
- (4) Although the European Aviation Safety Agency (EASA) MCAI allows the pilot-owner to do the inspection and correction required in paragraphs (f)(1), (f)(2), and (f)(3) of this AD, the U.S. regulatory system requires all actions of this AD be done by a certified mechanic.

(g) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs):* The Manager, Standards Office, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. Send information to ATTN: Taylor Martin, Aerospace Engineer, FAA, Small Airplane Directorate, 901 Locust, Room 301, Kansas City, Missouri 64106; telephone: (816) 329-4138; fax: (816) 329-4090; email: taylor.martin@faa.gov. Before using any approved AMOC on any airplane to which the AMOC applies, notify your appropriate principal inspector (PI) in the FAA Flight Standards District Office (FSDO), or lacking a PI, your local FSDO.

(2) *Airworthy Product:* For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they are approved by the State of

Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

(3) **Reporting Requirements:** For any reporting requirement in this AD, a federal agency may not conduct or sponsor, and a person is not required to respond to, nor shall a person be subject to a penalty for failure to comply with a collection of information subject to the requirements of the Paperwork Reduction Act unless that collection of information displays a current valid OMB Control Number. The OMB Control Number for this information collection is 2120-0056. Public reporting for this collection of information is estimated to be approximately 5 minutes per response, including the time for reviewing instructions, completing and reviewing the collection of information. All responses to this collection of information are mandatory. Comments concerning the accuracy of this burden and suggestions for reducing the burden should be directed to the FAA at: 800 Independence Ave. SW., Washington, DC 20591. Attn: Information Collection Clearance Officer, AES-200.

(h) Related Information

Refer to MCAI European Aviation Safety Agency AD 12-053, dated May 25, 2012; and Lindstrand Hot Air Balloons Ltd Service Bulletin No. 12, dated May 10, 2012, for related information. For service information related to this AD, contact Lindstrand Hot Air Balloons Ltd., Maesbury Road, Oswestry, Shropshire SY10 8ZZ, The United Kingdom; telephone: +44 (0) 1691-671717; fax: +44 (0) 1691-671122; email: simon@lindstrand.co.uk; Internet: <http://www.lindstrand.co.uk/>. You may review copies of the referenced service information at the FAA, Small Airplane Directorate, 901 Locust, Kansas City, Missouri 64106. For information on the availability of this material at the FAA, call (816) 329-4148.

Issued in Kansas City, Missouri, on October 17, 2012.

Pat Mullen,

Acting Manager, Small Airplane Directorate, Aircraft Certification Service.

[FR Doc. 2012-26064 Filed 10-22-12; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2012-1105; Directorate Identifier 2012-NM-137-AD]

RIN 2120-AA64

Airworthiness Directives; Airbus Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of Proposed Rulemaking (NPRM).

SUMMARY: We propose to adopt a new airworthiness directive (AD) for all

Airbus Model A318, A319, and A320 series airplanes. This proposed AD was prompted by fuel system reviews conducted by the manufacturer, which revealed that certain fuel pumps under certain conditions can create an ignition source in the fuel tank. This proposed AD would require modification of the center tank fuel pump control circuit by installation of ground fault interrupters (GFIs). This proposed AD would also require either replacement of the GFI or deactivation of the associated fuel pump following failure of any post-modification operational test of the GFI. We are proposing this AD to prevent the potential of ignition sources inside fuel tanks, which, in combination with flammable fuel vapors, could result in fuel tank explosions and consequent loss of the airplane.

DATES: We must receive comments on this proposed AD by December 7, 2012.

ADDRESSES: You may send comments by any of the following methods:

- **Federal eRulemaking Portal:** Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.

- **Fax:** (202) 493-2251.

- **Mail:** U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC 20590.

- **Hand Delivery:** U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this proposed AD, contact Airbus, Airworthiness Office—EAS, 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France; telephone +33 5 61 93 36 96; fax +33 5 61 93 44 51; email account.airworth-eas@airbus.com; Internet <http://www.airbus.com>. You may review copies of the referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov>; or in person at the Docket Operations office between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this proposed AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Operations office (telephone (800) 647-5527) is in

the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT: Sanjay Ralhan, Aerospace Engineer, International Branch, ANM-116, Transport Airplane Directorate, FAA, 1601 Lind Avenue SW., Renton, Washington 98057-3356; phone: 425-227-1405; fax: 425-227-1149.

SUPPLEMENTARY INFORMATION:

Comments Invited

We invite you to send any written relevant data, views, or arguments about this proposed AD. Send your comments to an address listed under the **ADDRESSES** section. Include “Docket No. FAA-2012-1105; Directorate Identifier 2012-NM-137-AD” at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this proposed AD. We will consider all comments received by the closing date and may amend this proposed AD based on those comments.

We will post all comments we receive, without change, to <http://www.regulations.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact we receive about this proposed AD.

Discussion

The European Aviation Safety Agency (EASA), which is the Technical Agent for the Member States of the European Community, has issued Airworthiness Directive 2012-0198, dated September 26, 2012 (which superseded EASA AD 2012-0133, dated July 18, 2012) (referred to after this as “the MCAI”), to correct an unsafe condition for the specified products. The MCAI states:
* * * The FAA published Special Federal Aviation Regulation (SFAR) 88, and the Joint Aviation Authorities (JAA) published Interim Policy INT/POL/25/12.

In the framework of these requirements, EASA have determined that the electrical power supply circuits of certain fuel pumps, installed on A320 family aeroplanes, for which the canisters become uncovered during normal operation, could, under certain conditions, create an ignition source in the tank vapour space.

This condition, if not corrected, could result in a fuel tank explosion and consequent loss of the aeroplane.

To address this potential unsafe condition, Airbus developed a modification which includes installing Ground Fault Interrupters (GFI) into the centre tank fuel pump control circuit, providing additional system protection by electrically isolating the pump in case of a ground fault condition downstream of the GFI.

Consequently, EASA issued AD 2012-0133 to require modification of the centre tank fuel