

(g) Definitions

(1) For the purpose of this AD, an “engine shop visit” is the induction of an engine into the shop for maintenance involving the separation of pairs of major mating engine flanges, except that the separation of engine flanges solely for the purposes of transportation without subsequent engine maintenance does not constitute an engine shop visit.

(2) For the purpose of this AD, an EEC “eligible for installation” is any EEC that does not contain software standard A14 or earlier.

(h) Credit for Previous Actions

If before the effective date of this AD you removed from an engine any EEC that had EEC software standard A14 or earlier and your engine no longer has an EEC with software standard A14 or earlier, you have met the requirements of this AD.

(i) Alternative Methods of Compliance (AMOCs)

The Manager, Engine Certification Office, FAA, may approve AMOCs to this AD. Use the procedures found in 14 CFR 39.19 to make your request.

(j) Related Information

(1) For more information about this AD, contact Kenneth Steeves, Aerospace Engineer, Engine Certification Office, FAA, Engine & Propeller Directorate, 12 New England Executive Park, Burlington, MA 01803; phone: (781) 238-7765; fax: (781) 238-7199; email: Kenneth.Steeves@faa.gov.

(2) Refer to MCAI European Aviation Safety Agency AD 2013-0190, dated August 20, 2013, for more information. You may examine the MCAI in the AD docket on the Internet at <http://www.regulations.gov/#!docketDetail;D=FAA-2013-0876>.

(3) RR Alert Service Bulletin No. RB.211-73-AG829, dated April 18, 2012, which is not incorporated by reference in this AD, can be obtained from Rolls-Royce plc, using the contact information in paragraph (j)(4) of this AD.

(4) For service information identified in this AD, contact Rolls-Royce plc, Corporate Communications, P.O. Box 31, Derby, England, DE248BJ; phone: 011-44-1332-242424; fax: 011-44-1332-249936; email: http://www.rolls-royce.com/contact/civil_team.jsp; or Web site: <https://www.aeromanager.com>.

(5) You may view this service information at the FAA, Engine & Propeller Directorate, 12 New England Executive Park, Burlington, MA. For information on the availability of this material at the FAA, call 781-238-7125.

(k) Material Incorporated by Reference

None.

Issued in Burlington, Massachusetts, on June 30, 2014.

Colleen M. D'Alessandro,

Assistant Directorate Manager, Engine & Propeller Directorate, Aircraft Certification Service.

[FR Doc. 2014-16184 Filed 7-10-14; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION**Federal Aviation Administration****14 CFR Part 39**

[Docket No. FAA-2013-1059; Directorate Identifier 2013-NE-36-AD; Amendment 39-17896; AD 2014-14-02]

RIN 2120-AA64

Airworthiness Directives; Pratt & Whitney Canada Corp. Turboprop Engines

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: We are adopting a new airworthiness directive (AD) for certain Pratt & Whitney Canada Corp. (P&WC) PW120, PW121, PW121A, PW124B, PW127, PW127E, PW127F, PW127G, and PW127M turboprop engines. This AD requires removal of the O-ring seal from the fuel manifold fitting. This AD was prompted by reports of fuel leaks at the interface between the fuel manifold and the fuel nozzle that resulted in engine fire. We are issuing this AD to prevent in-flight fuel leakage, which could lead to engine fire, damage to the engine, and damage to the airplane.

DATES: This AD becomes effective August 15, 2014.

ADDRESSES: For service information identified in this AD, contact Pratt & Whitney Canada Corp., 1000 Marie-Victorin, Longueuil, Quebec, Canada, J4G 1A1; phone: 800-268-8000; fax: 450-647-2888; Web site: www.pwc.ca. You may view this service information at the FAA, Engine & Propeller Directorate, 12 New England Executive Park, Burlington, MA. For information on the availability of this material at the FAA, call 781-238-7125.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2013-1059; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this AD, the mandatory continuing airworthiness information (MCAI), the regulatory evaluation, any comments received, and other information. The address for the Docket Office (phone: 800-647-5527) is Document Management Facility, U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC 20590.

FOR FURTHER INFORMATION CONTACT:

Kevin Dickert, Aerospace Engineer, Engine Certification Office, FAA, Engine & Propeller Directorate, 12 New England Executive Park, Burlington, MA 01803; phone: 781-238-7117; fax: 781-238-7199; email: kevin.dickert@faa.gov.

SUPPLEMENTARY INFORMATION:**Discussion**

We issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 by adding an AD that would apply to the specified products. The NPRM was published in the **Federal Register** on March 21, 2014 (79 FR 15707). The NPRM proposed to correct an unsafe condition for the specified products. The MCAI states:

There have been reported incidences of fuel leaks at the interface between the flexible fuel manifold and the fuel nozzle. On occasion, these events resulted in an engine fire on PW100 series engine installations. The data indicates that nearly all of the subject manifold fuel leaks were caused by inadequate B-nut torque application during installation, after maintenance work was performed on the fuel nozzle/manifold.

Sealing of the fitting connections between the fuel manifolds and the fuel nozzle adapters is achieved through conical metal-to-metal surface seating. An additional O-ring seal on the fitting was installed to arrest any fuel leak past the conical sealing surfaces. In-service experience has indicated that leakage past the sealing surfaces, as a result of improper torquing during installation of the manifold, may not be immediately evident until the failure of the O-ring seal allows the fuel to leak into the nacelle area.

Comments

We gave the public the opportunity to participate in developing this AD. We considered the comment received.

Request To Mandate Incorporation of Service Bulletins

UTair Aviation JSC requested that we mandate incorporation of P&WC Service Bulletins (SBs) PW100-72-21841, Revision No. 1, dated November 29, 2013; and PW100-72-21848, Revision No. 1, dated November 15, 2013, in the AD. The commenter suggested that incorporation by reference of these SBs would improve safety compared to the compliance proposed in the NPRM (79 FR 15707, March 21, 2014).

We disagree. We note that prior to implementation of these SBs, an operator would need to remove the affected O-ring seals, which would fulfill the requirements of this AD. We do not find that requiring accomplishing these service bulletins through incorporation by reference in this AD is necessary. We did not change this AD.

Conclusion

We reviewed the available data, including the comment received, and determined that air safety and the public interest require adopting the AD as proposed.

Costs of Compliance

We estimate that this AD affects about 150 engines installed on airplanes of U.S. registry. We also estimate that it would take about 2.5 hours per engine to perform the inspection or replacement required by this AD. The average labor rate is \$85 per hour. Based on these figures, we estimate the cost of this AD on U.S. operators to be \$31,875.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. "Subtitle VII: Aviation Programs," describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in "Subtitle VII, Part A, Subpart III, Section 44701: General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We determined that this AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this AD:

- (1) Is not a "significant regulatory action" under Executive Order 12866,
- (2) Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979),
- (3) Will not affect intrastate aviation in Alaska to the extent that it justifies making a regulatory distinction, and
- (4) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

2014-14-02 Pratt & Whitney Canada Corp.:
Amendment 39-17896; Docket No. FAA-2013-1059; Directorate Identifier 2013-NE-36-AD.

(a) Effective Date

This AD becomes effective August 15, 2014.

(b) Affected ADs

None.

(c) Applicability

This AD applies to Pratt & Whitney Canada Corp. (P&WC) PW120, PW121, and PW121A turboprop engines with Post SB21610 configuration; PW124B, PW127, PW127E, and PW127F turboprop engines with either Post SB21607 or Post SB21705 configuration, or both; and PW127G and PW127M turboprop engines.

(d) Reason

This AD was prompted by reports of fuel leaks at the interface between the fuel manifold and the fuel nozzle that resulted in engine fire. We are issuing this AD to prevent in-flight fuel leakage, which could lead to engine fire, damage to the engine, and damage to the airplane.

(e) Actions and Compliance

Unless already done, during the next opportunity when the affected subassembly is accessible, but no later than 18 months after the effective date of this AD, remove the O-ring seal from the fuel manifold fitting.

(f) Alternative Methods of Compliance (AMOCs)

The Manager, Engine Certification Office, FAA, may approve AMOCs to this AD. Use the procedures found in 14 CFR 39.19 to make your request.

(g) Related Information

(1) For more information about this AD, contact Kevin Dickert, Aerospace Engineer, Engine Certification Office, FAA, Engine & Propeller Directorate, 12 New England Executive Park, Burlington, MA 01803; phone: (781) 238-7117; fax: (781) 238-7199; email: kevin.dickert@faa.gov.

(2) Refer to MCAI Transport Canada AD CF-2013-29, dated October 4, 2013, for related information. You may examine the MCAI in the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating it in Docket No. FAA-2013-1059.

(3) P&WC Service Bulletin PW100-72-21803, Revision No. 4, dated February 8, 2012, which is not incorporated by reference in this AD, can be obtained from Pratt & Whitney Canada, using the contact information in paragraph (g)(4) of this AD.

(4) For service information identified in this AD, contact Pratt & Whitney Canada Corp., 1000 Marie-Victorin Blvd., Longueuil, Quebec, Canada, J4G 1A1; phone: 800-268-8000; fax: 450-647-2888; Web site: www.pwc.ca.

(5) You may view this service information at the FAA, Engine & Propeller Directorate, 12 New England Executive Park, Burlington, MA. For information on the availability of this material at the FAA, call 781-238-7125.

(h) Material Incorporated by Reference

None.

Issued in Burlington, Massachusetts, on June 30, 2014.

Colleen M. D'Alessandro,

Assistant Directorate Manager, Engine & Propeller Directorate, Aircraft Certification Service.

[FR Doc. 2014-16187 Filed 7-10-14; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2013-0939; Directorate Identifier 2013-CE-043-AD; Amendment 39-17881; AD 2013-22-23 R1]

RIN 2120-AA64

Airworthiness Directives; AERMACCHI S.p.A. Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule; request for comments.

SUMMARY: We are rescinding Airworthiness Directive (AD) 2013-22-23 for AERMACCHI S.p.A. Models F.260, F.260B, F.260C, F.260D, F.260E, F.260F, S.208, and S.208A airplanes equipped with a Lycoming O-540, IO-540, or AEIO-540 (depending on the airplane model) wide cylinder flange engine with a front crankcase mounted propeller governor. AD 2013-22-23 resulted from mandatory continuing airworthiness information (MCAI) issued by the aviation authority of another country to identify and correct an unsafe condition on an aviation product. We issued the AD to detect and