

## PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701.

### § 39.13 [Amended]

■ 2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

**2017–21–03 Gulfstream Aerospace LP (Type Certificate Previously Held by Israel Aircraft Industries, Ltd.):**  
Amendment 39–19074; Docket No. FAA–2017–0693; Product Identifier 2017–NM–044–AD.

#### (a) Effective Date

This AD is effective November 27, 2017.

#### (b) Affected ADs

None.

#### (c) Applicability

This AD applies to Gulfstream Aerospace LP Model Gulfstream 100, Astra SPX, and 1125 Westwind Astra airplanes, certificated in any category, serial numbers 004, and 011 through 158 inclusive.

#### (d) Subject

Air Transport Association (ATA) of America Code 52, Doors.

#### (e) Reason

This AD was prompted by a report indicating that the main entrance door (MED) opened during flight, and by the determination that the “CABIN DOOR UNLOCK” crew alerting system (CAS) message may extinguish before the handle latch pin is fully engaged. We are issuing this AD to prevent the MED from opening during flight, which could lead to structural damage and loss of control of the airplane.

#### (f) Compliance

Comply with this AD within the compliance times specified, unless already done.

#### (g) Rigging Procedure

Within 12 months after the effective date of this AD: Do an updated rigging procedure for the adjustment of the MED microswitch, in accordance with the Accomplishment Instructions of Gulfstream G100 Service Bulletin 100–52–312, dated January 15, 2016.

#### (h) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs):* The Manager, International Section, Transport Standards Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the International Section, send it to the attention of the person identified in paragraph (i)(2) of this AD. Information may

be emailed to: 9-ANM-116-AMOC-REQUESTS@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(2) *Contacting the Manufacturer:* For any requirement in this AD to obtain corrective actions from a manufacturer, the action must be accomplished using a method approved by the Manager, International Section, Transport Standards Branch, FAA; or the Civil Aviation Authority of Israel (CAAI); or the CAAI's authorized Designee. If approved by the CAAI Designee, the approval must include the Designee's authorized signature.

#### (i) Related Information

(1) Refer to Mandatory Continuing Airworthiness Information (MCAI) CAAI Airworthiness Directive ISR–I–52–2017–03–29, dated January 3, 2017, for related information. This MCAI may be found in the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA–2017–0693.

(2) For more information about this AD, contact Tom Rodriguez, Aerospace Engineer, International Section, Transport Standards Branch, FAA, 1601 Lind Avenue SW., Renton, WA 98057–3356; telephone 425–227–1137; fax 425–227–1149.

#### (j) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) Gulfstream G100 Service Bulletin 100–52–312, dated January 15, 2016.

(ii) Reserved.

(3) For service information identified in this AD, contact Gulfstream Aerospace Corporation, P.O. Box 2206, Mail Station D–25, Savannah, GA 31402–2206; telephone 800–810–4853; fax 912–965–3520; email [pubs@gulfstream.com](mailto:pubs@gulfstream.com); Internet [http://www.gulfstream.com/product\\_support/technical\\_pubs/pubs/index.htm](http://www.gulfstream.com/product_support/technical_pubs/pubs/index.htm).

(4) You may view this service information at the FAA, Transport Standards Branch, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425–227–1221.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202–741–6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on October 11, 2017.

**Jeffrey E. Duven,**

*Director, System Oversight Division, Aircraft Certification Service.*

[FR Doc. 2017–22560 Filed 10–20–17; 8:45 am]

**BILLING CODE 4910–13–P**

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. FAA–2017–0697; Product Identifier 2017–NM–041–AD; Amendment 39–19080; AD 2017–21–09]

RIN 2120–AA64

### Airworthiness Directives; Embraer S.A. Airplanes

**AGENCY:** Federal Aviation Administration (FAA), Department of Transportation (DOT).

**ACTION:** Final rule.

**SUMMARY:** We are adopting a new airworthiness directive (AD) for certain Embraer S.A. Model ERJ 170 airplanes and Model ERJ 190–100 STD, –100 LR, –100 IGW, –200 STD, –200 LR, and –200 IGW airplanes. This AD was prompted by an evaluation by the design approval holder indicating that the forward pressure bulkhead is subject to widespread fatigue damage. This AD requires repetitive detailed inspections of the web aft face of the forward pressure bulkhead for any cracking and discrepancy, and repair if necessary. This AD also requires modification of the forward pressure bulkhead, which would terminate the inspections. We are issuing this AD to address the unsafe condition on these products.

**DATES:** This AD is effective November 27, 2017.

The Director of the Federal Register approved the incorporation by reference of certain publications listed in this AD as of November 27, 2017.

**ADDRESSES:** For service information identified in this final rule, contact Embraer S.A., Technical Publications Section (PC 060), Av. Brigadeiro Faria Lima, 2170—Putim—12227–901 São Jose dos Campos—SP—Brazil; telephone +55 12 3927–5852 or +55 12 3309–0732; fax +55 12 3927–7546; email [distrib@embraer.com.br](mailto:distrib@embraer.com.br); Internet <http://www.flyembraer.com>. You may view this referenced service information at the FAA, Transport Standards Branch, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425–227–1221. It is also available on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA–2017–0697.

#### Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA–2017–

0697; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Office (telephone 800-647-5527) is Docket Management Facility, U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC 20590.

**FOR FURTHER INFORMATION CONTACT:** Ana Martinez Hueto, Aerospace Engineer, International Section, Transport Standards Branch, FAA, 1601 Lind Avenue SW., Renton, WA 98057-3356; telephone 425-227-1622; fax 425-227-1149.

**SUPPLEMENTARY INFORMATION:**

**Discussion**

We issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 by adding an AD that would apply to certain Embraer S.A. Model ERJ 170 airplanes and Model ERJ 190-100 STD, -100 LR, -100 IGW, -200 STD, -200 LR, and -200 IGW airplanes. The NPRM published in the **Federal Register** on July 17, 2017 (82 FR 32658) (“the NPRM”).

The Agência Nacional de Aviação Civil (ANAC), which is the aviation authority for Brazil, has issued Brazilian Airworthiness Directive 2017-03-01, effective March 24, 2017 (referred to after this as the Mandatory Continuing Airworthiness Information, or “the MCAI”), to correct an unsafe condition for certain Embraer S.A. Model ERJ 170 airplanes and Model ERJ 190-100 STD, -100 LR, -100 IGW, -200 STD, -200 LR, and -200 IGW airplanes. The MCAI states:

This [Brazilian] AD was prompted by an evaluation by the design approval holder indicating that the forward pressure bulkhead is subject to widespread fatigue damage. The modification required by this [Brazilian] AD is intended to support the airplane reaching its limit of validity (LOV) of the engineering data that support the established structural maintenance program. We are issuing this [Brazilian] AD to prevent fatigue cracking of the forward pressure bulkhead, which could result in reduced structural integrity of the airplane.

Required actions include repetitive detailed inspections of the web aft face of the forward pressure bulkhead for any cracking and discrepancy (*i.e.*, corrosion, dents, gauge marks, fastener anomalies); repair if necessary; and modification of the forward pressure bulkhead, which would terminate the repetitive inspections. You may examine the MCAI in the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2017-0697.

**Comments**

We gave the public the opportunity to participate in developing this AD. We received no comments on the NPRM or on the determination of the cost to the public.

**Conclusion**

We reviewed the relevant data and determined that air safety and the public interest require adopting this AD as proposed except for minor editorial changes. We have determined that these minor changes:

- Are consistent with the intent that was proposed in the NPRM for correcting the unsafe condition; and
- Do not add any additional burden upon the public than was already proposed in the NPRM.

**Related Service Information Under 1 CFR Part 51**

Embraer S.A. has issued the following service information, which describes Task 53-10-001-0005, an airworthiness limitation task for a detailed inspection of the web aft face of the forward pressure bulkhead for any cracking and discrepancies. These documents are distinct since they apply to different airplane models.

- Embraer 170/175 MRB—Temporary Revision 12-3, dated September 19, 2016, to the Embraer 170/175 Maintenance Review Board Report, MRB-1621.
- Embraer 190/195 MRB—Temporary Revision 10-4, dated September 19, 2016, to the Embraer 190/195 Maintenance Review Board Report, MRB-1928.

Embraer S.A. has issued the following service information, which describes procedures for modifying the forward pressure bulkhead. These documents are distinct since they apply to different airplane models.

- Embraer Service Bulletin 170-53-0051, Revision 03, dated August 21, 2013.
- Embraer Service Bulletin 190-53-0019, Revision 03, dated August 21, 2013.

This service information is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the **ADDRESSES** section.

**Costs of Compliance**

We estimate that this AD affects 482 airplanes of U.S. registry.

We estimate the following costs to comply with this AD:

**ESTIMATED COSTS**

Action	Labor cost	Parts cost	Cost per product	Cost on U.S. operators
Inspection .....	1 work-hour × \$85 per hour = \$85 per inspection cycle.	\$0 .....	\$85 per inspection cycle.	\$40,970 per inspection cycle.
Modification .....	158 work-hours × \$85 per hour = \$13,430.	Up to \$13,409 .....	Up to \$26,839 .....	Up to \$12,936,398.

We have received no definitive data that would enable us to provide cost estimates for the on-condition actions specified in this AD.

**Authority for This Rulemaking**

Title 49 of the United States Code specifies the FAA’s authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. “Subtitle VII:

Aviation Programs,” describes in more detail the scope of the Agency’s authority.

We are issuing this rulemaking under the authority described in “Subtitle VII, Part A, Subpart III, Section 44701: General requirements.” Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures

the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

This AD is issued in accordance with authority delegated by the Executive Director, Aircraft Certification Service, as authorized by FAA Order 8000.51C.

In accordance with that order, issuance of ADs is normally a function of the Compliance and Airworthiness Division, but during this transition period, the Executive Director has delegated the authority to issue ADs applicable to transport category airplanes to the Director of the System Oversight Division.

### Regulatory Findings

We determined that this AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

1. Is not a "significant regulatory action" under Executive Order 12866;
2. Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979);
3. Will not affect intrastate aviation in Alaska; and
4. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

### List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

### Adoption of the Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

### PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701.

#### § 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

**2017-21-09 Embraer S.A.:** Amendment 39-19080; Docket No. FAA-2017-0697; Product Identifier 2017-NM-041-AD.

#### (a) Effective Date

This AD is effective November 27, 2017.

#### (b) Affected ADs

None.

#### (c) Applicability

This AD applies to the airplanes specified in paragraphs (c)(1) and (c)(2) of this AD, certificated in any category.

(1) Embraer S.A. Model ERJ 170-100 LR, -100 STD, -100 SE., and -100 SU airplanes; and Model ERJ 170-200 LR, -200 SU, and -200 STD airplanes; as identified in Embraer Service Bulletin 170-53-0051, Revision 03, dated August 21, 2013.

(2) Embraer S.A. Model ERJ 190-100 STD, -100 LR, and -100 IGW airplanes; and Model ERJ 190-200 STD, -200 LR, and -200 IGW airplanes; as identified in Embraer Service Bulletin 190-53-0019, Revision 03, dated August 21, 2013.

#### (d) Subject

Air Transport Association (ATA) of America Code 53, Fuselage.

#### (e) Reason

This AD was prompted by an evaluation by the design approval holder indicating that the forward pressure bulkhead is subject to widespread fatigue damage. We are issuing this AD to prevent fatigue cracking of the forward pressure bulkhead, which could result in reduced structural integrity of the airplane.

#### (f) Compliance

Comply with this AD within the compliance times specified, unless already done.

#### (g) Repetitive Inspections and Repairs

Before the accumulation of 25,954 total flight cycles, or within 3,600 flight cycles after the effective date of this AD, whichever occurs later: Do a detailed inspection of the web aft face of the forward pressure bulkhead for any cracking and discrepancy (*i.e.*, corrosion, dents, gauge marks, fastener anomalies), in accordance with Task 53-10-001-0005 specified in Embraer 170/175 MRB—Temporary Revision 12-3, dated September 19, 2016, to the Embraer 170/175 Maintenance Review Board Report, MRB-1621; or Task 53-10-001-0005 specified in Embraer 190/195 MRB—Temporary Revision 10-4, dated September 19, 2016, to the Embraer 190/195 Maintenance Review Board Report, MRB-1928; as applicable. Repeat the inspection thereafter at intervals not to exceed 6,489 flight cycles. If any cracking or discrepancy is found during any inspection required by this paragraph, before further flight, repair the forward pressure bulkhead using a method approved by the Manager, International Section, Transport Standards Branch, FAA; or the Agência Nacional de Aviação Civil (ANAC); or ANAC's authorized Designee. If approved by the ANAC Designee, the approval must include the Designee's authorized signature.

#### (h) Modification of the Forward Pressure Bulkhead

Before the accumulation of 38,931 total flight cycles: Modify the forward pressure bulkhead, in accordance with the Accomplishment Instructions of Embraer Service Bulletin 170-53-0051, Revision 03, dated August 21, 2013; or Embraer Service Bulletin 190-53-0019, Revision 03, dated August 21, 2013; as applicable. Accomplishing the modification required by this paragraph terminates the requirements of paragraph (g) of this AD.

#### (i) Credit for Previous Actions

(1) This paragraph provides credit for the actions applicable to Model ERJ 170 airplanes required by paragraph (h) of this AD, if those actions were performed before the effective date of this AD, using the service information specified in paragraph (i)(1)(i), (i)(1)(ii), or (i)(1)(iii) of this AD.

(i) Embraer Service Bulletin 170-53-0051, dated February 26, 2010.

(ii) Embraer Service Bulletin 170-53-0051, Revision 01, dated May 25, 2011.

(iii) Embraer Service Bulletin 170-53-0051, Revision 02, May 28, 2012.

(2) This paragraph provides credit for actions applicable to Model ERJ 190 airplanes required by paragraph (h) of this AD, if those actions were performed before the effective date of this AD, using the service information specified in paragraph (i)(2)(i), (i)(2)(ii), or (i)(2)(iii) of this AD.

(i) Embraer Service Bulletin 190-53-0019, dated February 26, 2010.

(ii) Embraer Service Bulletin 190-53-0019, Revision 01, dated May 25, 2011.

(iii) Embraer Service Bulletin 190-53-0019, Revision 02, dated May 28, 2012.

#### (j) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs):* The Manager, International Section, Transport Standards Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the International Section, send it to the attention of the person identified in paragraph (k)(2) of this AD. Information may be emailed to: [9-ANM-116-AMOC-REQUESTS@faa.gov](mailto:9-ANM-116-AMOC-REQUESTS@faa.gov). Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(2) *Contacting the Manufacturer:* For any requirement in this AD to obtain corrective actions from a manufacturer, the action must be accomplished using a method approved by the Manager, International Section, Transport Standards Branch, FAA; or the ANAC; or ANAC's authorized Designee. If approved by the ANAC Designee, the approval must include the Designee's authorized signature.

#### (k) Related Information

(1) Refer to Mandatory Continuing Airworthiness Information (MCAI) Brazilian AD 2017-03-01, dated March 24, 2017, for related information. This MCAI may be found in the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2017-0697.

(2) For more information about this AD, contact Ana Martinez Hueto, Aerospace Engineer, International Section, Transport Standards Branch, FAA, 1601 Lind Avenue SW., Renton, WA 98057-3356; telephone 425-227-1622; fax 425-227-1149.

(3) Service information identified in this AD that is not incorporated by reference is

available at the addresses specified in paragraphs (l)(3) and (l)(4) of this AD.

#### (l) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) Embraer 170/175 MRB—Temporary Revision 12–3, dated September 19, 2016, to the Embraer 170/175 Maintenance Review Board Report, MRB–1621.

(ii) Embraer 190/195 MRB—Temporary Revision 10–4, dated September 19, 2016, to the Embraer 190/195 Maintenance Review Board Report, MRB–1928.

(iii) Embraer Service Bulletin 170–53–0051, Revision 03, dated August 21, 2013.

(iv) Embraer Service Bulletin 190–53–0019, Revision 03, dated August 21, 2013.

(3) For service information identified in this AD, contact Embraer S.A., Technical Publications Section (PC 060), Av. Brigadeiro Faria Lima, 2170—Putim—12227–901 São Jose dos Campos—SP—Brasil; telephone +55 12 3927–5852 or +55 12 3309–0732; fax +55 12 3927–7546; email [distrib@embraer.com.br](mailto:distrib@embraer.com.br); Internet <http://www.flyembraer.com>.

(4) You may view this service information at the FAA, Transport Standards Branch, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425–227–1221.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202–741–6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on October 12, 2017.

Dionne Palermo,

Acting Director, System Oversight Division, Aircraft Certification Service.

[FR Doc. 2017–22779 Filed 10–20–17; 8:45 am]

BILLING CODE 4910–13–P

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 71

[Docket No. FAA–2016–9545; Airspace Docket No. 16–AGL–33]

#### Establishment of Class E Airspace; Rosebud, SD

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Final rule.

**SUMMARY:** This action establishes Class E airspace at Rosebud, SD. Controlled airspace is necessary to accommodate new special instrument approach

procedures developed at Rosebud Sioux Tribal Airport, for the safety and management of instrument flight rules (IFR) operations at the airport.

**DATES:** Effective 0901 UTC, December 7, 2017. The Director of the Federal Register approves this incorporation by reference action under title 1, Code of Federal Regulations, part 51, subject to the annual revision of FAA Order 7400.11 and publication of conforming amendments.

**ADDRESSES:** FAA Order 7400.11B, Airspace Designations and Reporting Points, and subsequent amendments can be viewed on line at [http://www.faa.gov/air\\_traffic/publications/](http://www.faa.gov/air_traffic/publications/). For further information, you can contact the Airspace Policy Group, Federal Aviation Administration, 800 Independence Avenue SW., Washington, DC 20591; telephone: (202) 267–8783. The Order is also available for inspection at the National Archives and Records Administration (NARA). For information on the availability of FAA Order 7400.11B at NARA, call (202) 741–6030, or go to <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

FAA Order 7400.11, Airspace Designations and Reporting Points, is published yearly and effective on September 15.

**FOR FURTHER INFORMATION CONTACT:** Rebecca Shelby, Federal Aviation Administration, Operations Support Group, Central Service Center, 10101 Hillwood Parkway, Fort Worth, TX 76177; telephone (817) 222–5857.

#### SUPPLEMENTARY INFORMATION:

##### Authority for This Rulemaking

The FAA's authority to issue rules regarding aviation safety is found in Title 49 of the United States Code. Subtitle I, Section 106 describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the agency's authority. This rulemaking is promulgated under the authority described in Subtitle VII, Part A, Subpart I, Section 40103. Under that section, the FAA is charged with prescribing regulations to assign the use of airspace necessary to ensure the safety of aircraft and the efficient use of airspace. This regulation is within the scope of that authority as it establishes controlled airspace extending upward from 700 feet above the surface at Rosebud Sioux Tribal Airport, Rosebud, SD, to support standard instrument approach procedures for IFR operations at the airport.

#### History

The FAA published in the **Federal Register** (82 FR 39549, August 21, 2017) Docket No. FAA–2016–9545 a notice of proposed rulemaking to establish Class E airspace extending upward from 700 feet above the surface at Rosebud Sioux Tribal Airport, Rosebud, SD. Interested parties were invited to participate in this rulemaking effort by submitting written comments on the proposal to the FAA. No comments were received.

Class E airspace designations are published in paragraph 6005 of FAA Order 7400.11B dated August 3, 2017, and effective September 15, 2017, which is incorporated by reference in 14 CFR 71.1. The Class E airspace designations listed in this document will be published subsequently in the Order.

#### Availability and Summary of Documents for Incorporation by Reference

This document amends FAA Order 7400.11B, Airspace Designations and Reporting Points, dated August 3, 2017, and effective September 15, 2017. FAA Order 7400.11B is publicly available as listed in the **ADDRESSES** section of this document. FAA Order 7400.11B lists Class A, B, C, D, and E airspace areas, air traffic service routes, and reporting points.

#### The Rule

This amendment to title 14, Code of Federal Regulations (14 CFR) part 71 establishes Class E airspace extending upward from 700 feet above the surface within a 6.4-mile radius of Rosebud Sioux Tribal Airport, Rosebud, SD, to accommodate new special instrument approach procedures. Controlled airspace is needed for the safety and management of IFR operations at the airport.

#### Regulatory Notices and Analyses

The FAA has determined that this regulation only involves an established body of technical regulations for which frequent and routine amendments are necessary to keep them operationally current, is non-controversial and unlikely to result in adverse or negative comments. It, therefore: (1) Is not a “significant regulatory action” under Executive Order 12866; (2) is not a “significant rule” under DOT Regulatory Policies and Procedures (44 FR 11034; February 26, 1979); and (3) does not warrant preparation of a regulatory evaluation as the anticipated impact is so minimal. Since this is a routine matter that will only affect air traffic procedures and air navigation, it is certified that this rule, when promulgated, does not have a significant