

the final rule that was published in the **Federal Register** on November 21, 2018 (83 FR 58724).

**Note:** Appendix A does not appear in the Code of Federal Regulations.

#### Appendix A—Text of Large Financial Institution Rating System (Corrected)

1. On page 58737, second column, line 25 from the top, “capital planning and position” is corrected to read “liquidity risk management and positions”; and

2. On page 58738, third column, line 28 from the top, “capital planning and position” is corrected to “governance and controls”.

By order of the Board of Governors of the Federal Reserve System, acting through the Secretary of the Board under delegated authority.

**Ann Misback,**

*Secretary of the Board.*

[FR Doc. 2019-02516 Filed 2-14-19; 8:45 am]

**BILLING CODE 6210-01-P**

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. FAA-2018-0788; Product Identifier 2018-NM-004-AD; Amendment 39-19544; AD 2019-01-05]

**RIN 2120-AA64**

#### Airworthiness Directives; Airbus SAS Airplanes

**AGENCY:** Federal Aviation Administration (FAA), Department of Transportation (DOT).

**ACTION:** Final rule.

**SUMMARY:** We are adopting a new airworthiness directive (AD) for certain Airbus SAS Model A330-200, -200F, and -300 series airplanes. This AD was prompted by a revision of the airworthiness limitations section (ALS), which provides new and more restrictive maintenance requirements and airworthiness limitations for airplane structures and systems. This AD requires revising the existing maintenance or inspection program to incorporate new maintenance requirements and airworthiness limitations. We are issuing this AD to address the unsafe condition on these products.

**DATES:** This AD is effective March 22, 2019.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in this AD as of March 22, 2019.

**ADDRESSES:** For service information identified in this final rule, contact Airbus SAS, Airworthiness Office—EAL, Rond-Point Emile Dewoitine No: 2, 31700 Blagnac Cedex, France; phone: +33 5 61 93 36 96; fax: +33 5 61 93 45 80; email: [airworthiness.A330-A340@airbus.com](mailto:airworthiness.A330-A340@airbus.com); internet: <http://www.airbus.com>. You may view this service information at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195. It is also available on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2018-0788.

#### Examining the AD Docket

You may examine the AD docket on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2018-0788; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this final rule, the regulatory evaluation, any comments received, and other information. The address for Docket Operations (phone: 800-647-5527) is U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

**FOR FURTHER INFORMATION CONTACT:** Vladimir Ulyanov, Aerospace Engineer, International Section, Transport Standards Branch, FAA, 2200 South 216th St., Des Moines, WA 98198; phone and fax: 206-231-3229.

#### SUPPLEMENTARY INFORMATION:

##### Discussion

We issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 by adding an AD that would apply to certain Airbus SAS Model A330-200, -200F, and -300 series airplanes. The NPRM published in the **Federal Register** on August 31, 2018 (83 FR 44510). The NPRM was prompted by a revision of the ALS, which provides new and more restrictive maintenance requirements and airworthiness limitations for airplane structures and systems. The NPRM proposed to require revising the existing maintenance or inspection program to incorporate new maintenance requirements and airworthiness limitations.

We are issuing this AD to address reduced airplane control due to the failure of system components.

The European Aviation Safety Agency (EASA), which is the Technical Agent

for the Member States of the European Union, has issued EASA AD 2017-0228, dated November 21, 2017 (referred to after this as the Mandatory Continuing Airworthiness Information, or “the MCAI”), to correct an unsafe condition for all Airbus SAS Model A330 and A340 series airplanes. The MCAI states:

The airworthiness limitations are currently defined and published in the Airbus A330 and A340 Airworthiness Limitations Section (ALS) documents. The airworthiness limitations applicable to the System Equipment Maintenance Requirements, which are approved by EASA, are specified in Airbus A330 and A340 ALS Part 4. Failure to comply with these instructions could result in an unsafe condition.

EASA issued AD 2016-0011 [which corresponds to FAA AD 2017-05-10, Amendment 39-18821 (82 FR 13379, March 13, 2017) (“AD 2017-05-10”)] to require the actions as specified in Airbus A330 and A340 ALS Part 4 at Revision 05 and Revision 04, respectively.

Since this [EASA] AD was issued, Airbus published Revision 06 and Revision 05, respectively, of Airbus A330 and A340 ALS Part 4, which introduce new and more restrictive maintenance requirements and/or airworthiness limitations.

For the reason described above, this [EASA] AD retains the requirements of EASA AD 2016-0011, which is superseded, and requires accomplishment of the actions specified in Airbus A330 ALS Part 4 Revision 06, or A340 ALS Part 4 Revision 05, as applicable.

The unsafe condition is reduced control of the airplane due to the failure of system components. You may examine the MCAI in the AD docket on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2018-0788.

#### Comments

We gave the public the opportunity to participate in developing this final rule. The following presents the comment received on the NPRM and the FAA’s response to each comment.

#### Request To Include Later Version of the Service Information

American Airlines (AAL) requested that we include Airbus A330 Airworthiness Limitations Section (ALS) Part 4, System Equipment Maintenance Requirements (SEMR), Variation 6.1, dated January 16, 2018, as the appropriate source of service information. AAL indicated that the variation document increases the flight cycle life limitation of trimmable horizontal stabilizer (THS) actuator P/N 47172-540 from 10,000 flight cycles to 20,000 flight cycles. AAL also pointed out an alternative method of compliance (AMOC) for AD 2017-05-10 has been

approved to allow the incorporation of the variation document into AAL's maintenance program (AMOC AIR-676-18-026R1, dated August 13, 2018).

We agree with the commenter's request for the reasons provided. We have revised paragraphs (g) and (h) of this AD to include Airbus A330 Airworthiness Limitations Section (ALS) Part 4, System Equipment Maintenance Requirements (SEMR), Variation 6.1, dated January 16, 2018, as an appropriate source of service information.

### Conclusion

We reviewed the relevant data, considered the comment received, and determined that air safety and the public interest require adopting this final rule with the changes described previously and minor editorial changes. We have determined that these minor changes:

- Are consistent with the intent that was proposed in the NPRM for addressing the unsafe condition; and
- Do not add any additional burden upon the public than was already proposed in the NPRM.

We also determined that these changes will not increase the economic burden on any operator or increase the scope of this final rule.

### Related Service Information Under 1 CFR Part 51

Airbus SAS has issued the following service information.

- A330 Airworthiness Limitations Section (ALS) Part 4, System Equipment Maintenance Requirements (SEMR), Revision 06, dated September 18, 2017. This service information describes preventative maintenance requirements and associated airworthiness limitations applicable to aircraft systems susceptible to aging effects.
- A330 Airworthiness Limitations Section (ALS) Part 4, System Equipment Maintenance Requirements (SEMR), Variation 6.1, dated January 16, 2018. This service information describes preventative maintenance requirements and associated airworthiness limitations applicable to the THS actuator P/N 47172-540 and changes the flight cycle life limitation from 10,000 flight cycles to 20,000 flight cycles.

This service information is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the ADDRESSES section.

### Costs of Compliance

We estimate that this AD affects 104 airplanes of U.S. registry.

We have determined that revising the existing maintenance or inspection program takes an average of 90 work-hours per operator, although we recognize that this number may vary from operator to operator. In the past, we have estimated that this action takes 1 work-hour per airplane. Since operators incorporate maintenance or inspection program changes for their affected fleet(s), we have determined that a per-operator estimate is more accurate than a per airplane estimate. Therefore, we estimate the total cost per operator to be \$7,650 (90 work-hours × \$85 per workhour).

### Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: "General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

This AD is issued in accordance with authority delegated by the Executive Director, Aircraft Certification Service, as authorized by FAA Order 8000.51C. In accordance with that order, issuance of ADs is normally a function of the Compliance and Airworthiness Division, but during this transition period, the Executive Director has delegated the authority to issue ADs applicable to transport category airplanes and associated appliances to the Director of the System Oversight Division.

### Regulatory Findings

This AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

(1) Is not a "significant regulatory action" under Executive Order 12866,

(2) Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979),

(3) Will not affect intrastate aviation in Alaska, and

(4) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

### List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

### Adoption of the Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

### PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

#### § 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

**2019-01-05 Airbus SAS:** Amendment 39-19544; Docket No. FAA-2018-0788; Product Identifier 2018-NM-004-AD.

#### (a) Effective Date

This AD is effective March 22, 2019.

#### (b) Affected ADs

This AD affects AD 2017-05-10, Amendment 39-18821 (82 FR 13379, March 13, 2017) ("AD 2017-05-10").

#### (c) Applicability

This AD applies to Airbus SAS Model A330-201, A330-202, A330-203, A330-223, A330-243, A330-223F, A330-243F, A330-301, A330-302, A330-303, A330-321, A330-322, A330-323, A330-341, A330-342, and A330-343 airplanes, certificated in any category, with an original certificate of airworthiness or original export certificate of airworthiness issued on or before September 18, 2017.

#### (d) Subject

Air Transport Association (ATA) of America Code 05, Time Limits/Maintenance Checks.

#### (e) Reason

This AD was prompted by a revision of the airworthiness limitations section (ALS), which provides new and more restrictive maintenance requirements and airworthiness limitations for airplane structures and systems. We are issuing this AD to prevent

reduced airplane control due to the failure of system components.

#### (f) Compliance

Comply with this AD within the compliance times specified, unless already done.

#### (g) Maintenance Program Revision

Within 90 days after the effective date of this AD, revise the existing maintenance or inspection program, as applicable, by incorporating Airbus A330 Airworthiness Limitations Section (ALS) Part 4, System Equipment Maintenance Requirements (SEMR), Revision 06, dated September 18, 2017; or Airbus A330 Airworthiness Limitations Section (ALS) Part 4, System Equipment Maintenance Requirements (SEMR), Variation 6.1, dated January 16, 2018. The initial compliance times for the actions specified in Airbus A330 Airworthiness Limitations Section (ALS) Part 4, System Equipment Maintenance Requirements (SEMR), Revision 06, dated September 18, 2017, or the actions specified in Airbus A330 Airworthiness Limitations Section (ALS) Part 4, System Equipment Maintenance Requirements (SEMR), Variation 6.1, dated January 16, 2018, are within the applicable compliance times specified in Airbus A330 Airworthiness Limitations Section (ALS) Part 4, System Equipment Maintenance Requirements (SEMR), Revision 06, dated September 18, 2017, or Airbus A330 Airworthiness Limitations Section (ALS) Part 4, System Equipment Maintenance Requirements (SEMR), Variation 6.1, dated January 16, 2018; or within 90 days after the effective date of this AD; whichever occurs later; except as required by paragraph (h) of this AD.

#### (h) Exceptions to Initial Compliance Times

(1) Where Airbus A330 Airworthiness Limitations Section (ALS) Part 4, System Equipment Maintenance Requirements (SEMR), Revision 06, dated September 18, 2017; or Airbus A330 Airworthiness Limitations Section (ALS) Part 4, System Equipment Maintenance Requirements (SEMR), Variation 6.1, dated January 16, 2018; defines a calendar compliance time for elevator servo-controls having part number (P/N) SC4800–2, SC4800–3, SC4800–4, SC4800–6, SC4800–7, or SC4800–8 as “August 31, 2004,” the calendar compliance time is June 13, 2007 (34 months after August 13, 2004 (the effective date of AD 2004–13–25, Amendment 39–13707 (69 FR 41394, July 9, 2004))).

(2) Where Airbus A330 Airworthiness Limitations Section (ALS) Part 4, System Equipment Maintenance Requirements (SEMR), Revision 06, dated September 18, 2017; or Airbus A330 Airworthiness Limitations Section (ALS) Part 4, System Equipment Maintenance Requirements (SEMR), Variation 6.1, dated January 16, 2018; defines a calendar compliance time for spoiler servo-controls (SSCs) having P/N 1386A0000–01, 1386B0000–01, 1387A0000–01, or 1387B0000–01 as “December 31, 2003,” the calendar compliance time is November 19, 2005 (13 months after October 19, 2004 (the effective date of AD 2004–18–

14, Amendment 39–13793 (69 FR 55326, September 14, 2004))).

(3) Where Airbus A330 Airworthiness Limitations Section (ALS) Part 4, System Equipment Maintenance Requirements (SEMR), Revision 06, dated September 18, 2017; or Airbus A330 Airworthiness Limitations Section (ALS) Part 4, System Equipment Maintenance Requirements (SEMR), Variation 6.1, dated January 16, 2018; defines a calendar compliance time for elevator servo-controls having P/N SC4800–73, SC4800–93, SC4800–103, and SC4800–113 as “June 30, 2008,” the calendar compliance time is September 16, 2009 (17 months after April 16, 2008 (the effective date of AD 2008–06–07, Amendment 39–15419 (73 FR 13103, March 12, 2008; corrected April 15, 2008 (73 FR 20367))))).

(4) The initial compliance time for replacement of the retraction brackets of the main landing gear (MLG) having a part number specified in paragraphs (h)(4)(i) through (h)(4)(xvi) of this AD is before the accumulation of 19,800 total landings on the affected retraction brackets of the MLG, or within 900 flight hours after April 9, 2012 (the effective date of AD 2012–04–07, Amendment 39–16963 (77 FR 12989, March 5, 2012)), whichever occurs later.

- (i) 201478303.
- (ii) 201478304.
- (iii) 201478305.
- (iv) 201478306.
- (v) 201478307.
- (vi) 201478308.
- (vii) 201428380.
- (viii) 201428381.
- (ix) 201428382.
- (x) 201428383.
- (xi) 201428384.
- (xii) 201428385.
- (xiii) 201428378.
- (xiv) 201428379.
- (xv) 201428351.
- (xvi) 201428352.

(5) Where Airbus A330 Airworthiness Limitations Section (ALS) Part 4, System Equipment Maintenance Requirements (SEMR), Revision 06, dated September 18, 2017; or Airbus A330 Airworthiness Limitations Section (ALS) Part 4, System Equipment Maintenance Requirements (SEMR), Variation 6.1, dated January 16, 2018; defines a calendar compliance time for the modification of SSCs on three hydraulic circuits having P/N MZ4339390–01X, MZ4306000–01X, MZ4339390–02X, MZ4306000–02X, MZ4339390–10X, or MZ4306000–10X as “March 5, 2010,” the calendar compliance time is April 14, 2011 (18 months after October 14, 2009 (the effective date of AD 2009–18–20, Amendment 39–16017 (74 FR 46313, September 9, 2009) (“AD 2009–18–20”))).

(6) Where Note (17) of Sub-Part 1, “Life Limits,” of Section 3, “Systems Life-Limited Components,” of Airbus A330 Airworthiness Limitations Section (ALS) Part 4, System Equipment Maintenance Requirements (SEMR), Revision 06, dated September 18, 2017; or Airbus A330 Airworthiness Limitations Section (ALS) Part 4, System Equipment Maintenance Requirements (SEMR), Variation 6.1, dated January 16, 2018; defines a calendar date of “September

5, 2008,” as a date for the determination of accumulated flight cycles since the airplane’s initial entry into service, the date is October 14, 2009 (the effective date of AD 2009–18–20).

(7) Where Note (17) of Sub-Part 1, “Life Limits,” of Section 3, “Systems Life-Limited Components,” of Airbus A330 Airworthiness Limitations Section (ALS) Part 4, System Equipment Maintenance Requirements (SEMR), Revision 06, dated September 18, 2017; or Airbus A330 Airworthiness Limitations Section (ALS) Part 4, System Equipment Maintenance Requirements (SEMR), Variation 6.1, dated January 16, 2018; defines a calendar compliance time as “March 5, 2010,” for the modification of affected servo controls, the calendar compliance time is April 14, 2011 (18 months after October 14, 2009 (the effective date of AD 2009–18–20)).

#### (i) No Alternative Actions or Intervals

After accomplishing the revision required by paragraph (g) of this AD, no alternative actions (e.g., inspections) or intervals may be used unless the actions or intervals are approved as an alternative method of compliance (AMOC) in accordance with the procedures specified in paragraph (k)(1) of this AD.

#### (j) Terminating Actions for the Requirements of AD 2017–05–10

Accomplishing the actions required by paragraph (g) of this AD terminates all requirements of AD 2017–05–10.

#### (k) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs)*: The Manager, International Section, Transport Standards Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the International Section, send it to the attention of the person identified in paragraph (l)(2) of this AD. Information may be emailed to: [9-ANM-116-AMOCREQUESTS@faa.gov](mailto:9-ANM-116-AMOCREQUESTS@faa.gov). Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(2) *Contacting the Manufacturer*: For any requirement in this AD to obtain corrective actions from a manufacturer, the action must be accomplished using a method approved by the Manager, International Section, Transport Standards Branch, FAA; or the European Aviation Safety Agency (EASA); or Airbus SAS’s EASA Design Organization Approval (DOA). If approved by the DOA, the approval must include the DOA-authorized signature.

#### (l) Related Information

(1) Refer to Mandatory Continuing Airworthiness Information (MCAI) EASA AD 2017–0228, dated November 21, 2017, for related information. This MCAI may be

found in the AD docket on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA–2018–0788.

(2) For more information about this AD, contact Vladimir Ulyanov, Aerospace Engineer, International Section, Transport Standards Branch, FAA, 2200 South 216th St., Des Moines, WA 98198; phone and fax: 206–231–3229.

#### (m) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) Airbus A330 Airworthiness Limitations Section (ALS) Part 4, System Equipment Maintenance Requirements (SEMR), Revision 06, dated September 18, 2017.

(ii) Airbus A330 Airworthiness Limitations Section (ALS) Part 4, System Equipment Maintenance Requirements (SEMR), Variation 6.1, dated January 16, 2018.

(3) For service information identified in this AD, contact Airbus SAS, Airworthiness Office—EAL, Rond-Point Emile Dewoitine No: 2, 31700 Blagnac Cedex, France; phone: +33 5 61 93 36 96; fax: +33 5 61 93 45 80; email: [airworthiness.A330-A340@airbus.com](mailto:airworthiness.A330-A340@airbus.com); internet: <http://www.airbus.com>.

(4) You may view this service information at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206–231–3195.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202–741–6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Des Moines, Washington, on January 10, 2019.

**Jeffrey E. Duven,**

*Director, System Oversight Division, Aircraft Certification Service.*

[FR Doc. 2019–02161 Filed 2–14–19; 8:45 am]

**BILLING CODE 4910–13–P**

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. FAA–2018–0902; Product Identifier 2018–NM–047–AD; Amendment 39–19543; AD 2019–01–04]

RIN 2120–AA64

#### Airworthiness Directives; The Boeing Company Airplanes

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Final rule.

**SUMMARY:** We are adopting a new airworthiness directive (AD) for all The Boeing Company Model 787 series airplanes. This AD was prompted by a report of an uncommanded descent and turn that occurred after an inflight switch to the spare flight management function (FMF). This AD requires an inspection of the flight management system (FMS) to determine if certain operational program software (OPS) is installed and installation of new FMS OPS and a software check if necessary. For certain airplanes, this AD also requires concurrent actions. We are issuing this AD to address the unsafe condition on these products.

**DATES:** This AD is effective March 22, 2019.

The Director of the Federal Register approved the incorporation by reference of certain publications listed in this AD as of March 22, 2019.

**ADDRESSES:** For service information identified in this final rule, contact Boeing Commercial Airplanes, Attention: Contractual & Data Services (C&DS), 2600 Westminister Blvd., MC 110–SK57, Seal Beach, CA 90740–5600; telephone 562–797–1717; internet <https://www.myboeingfleet.com>. You may view this service information at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206–231–3195. It is also available on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA–2018–0902.

#### Examining the AD Docket

You may examine the AD docket on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA–2018–0902; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this final rule, the regulatory evaluation, any comments received, and other information. The address for Docket Operations (phone: 800–647–5527) is U.S. Department of Transportation, Docket Operations, M–30, West Building Ground Floor, Room W12–140, 1200 New Jersey Avenue SE, Washington, DC 20590.

#### FOR FURTHER INFORMATION CONTACT:

Nelson Sanchez, Aerospace Engineer, Systems and Equipment Section, FAA, Seattle ACO Branch, 2200 South 216th St., Des Moines, WA 98198; phone and fax: 206–231–3543; email: [nelson.sanchez@faa.gov](mailto:nelson.sanchez@faa.gov).

#### SUPPLEMENTARY INFORMATION:

#### Discussion

We issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 by adding an AD that would apply to all The Boeing Company Model 787 series airplanes. The NPRM published in the **Federal Register** on October 23, 2018 (83 FR 53404). The NPRM was prompted by a report of an uncommanded descent and turn that occurred after an inflight switch to the spare FMF. The NPRM proposed to require an inspection of the FMS to determine if certain OPS is installed and installation of new FMS OPS and a software check if necessary. For certain airplanes, it also proposed to require concurrent actions.

We are issuing this AD to address the retention of stale flight data in the spare FMF, which, if not addressed, could result in controlled flight into terrain or a mid-air collision.

#### Comments

We gave the public the opportunity to participate in developing this final rule. We have considered the comments received. Boeing, Delta Air Lines, and B McCann indicated their support for the NPRM.

#### Conclusion

We reviewed the relevant data, considered the comments received, and determined that air safety and the public interest require adopting this final rule as proposed, except for minor editorial changes. We have determined that these minor changes:

- Are consistent with the intent that was proposed in the NPRM for addressing the unsafe condition; and
- Do not add any additional burden upon the public than was already proposed in the NPRM.

#### Related Service Information Under 14 CFR Part 51

We reviewed Boeing Alert Requirements Bulletin B787–81205–SB340038–00 RB, Issue 001, dated November 16, 2017. The service information describes procedures for installing FMS OPS Block Point 3B (BP3B) and performing a software check.

We also reviewed Boeing Service Bulletin B787–81205–SB340013–00, Issue 002, dated May 6, 2016. The service information describes procedures for installing FMS OPS Block Point 3 (BP3) and performing a software check. This service information is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the **ADDRESSES** section.