

SUPPLEMENTARY INFORMATION:**Discussion**

What action has FAA taken to date? We issued a proposal to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) to include an AD that would apply to all Shorts Models SC-7 Series 2 and SC-7 Series 3 airplanes that are equipped with pneumatic deicing boots. The proposal was published in the **Federal Register** as an NPRM on October 12, 1999 (64 FR 55197). The NPRM proposed to require revising the Limitations Section of the AFM to include requirements for activation of pneumatic deicing boots at the first sign of ice accumulation on the airplane.

Was the public invited to comment? The FAA invited interested persons to participate in the making of this amendment. We did not receive any comments on the proposed rule.

What additional information has FAA found? The FAA has found that all of the affected airplanes incorporate a freezing point fluid system. These airplanes do not have deice boots. Therefore, FAA has determined that the unsafe condition defined in the NPRM does not exist on these airplanes.

The FAA's Determination

What is FAA's final determination on this issue? Based on the above information, we have determined that there is no need for the NPRM, Docket No. 99-CE-48-AD, and that we should withdraw it.

Withdrawal of this NPRM does not prevent us from issuing another notice in the future, nor will it commit us to any course of action in the future.

Regulatory Impact

Does this AD involve a significant rule or regulatory action? Since this action only withdraws a proposed AD, it is not an AD and, therefore, is not covered under Executive Order 12866, the Regulatory Flexibility Act, or DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979).

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

The Withdrawal

Accordingly, FAA withdraws the notice of proposed rulemaking, Docket No. 99-CE-48-AD, published in the **Federal Register** on October 12, 1999 (64 FR 55197).

Issued in Kansas City, Missouri, on August 23, 2000.

Marvin R. Nuss,

Acting Manager, Small Airplane Directorate, Aircraft Certification Service.

[FR Doc. 00-22125 Filed 8-29-00; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION**Federal Aviation Administration****14 CFR Part 39**

[Docket No. 99-CE-46-AD]

RIN 2120-AA64

Airworthiness Directives; Raytheon Aircraft Company 90, 99, 100, 200, 300, 1900, and 2000 Series Airplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Proposed rule; withdrawal.

SUMMARY: This document withdraws a notice of proposed rulemaking (NPRM) that would have applied to all Raytheon Aircraft Company (Raytheon) 90, 99, 100, 200, 300, 1900, and 2000 series airplanes. The proposed AD would have required you to revise the Airplane Flight Manual (AFM) to include requirements for activation of the airframe pneumatic deicing boots. The proposed AD was the result of reports of in-flight incidents and an accident (on airplanes other than the referenced Raytheon airplanes) that occurred in icing conditions where the airframe pneumatic deicing boots were not activated. Raytheon has demonstrated that the design of the affected airplanes, including the language currently in the AFM, is adequate to address the conditions identified in the proposed AD for these airplanes. Therefore, AD action is not necessary to address the conditions on these airplanes and we are withdrawing the NPRM.

ADDRESSES: You may look at information related to this action at the Federal Aviation Administration (FAA), Central Region, Office of the Regional Counsel, Attention: Rules Docket No. 99-CE-46-AD, 901 Locust, Room 506, Kansas City, Missouri 64106, between 8 a.m. and 4 p.m., Monday through Friday, except holidays.

FOR FURTHER INFORMATION CONTACT: Mr. Larry E. Werth, Airworthiness Directive Coordinator, FAA, Small Airplane Directorate, 901 Locust, Room 301, Kansas City, Missouri 64106; telephone: (816) 329-4147; facsimile: (816) 329-4090.

SUPPLEMENTARY INFORMATION:

Discussion

What action has FAA taken to date? We issued a proposal to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) to include an AD that would apply to all Raytheon 90, 99, 100, 200, 300, 1900, and 2000 series airplanes that are equipped with pneumatic deicing boots. The proposal was published in the **Federal Register** as an NPRM on October 12, 1999 (64 FR 55188). The NPRM proposed to require revising the Limitations Section of the AFM to include requirements for activation of pneumatic deicing boots at the first sign of ice accumulation on the airplane.

Was the public invited to comment? The FAA invited interested persons to participate in the making of this amendment. We received a comment on the proposed AD from Raytheon. Our analysis and disposition of this comment follow:

Comment Disposition

What is the commenter's concern? Raytheon provides data it believes demonstrates that the design of the affected airplanes, including the language currently in the AFM, is adequate to address the conditions identified in the proposed AD for these airplanes. Therefore, Raytheon requests that FAA withdraw the NPRM.

What is FAA's response to the concern? After evaluating the data that Raytheon submitted, we have determined that the design of the affected airplanes, including the language currently in the AFM, is adequate to address the conditions identified in the proposed AD for these airplanes. We will withdraw the NPRM per the Raytheon request.

The FAA's Determination

What is FAA's final determination on this issue? Based on the above information, we have determined that there is no need for the NPRM, Docket No. 99-CE-46-AD, and that we should withdraw it.

Withdrawal of this NPRM does not prevent us from issuing another notice in the future, nor will it commit us to any course of action in the future.

Regulatory Impact

Does this AD involve a significant rule or regulatory action? Since this action only withdraws a proposed AD, it is not an AD and, therefore, is not covered under Executive Order 12866, the Regulatory Flexibility Act, or DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979).

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

The Withdrawal

Accordingly, FAA withdraws the notice of proposed rulemaking, Docket No. 99-CE-46-AD, published in the **Federal Register** on October 12, 1999 (64 FR 55188).

Issued in Kansas City, Missouri, on August 23, 2000.

Marvin R. Nuss,

Acting Manager, Small Airplane Directorate, Aircraft Certification Service.

[FR Doc. 00-22124 Filed 8-29-00; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION**Federal Aviation Administration****14 CFR Part 39**

[Docket No. 2000-NM-265-AD]

RIN 2120-AA64

Airworthiness Directives; Lockheed Model 188A and 188C Series Airplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: This document proposes the adoption of a new airworthiness directive (AD) that is applicable to all Lockheed Model 188A and 188C series airplanes. This proposal would require a revision of the Airplane Flight Manual (AFM) to add procedures for donning the flightcrew oxygen masks when the cabin altitude warning horn is activated. This action is intended to prevent incapacitation of the flightcrew as a result of lack of oxygen and consequent loss of control of the airplane due to absence of AFM procedures for donning the flightcrew oxygen masks when the cabin altitude warning horn is activated.

DATES: Comments must be received by October 16, 2000.

ADDRESSES: Submit comments in triplicate to the Federal Aviation Administration (FAA), Transport Airplane Directorate, ANM-114, Attention: Rules Docket No. 2000-NM-265-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056. Comments may be inspected at this location between 9 a.m. and 3 p.m., Monday through Friday, except Federal holidays. Comments may be submitted via fax to (425) 227-1232. Comments may also be sent via the Internet using the following address: 9-anm-

nprmcmmnt@faa.gov. Comments sent via fax or the Internet must contain "Docket No. 2000-NM-265-AD" in the subject line and need not be submitted in triplicate. Comments sent via the Internet as attached electronic files must be formatted in Microsoft Word 97 for Windows or ASCII text.

This information may be examined at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the FAA, Atlanta Aircraft Certification Office, One Crown Center, 1895 Phoenix Boulevard, suite 450, Atlanta, Georgia 30349.

FOR FURTHER INFORMATION CONTACT:

Thomas Peters, Aerospace Engineer, Systems and Flight Test Branch, ACE-116A, FAA, Atlanta Aircraft Certification Office, One Crown Center, 1895 Phoenix Boulevard, suite 450, Atlanta, Georgia 30349; telephone (770) 703-6063 fax (770) 703-6097.

SUPPLEMENTARY INFORMATION:**Comments Invited**

Interested persons are invited to participate in the making of the proposed rule by submitting such written data, views, or arguments as they may desire. Communications shall identify the Rules Docket number and be submitted in triplicate to the address specified above. All communications received on or before the closing date for comments, specified above, will be considered before taking action on the proposed rule. The proposals contained in this notice may be changed in light of the comments received.

Submit comments using the following format:

- Organize comments issue-by-issue. For example, discuss a request to change the compliance time and a request to change the service bulletin reference as two separate issues.
- For each issue, state what specific change to the proposed AD is being requested.
- Include justification (*e.g.*, reasons or data) for each request.

Comments are specifically invited on the overall regulatory, economic, environmental, and energy aspects of the proposed rule. All comments submitted will be available, both before and after the closing date for comments, in the Rules Docket for examination by interested persons. A report summarizing each FAA-public contact concerned with the substance of this proposal will be filed in the Rules Docket.

Commenters wishing the FAA to acknowledge receipt of their comments submitted in response to this notice

must submit a self-addressed, stamped postcard on which the following statement is made: "Comments to Docket Number 2000-NM-265-AD." The postcard will be date stamped and returned to the commenter.

Availability of NPRMs

Any person may obtain a copy of this NPRM by submitting a request to the FAA, Transport Airplane Directorate, ANM-114, Attention: Rules Docket No. 2000-NM-265-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056.

Discussion

On October 25, 1999, a Learjet Model 35 series airplane operating under part 135 of the Federal Aviation Regulations (14 CFR part 135) departed Orlando International Airport enroute to Dallas, Texas. Air traffic control lost communication with the airplane near Gainesville, Florida. Air Force and National Guard airplanes intercepted the airplane, but the flightcrews of the chase airplanes indicated that the windows of the Model 35 series airplane were apparently frosted over and prevented the chase airplane flightcrews from observing the interior of the Model 35 series airplane. The flightcrews of the chase airplanes reported that they did not observe any damage to the airplane. Subsequently, the Model 35 series airplane ran out of fuel and crashed in South Dakota. To date, causal factors of the accident have not been determined. However, lack of the Learjet flightcrew's response to air traffic control poses the possibility of flightcrew incapacitation and raises concerns with the pressurization and oxygen systems.

Recognizing these concerns, the FAA initiated a special certification review (SCR) to determine if pressurization and oxygen systems on Model 35 series airplanes were certificated properly, and to determine if any unsafe design features exist in the pressurization and oxygen systems.

The SCR team found that there have been several accidents and incidents that may have involved incapacitation of the flightcrews during flight. In one case, the airplane flightcrew did not activate the pressurization system or don their oxygen masks and the airplane flew in excess of 35,000 feet altitude. In another case, the airplane flightcrews did not don their oxygen masks when the cabin aural warning was activated. Further review by the SCR team indicates that the Airplane Flight Manual (AFM) of Learjet Model 35/36 series airplanes do not have an emergency procedure that requires donning the flightcrew oxygen masks when the cabin altitude aural warning is