

A copy of it may be obtained by contacting the Rules Docket at the location provided under the caption **ADDRESSES**.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

The Proposed Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration proposes to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. Section 39.13 is amended by removing Amendment 39–11734 (65 FR 32016, May 22, 2000) and by adding a new airworthiness directive (AD) to read as follows:

Eurocopter France: Docket No. 2000–SW–30–AD. Supersedes AD 2000–10–10, Amendment 39–11734, Docket No. 99–SW–39–AD.

Applicability: Model AS–350B, BA, B1, B2, and D; and AS–355E, F, F1, F2, and N helicopters, with main gearbox suspension bi-directional cross beam (cross beam), part number (P/N) 350A38–1018-all dash numbers, installed, certificated in any category.

Note 1: This AD applies to each helicopter identified in the preceding applicability provision, regardless of whether it has been otherwise modified, altered, or repaired in the area subject to the requirements of this AD. For helicopters that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (e) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

Compliance: Required as indicated, unless accomplished previously.

To prevent failure of the cross beam that could lead to rotation of the main gearbox, severe vibrations, and a subsequent forced landing, accomplish the following:

(a) For cross beams having 2,000 or more hours time-in-service (TIS) or 10,000 or more operating cycles, whichever occurs first:

Note 2: The Master Service Recommendations and the flight log contain accepted procedures that are used to determine the cumulative operating cycles on the rotorcraft.

(1) Within 30 hours TIS, and thereafter at intervals not to exceed 30 hours TIS or 150 operating cycles, whichever occurs first, visually inspect the cross beam for a crack in accordance with paragraph 2.B.1) of Eurocopter France Service Bulletin No. 05.00.28, applicable to Model AS–350 helicopters, or Eurocopter France Service Bulletin No. 05.00.29, applicable to Model AS–355 helicopters, both dated May 26, 1997.

(2) If a crack is found, remove the cross beam and replace it with an airworthy cross beam.

(b) For cross beams having 5,000 or more hours TIS:

(1) Within 550 hours TIS or 2,750 operating cycles, whichever occurs first, perform a dye-penetrant inspection in accordance with paragraph 2.B.2) of Eurocopter France Service Bulletin No. 05.00.28, applicable to Model AS–350 helicopters, or Eurocopter Service Bulletin No. 05.00.29, applicable to Model AS–355 helicopters, both dated May 26, 1996.

(2) If a crack is found, remove the cross beam and replace it with an airworthy cross beam.

(c) Before installing any replacement cross beams, regardless of TIS or operating cycles, inspect the replacement cross beam in accordance with paragraph (b)(1) of this AD.

(d) Modifying the helicopter in accordance with paragraph 2.B of the Accomplishment Instructions in Eurocopter Service Bulletin No. 63.00.07, applicable to Model AS–350B, BA, B1, B2, and D helicopters, or Eurocopter Service Bulletin No. 63.00.13, applicable to Model AS–355E, F, F1, F2, and N helicopters, both dated April 7, 1997, constitutes terminating action for the requirements of this AD.

(e) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, Regulations Group, FAA, Rotorcraft Directorate. Operators shall submit their requests through an FAA Principal Maintenance Inspector, who may concur or comment and then send it to the Manager, Regulations Group.

Note 3: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Regulations Group.

(f) Special flight permits may be issued in accordance with 14 CFR 21.197 and 21.199 to operate the helicopter to a location where the requirements of this AD can be accomplished.

Note 4: The subject of this AD is addressed in Direction Generale De L'Aviation Civile (France) AD 96–156–071(B)R1 and AD 96–155–053(B)R1, both dated June 4, 1997.

Issued in Fort Worth, Texas, on September 1, 2000.

Henry A. Armstrong,

Manager, Rotorcraft Directorate, Aircraft Certification Service.

[FR Doc. 00–23210 Filed 9–8–00; 8:45 am]

BILLING CODE 4910–13–U

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 71

[Airspace Docket No. 00–AEA–03]

Proposed Amendment to Class E Airspace; Salisbury, MD

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking.

SUMMARY: This notice proposes to amend the Class E airspace area at Salisbury, MD. Establishment of Class D airspace at Salisbury, MD, necessitated by the opening of a new Control Tower (ATCT) at the airport, requires this action be taken to amend the Class E airspace.

DATES: Comments must be received on or before October 11, 2000.

ADDRESSES: Send comments on the proposal in triplicate to: Manager, Airspace Branch, AEA–520, Docket No. 00–AEA–03, Eastern Region, 1 Aviation Plaza, Jamaica, NY 11434–4809.

The official docket may be examined in the Office of the Regional Counsel, AEA–7 Eastern Region, 1 Aviation Plaza, Jamaica, NY 11434–4809.

An informal docket may also be examined during normal business hours in the Airspace Branch, AEA–520, Eastern Region, 1 Aviation Plaza, Jamaica, NY 11434–4809.

FOR FURTHER INFORMATION CONTACT: Mr. Francis T. Jordan, Jr., Airspace Specialist, Airspace Branch, AEA–520 Eastern Region, 1 Aviation Plaza, Jamaica, NY 11434–4809, telephone: (718) 553–4521.

SUPPLEMENTARY INFORMATION:

Comments Invited

Interested parties are invited to participate in this proposed rulemaking by submitting such written data, views, or arguments as they may desire. Comments that provide the factual basis supporting the views and suggestions presented are particularly helpful in developing reasoned regulatory decisions on the proposal. Comments are specifically invited on the overall regulatory, economic, environmental, and energy-related aspects of the proposal. Communications should identify the airspace docket number and be submitted in triplicate to the address listed above. Comments wishing the FAA to acknowledge receipt of their comments on this notice must submit with those comments a self-addressed, stamped postcard on which the following statement is made:

"Comments to Airspace Docket No. 00-AEA-03." The postcard will be date/time stamped and returned to the commenter. All communications received on or before the closing date for comments will be considered before taking action on the proposed rule. The proposal contained in this notice may be changed in light of comments received. All comments submitted will be available for examination in the Rules Docket both before and after the closing date for comments. A report summarizing each substantive public contact with the FAA personnel concerned with this rulemaking will be filed in the docket.

Availability of NPRMs

Any person may obtain a copy of this Notice of Proposed Rulemaking (NPRM) by submitting a request to the Office of the Regional Counsel, AEA-7, Eastern Region, 1 Aviation Plaza, Jamaica, NY, 11434-4809. Communications must identify the notice number of this NPRM. Persons interested in being placed on a mailing list for future NPRMs should also request a copy of Advisory Circular No. 11-2A, which describes the application procedure.

The Proposal

The FAA is considering an amendment to Part 71 of the Federal Aviation Regulations (14 CFR Part 71) to amend the Class E airspace area at Salisbury, MD. Class D airspace extending upward from the surface to and including 2,500 feet MSL is now in effect during times as published in the Airport Facility Directory. During other periods of time the airspace reverts back to Class E airspace. Class E airspace designations for airspace areas extending upward from the surface are published in Paragraph 6002 of FAA Order 7400.9F, dated September 10, 1999, and effective September 16, 1999, which in incorporated by reference in 14 CFR 71.1. The Class E airspace designation listed in this document would be published subsequently in the Order.

The Rule

The FAA has determined that this proposed regulation only involves an established body of technical regulations for which frequent and routine amendments are necessary to keep them operationally current. Therefore, this proposed regulation—(1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034; February 26, 1979); and (3) does not warrant preparation of a

regulatory evaluation as the anticipated impact is so minimal. Since this is a routine matter that would only affect air traffic procedures and air navigation, it is certified that this proposal rule would not have significant economic impact on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 71

Airspace, Incorporation by reference, Navigation (air).

The Proposed Amendment

In consideration of the foregoing, the Federal Aviation Administration proposed to amend 14 CFR Part 71 as follows:

PART 71—[AMENDED]

1. The authority citation for 14 CFR Part 71 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40103, 40113, 40120; E.O. 10854; 24 FR 9565, 3 CFR, 1959-1963 Comp., p. 389.

§ 71.1 [Amended]

2. The incorporation by reference in 14 CFR 71.1 of Federal Aviation Administration Order 7400.9F, dated September 10, 1999, and effective September 16, 1999, is proposed to be amended as follows:

Paragraph 60002 Class E airspace areas extending upward from the surface of the earth.

* * * * *

AEA MD E2 Salisbury, MD [Revised]

Salisbury-Ocean City, Wicomico County Regional Airport, MD
(Lat. 38°20.43' N./long. 75°30.62' W.)

Within a 4.1 mile radius of the Salisbury-Wicomico County Airport and within 3.1 miles each side of the Salisbury VORTAC 209° radial extending from the 4.1 mile radius to 9.2 miles southwest of the VORTAC and within 3.1 miles each side of the Salisbury VORTAC 052° radial extending from the 4.1 mile radius to 8.3 miles northeast of the VORTAC and within 1 mile each side of the Salisbury-Wicomico County Airport localizer northwest course extending from the 4.1 mile radius to 4.8 miles northwest of the localizer and within 3.1 miles each side of the Salisbury VORTAC 132° radial extending from the 4.1 mile radius to 9.2 miles southeast of the VORTAC. This Class E airspace area is effective during those times when the Class D airspace is not in effect.

* * * * *

Dated: Issued in Jamaica, New York, on September 1, 2000.

Franklin D. Hatfield,

Manager, Air Traffic Division, Eastern Region.

[FR Doc. 00-23265 Filed 9-8-00; 8:45 am]

BILLING CODE 4910-13-M

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 71

[Airspace Docket No. 00-AEA-04]

Proposed Amendment to Class E Airspace; Westminster Clearview Airpark, MD

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking.

SUMMARY: This notice proposes to amend the Class E airspace area at Westminster, MD. The development of a Standard Instrument Approach Procedure (SIAP) based on the Global Positioning System (GPS) at Clearview Airpark (2W2), Westminster, MD has made this proposal necessary. Sufficient controlled airspace is needed to accommodate the SIAP and for Instrument Flight Rules (IFR) operations to the airport. The area would be depicted on aeronautical charts for pilot reference.

DATES: Comments must be received on or before October 11, 2000.

ADDRESSES: Send comments on the proposal in triplicate to: Manager, Airspace Branch, AEA-520, Docket No. 00-AEA-04, Eastern Region, 1 Aviation Plaza, Jamaica, NY 11434-4809.

The official docket may be examined in the Office of the Regional Counsel, AEA-7, Eastern Region, 1 Aviation Plaza, Jamaica, NY 11434-4809.

An informal docket may also be examined during normal business hours in the Airspace Branch, AEA-520, Eastern Region, 1 Aviation Plaza, Jamaica, NY 11434-4809.

FOR FURTHER INFORMATION CONTACT: Mr. Francis T. Jordan, Jr., Airspace Specialist, Airspace Branch, AEA-520, Eastern Region, 1 Aviation Plaza, Jamaica, NY 11434-4809, telephone: (718) 553-4521.

SUPPLEMENTARY INFORMATION:

Comments Invited

Interested parties are invited to participate in this proposed rulemaking by submitting such written data, views, or arguments as they may desire. Comments that provide the factual basis supporting the views and suggestions presented are particularly helpful in developing reasoned regulatory decisions on the proposal. Comments are specifically invited on the overall regulatory, economic, environmental, and energy-related aspects of the proposal. Communications should identify the airspace docket number and