

development and revitalization of the communities they serve. Student credit unions not only provide their members with valuable financial services generally not available but also a unique opportunity for financial education. NCUA believes that well run student credit unions would benefit greatly from participation in the CDRLP and, as a result, would be better able to serve their communities. Accordingly, NCUA proposes to amend the CDRLP regulations to allow student credit unions to participate in the program.

B. 30-Day Comment Period

As a matter of agency policy, NCUA generally allows interested persons a 60-day period to comment on a proposed rule. NCUA's Interpretive Ruling and Policy Statement 87-2. NCUA has determined that a 30-day comment period is sufficient in this instance. The simplicity of the rule change will allow meaningful public participation in the rulemaking process in a shorter time period. Additionally, the shorter comment period will enable student credit unions newly eligible to participate in the CDRLP to take advantage of current funding opportunities due to expire in a number of months.

Regulatory Procedures

Regulatory Flexibility Act

The Regulatory Flexibility Act requires NCUA to prepare an analysis to describe any significant economic impact a proposed rule may have on a substantial number of small credit unions (those under ten million dollars in assets). The proposed rule permits student credit unions to participate in the CDRLP, without imposing any additional regulatory burden. The proposed rule would not have a significant economic impact on a substantial number of small credit unions, and, therefore, a regulatory flexibility analysis is not required.

Paperwork Reduction Act

NCUA has determined that the proposed rule would not increase paperwork requirements under the Paperwork Reduction Act of 1995 and regulations of the Office of Management and Budget.

Executive Order 13132

Executive Order 13132 encourages independent regulatory agencies to consider the impact of their actions on state and local interests. In adherence to fundamental federalism principles, NCUA, an independent regulatory agency as defined in 44 U.S.C. 3502(5), voluntarily complies with the executive

order. The proposed rule would not have substantial direct effects on the states, on the connection between the national government and the states, or on the distribution of power and responsibilities among the various levels of government. NCUA has determined that this proposed rule does not constitute a policy that has federalism implications for purposes of the executive order.

The Treasury and General Government Appropriations Act, 1999—Assessment of Federal Regulations and Policies on Families

The NCUA has determined that this proposed rule would not affect family well-being within the meaning of section 654 of the Treasury and General Government Appropriations Act, 1999, Public Law 105-277, 112 Stat. 2681 (1998).

Agency Regulatory Goal

NCUA's goal is to promulgate clear and understandable regulations that impose minimal regulatory burden. We request your comments on whether the proposed rule is understandable and minimally intrusive.

List of Subjects in 12 CFR Part 705

Community development, Credit unions, Loan programs-housing and community development, Reporting and recordkeeping requirements, Technical assistance.

By the National Credit Union Administration Board on April 15, 2004.

Becky Baker,

Secretary of the Board.

For the reasons stated, NCUA proposes to amend 12 CFR part 705 as follows:

PART 705—COMMUNITY DEVELOPMENT REVOLVING LOAN PROGRAM FOR CREDIT UNIONS

1. The authority citation for part 705 continues to read as follows:

Authority: 12 U.S.C. 1772c-1; 42 U.S.C. 9822 and 9822 note.

§ 705.3 [Amended]

2. Remove the parenthetical clause "(excluding student credit unions)" from § 705.3(b).

[FR Doc. 04-9001 Filed 4-20-04; 8:45 am]

BILLING CODE 7535-01-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 2003-CE-68-AD]

RIN 2120-AA64

Airworthiness Directives; Przedsiębiorstwo Doswiadczalno-Produkcyjne Szybownictwa "PZL-Bielsko" Model SZD-50-3 "Puchacz" Sailplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: The FAA proposes to adopt a new airworthiness directive (AD) for all Przedsiębiorstwo Doswiadczalno-Produkcyjne Szybownictwa "PZL-Bielsko" (PZL-Bielsko) Model SZD-50-3 "Puchacz" sailplanes. This proposed AD would require you to repetitively inspect the front and back of the fuselage front bulkhead attachment fitting for cracks and replace the attachment fitting if any cracks are found. This proposed AD is the result of mandatory continuing airworthiness information (MCAI) issued by the airworthiness authority for Poland. We are issuing this proposed AD to detect and correct cracks in the fuselage front bulkhead attachment fitting, which could result in structural failure of the bulkhead. This failure could lead to loss of control of the sailplane.

DATES: We must receive any comments on this proposed AD by May 24, 2004.

ADDRESSES: Use one of the following to submit comments on this proposed AD:

- *By mail:* FAA, Central Region, Office of the Regional Counsel, Attention: Rules Docket No. 2003-CE-68-AD, 901 Locust, Room 506, Kansas City, Missouri 64106.
- *By fax:* (816) 329-3771.
- *By e-mail:* 9-ACE-7-

Docket@faa.gov. Comments sent electronically must contain "Docket No. 2003-CE-68-AD" in the subject line. If you send comments electronically as attached electronic files, the files must be formatted in Microsoft Word 97 for Windows or ASCII.

You may get the service information identified in this proposed AD from Przedsiębiorstwo Doswiadczalno-Produkcyjne Szybownictwa PZL-Bielsko, ul. Cieszyńska 325, 43-300 Bielsko-Biala; telephone: +48 033 812 50 21; facsimile: +48 033 812 37 39.

You may view the AD docket at FAA, Central Region, Office of the Regional Counsel, Attention: Rules Docket No.

2003-CE-68-AD, 901 Locust, Room 506, Kansas City, Missouri 64106. Office hours are 8 a.m. to 4 p.m., Monday through Friday, except Federal holidays.

FOR FURTHER INFORMATION CONTACT: Greg Davison, Aerospace Engineer, FAA, Small Airplane Directorate, 901 Locust, Room 301, Kansas City, Missouri 64106; telephone: (816) 329-4130; facsimile: (816) 329-4090.

SUPPLEMENTARY INFORMATION:

Comments Invited

How do I comment on this proposed AD? We invite you to submit any written relevant data, views, or arguments regarding this proposal. Send your comments to an address listed under **ADDRESSES**. Include "AD Docket No. 2003-CE-68-AD" in the subject line of your comments. If you want us to acknowledge receipt of your mailed comments, send us a self-addressed, stamped postcard with the docket number written on it. We will date-stamp your postcard and mail it back to you.

Are there any specific portions of this proposed AD I should pay attention to? We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this proposed AD. If you contact us through a nonwritten communication and that contact relates to a substantive part of this proposed AD, we will summarize the contact and place the summary in the docket. We will consider all comments received by the closing date and may amend this proposed AD in light of those comments and contacts.

Discussion

What events have caused this proposed AD? The General Inspectorate of Civil Aviation (GICA), which is the airworthiness authority for Poland recently notified FAA that an unsafe condition may exist on all PZL-Bielsko Model SZD-50-3 "Puchacz" sailplanes. The GICA reports that cracks were detected in the front bracket console mounted on the fuselage front bulkhead.

What are the consequences if the condition is not corrected? This condition, if not detected and corrected, could cause the fuselage front bulkhead to fail. Failure of the fuselage front bulkhead could result in loss of control of the sailplane.

Is there service information that applies to this subject? Przedsiębiorstwo Doświadczalno-Produkcyjne

Szybownictwa PZL-Bielsko (PDPS "PZL-Bielsko") has issued Mandatory Bulletin No. BE-048/SZD-50-3/2000 "Puchacz," dated June 6, 2000, and Mandatory Bulletin No. BE-049/SZD-50-3/2000 "Puchacz," dated September 14, 2000.

What are the provisions of this service information? These service bulletins include procedures for:

- Repetitively inspecting the front and back of the fuselage front bulkhead attachment fitting for cracks; and
- Replacing the attachment fitting on the fuselage front bulkhead if any cracks are found.

What action did the GICA take? The GICA classified these service bulletins as mandatory and issued Republic of Poland AD Number SP-0059-2000-A, dated June 5, 2000, and AD Number SP-0094-2000-A, dated September 18, 2000, to ensure the continued airworthiness of these sailplanes in Poland.

Did the GICA inform the United States under the bilateral airworthiness agreement? These PZL-Bielsko Model SZD-50-3 "Puchacz" sailplanes are manufactured in Poland and are type-certificated for operation in the United States under the provisions of section 21.29 of the Federal Aviation Regulations (14 CFR 21.29) and the applicable bilateral airworthiness agreement.

Under this bilateral airworthiness agreement, the GICA has kept us informed of the situation described above.

FAA's Determination and Requirements of This Proposed AD

What has FAA decided? We have examined the GICA's findings, reviewed all available information, and determined that AD action is necessary for products of this type design that are certificated for operation in the United States.

Since the unsafe condition described previously is likely to exist or develop on other PZL-Bielsko Model SZD-50-3 "Puchacz" sailplanes of the same type design that are registered in the United States, we are proposing AD action to detect and correct cracks in the fuselage front bulkhead, which could result in structural failure of the bulkhead. This failure could lead to loss of control of the sailplane.

Is there a modification I can incorporate instead of repetitively inspecting the front and back of the fuselage front bulkhead attachment

fitting for cracks? The FAA has determined that long-term continued operational safety would be better assured by design changes that remove the source of the problem rather than by repetitive inspections or other special procedures. With this in mind, FAA will continue to work with PZL-Bielsko in performing further tests to determine the cause of the cracking and to provide a corrective action that would terminate the need for repetitive inspections.

What would this proposed AD require? This proposed AD would require you to incorporate the actions in the previously-referenced service bulletins.

What is the difference between this proposed AD and the service information? The manufacturer's service information allows continued flight if cracks are found in the fuselage front bulkhead attachment fitting that do not exceed certain limits. The applicable service bulletin specifies replacement of the fuselage front bulkhead attachment fitting only if cracks are found exceeding this limit. This proposed AD would not allow continued flight if any crack is found. FAA policy is to disallow airplane operation when known cracks exist in primary structure, unless the ability to sustain ultimate load with these cracks is proven. The fuselage front bulkhead is considered primary structure, and the FAA has not received any analysis to prove that ultimate load can be sustained with cracks in this area.

How does the revision to 14 CFR part 39 affect this proposed AD? On July 10, 2002, we published a new version of 14 CFR part 39 (67 FR 47997, July 22, 2002), which governs FAA's AD system. This regulation now includes material that relates to altered products, special flight permits, and alternative methods of compliance. This material previously was included in each individual AD. Since this material is included in 14 CFR part 39, we will not include it in future AD actions.

Costs of Compliance

How many sailplanes would this proposed AD impact? We estimate that this proposed AD affects 8 sailplanes in the U.S. registry.

What would be the cost impact of this proposed AD on owners/operators of the affected sailplanes? We estimate the following costs to accomplish this proposed inspection:

Labor cost	Parts cost	Total cost per sailplane	Total cost on U.S. operators
2 workhours × \$65 per hour = \$130	Not applicable	\$130	\$130 × 8 = \$1,040

We estimate the following costs to accomplish any necessary replacement that would be required based on the

results of this proposed inspection. We have no way of determining the number

of sailplanes that may need such a replacement:

Labor cost	Parts cost	Total cost per sailplane
10 workhours × \$65 per hour = \$650	\$680	\$650 + \$680 = \$1,330

Regulatory Findings

Would this proposed AD impact various entities? We have determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

Would this proposed AD involve a significant rule or regulatory action? For the reasons discussed above, I certify that this proposed AD:

1. Is not a "significant regulatory action" under Executive Order 12866;
2. Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and
3. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared a summary of the costs to comply with this proposed AD and placed it in the AD Docket. You may get

a copy of this summary by sending a request to us at the address listed under **ADDRESSES**. Include "AD Docket No. 2003-CE-68-AD" in your request.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the Federal Aviation Administration proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

Przedsiębiorstwo Doświadczalno-Produkcyjne Szybownictwa "PZL-Bielsko": Docket No. 2003-CE-68-AD

When Is the Last Date I Can Submit Comments on This Proposed AD?

- (a) We must receive comments on this proposed airworthiness directive (AD) by May 24, 2004.

What Other ADs Are Affected by This Action?

- (b) None.

What Sailplanes Are Affected by This AD?

- (c) This AD affects Model SZD-50-3 "Puchacz" sailplanes, all serial numbers, that are certificated in any category.

What Is the Unsafe Condition Presented in This AD?

- (d) This AD is the result of mandatory continuing airworthiness information (MCAI) issued by the airworthiness authority for Poland. We are issuing this proposed AD to detect and correct cracks in the fuselage front bulkhead attachment fitting, which could result in structural failure of the bulkhead. This failure could lead to loss of control of the sailplane.

What Must I Do To Address This Problem?

- (e) To address this problem, you must do the following:

Actions	Compliance	Procedures
(1) Using a fluorescent dye-penetrant or dye-check method, inspect the front and back of the fuselage front bulkhead attachment fitting for cracks.	Within the next 25 hours time-in-service (TIS) after the effective date of this AD. Repetitively inspect thereafter at intervals not to exceed 12 calendar months.	Follow Przedsiębiorstwo Doświadczalno-Produkcyjne Szybownictwa PZL-Bielsko (PDPS "PZL-Bielsko") Mandatory Bulletin No. BE-048/SZD-50-3/2000 "Puchacz", dated June 6, 2000.
(2) If cracks are found during any inspection required in paragraph (e)(1) of this AD, replace the fuselage front bulkhead attachment fitting.	Prior to further flight after any inspection required in paragraph (e)(1) of this AD in which cracks are found.	Follow Przedsiębiorstwo Doświadczalno-Produkcyjne Szybownictwa PZL-Bielsko (SZD "PZL-Bielsko") Mandatory Bulletin No. BE-049/SZD-50-3/2000 "Puchacz", dated September 14, 2000.

May I Request an Alternative Method of Compliance?

- (f) You may request a different method of compliance or a different compliance time for this AD by following the procedures in 14 CFR 39.19. Unless FAA authorizes otherwise, send your request to your principal inspector. The principal inspector may add comments and will send your request to the

Manager, Standards Office, Small Airplane Directorate, FAA. For information on any already approved alternative methods of compliance, contact Greg Davison, Aerospace Engineer, FAA, Small Airplane Directorate, 901 Locust, Room 301, Kansas City, Missouri 64106; telephone: (816) 329-4130; facsimile: (816) 329-4090.

May I Get Copies of the Documents Referenced in This AD?

- (g) You may get copies of the documents referenced in this AD from Przedsiębiorstwo Doświadczalno-Produkcyjne Szybownictwa PZL-Bielsko, ul. Cieszyńska 325, 43-300 Bielsko-Biala; telephone: +48 033 812 50 21; facsimile: +48 033 812 37 39. You may view these documents at FAA, Central Region,

Office of the Regional Counsel, 901 Locust, Room 506, Kansas City, Missouri 64106.

Is There Other Information That Relates to This Subject?

(h) Republic of Poland AD Number SP-0059-2000-A, dated June 5, 2000, and AD Number SP-0094-2000-A, dated September 18, 2000, also address the subject of this AD.

Issued in Kansas City, Missouri, on April 15, 2004.

James E. Jackson,

Acting Manager, Small Airplane Directorate, Aircraft Certification Service.

[FR Doc. 04-9018 Filed 4-20-04; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 71

[Docket No. FAA-2004-17136; Airspace Docket No. 04-AGL-08]

Proposed Modification of Class D Airspace; Camp Douglas, WI

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking.

SUMMARY: This document proposes to modify Class D airspace at Camp Douglas, WI. Instrument Flight Rules (IFR) Category E circling procedures are being used at Volk Field, WI. Increasing the current radius of the Class D airspace area will allow for a lower Circling Minimum Descent Altitude. Controlled airspace extending upward from the surface of the earth is needed to contain aircraft executing these approach procedures. This action would increase the area of the existing controlled airspace for Volk Field, Camp Douglas, WI.

DATES: Comments must be received on or before June 21, 2004.

ADDRESSES: Send comments on the proposal to the Docket Management System, U.S. Department of Transportation, Room Plaza 401, 400 Seventh Street, SW., Washington, DC 20590-0001. You must identify the docket Number FAA-2004-17136/ Airspace Docket No. 04-AGL-08, at the beginning of your comments. You may also submit comments on the Internet at <http://dms.dot.gov>. You may review the public docket containing the proposal, any comments received, and any final disposition in person in the Dockets Office between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The Docket Office (telephone 1-800-647-5527) is on the plaza level of the Department of Transportation NASSIF Building at the above address.

An informal docket may also be examined during normal business hours at the office of the Regional Air Traffic Division, Federal Aviation Administration, 2300 East Devon Avenue, Des Plaines, Illinois 60018.

FOR FURTHER INFORMATION CONTACT: Patricia A. Graham, Air Traffic Division, Airspace Branch, AGL-520, Federal Aviation Administration, 2300 East Devon Avenue, Des Plaines, Illinois 60018, telephone (847) 294-7568.

SUPPLEMENTARY INFORMATION:

Comments Invited

Interested parties are invited to participate in this proposed rulemaking by submitting such written data, views, or arguments as they may desire. Comments that provide the factual basis supporting the views and suggestions presented are particularly helpful in developing reasoned regulatory decisions on the proposal. Comments are specifically invited on the overall regulatory, aeronautical, economic, environmental, and energy-related aspects of the proposal. Communications should identify both docket numbers and be submitted in triplicate to the address listed above. Commenters wishing the FAA to acknowledge receipt of their comments on this document must submit with those comments a self-addressed, stamped postcard on which the following statement is made: "Comments to Docket No. FAA-2004-17136/Airspace Docket No. 04-AGL-08." The postcard will be date/time stamped and returned to the commenter. All communications received on or before the specified closing date for comments will be considered before taking action on the proposed rule. The proposal contained in this action may be changed in light of comments received. All comments submitted will be available for examination in the Rules Docket, FAA, Great Lakes Region, Office of the Regional Counsel, 2300 East Devon Avenue, Des Plaines, Illinois, both before and after the closing date for comments. A report summarizing each substantive public contact with FAA personnel concerned with this rulemaking will be filed in the docket.

Availability of NPRM's

An electronic copy of this document may be downloaded through the Internet at <http://dms.dot.gov>. Recently published rulemaking documents can also be accessed through the FAA's Web page at <http://www.faa.gov> or the Superintendent of Document's Web page at <http://www.access.gpo.gov/nara>.

Additionally, any person may obtain a copy of this notice by submitting a request to the Federal Aviation Administration, Office of Air Traffic Airspace Management, ATA-400, 800 Independence Avenue, SW., Washington, DC 20591, or by calling (202) 267-8783. Communications must identify both docket numbers for this notice. Persons interested in being placed on a mailing list for future NPRM's should contact the FAA's Office of Rulemaking, (202) 267-9677, to request a copy of Advisory Circular No. 11-2A, Notice of Proposed Rulemaking Distribution System, which describes the application procedure.

The Proposal

The FAA is considering an amendment to 14 CFR part 71 to modify Class D airspace at Camp Douglas, WI, for Volk Field. Controlled airspace extending upward from the surface of the earth is needed to contain aircraft executing instrument approach procedures. The area would be depicted on appropriate aeronautical charts. Class D airspace areas extending upward from the surface of the earth are published in paragraph 5000 of FAA Order 7400.9L dated September 2, 2003, and effective September 16, 2003, which is incorporated by reference in 14 CFR 71.1. The Class E designations listed in this document would be published subsequently in the order.

The FAA has determined that this proposed regulation only involves an establishment body of technical regulations for which frequent and routine amendments are necessary to keep them operationally current. Therefore this, proposed regulation (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034; February 26, 1979); and (3) does not warrant preparation of a Regulatory Evaluation as the anticipated impact is so minimal. Since this is a routine matter that will only affect air traffic procedures and air navigation, it is certified that this proposed rule will not have a significant economic impact on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 71

Airspace, Incorporation by Reference, Navigation (air).

The Proposed Amendment

Accordingly, pursuant to the authority delegated to me, the Federal Aviation Administration proposes to amend 14 CFR part 71 as follows: