#### List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

### The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the Federal Aviation Administration proposes to amend 14 CFR part 39 as follows:

## PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

#### § 39.13 [Amended]

2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

Pilatus Aircraft Limited: Docket No. FAA– 2004–20006; Directorate Identifier 2004– CE–49–AD

## When Is the Last Date I Can Submit Comments on This Proposed AD?

(a) We must receive comments on this proposed airworthiness directive (AD) by March 18, 2005.

## What Other ADs Are Affected By This Action?

(b) None.

### What Sailplanes Are Affected by This AD?

(c) This AD affects Models B4–PC11, B4–PC11A, and B4–PC11AF sailplanes, all serial numbers, that are certificated in any category.

### What Is the Unsafe Condition Presented in This AD?

(d) This AD is the result of mandatory continuing airworthiness information (MCAI) issued by the airworthiness authority for Switzerland. The actions specified in this AD are intended to detect and correct cracks in the control-column support, which could result in failure of the support. This failure could lead to loss of the primary flight control system.

#### What Must I Do To Address This Problem?

(e) To address this problem, you must do the following:

Actions	Compliance	Procedures
(1) Inspect the control-column support (part number (P/N) 112.35.11.072) for cracks.	Within 12 calendar months after the last inspection under Pilatus Aircraft Ltd. Service Bulletin No. 1005, Revision No. 1, dated April 9, 2003, or Pilatus Aircraft Ltd. Service Bulletin No. 1005, Revision No. 2, dated April 22, 2004, where no cracks were found or within the next 30 days after the effective date of this AD, whichever occurs later, unless already done. Repetitively inspect thereafter at intervals not to exceed every 12 calendar months regardless of whether the control-column support was replaced.	Follow Pilatus Aircraft Ltd. Service Bulletin No. 1005, Revision No. 2, dated April 22, 2004.
(2) If any cracks are found after the inspection required by paragraph (e)(1) of this AD, replace the control-column support (P/N 112.35.11.072) with a new control-column support (P/N 112.35.11.072).	Before further flight after the inspection required by paragraph (e)(1) of this AD where you found the crack. Continue the repetitive inspections required by paragraph (e)(1) of this AD.	Follow Pilatus Aircraft Ltd. Service Bulletin No. 1005, Revision No. 2, dated April 22, 2004.

## May I Request an Alternative Method of Compliance?

(f) You may request a different method of compliance or a different compliance time for this AD by following the procedures in 14 CFR 39.19. Unless FAA authorizes otherwise, send your request to your principal inspector. The principal inspector may add comments and will send your request to the Manager, Standards Office, Small Airplane Directorate, FAA. For information on any already approved alternative methods of compliance, contact Doug Rudolph, Aerospace Engineer, FAA, Small Airplane Directorate, 901 Locust, Room 301, Kansas City, Missouri 64106; telephone: (816) 329–4059; facsimile: (816) 329–4090.

# May I Obtain a Special Flight Permit for the Initial Inspection Requirement of This AD?

(g) No. Special flight permits are not allowed for this AD.

# Is There Other Information That Relates to This Subject?

(h) Swiss AD Number HB 2004–491, dated December 23, 2004, also addresses the subject of this AD.

## May I Get Copies of the Documents Referenced in This AD?

(i) To get copies of the documents referenced in this AD, contact Pilatus Aircraft

Ltd., Customer Liaison Manager, CH–6371 Stans, Switzerland; telephone: +41 41 619 6208; facsimile: +41 41 619 7311; email: fodermatt@pilatus-aircraft.com or from Pilatus Business Aircraft Ltd., Product Support Department, 11755 Airport Way, Broomfield, Colorado 80021; telephone: (303) 465–9099; facsimile: (303) 465–6040. To view the AD docket, go to the Docket Management Facility; U.S. Department of Transportation, 400 Seventh Street, SW., Nassif Building, Room PL–401, Washington, DC, or on the Internet at http://dms.dot.gov. This is docket number FAA–2004–20006.

Issued in Kansas City, Missouri, on February 7, 2005.

### David R. Showers,

Acting Manager, Small Airplane Directorate, Aircraft Certification Service. [FR Doc. 05–2696 Filed 2–10–05; 8:45 am]

BILLING CODE 4910-13-P

# FEDERAL COMMUNICATIONS COMMISSION

#### 47 CFR Part 73

[DA 05-74; MB Docket No. 05-17, RM-11113, RM-11114]

Radio Broadcasting Services; Connersville, IN, Erlanger, KY, Lebanon, KY, Lebanon Junction, KY, Madison, IN, Richmond, IN, New Haven, KY, Norwood, OH, and Springfield, KY

**AGENCY:** Federal Communications Commission.

**ACTION:** Proposed rule.

SUMMARY: The Audio Division requests comment on two petitions that are mutually exclusive filed by Rodgers Broadcasting Corporation, licensee of Station WIFE(FM), Channel 262B at Connersville, Indiana; and jointly filed by Washington County CBC, Inc., licensee of Station WAKY–FM, Channel 274A, Springfield, Kentucky, Elizabethtown CBC, Inc., licensee of Station WTHX(FM), Channel 297A, Lebanon Junction, Kentucky and CBC of

Marion County, Inc., licensee of Station WLSK(FM), Channel 265C3, Lebanon, Kentucky. See Supplementary Information.

DATES: Comments must be filed on or

before March 21, 2004, and reply comments on or before April 5, 2005. **ADDRESSES:** Federal Communications Commission, 445 Twelfth Street, SW., Washington, DC. 20554. In addition to filing comments with the FCC, interested parties should serve the petitioner, his counsel, or consultant, as follows: Mark N. Lipp, Esq., J. Thomas Nolan, Esq., Scott Woodworth, Esq, Counsel, Rodgers Broadcasting Corporation, Vinson & Elkins, LLP, 1455 Pennsylvania Avenue, NW., Suite 600, Washington, DC 20004 and John F. Garziglia, Esq., Howard Barr, Esq., Counsel for Washington County CBC, Inc., Elizabethtown CBC, Inc., and CBC of Marion County, Inc., Womble Carlyle

FOR FURTHER INFORMATION CONTACT: Rolanda F. Smith, Media Bureau, (202) 418–2180.

Street, NW., Seventh Floor, Washington,

Sandridge & Rice, PLLC, 1401 Eye

DC 20005.

SUPPLEMENTARY INFORMATION: This is a synopsis of the Commission's Notice of Proposed Rule Making, MB Docket No. 05-17, adopted January 26, 2005 and released January 28, 2005. The full text of this Commission decision is available for inspection and copying during regular business hours at the FCC's Reference Information Center, Portals II, 445 Twelfth Street, SW., Room CY-A257, Washington, DC 20554. The complete text of this decision may also be purchased from the Commission's duplicating contractor, Best Copy and Printing, Inc., 445 12th Street, SW., Room CY-B402, Washington, DC, 20054, telephone 1-800-378-3160 or http://www.BCPIWEB.com.

The first proposal, filed by Rodgers Broadcasting seeks the substitution of Channel 262A for Channel 262B at Connersville, Indiana, reallotment of Channel 262A from Connersville, Indiana to Norwood, Ohio, as its first local service and modification of Station WIFE(FM) license accordingly. Rodgers Broadcasting also requests the substitution of Channel \*265A for vacant Channel \*266A at Madison, Indiana; substitution of Channel 267B1 for Channel 267B at Richmond, Indiana and modification of the FM Station WFMG license; substitution of Channel 266A for Channel 265A at Erlanger, Kentucky and modification of the FM Station WIZF license; and substitution of Channel 265A for Channel 265C3 at Lebanon, Kentucky and modification of the WLSK(FM) license. Channel 262A

can be allotted to Norwood provided there is a site restriction of 9.4 kilometers (5.8 miles) southwest at coordinates 39-07-19 NL and 84-32-52 WL. Channel 266A can be allotted to Erlanger at Station's WIZF current license site at coordinates 39–06–18 NL and 84-33-24 WL. Channel 265A can be allotted to Madison at its current reference site at coordinates 38-49-15 NL and 85-18-46 WL. Channel 267B1 can be allotted to Richmond provided there is a site restriction of 11.6 kilometers (7.2 miles) northwest at coordinates 39-55-09 NL and 84-57-47 WL. Channel 265A can be allotted to Lebanon provided there is a site restriction 9.6 kilometers (6.0 miles) northeast at coordinates 37-38-50 NL and 85-11-50 WL.

The second proposal, jointly filed by Washington County CBC, Inc., licensee of Station WAKY-FM, Channel 274A, Springfield, Kentucky, Elizabethtown CBC, Inc. requests the reallotment of Channel 297A from Lebanon Junction to New Haven, Kentucky, as its first local service and modification of the Station WTHX(FM) license. To prevent removal of Lebanon Junction's sole local service, the Joint Petitioners proposes the reallotment of Channel 274A from Springfield to Lebanon Junction, Kentucky and modification of the Station WAKY-FM license. Moreover, to prevent removal of Springfield's sole local service, the Joint Petitioners requests the substitution of Channel 265A for Channel 265C3 at Lebanon, Kentucky, reallotment of Channel 265A from Lebanon to Springfield, Kentucky and modification of the Station WLSK(FM) license. Channel 297A can be reallotted to New Haven provided there is a site restriction 12.4 kilometers (7.7 miles) northwest at coordinates 37– 43-00 NL and 85-42-38 WL. Channel 274A can be reallotted to Lebanon Junction provided there is a site restriction 13.8 kilometers (8.6 miles) southeast at coordinates 37-46-07 NL and 85-35-57 WL. Channel 265A can be reallotted to Springfield provided there is a site restriction 4.8 kilometers (3.0 miles) at coordinates 37-38-50 NL and 85-11-50 WL.

Provisions of the Regulatory Flexibility Act of 1980 do not apply to this proceeding.

Members of the public should note that from the time a Notice of Proposed Rule Making is issued until the matter is no longer subject to Commission consideration or court review, all *ex parte* contacts are prohibited in Commission proceedings, such as this one, which involve channel allotments. See 47 CFR 1.1204(b) for rules governing permissible *ex parte* contact.

For information regarding proper filing procedures for comments, *see* 47 CFR 1.415 and 1.420.

### List of Subjects in 47 CFR Part 73

Radio, Radio broadcasting.

For the reasons discussed in the preamble, the Federal Communications Commission proposes to amend 47 CFR Part 73 as follows:

# PART 73—RADIO BROADCAST SERVICES

1. The authority citation for part 73 continues to read as follows:

Authority: 47 U.S.C. 154, 303, 334 and 336.

#### §73.202 [Amended]

2. Section 73.202(b), the Table of FM Allotments under Indiana, is amended by removing Connersville, Channel 262B, by removing Channel \*266A and adding Channel \*265A at Madison, by removing Channel 267B and by adding Channel 267B1 at Richmond.

3. Section 73.202(b), the Table of FM Allotments under Kentucky, is amended by removing Channel 265A and adding Channel 266A at Erlanger, by removing Lebanon, Channel 265C3, by removing Channel 297A and adding Channel 274A at Lebanon Junction, by adding New Haven, Channel 297A and by removing Channel 274A and adding Channel 265A at Springfield.

4. Section 73.202(b), the Table of FM Allotments under Ohio, is amended by adding Norwood, Channel 262A.

Federal Communications Commission.

#### John A. Karousos,

Assistant Chief, Audio Division, Media Bureau.

[FR Doc. 05–2705 Filed 2–10–05; 8:45 am] BILLING CODE 6712–01–P

## FEDERAL COMMUNICATIONS COMMISSION

### 47 CFR Part 73

[DA 05-76; MB Docket No. 05-16; RM-11143]

Radio Broadcasting Services; Richlands, Shallotte, Topsail Beach, and Wrightsville Beach, NC

**AGENCY:** Federal Communications Commission.

**ACTION:** Proposed rule.

**SUMMARY:** This document requests comments on a Petition for Rule Making filed by Sea-Comm, Inc., ("Petitioner"), licensee of FM Stations WBNU, Shallotte, North Carolina; WWTB, Topsail Beach, North Carolina, and WBNE, Wrightsville Beach, North