

inspection to determine whether this equipment is installed on the airplane, calculating the total weight of the installed equipment, and comparing that total to the weight limit specified on the placard installed per paragraph (a)(1) of this AD. If the weight is outside the limits specified in the placard to be installed per the service bulletin, before further flight, remove equipment from the rack to meet the weight limit specified in the placard.

(i) For airplanes on which the actions required by paragraph (a)(1) of this AD were done before the effective date of this AD: Within 12 months after the effective date of this AD.

(ii) For airplanes on which the actions required by paragraph (a)(1) of this AD are done after the effective date of this AD: Before further flight after installing the placards.

Note 1: For the purposes of this AD, a detailed inspection is defined as: "An intensive visual examination of a specific structural area, system, installation, or assembly to detect damage, failure, or irregularity. Available lighting is normally supplemented with a direct source of good lighting at intensity deemed appropriate by the inspector. Inspection aids such as mirror, magnifying lenses, etc., may be used. Surface cleaning and elaborate access procedures may be required."

Inspection To Measure Exposed Thread and Corrective Actions

(b) For airplanes in the groups listed in the table under paragraph 3.B.1.b.(1) of the Accomplishment Instructions of Boeing Special Attention Service Bulletin 777-25-0144, Revision 2, dated January 15, 2004: Within 5 years after the effective date of this AD, perform a detailed inspection of the clevis end of the vertical support tie rod for the center stowage bin to measure the exposed thread, per the Accomplishment Instructions of the service bulletin. If the measurement of the exposed thread is outside the limits specified in Figure 2 of the service bulletin, before further flight, perform all corrective actions specified in steps 2 through 14 inclusive of Figure 2 of the service bulletin (including installing a threaded sleeve, torquing the jam nuts, inserting a pin in the witness hole to ensure that the witness hole is blocked by the clevis shank, and making any applicable adjustment of the clevis). Perform the corrective actions per the Accomplishment Instructions of the service bulletin, except as provided by paragraph (e) of this AD.

Replacement of Tie Rods for Center Stowage Bin

(c) For airplanes in Group 21, as listed in the Airplane Group column of the table under 3.B.1.b.(2) of the Accomplishment Instructions of Boeing Special Attention Service Bulletin 777-25-0144, Revision 2, dated January 15, 2004: Within 5 years after the effective date of this AD, replace the vertical support tie rods for the center stowage bin with new improved tie rods (including replacing the existing tie rod with a new improved tie rod, torquing the jam nuts, inserting a pin in the witness hole to

ensure that the witness hole is blocked by the clevis shank, and making any applicable adjustment of the clevis) by doing all actions specified in steps 1 through 8 of Figure 3 of the service bulletin. Do these actions per the Accomplishment Instructions of the service bulletin. Any required adjustment of the clevis must be done before further flight.

Inspection To Determine Weight, Tie Rod Replacement, and Placard Installation

(d) For airplanes in the groups listed in the table under paragraph 3.B.1.b.(4) of the Accomplishment Instructions of Boeing Special Attention Service Bulletin 777-25-0144, Revision 2, dated January 15, 2004: Do the actions in paragraphs (d)(1), (d)(2), and (d)(3) of this AD.

(1) Within 5 years after the effective date of this AD, replace the vertical support tie rods for electrical racks E9, E11, and E13 (including replacing the existing tie rods with new improved tie rods, replacing an existing tie rod clamp with a new improved tie rod clamp, performing a free-play inspection of certain electrical racks, adjusting jam nuts as applicable, performing a general visual inspection through the witness hole to make sure tie rod threads are visible, and making any applicable adjustment to ensure tie rod threads are visible) by doing all actions specified in Figures 5, 6, 7, and 9 of the service bulletin; as applicable. Do these actions per the Accomplishment Instructions of the service bulletin. Any required adjustment must be done before further flight.

(2) Before further flight after accomplishing paragraph (d)(1) of this AD, install placards that show weight limits for electrical racks E9, E11, and E13; as applicable; per the Accomplishment Instructions of the service bulletin.

(3) For each electrical rack on which a placard was installed per paragraph (d)(2) of this AD: Before further flight after accomplishing paragraphs (d)(1) and (d)(2) of this AD, perform a one-time inspection and records check to determine the weight of equipment installed in that electrical rack. This records review and inspection must include determining what, if any, extra equipment has been installed in the subject racks of the airplane, performing a detailed inspection to determine that this equipment is installed on the airplane, calculating the total weight of the installed equipment, and comparing that total to the weight limit specified on the placard installed per paragraph (d)(2) of this AD. If the weight is outside the limits specified in the placard, before further flight, remove equipment from the rack to meet the weight limit specified in the placard.

Actions Accomplished Previously

(e) Actions accomplished before the effective date of this AD per the Accomplishment Instructions of Boeing Special Attention Service Bulletin 777-25-0144, dated January 25, 2001; or Revision 1, dated January 10, 2002; are acceptable for compliance with the corresponding actions required by this AD, provided that the additional actions specified in Part 2 or 3 of the Accomplishment Instructions of Boeing

Special Attention Service Bulletin 777-25-0144, Revision 2, dated January 15, 2004, are accomplished within the compliance time specified in this AD.

Alternative Methods of Compliance

(f) In accordance with 14 CFR 39.19, the Manager, Seattle Aircraft Certification Office, FAA, is authorized to approve alternative methods of compliance (AMOCs) for this AD.

Issued in Renton, Washington, on December 27, 2004.

Kevin M. Mullin,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 05-171 Filed 1-4-05; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF COMMERCE

National Oceanic and Atmospheric Administration

15 CFR Part 904

[Docket No. 040902252-4252-01; I.D. 092804C]

RIN 0648-AS54

Civil Procedures

AGENCY: Office of General Counsel for Enforcement and Litigation, National Oceanic and Atmospheric Administration (NOAA), Commerce.

ACTION: Proposed rule; amendments and technical refinements to Civil Procedures; reopening of the comment period.

SUMMARY: In a proposed rule published in the **Federal Register** on October 12, 2004, NOAA requested comments on proposed revisions to its Civil Procedures which govern the Agency's administrative proceedings for the assessment of civil penalties; suspension, revocation, modification, or denial of permits; issuance and use of written warnings; and release or forfeiture of seized property. The comment period for the proposed rule closed on December 13, 2004. Comments addressed various issues and included requests to extend the comment period. The intent of this document is to announce the reopening of the public comment period.

DATES: Written comments must be received on or before January 31, 2005.

ADDRESSES: Send comments to Meggan Engelke-Ros, Enforcement Attorney, Office of General Counsel for Enforcement and Litigation, NOAA. Comments may be submitted by:

- Mail to 8484 Georgia Avenue, Suite 400, Silver Spring, MD 20910;
- E-mail to Part904.comments@noaa.gov; or

• Webform at the Federal eRulemaking Portal: www.regulations.gov. Follow the instructions at that site for submitting comments.

FOR FURTHER INFORMATION CONTACT:

Meggan Engelke-Ros or Susan S. Beresford, 301-427-2202.

SUPPLEMENTARY INFORMATION: As announced in the **Federal Register** on October 12, 2004 (69 FR 60569), NOAA is proposing revisions to its Civil Procedures which govern the Agency's administrative proceedings for the assessment of civil penalties; suspension, revocation, modification, or denial of permits; issuance and use of written warnings; and release or forfeiture of seized property. The comment period for the proposed rule closed on December 13, 2004. While NOAA received comments expressing opinions about whether, and in what way, its Civil Procedures should be revised, NOAA was also asked to extend the comment period beyond the original 60 days. NOAA has reopened the comment period to provide the public an additional opportunity to comment on the proposed revisions. The agency believes these additional comments will aid in the evaluation of the proposed revisions. Comments received between December 13, 2004, and the publication date of this document will be given full consideration by NOAA.

Background

In October 2004, NOAA proposed revisions (69 FR 60569) to the civil procedure rules that apply to its administrative proceedings under 15 CFR part 904. Part 904 has been largely unchanged since 1987 and the proposed changes were intended to: (1) conform the civil procedure rules to changes in applicable Federal laws and regulations; (2) improve efficiency and fairness of administrative proceedings; (3) clarify any ambiguities or inconsistencies in the existing civil procedure rules; (4) eliminate redundant language and correct language errors; and (5) conform the civil procedure rules to current Agency practice.

NOAA invites comments on all aspects of the revisions proposed to part 904 from all interested parties. Information on the time period for submission of comments and directions for their submission may be found in the DATES and ADDRESSES section of this document.

It has been determined that this rule is not a "significant regulatory action" under the terms of Executive Order 12866 and is therefore not subject to OMB review.

Authority: 16 U.S.C. 1801-1882; 16 U.S.C. 1531-1543; 16 U.S.C. 1361-1407; 16 U.S.C. 3371-3378; 16 U.S.C. 1431-1439; 16 U.S.C. 773-773k; 16 U.S.C. 951-961; 16 U.S.C. 1021-1032; 16 U.S.C. 3631-3644; 42 U.S.C. 9101 *et seq.*; 30 U.S.C. 1401 *et seq.*; 16 U.S.C. 971-971k; 16 U.S.C. 781 *et seq.*; 16 U.S.C. 2401-2413; 16 U.S.C. 2431-2444; 16 U.S.C. 972-972h; 16 U.S.C. 916-916l; 16 U.S.C. 1151-1175; 16 U.S.C. 3601-3608; 16 U.S.C. 1851 note; 15 U.S.C. 4201 *et seq.*; Pub. L. 102-587; 106 Stat. 5039.

Dated: December 29, 2004.

Jane H. Chalmers,

Acting General Counsel, National Oceanic and Atmospheric Administration.

[FR Doc. 04-28751 Filed 12-30-04; 3:39 pm]

BILLING CODE 3510-12-S

DEPARTMENT OF HEALTH AND HUMAN SERVICES

Food and Drug Administration

21 CFR Part 357

[Docket No. 1982N-0166]

RIN 0910-AF51

Orally Administered Drug Products for Relief of Symptoms Associated With Overindulgence in Food and Drink for Over-the-Counter Human Use; Proposed Amendment of the Tentative Final Monograph

AGENCY: Food and Drug Administration, HHS.

ACTION: Proposed rule.

SUMMARY: The Food and Drug Administration (FDA) is proposing to amend the tentative final monograph (TFM) for over-the-counter (OTC) orally administered drug products for relief of symptoms associated with overindulgence in food and drink to include an additional use for products that contain bismuth subsalicylate as an active ingredient labeled for the relief of symptoms of upset stomach due to overindulgence resulting from food and drink. This proposal is part of FDA's ongoing review of OTC drug products.

DATES: Submit written or electronic comments by April 5, 2005. Please see section X of this document for the proposed effective date of any final rule that may publish based on this proposal.

ADDRESSES: You may submit comments, identified by Docket No. 1982N-0166 or RIN 0910-AF51, by any of the following methods:

- Federal eRulemaking Portal: <http://www.regulations.gov>. Follow the instructions for submitting comments.
- Agency Web site: <http://www.fda.gov/dockets/ecomments>.

Follow the instructions for submitting comments on the agency Web site.

• E-mail: fdadockets@oc.fda.gov. Include Docket No. 1982N-0166 or RIN 0910-AF51 in the subject line of your e-mail message.

• FAX: 301-827-6870.

• Mail/Hand delivery/Courier [For paper, disk, or CD-ROM submissions]: Division of Dockets Management, 5630 Fishers Lane, rm. 1061, Rockville, MD 20852.

Instructions: All submissions received must include the agency name and Docket No. or Regulatory Information Number (RIN) for this rulemaking. All comments received will be posted without change to <http://www.fda.gov/dockets/ecomments>, including any personal information provided. For detailed instructions on submitting comments and additional information on the rulemaking process, see the "Request for Comments" heading of the **SUPPLEMENTARY INFORMATION** section of this document.

Docket: For access to the docket to read background documents or comments received, go to <http://www.fda.gov/dockets/ecomments> and/or the Division of Dockets Management, 5630 Fishers Lane, rm. 1061, Rockville, MD 20852.

FOR FURTHER INFORMATION CONTACT:

Gerald M. Rachanow, Center for Drug Evaluation and Research (HFD-560), Food and Drug Administration, 5600 Fishers Lane, Rockville, MD 20857, 301-827-2307.

SUPPLEMENTARY INFORMATION:

I. Background

In the **Federal Register** of October 1, 1982 (47 FR 43540), FDA published an advance notice of proposed rulemaking to establish a monograph for OTC orally administered drug products for relief of symptoms associated with overindulgence in alcohol and food, together with the recommendations of the Advisory Review Panel on OTC Miscellaneous Internal Drug Products (the Panel), which was the advisory review panel responsible for evaluating data on the active ingredients in these drug products (§ 330.10(a)(6) (21 CFR 330.10(a)(6))).

In the **Federal Register** of December 24, 1991 (56 FR 66742), FDA published the proposed rule (in the form of a TFM) for OTC orally administered drug products for relief of symptoms associated with overindulgence in food and drink. In the **Federal Register** of May 5, 1993 (58 FR 26886), FDA proposed to amend the overindulgence TFM to include a Reye's syndrome warning for OTC drug products containing bismuth subsalicylate. In the