

Starter Interlock, and Transmission Braking Effect, 103 Windshield Defrosting and Defogging Systems, 104 Windshield Wiping and Washing Systems, 106 Brake Hoses, 109 New Pneumatic Tires, 113 Hood Latch System, 116 Motor Vehicle Brake Fluids, 124 Accelerator Control Systems, 135 Passenger Car Brake Systems, 201 Occupant Protection in Interior Impact, 202 Head Restraints, 205 Glazing Materials, 206 Door Locks and Door Retention Components, 207 Seating Systems, 210 Seat Belt Assembly Anchorages, 212 Windshield Mounting, 214 Side Impact Protection, 216 Roof Crush Resistance, 219 Windshield Zone Intrusion, 301 Fuel System Integrity, and 302 Flammability of Interior Materials.

The petitioner also contends that the vehicles are capable of being readily altered to meet the following standards, in the manner indicated:

Standard No. 101 Controls and Displays: replacement of the instrument cluster with a U.S.-model component and reprogramming of the replacement unit to meet the requirements of this standard.

Standard No. 108 Lamps, Reflective Devices and Associated Equipment: (a) installation of U.S.-model front sidemarker lamps; (b) installation of U.S.-model headlamps; and (c) installation of U.S.-model taillamp assemblies that incorporate rear sidemarker lamps.

Standard No. 110 Tire Selection and Rims: installation of a tire information placard.

Standard No. 111 Rearview Mirrors: installation of a U.S.-model passenger side rearview mirror, or inscription of the required warning statement on the face of that mirror.

Standard No. 114 Theft Protection: installation of U.S. version software to meet the requirements of this standard.

Standard No. 118 Power-Operated Window, Partition, and Roof Panel Systems: installation of U.S. version software to meet the requirements of the standard.

Standard No. 204 Steering Control Rearward Displacement: installation of a U.S.-model steering shaft support mount.

Standard No. 208 Occupant Crash Protection: (a) inspection of all vehicles and replacement of any non U.S.-model seat belts, air bag control units, air bags, sensors, and knee bolsters with U.S.-model components on vehicles that are not already so equipped, and (b) reprogramming the vehicle computer to the U.S.-mode to ensure compliance with the standard.

The petitioner states that the occupant restraints used in these vehicles consist

of dual front airbags and combination lap and shoulder belts at the front and rear outboard seating positions. The seat belt systems are self-tensioning and are released by means of a single red push-button.

Standard No. 209 Seat Belt Assemblies: replacement of rear seatbelts with U.S.-model components.

The petitioner also states that the bumpers must be modified to meet the requirements of the Bumper Standard found in 49 CFR part 581.

The petitioner additionally states that a vehicle identification plate must be affixed to the vehicles near the left windshield post to meet the requirements of 49 CFR part 565.

Interested persons are invited to submit comments on the petition described above. Comments should refer to the docket number and be submitted to: Docket Management, Room PL-401, 400 Seventh St., SW., Washington, DC 20590. [Docket hours are from 9 am to 5 pm]. It is requested but not required that 10 copies be submitted.

All comments received before the close of business on the closing date indicated above will be considered, and will be available for examination in the docket at the above address both before and after that date. To the extent possible, comments filed after the closing date will also be considered. Notice of final action on the petition will be published in the **Federal Register** pursuant to the authority indicated below.

Authority: 49 U.S.C. 30141(a)(1)(A) and (b)(1); 49 CFR 593.8; delegations of authority at 49 CFR 1.50 and 501.8.

Issued on: August 2, 2006.

Claude H. Harris,
Director, Office of Vehicle, Safety
Compliance.

[FR Doc. E6-12846 Filed 8-7-06; 8:45 am]

BILLING CODE 4910-59-P

DEPARTMENT OF TRANSPORTATION

National Highway Traffic Safety Administration

[Docket No. NHTSA-2006-25555; Notice 1]

Foreign Tire Sales, Inc., Receipt of Petition for Decision of Inconsequential Noncompliance

Foreign Tire Sales, Inc. (FTS) has determined that certain tires that it imported in 2005 and 2006 do not comply with S6.5(d) of 49 CFR 571.119, Federal Motor Vehicle Safety Standard (FMVSS) No. 119, "New pneumatic tires for vehicles other than passenger cars." FTS has filed an appropriate report

pursuant to 49 CFR part 573, "Defect and Noncompliance Reports."

Pursuant to 49 U.S.C. 30118(d) and 30120(h), FTS has petitioned for an exemption from the notification and remedy requirements of 49 U.S.C. Chapter 301 on the basis that this noncompliance is inconsequential to motor vehicle safety.

This notice of receipt of FTS's petition is published under 49 U.S.C. 30118 and 30120 and does not represent any agency decision or other exercise of judgment concerning the merits of the petition.

Affected are a total of approximately 18,900 Danzig and Direction size 10.00-20 bias ply container chassis tires manufactured by Wendeng Sanfeng Tyre Co., Ltd. of Wendeng City, China, and imported between August 2005 and April 2006. S6.5(d) of FMVSS No. 119 requires that each tire shall be marked on each sidewall with "[t]he maximum load rating and corresponding inflation pressure of the tire * * * ." The subject tires are not marked with the maximum load rating and corresponding inflation values for single tire use. FTS has corrected the problem that caused these errors so that they will not be repeated in future production.

FTS believes that the noncompliance is inconsequential to motor vehicle safety and that no corrective action is warranted. FTS states that there is no safety issue relating to single use because the tires are clearly labeled "dual use only" and "trailer service only," and because FTS's "customers understand that said tires are to be used on container chassis only."

Interested persons are invited to submit written data, views, and arguments on this petition. Comments must refer to the docket and notice number cited at the beginning of this notice and be submitted by any of the following methods. Mail: Docket Management Facility, U.S. Department of Transportation, Nassif Building, Room PL-401, 400 Seventh Street, SW., Washington, DC 20590-0001. Hand Delivery: Room PL-401 on the plaza level of the Nassif Building, 400 Seventh Street, SW., Washington, DC. It is requested, but not required, that two copies of the comments be provided. The Docket Section is open on weekdays from 10 a.m. to 5 p.m. except Federal Holidays. Comments may be submitted electronically by logging onto the Docket Management System Web site at <http://dms.dot.gov>. Click on "Help" to obtain instructions for filing the document electronically. Comments may be faxed to 1-202-493-2251, or may be submitted to the Federal eRulemaking Portal: go to <http://>

www.regulations.gov. Follow the online instructions for submitting comments.

The petition, supporting materials, and all comments received before the close of business on the closing date indicated below will be filed and will be considered. All comments and supporting materials received after the closing date will also be filed and will be considered to the extent possible. When the petition is granted or denied, notice of the decision will be published in the **Federal Register** pursuant to the authority indicated below.

Comment closing date: September 7, 2006.

Authority: (49 U.S.C. 30118, 30120; delegations of authority at CFR 1.50 and 501.8).

Issued on: August 3, 2006.

Claude H. Harris,

Director, Office of Vehicle Safety Compliance.
[FR Doc. E6-12879 Filed 8-7-06; 8:45 am]

BILLING CODE 4910-59-P

DEPARTMENT OF TRANSPORTATION

National Highway Traffic Safety Administration

[Docket No. NHTSA-2006-25525; Notice 1]

Fulmer Helmets, Inc., Receipt of Petition for Decision of Inconsequential Noncompliance

Fulmer Helmets, Inc. (Fulmer) has determined that certain helmets it produced in 2001 through 2006 do not comply with S5.2 of 49 CFR 571.218, Federal Motor Vehicle Safety Standard (FMVSS) No. 218, "Motorcycle Helmets." Fulmer has filed an appropriate report pursuant to 49 CFR part 573, "Defect and Noncompliance Reports."

Pursuant to 49 U.S.C. 30118(d) and 30120(h), Fulmer has petitioned for an exemption from the notification and remedy requirements of 49 U.S.C. Chapter 301 on the basis that this noncompliance is inconsequential to motor vehicle safety.

This notice of receipt of Fulmer's petition is published under 49 U.S.C. 30118 and 30120 and does not represent any agency decision or other exercise of judgment concerning the merits of the petition.

Affected are a total of approximately 32,052 helmets which Fulmer certified as complying with FMVSS No. 218. These consist of approximately 26,762 Modular Motorcycle Helmets AF-M produced between January 2002 and April 2006, and approximately 5,290 Modular Snowmobile Helmets SN-M produced between November 2001 and

November 2005. S5.2 of FMVSS No. 218, penetration, requires that "when a penetration test is conducted in accordance with S7.2, the striker shall not contact the surface of the test headform." When this test was conducted on the subject helmets, the striker contacted the surface of the test headform. Fulmer has corrected the problem that caused these errors so that they will not be repeated in future production.

Fulmer believes that the noncompliance is inconsequential to motor vehicle safety and that no corrective action is warranted. Fulmer states that it asked Harry Hurt, "a leading expert in helmet testing and motorcycle accident research * * * [whose] experience is more than 50 years," to review the test results. Fulmer further states,

[Harry Hurt's] opinion is that the noncompliance on the penetration test is inconsequential because the helmets performed exceptionally well on all impact attenuation tests. In his experience, there has never been any correlation between the penetration test and accident performance, and damage like the penetration test is never seen in crash involved motorcycle helmets.

Mr. Hurt's full statement is available in the docket.

Interested persons are invited to submit written data, views, and arguments on this petition. Comments must refer to the docket and notice number cited at the beginning of this notice and be submitted by any of the following methods. Mail: Docket Management Facility, U.S. Department of Transportation, Nassif Building, Room PL-401, 400 Seventh Street, SW., Washington, DC 20590-0001. Hand Delivery: Room PL-401 on the plaza level of the Nassif Building, 400 Seventh Street, SW., Washington, DC. It is requested, but not required, that two copies of the comments be provided. The Docket Section is open on weekdays from 10 a.m. to 5 p.m. except Federal Holidays. Comments may be submitted electronically by logging onto the Docket Management System Web site at <http://dms.dot.gov>. Click on "Help" to obtain instructions for filing the document electronically. Comments may be faxed to 1-202-493-2251, or may be submitted to the Federal eRulemaking Portal: go to <http://www.regulations.gov>. Follow the online instructions for submitting comments.

The petition, supporting materials, and all comments received before the close of business on the closing date indicated below will be filed and will be considered. All comments and supporting materials received after the closing date will also be filed and will

be considered to the extent possible. When the petition is granted or denied, notice of the decision will be published in the **Federal Register** pursuant to the authority indicated below.

Comment closing date: September 7, 2006.

Authority: (49 U.S.C. 30118, 30120; delegations of authority at CFR 1.50 and 501.8).

Issued on: August 3, 2006.

Claude H. Harris,

Director, Office of Vehicle Safety Compliance.
[FR Doc. E6-12878 Filed 8-7-06; 8:45 am]

BILLING CODE 4910-59-P

DEPARTMENT OF TRANSPORTATION

Pipeline and Hazardous Materials Safety Administration, Office of Hazardous Materials Safety

Notice of Delays in Processing of Special Permit Applications

AGENCY: Pipeline and Hazardous Safety Administration, DOT.

ACTION: List of applications delayed more than 180 days.

SUMMARY: In accordance with the requirements of 49 U.S.C. 5117(c), PHMSA is publishing the following list of special permit applications that have been in process for 180 days or more. The reason(s) for delay and the expected completion date for action on each application is provided in association with each identified application.

FOR FURTHER INFORMATION CONTACT: Ann Mazzullo, Office of Hazardous Materials Special Permits and Approvals, Pipeline and Hazardous Materials Safety Administration, U.S. Department of Transportation, 400 Seventh Street, SW., Washington, DC 20590-0001, (202) 366-4535.

Key to "Reason for Delay"

1. Awaiting additional information from applicant.
2. Extensive public comment under review.
3. Application is technically complex and is of significant impact or precedent-setting and requires extensive analysis.
4. Staff review delayed by other priority issues or volume of special permit applications.

Meaning of Application Number Suffixes

- N—new applications.
- M—Modification request.
- X—Renewal.
- PM—Party to application with modification request.