

retainers thereafter at intervals not to exceed 12 months.

(1) Within 12 months since the date of issuance of the original airworthiness certificate or the date of issuance of the original export certificate of airworthiness.

(2) Within 12 months after installation of new retainers.

(3) Within 9 months after the effective date of this AD.

**(n) New Requirement of This AD: Replacement of Retainers With Findings**

If, during any detailed inspection specified in paragraph (m) of this AD, any installed aft engine mount retainer is found damaged, cracked, broken, or missing: Before further flight, replace all affected aft engine mount retainers with new retainers, in accordance with the Accomplishment Instructions of Airbus Service Bulletin A320-71-1060, dated October 9, 2014.

**(o) New Requirement of This AD: No Terminating Action**

Replacement of retainers on an airplane, as required by paragraph (n) of this AD, does not constitute terminating action for the repetitive inspections required by paragraph (m) of this AD for that airplane.

**(p) New Requirement of This AD: Required Reporting**

Submit a report of positive findings of any inspection required by paragraph (m) of this AD to Airbus at the applicable time specified in paragraph (p)(1) or (p)(2) of this AD. The report must include the inspection results, a description of any discrepancies found, the airplane serial number, and the number of landings and flight hours on the airplane.

(1) If the inspection was done on or after the effective date of this AD: Submit the report within 30 days after the inspection.

(2) If the inspection was done before the effective date of this AD: Submit the report within 30 days after the effective date of this AD.

**(q) Other FAA AD Provisions**

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs)*: The Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the International Branch, send it to ATTN: Sanjay Ralhan, Aerospace Engineer, International Branch, ANM-116, Transport Airplane Directorate, FAA, 1601 Lind Avenue SW., Renton, WA 98057-3356; telephone 425-227-1405; fax 425-227-1149. Information may be emailed to: [9-0ANM-116-AMOC-REQUESTS@faa.gov](mailto:9-0ANM-116-AMOC-REQUESTS@faa.gov). Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office. The AMOC approval letter must specifically reference this AD.

(2) *Contacting the Manufacturer*: As of the effective date of this AD, for any requirement in this AD to obtain corrective actions from a manufacturer, the action must be accomplished using a method approved by the Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA; or the European Aviation Safety Agency (EASA); or Airbus's EASA Design Organization Approval (DOA). If approved by the DOA, the approval must include the DOA-authorized signature.

(3) *Reporting Requirements*: A federal agency may not conduct or sponsor, and a person is not required to respond to, nor shall a person be subject to a penalty for failure to comply with a collection of information subject to the requirements of the Paperwork Reduction Act unless that collection of information displays a current valid OMB Control Number. The OMB Control Number for this information collection is 2120-0056. Public reporting for this collection of information is estimated to be approximately 5 minutes per response, including the time for reviewing instructions, completing and reviewing the collection of information. All responses to this collection of information are mandatory. Comments concerning the accuracy of this burden and suggestions for reducing the burden should be directed to the FAA at: 800 Independence Ave. SW., Washington, DC 20591, Attn: Information Collection Clearance Officer, AES-200.

(4) *Required for Compliance (RC)*: If any Airbus service information contains procedures or tests that are identified as RC, those procedures and tests must be done to comply with this AD; any procedures or tests that are not identified as RC are recommended. Those procedures and tests that are not identified as RC may be deviated from using accepted methods in accordance with the operator's maintenance or inspection program without obtaining approval of an AMOC, provided the procedures and tests identified as RC can be done and the airplane can be put back in a serviceable condition. Any substitutions or changes to procedures or tests identified as RC require approval of an AMOC.

**(r) Special Flight Permits**

Special flight permits, as described in Section 21.197 and Section 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199), are not allowed.

**(s) Related Information**

(1) Refer to Mandatory Continuing Airworthiness Information (MCAI) European Aviation Safety Agency Airworthiness Directive 2015-0021, dated February 13, 2015, for related information. This MCAI may be found in the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2015-3632.

(2) For Airbus service information identified in this AD, contact Airbus, Airworthiness Office—EIAS, 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France; telephone +33 5 61 93 36 96; fax +33 5 61 93 44 51; email [account.airworth-eas@airbus.com](mailto:account.airworth-eas@airbus.com); Internet <http://www.airbus.com>.

(3) For Goodrich Aerostructures service information identified in this AD, contact Goodrich Aerostructures, 850 Lagoon Drive, Chula Vista, CA 91910-2098; telephone 619-691-2719; email [jan.lewis@goodrich.com](mailto:jan.lewis@goodrich.com); Internet <http://www.goodrich.com/TechPubs>.

(4) You may view this service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

Issued in Renton, Washington, on September 9, 2015.

**Michael Kaszycki,**

*Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.*

[FR Doc. 2015-23328 Filed 9-16-15; 8:45 am]

**BILLING CODE 4910-13-P**

**DEPARTMENT OF COMMERCE**

**National Oceanic and Atmospheric Administration**

**15 CFR Part 922**

**Initiation of Review of Management Plan and Regulations of the Monterey Bay National Marine Sanctuary; Intent To Conduct Scoping and Prepare Draft Environmental Impact Statement and Management Plan; Correction**

**AGENCY:** Office of National Marine Sanctuaries (ONMS), National Ocean Service (NOS), National Oceanic and Atmospheric Administration (NOAA), Department of Commerce (DOC).

**ACTION:** Correction.

**SUMMARY:** On August 27, 2015, NOAA published a notice of intent in the **Federal Register** (80 FR 51973) to initiate public scoping for the management plan review for Monterey Bay National Marine Sanctuary (MBNMS). This notice alerts the public of the addition of a public scoping meeting in Half Moon Bay on October 14, 2015. It also makes a correction to the docket number for submission of public comments on the online rulemaking portal at [www.regulations.gov](http://www.regulations.gov). The correct docket number is NOAA-NOS-2015-0099. The end of the scoping period remains October 30, 2015.

**DATES:** NOAA will accept public comments on the notice of intent published at 80 FR 51973 (August 27, 2015) through October 30, 2015. Locations and dates for public scoping meetings remain the same as described in the notice of intent, with the addition of a meeting on October 14, 2015 from 6 p.m. to 8 p.m. at the Half Moon Bay Yacht Club in Half Moon Bay, CA.

**ADDRESSES:** You may submit comments on this document, identified by NOAA-

NOS–2015–0099, by any of the following methods:

- *Electronic Submission:* Submit all electronic public comments via the Federal e-Rulemaking Portal. Go to [www.regulations.gov](http://www.regulations.gov)

#!docketDetail;D=NOAA-NOS-2015-0099, click the “Comment Now!” icon, complete the required fields, and enter or attach your comments.

- *Mail:* 99 Pacific Street, Bldg. 455A, Monterey, California 93940, Attn: Paul Michel, Superintendent.

*Instructions:* Comments sent by any other method, to any other address or individual, or received after the end of the comment period, may not be considered by NOAA. All comments received are a part of the public record and will generally be posted for public viewing [www.regulations.gov](http://www.regulations.gov) without change. All personal identifying information (e.g., name, address, etc.), confidential business information, or otherwise sensitive information submitted voluntarily by the sender will be publicly accessible. NOAA will accept anonymous comments (enter “N/A” in the required fields if you wish to remain anonymous). Attachments to electronic comments will be accepted in Microsoft Word, Excel, or Adobe PDF file formats only.

**FOR FURTHER INFORMATION CONTACT:**  
Dawn Hayes, 831.647.4256,  
[mbnmsmanagementplan@noaa.gov](mailto:mbnmsmanagementplan@noaa.gov).

**SUPPLEMENTARY INFORMATION:**

On August 27, 2015, NOAA published a notice of intent in the **Federal Register** (80 FR 51973) to initiate public scoping for the management plan review for Monterey Bay National Marine Sanctuary (MBNMS). In that notice, the docket number for submitting comments on the online rulemaking portal at [www.regulations.gov](http://www.regulations.gov) was incorrect. The correct docket number is NOAA–NOS–2015–0099. This notice makes a correction to the docket number for the online submission of public comments.

In addition, this notice alerts the public that NOAA will hold a fourth public scoping meeting in addition to the three meetings listed in the August 27, 2015 notice (80 FR 51973). The fourth meeting will be held at the Half Moon Bay Yacht Club in Half Moon Bay, CA on October 14, 2015 from 6 p.m. to 8 p.m.

**Authority:** 16 U.S.C. 1431 *et seq.*; 16 U.S.C. 470.

Dated: September 9, 2015.

**John Armor,**

*Acting Director, Office of National Marine Sanctuaries.*

[FR Doc. 2015–23417 Filed 9–16–15; 8:45 am]

**BILLING CODE 3510–NK–P**

**DEPARTMENT OF HEALTH AND HUMAN SERVICES**

**Food and Drug Administration**

**21 CFR Part 1**

[Docket No. FDA–2011–N–0146]

RIN 0910–AH23

**User Fee Program To Provide for Accreditation of Third-Party Auditors/ Certification Bodies To Conduct Food Safety Audits and To Issue Certifications; Correction**

**AGENCY:** Food and Drug Administration, HHS.

**ACTION:** Proposed rule; correction.

**SUMMARY:** The Food and Drug Administration (FDA or we) is correcting a document that appeared in the **Federal Register** of July 24, 2015, entitled “User Fee Program for Accreditation of Third-Party Auditors/ Certification Bodies To Conduct Food Safety Audits and To Issue Certifications.” That document proposed amending the document, “Accreditation of Third-Party Auditors/ Certification Bodies to Conduct Food Safety Audits and to Issue Certifications,” and proposed establishing a reimbursement (user fee) program to assess fees and require reimbursement for the work performed to establish and administer the system for the Accreditation of Third-Party Auditors under the FDA Food Safety Modernization Act (FSMA). The document was published with an incorrect RIN. This document corrects that error.

**FOR FURTHER INFORMATION CONTACT:** Charlotte Christin, Center for Food Safety and Applied Nutrition, Food and Drug Administration, 5100 Paint Branch Pkwy., College Park, MD 20740, 240–402–3708.

**SUPPLEMENTARY INFORMATION:** In FR Doc. 2015–18141, in the **Federal Register** of July 24, 2015 (80 FR 43987), appearing on page 43987, in the second column, the RIN number heading is corrected to read “RIN 0910–AH23.”

Dated: September 11, 2015.

**Leslie Kux,**

*Associate Commissioner for Policy.*

[FR Doc. 2015–23333 Filed 9–16–15; 8:45 am]

**BILLING CODE 4164–01–P**

**DEPARTMENT OF THE TREASURY**

**Internal Revenue Service**

**26 CFR Part 1**

[REG–138344–13]

RIN 1545–BL94

**Substantiation Requirement for Certain Contributions**

**AGENCY:** Internal Revenue Service (IRS), Treasury.

**ACTION:** Notice of proposed rulemaking.

**SUMMARY:** This document contains proposed regulations to implement the exception to the “contemporaneous written acknowledgement” requirement for substantiating charitable contribution deductions of \$250 or more. These proposed regulations provide rules concerning the time and manner for donee organizations to file information returns that report the required information about contributions (donee reporting).

**DATES:** Written or electronic comments must be received by December 16, 2015.

**ADDRESSES:** Send submissions to CC:PA:LPD:PR (REG–138344–13), Room 5203, Internal Revenue Service, POB 7604, Ben Franklin Station, Washington, DC 20044. Submissions may be hand-delivered Monday through Friday between the hours of 8 a.m. and 4 p.m. to: CC:PA:LPD:PR (REG–138344–13), Courier’s Desk, Internal Revenue Service, 1111 Constitution Avenue NW., Washington, DC, or sent electronically via the Federal eRulemaking Portal at [www.regulations.gov](http://www.regulations.gov) (IRS REG–138344–13).

**FOR FURTHER INFORMATION CONTACT:** Concerning the proposed regulations, Robert Basso at (202) 317–7011 (not a toll-free number); concerning comments or a request for a public hearing, Oluwafunmilayo Taylor at (202) 317–6901 (not a toll-free number).

**SUPPLEMENTARY INFORMATION:**

**Paperwork Reduction Act**

The collection of information contained in this notice of proposed rulemaking will be submitted to the Office of Management and Budget in accordance with the Paperwork Reduction Act of 1995 (44 U.S.C. 3507(d)). Comments on the collection of information should be sent to the Office of Management and Budget, Attn: Desk Officer for the Department of the Treasury, Office of Information and Regulatory Affairs, Washington, DC 20503, with copies to the Internal Revenue Service, Attn: IRS Reports Clearance Officer,