# TABLE 1—STRUCTURAL REPAIR MANUALS

Document	Revision	Date
Airbus A330 Structural Repair Manual Airbus A330 Structural Repair Manual Airbus A340–200/–300 Structural Repair Manual Airbus A340–200/–300 Structural Repair Manual	64	October 1, 2008. January 1, 2009. October 1, 2008. January 1, 2009.

(4) As of the effective date of this AD, no person may install a movable flap track fairing No. 3 on that airplane, unless it has been modified or repaired in accordance with the requirements of this AD.

#### **FAA AD Differences**

**Note 1:** This AD differs from the MCAI and/or service information as follows: No Differences.

# Other FAA AD Provisions

- (g) The following provisions also apply to this AD:
- (1) Alternative Methods of Compliance (AMOCs): The Manager, International Branch, ANM-116, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. Send information to ATTN: Vladimir Ulyanov, Aerospace Engineer, International Branch, ANM-116, Transport Airplane Directorate, FAA, 1601 Lind Avenue, SW., Renton, Washington 98057–3356; telephone (425) 227-1138; fax (425) 227-1320. Before using any approved AMOC on any airplane to which the AMOC applies, notify your principal maintenance inspector (PMI) or principal avionics inspector (PAI), as appropriate, or lacking a principal inspector, your local Flight Standards District Office.
- (2) Airworthy Product: For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they are approved by the State of Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.
- (3) Reporting Requirements: For any reporting requirement in this AD, under the provisions of the Paperwork Reduction Act, the Office of Management and Budget (OMB) has approved the information collection requirements and has assigned OMB Control Number 2120–0056.

#### **Related Information**

(h) Refer to MCAI European Aviation Safety Agency Airworthiness Directive 2008– 0153, dated August 8, 2008; and Airbus Mandatory Service Bulletins A330–57–3095, Revision 02, and A340–57–4103, Revision 01, both dated April 3, 2008; for related information.

Issued in Renton, Washington, on March 30, 2009.

# Stephen P. Boyd,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service. [FR Doc. E9–7642 Filed 4–3–09; 8:45 am] BILLING CODE 4910–13–P

#### **DEPARTMENT OF TRANSPORTATION**

#### **Federal Aviation Administration**

#### 14 CFR Part 71

[Docket No. FAA-2009-0229; Airspace Docket No. 09-ASO-13]

#### RIN 2120-AA66

# Proposed Revocation of VOR Federal Airway V–329; Alabama-Florida

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Notice of proposed rulemaking (NPRM).

SUMMARY: This action proposes to revoke very high frequency omnidirectional range (VOR) Federal airway V–329, which extends between Montgomery, AL and the Crestview, FL, area. Revocation of the route is being proposed because a navigation aid that forms a segment of V–329 is planned for decommissioning due to recurring

**DATES:** Comments must be received on or before May 21, 2009.

outages and maintenance problems.

ADDRESSES: Send comments on this proposal to the U.S. Department of Transportation, Docket Operations, M—30, 1200 New Jersey Avenue, SE., West Building Ground Floor, Room W12–140, Washington, DC 20590–0001; telephone: (202) 366–9826. You must identify FAA Docket No. FAA–2009–0229 and Airspace Docket No. 09–ASO–13 at the beginning of your comments. You may also submit comments through the Internet at

http://www.regulations.gov.

FOR FURTHER INFORMATION CONTACT: Paul Gallant, Airspace and Rules Group, Office of System Operations Airspace and AIM, Federal Aviation Administration, 800 Independence Avenue, SW., Washington, DC 20591; telephone: (202) 267–8783.

#### SUPPLEMENTARY INFORMATION:

# **Comments Invited**

Interested parties are invited to participate in this proposed rulemaking by submitting such written data, views, or arguments as they may desire. Comments that provide the factual basis supporting the views and suggestions

presented are particularly helpful in developing reasoned regulatory decisions on the proposal. Comments are specifically invited on the overall regulatory, aeronautical, economic, environmental, and energy-related aspects of the proposal.

Communications should identify both docket numbers (FAA Docket No. FAA–2009–0229 and Airspace Docket No. 09–ASO–13) and be submitted in triplicate to the Docket Management Facility (see "ADDRESSES" section for address and phone number). You may also submit comments through the Internet at <a href="http://www.regulations.gov">http://www.regulations.gov</a>.

Commenters wishing the FAA to acknowledge receipt of their comments on this action must submit with those comments a self-addressed, stamped postcard on which the following statement is made: "Comments to FAA Docket No. FAA–2009–0229 and Airspace Docket No. 09–ASO–13." The postcard will be date/time stamped and returned to the commenter.

All communications received on or before the specified closing date for comments will be considered before taking action on the proposed rule. The proposal contained in this action may be changed in light of comments received. All comments submitted will be available for examination in the public docket both before and after the closing date for comments. A report summarizing each substantive public contact with FAA personnel concerned with this rulemaking will be filed in the docket.

#### **Availability of NPRMs**

An electronic copy of this document may be downloaded through the Internet at http://www.regulations.gov. Recently published rulemaking documents can also be accessed through the FAA's Web page at http://www.faa.gov/airports\_airtraffic/air\_traffic/publications/airspace\_amendments/.

You may review the public docket containing the proposal, any comments received and any final disposition in person in the Dockets Office (see "ADDRESSES" section for address and phone number) between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. An informal docket

may also be examined during normal business hours at the office of the Eastern Service Center, Operations Support Group, Federal Aviation Administration, Room 210, 1701 Columbia Ave., College Park, GA 30337.

Persons interested in being placed on a mailing list for future NPRM's should contact the FAA's Office of Rulemaking, (202) 267–9677, for a copy of Advisory Circular No. 11–2A, Notice of Proposed Rulemaking Distribution System, which describes the application procedure.

## The Proposal

The FAA is proposing an amendment to Title 14, Code of Federal Regulations (14 CFR) part 71 to revoke VOR Federal airway V-329 which extends between the Montgomery, AL, very high frequency omnidirectional range/ tactical air navigation (VORTAC) aid and the vicinity of Crestview, FL. The Andalusia, AL, VOR, which is used to form segments of V-329, is owned and operated by the U.S. Army. Due to recurring outages and maintenance issues, the U.S. Army requested to decommission the Andalusia, AL, VOR. This action would render V-329 unusable. The FAA has conducted an aeronautical study of the request and determined that decommissioning the Andalusia VOR would not adversely impact National Airspace System operations. An alternative route, V-115. currently extends between the Crestview, FL, VORTAC and the Montgomery, AL, VORTAC.

VOR Federal airways are published in paragraph 6010 of FAA Order 7400.9S signed October 3, 2008 and effective October 31, 2008, which is incorporated by reference in 14 CFR 71.1. The VOR Federal airway listed in this document would be deleted subsequently from the Order.

The FAA has determined that this proposed regulation only involves an established body of technical regulations for which frequent and routine amendments are necessary to keep them operationally current. Therefore, this proposed regulation: (1) Is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under Department of Transportation (DOT) Regulatory Policies and Procedures (44 FR 11034; February 26, 1979); and (3) does not warrant preparation of a regulatory evaluation as the anticipated impact is so minimal. Since this is a routine matter that will only affect air traffic procedures and air navigation, it is certified that this proposed rule, when promulgated, will not have a significant economic impact on a substantial

number of small entities under the criteria of the Regulatory Flexibility Act.

The FAA's authority to issue rules regarding aviation safety is found in Title 49 of the United States Code. Subtitle I, Section 106 describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the agency's authority.

This rulemaking is promulgated under the authority described in Subtitle VII, Part A, Subpart I, Section 40103. Under that section, the FAA is charged with prescribing regulations to assign the use of the airspace necessary to ensure the safety of aircraft and the efficient use of airspace. This regulation is within the scope of that authority as it modifies the route structure as required to preserve the safe and efficient flow of air traffic.

## **Environmental Review**

The FAA has determined that this action qualifies for categorical exclusion under the National Environmental Policy Act in accordance with FAA Order 1050.1E, "Environmental Impacts: Policies and Procedures," paragraph 311a and 311b. This airspace action is not expected to cause any potentially significant environmental impacts, and no extraordinary circumstances exist that warrant preparation of an environmental assessment.

# List of Subjects in 14 CFR Part 71

Airspace, Incorporation by reference, Navigation (air).

## The Proposed Amendment

In consideration of the foregoing, the Federal Aviation Administration proposes to amend 14 CFR part 71 as follows:

# PART 71—DESIGNATION OF CLASS A, B, C, D, AND E AIRSPACE AREAS; AIR TRAFFIC SERVICE ROUTES; AND REPORTING POINTS

1. The authority citation for part 71 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40103, 40113, 40120; E.O. 10854, 24 FR 9565, 3 CFR, 1959–1963 Comp., p. 389.

#### §71.1 [Amended]

2. The incorporation by reference in 14 CFR 71.1 of FAA Order 7400.9S, Airspace Designations and Reporting Points, signed October 3, 2008 and effective October 31, 2008, is amended as follows:

Paragraph 6010 VOR Federal airways.

\* \* \* \* \*

#### V-329 [Removed]

\* \* \* \* \*

Issued in Washington, DC, on March 27, 2009.

#### Edith V. Parish,

Manager, Airspace & Rules Group. [FR Doc. E9–7679 Filed 4–3–09; 8:45 am] BILLING CODE 4910–13–P

# DEPARTMENT OF HOMELAND SECURITY

#### **Coast Guard**

## 33 CFR Part 165

[Docket No. USCG-2009-0123]

RIN 1625-AA00

## Safety Zone; Big Bay Fourth of July Fireworks; San Diego Bay, San Diego, CA

AGENCY: Coast Guard, DHS.

**ACTION:** Notice of proposed rulemaking.

summary: The Coast Guard proposes establishing a temporary safety zone on the navigable waters of the San Diego Bay in support of the Big Bay July Fourth Show to Benefit the San Diego Armed Services YMCA. This temporary safety zone is necessary to provide for the safety of crew, spectators, and other users and vessels of the waterway. Persons and vessels are prohibited from entering into, transiting through, or anchoring within this temporary safety zone unless authorized by the Captain of the Port or his designated representative.

**DATES:** Comments and related material must either be submitted to our online docket via *http://www.regulations.gov* on or before May 6, 2009 or reach the Docket Management Facility by that date

**ADDRESSES:** You may submit comments identified by docket number USCG—2009—0123 using any one of the following methods:

- (1) Federal eRulemaking Portal: http://www.regulations.gov.
  - (2) *Fax:* 202–493–2251.
- (3) Mail: Docket Management Facility (M–30), U.S. Department of Transportation, West Building Ground Floor, Room W12–140, 1200 New Jersey Avenue, SE., Washington, DC 20590–0001
- (4) Hand delivery: Same as mail address above, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The telephone number is 202–366–9329.

To avoid duplication, please use only one of these methods. For instructions