

Other FAA AD Provisions

(g) The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs)*: The Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. Send information to ATTN: Tom Rodriguez, Aerospace Engineer, International Branch, ANM-116, Transport Airplane Directorate, FAA, 1601 Lind Avenue SW., Renton, Washington 98057-3356; telephone (425)

227-1137; fax (425) 227-1149. Before using any approved AMOC on any airplane to which the AMOC applies, notify your principal maintenance inspector (PMI) or principal avionics inspector (PAI), as appropriate, or lacking a principal inspector, your local Flight Standards District Office.

(2) *Airworthy Product*: For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they are approved by the State of Design Authority (or their delegated agent). You are required

to assure the product is airworthy before it is returned to service.

(3) *Reporting Requirements*: For any reporting requirement in this AD, under the provisions of the Paperwork Reduction Act, the Office of Management and Budget (OMB) has approved the information collection requirements and has assigned OMB Control Number 2120-0056.

Related Information

(h) Refer to MCAI European Aviation Safety Agency Airworthiness Directive 2009-0050, and the service information in Table 3 of this AD, for related information.

TABLE 3—SERVICE INFORMATION

Document	Revision	Date
Dassault Mandatory Service Bulletin F2000EX-167	1	December 1, 2008.
Dassault Service Bulletin F2000EX-185	2	February 4, 2009.
Dassault Mandatory Service Bulletin F2000-366	2	December 1, 2008.
Dassault Service Bulletin F2000-367	4	February 4, 2009.

Issued in Renton, Washington, on September 16, 2009.

Ali Bahrami,

Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. E9-23095 Filed 9-23-09; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION**Federal Aviation Administration****14 CFR Part 71**

[Docket No. FAA-2009-0695; Airspace Docket No. 09-AWP-7]

Proposed Establishment and Modification of Class E Airspace; Bishop, CA

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking.

SUMMARY: This action proposes to establish Class E surface airspace and modify existing Class E airspace at Eastern Sierra Regional Airport, Bishop, CA. Additional controlled airspace is necessary to accommodate aircraft using a new Area Navigation (RNAV) Global Positioning System (GPS) Standard Instrument Approach Procedure (SIAP) at Eastern Sierra Regional Airport, Bishop, CA. The FAA is proposing this action to enhance the safety and management of aircraft operations at Eastern Sierra Regional Airport, Bishop, CA.

DATES: Comments must be received on or before November 9, 2009.

ADDRESSES: Send comments on this proposal to the U.S. Department of Transportation, Docket Operations, M-

30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue, SE., Washington, DC 20590. Telephone (202) 366-9826. You must identify FAA Docket No. FAA-2009-0695; Airspace Docket No. 09-AWP-7, at the beginning of your comments. You may also submit comments through the Internet at <http://www.regulations.gov>.

FOR FURTHER INFORMATION CONTACT:

Eldon Taylor, Federal Aviation Administration, Operations Support Group, Western Service Center, 1601 Lind Avenue, SW., Renton, WA 98057; telephone (425) 203-4537.

SUPPLEMENTARY INFORMATION:**Comments Invited**

Interested parties are invited to participate in this proposed rulemaking by submitting such written data, views, or arguments, as they may desire. Comments that provide the factual basis supporting the views and suggestions presented are particularly helpful in developing reasoned regulatory decisions on the proposal. Comments are specifically invited on the overall regulatory, aeronautical, economic, environmental, and energy-related aspects of the proposal.

Communications should identify both docket numbers (FAA Docket No. FAA-2009-0695 and Airspace Docket No. 09-AWP-7) and be submitted in triplicate to the Docket Management System (see **ADDRESSES** section for address and phone number). You may also submit comments through the Internet at <http://www.regulations.gov>.

Commenters wishing the FAA to acknowledge receipt of their comments on this action must submit with those comments a self-addressed stamped

postcard on which the following statement is made: "Comments to FAA Docket No. FAA-2009-0695 and Airspace Docket No. 09-AWP-7". The postcard will be date/time stamped and returned to the commenter.

All communications received on or before the specified closing date for comments will be considered before taking action on the proposed rule. The proposal contained in this action may be changed in light of comments received. All comments submitted will be available for examination in the public docket both before and after the closing date for comments. A report summarizing each substantive public contact with FAA personnel concerned with this rulemaking will be filed in the docket.

Availability of NPRMs

An electronic copy of this document may be downloaded through the Internet at <http://www.regulations.gov>. Recently published rulemaking documents can also be accessed through the FAA's Web page at http://www.faa.gov/airports_airtraffic/air_traffic/publications/airspace_amendments/.

You may review the public docket containing the proposal, any comments received, and any final disposition in person in the Dockets Office (see the **ADDRESSES** section for the address and phone number) between 9 a.m. and 5 p.m., Monday through Friday, except federal holidays. An informal docket may also be examined during normal business hours at the Northwest Mountain Regional Office of the Federal Aviation Administration, Air Traffic Organization, Western Service Area,

Operations Support Group, 1601 Lind Avenue, SW., Renton, WA 98057.

Persons interested in being placed on a mailing list for future NPRM's should contact the FAA's Office of Rulemaking, (202) 267-9677, for a copy of Advisory Circular No. 11-2A, Notice of Proposed Rulemaking Distribution System, which describes the application procedure.

The Proposal

The FAA is proposing an amendment to Title 14 Code of Federal Regulations (14 CFR) part 71 by establishing Class E airspace designated as surface areas and modifying existing Class E airspace extending upward from 700 feet above the surface at Eastern Sierra Regional Airport, Bishop, CA. Controlled airspace is necessary to accommodate aircraft using the new RNAV (GPS) SIAP at Eastern Sierra Regional Airport, Bishop, CA. This action would enhance the safety and management of aircraft operations at Eastern Sierra Regional Airport, Bishop, CA.

Class E airspace designations are published in paragraph 6002 and 6005, respectively, of FAA Order 7400.9T, signed August 27, 2009, and effective September 15, 2009, which is incorporated by reference in 14 CFR 71.1. The Class E airspace designation listed in this document will be published subsequently in this Order.

The FAA has determined that this proposed regulation only involves an established body of technical regulations for which frequent and routine amendments are necessary to keep them operationally current. Therefore, this proposed regulation; (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034; February 26, 1979); and (3) does not warrant preparation of a regulatory evaluation as the anticipated impact is so minimal. Since this is a routine matter that will only affect air traffic procedures and air navigation, it is certified that this proposed rule, when promulgated, would not have a significant economic impact on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

The FAA's authority to issue rules regarding aviation safety is found in Title 49 of the U.S. Code. Subtitle 1, Section 106, describes the authority for the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the agency's authority. This rulemaking is promulgated under the authority described in Subtitle VII, Part A, Subpart I, Section 40103. Under that

section, the FAA is charged with prescribing regulations to assign the use of the airspace necessary to ensure the safety of aircraft and the efficient use of airspace. This regulation is within the scope of that authority as it establishes additional controlled airspace at Eastern Sierra Regional Airport, Bishop, CA.

List of Subjects in 14 CFR Part 71

Airspace, Incorporation by reference, Navigation (air).

The Proposed Amendment

Accordingly, pursuant to the authority delegated to me, the Federal Aviation Administration proposes to amend 14 CFR part 71 as follows:

PART 71—DESIGNATION OF CLASS A, B, C, D, AND E AIRSPACE AREAS; AIR TRAFFIC SERVICE ROUTES; AND REPORTING POINTS

1. The authority citation for 14 CFR part 71 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40103, 40113, 40120; E.O. 10854, 24 FR 9565, 3 CFR, 1959–1963 Comp., p. 389.

§ 71.1 [Amended]

2. The incorporation by reference in 14 CFR 71.1 of the FAA Order 7400.9T, Airspace Designations and Reporting Points, signed August 27, 2009, and effective September 15, 2009, is amended as follows:

Paragraph 6002 Class E airspace designated as surface areas.

* * * * *

AWP CA, E2 Bishop, CA [New]

Eastern Sierra Regional, CA
(Lat. 37°22'23" N., long. 118°21'49" W.)

Within a 4.2-mile radius of Eastern Sierra Regional Airport. This Class E airspace area is effective during the specific dates and times established in advance by a Notice to Airmen. The effective date and time will thereafter be continuously published in the Airport/Facility Directory.

* * * * *

Paragraph 6005 Class E airspace areas extending upward from 700 feet or more above the surface of the earth.

* * * * *

AWP CA, E5 Bishop, CA [Modified]

Eastern Sierra Regional, CA
(Lat. 37°22'23" N., long. 118°21'49" W.)
Beatty VORTAC
(Lat. 36°48'02" N., long. 116°44'52" W.)
LIDAT Intersection
(Lat. 37°25'49" N., long. 117°16'41" W.)

That airspace extending upward from 700 feet above the surface within a 6.7-mile radius of Eastern Sierra Regional Airport and that airspace within 2.2 miles each side of the Eastern Sierra Regional Airport 337° bearing extending from the 6.7-mile radius to

27.8 miles northwest of the Eastern Sierra Regional Airport; and that airspace extending upward from 1,200 feet above the surface of the earth bounded by a line beginning at lat. 38°11'08" N., long. 118°46'30" W.; to lat. 38°13'14" N., long. 118°41'00" W.; to lat. 38°14'25" N., long. 118°17'04" W.; to lat. 38°03'17" N., long. 118°02'30" W.; to lat. 37°41'20" N., long. 118°16'42" W.; to lat. 37°09'50" N., long. 118°00'13" W.; to lat. 37°02'00" N., long. 118°21'30" W.; to lat. 38°11'08" N., long. 118°57'00" W.; thence to the point of origin. That airspace extending upward from 12,500 feet MSL within 4.3 miles each side of a direct course between the Eastern Sierra Regional Airport and LIDAT Intersection, 36.5 miles 12,500 feet MSL, 10,500 feet MSL LIDAT Intersection; and within 4.3 miles each side of a direct course between Eastern Sierra Regional Airport and the Beatty VORTAC 69.5 miles 12,500 feet MSL, 10,500 feet MSL Beatty VORTAC.

* * * * *

Issued in Seattle, Washington, on September 18, 2009.

William Buck,

Acting Manager, Operations Support Group, Western Service Center.

[FR Doc. E9-23105 Filed 9-23-09; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF THE TREASURY

Internal Revenue Service

26 CFR Parts 1 and 53

[REG-155929-06]

RIN 1545-BG31

Payout Requirements for Type III Supporting Organizations That Are Not Functionally Integrated

AGENCY: Internal Revenue Service (IRS), Treasury.

ACTION: Notice of proposed rulemaking.

SUMMARY: This document contains proposed regulations regarding the requirements to qualify as a Type III supporting organization that is operated in connection with one or more supported organizations. The regulations reflect changes to the law made by the Pension Protection Act of 2006. The regulations will affect Type III supporting organizations and their supported organizations.

DATES: Written or electronic comments and requests for a public hearing must be received by *December 23, 2009*.

ADDRESSES: Send submissions to: CC:PA:LPD:PR (REG-155929-06), room 5203, Internal Revenue Service, P.O. Box 7604, Ben Franklin Station, Washington, DC 20044. Submissions may be hand-delivered Monday through