PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§39.13 [Amended]

■ 2. The FAA amends § 39.13 by adding the following new AD:

2012–09–03 Saab AB, Saab Aerosystems: Amendment 39–17038. Docket No. FAA–2011–1410; Directorate Identifier 2011–NM–033–AD.

(a) Effective Date

This airworthiness directive (AD) becomes effective June 7, 2012.

(b) Affected ADs

None.

(c) Applicability

This AD applies to Saab AB, Saab Aerosystems Model SAAB 2000 airplanes, certificated in any category; all serial numbers.

(d) Subject

Air Transport Association (ATA) of America Code 29: Hydraulic Power.

(e) Reason

This AD was prompted by reports of hydraulic accumulator failure. We are issuing this AD to prevent failure of hydraulic accumulators, which may result in damage to the airplane and injury to occupants.

(f) Compliance

You are responsible for having the actions required by this AD performed within the compliance times specified, unless the actions have already been done.

(g) Actions

Within 12 months after the effective date of this AD, replace all hydraulic accumulators having part number (P/N) 08 8423 030 1, with stainless steel hydraulic accumulators having P/N 40800–2050, and do the structural modifications in the nose landing gear bay, in accordance with the Accomplishment Instructions of Saab Service Bulletin 2000–29–024, Revision 01, dated November 5, 2010.

(h) Parts Installation

After replacing hydraulic accumulators having P/N 08 8423 030 1 with hydraulic accumulators having P/N 40800–2050, and doing the structural modifications in the nose landing gear bay, as required by paragraph (g) of this AD, no person may install any hydraulic accumulator having P/N 08 8423 030 1 on any airplane.

(i) Credit for Previous Actions

This paragraph provides credit for the actions required by paragraph (g) of this AD, if those actions were performed before the effective date of this AD using Saab Service Bulletin 2000–29–024, dated November 18, 2009.

(j) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) Alternative Methods of Compliance (AMOCs): The Manager, ANM-116, International Branch, Transport Airplane Directorate, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the International Branch, send it to ATTN: Shahram Daneshmandi, Aerospace Engineer, International Branch, ANM-116, Transport Airplane Directorate, FAA, 1601 Lind Avenue SW., Renton, Washington 98057-3356; telephone (425) 227-1112; fax (425) 227-1149. Information may be emailed to: 9-ANM-116-AMOC-REQUESTS@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/ certificate holding district office. The AMOC approval letter must specifically reference this AD.

(2) Airworthy Product: For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they are approved by the State of Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

(k) Related Information

Refer to MCAI European Aviation Safety Agency Airworthiness Directive 2011–0004, dated January 17, 2011; and Saab Service Bulletin 2000–29–024, Revision 01, dated November 5, 2010; for related information.

(l) Material Incorporated by Reference

(1) You must use the following service information to do the actions required by this AD, unless the AD specifies otherwise. The Director of the Federal Register approved the incorporation by reference (IBR) of the following service information under 5 U.S.C. 552(a) and 1 CFR part 51:

(i) Saab Service Bulletin 2000–29–024, Revision 01, dated November 5, 2010. (2) For service information identified in this AD, contact Saab AB, Saab Aerosystems, SE–581 88, Linköping, Sweden; telephone +46 13 18 5591; fax +46 13 18 4874; email saab2000.techsupport@saabgroup.com; Internet http://www.saabgroup.com.

(3) You may review copies of the service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, Washington. For information on the availability of this material at the FAA, call 425–227–1221.

(4) You may also review copies of the service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at an NARA facility, call 202–741–6030, or go to http://www.archives.gov/federal_register/code_of_federal_regulations/ibr_locations.html.

Issued in Renton, Washington, on April 23, 2012.

Michael Kaszycki,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service. [FR Doc. 2012–10469 Filed 5–2–12; 8:45 am] BILLING CODE 4910–13–P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 71

[Docket No. FAA-2012-0227; Airspace Docket No. 12-ACE-1]

Modification of VOR Federal Airway V–14; Missouri

AGENCY: Federal Aviation Administration (FAA), DOT. **ACTION:** Final rule, technical amendment.

SUMMARY: This action amends VOR Federal airway V–14 in the vicinity of St. Louis, MO. The FAA is taking this action to correct the V–14 description contained in Part 71 to ensure it matches the information contained in the FAA's aeronautical database, matches the depiction on the associated charts, and to ensure the safety and efficiency of the National Airspace System (NAS).

DATES: Effective date 0901 UTC May 3, 2012. The Director of the Federal Register approves this incorporation by reference action under 1 CFR part 51, subject to the annual revision of FAA Order 7400.9 and publication of conforming amendments.

FOR FURTHER INFORMATION CONTACT:

Colby Abbott, Airspace, Regulations and ATC Procedures Group, Office of Mission Support Services, Federal Aviation Administration, 800 Independence Avenue SW., Washington, DC 20591; telephone: (202) 267–8783.

SUPPLEMENTARY INFORMATION:

History

After a recent review of aeronautical data, the Aeronautical Navigation Products Group identified the VOR Federal airway V–14 description published in FAA Order 7400.9, Airspace Designations and Reporting Points, did not match the airway information contained in the FAA's aeronautical database or the charted depiction of the airway. When V–14 was amended in the **Federal Register** of May 7, 1990 (55 FR 18862), the St. Louis, MO, VOR/DME was deleted from the description in error. The FAA aeronautical database retained the navigation aid in the route description correctly and the associated aeronautical charts were published accordingly. To overcome any confusion or flight safety issues associated with conflicting route description information being published, the FAA is amending the V–14 legal description to reflect the airway aligned over the St. Louis, MO, VOR/DME. Accordingly, since this is an administrative correction to update the V-14 description to be in concert with the FAA's aeronautical database and charting, notice and public procedures under Title 5 U.S.C. 553(b) are unnecessary.

The Rule

The FAA amends Title 14 Code of Federal Regulations (14 CFR) part 71 by amending the legal description of VOR Federal airway V–14 in the vicinity of St. Louis, MO. Specifically, the FAA amends V-14 to reflect the airway aligned over the St. Louis, MO, VOR/ DME; thus, matching the information currently contained in the FAA's aeronautical database and the charted depiction of the airway.

VOR Federal airways are listed in paragraph 6010 of FAA Order 7400.9V dated August 9, 2011, and effective September 15, 2011, which is incorporated by reference in 14 CFR 71.1. The VOR Federal airway listed in this document will be revised subsequently in the Order.

The FAA has determined that this regulation only involves an established body of technical regulations for which frequent and routine amendments are necessary to keep them operationally current. Therefore, this regulation: (1) Is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under Department of Transportation (DOT) Regulatory Policies and Procedures (44 FR 11034; February 26, 1979); and (3) does not warrant preparation of a regulatory evaluation as the anticipated impact is so minimal. Since this is a routine matter that will only affect air traffic procedures and air navigation, it is certified that this rule, when promulgated, will not have a significant economic impact on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

The FAA's authority to issue rules regarding aviation safety is found in Title 49 of the United States Code. Subtitle I, Section 106 describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the agency's authority.

This rulemaking is promulgated under the authority described in Subtitle VII, Part A, Subpart I, Section 40103. Under that section, the FAA is charged with prescribing regulations to assign the use of the airspace necessary to ensure the safety of aircraft and the efficient use of airspace. This regulation is within the scope of that authority as it amends an existing VOR Federal airway within the NAS.

Environmental Review

The FAA has determined that this action qualifies for categorical exclusion under the National Environmental Policy Act in accordance with 311a, FAA Order 1050.1E, "Environmental Impacts: Policies and Procedures." This airspace action is not expected to cause any potentially significant environmental impacts, and no extraordinary circumstances exist that warrant preparation of an environmental assessment.

List of Subjects in 14 CFR Part 71

Airspace, Incorporation by reference, Navigation (air).

Adoption of the Amendment

In consideration of the foregoing, the Federal Aviation Administration amends 14 CFR part 71 as follows:

PART 71-DESIGNATION OF CLASS A, B, C, D, AND E AIRSPACE AREAS; AIR **TRAFFIC SERVICE ROUTES; AND REPORTING POINTS**

■ 1. The authority citation for part 71 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40103, 40113, 40120; E.O. 10854, 24 FR 9565, 3 CFR, 1959-1963 Comp., p. 389.

§71.1 [Amended]

■ 2. The incorporation by reference in 14 CFR 71.1 of FAA Order 7400.9V, Airspace Designations and Reporting Points, signed August 9, 2011, and effective September 15, 2011, is amended as follows:

Paragraph 6010 VOR Federal airways. (a) Domestic VOR Federal airways. * *

V-14

*

From Chisum, NM; Lubbock, TX; Childress, TX; Hobart, OK; Will Rogers, OK; INT Will Rogers 052° and Tulsa, OK 246° radials; Tulsa; Neosho, MO; Springfield, MO; Vichy, MO; INT Vichy 067° and St. Louis, MO, 225° radials; St. Louis; Vandalia, IL; Terre Haute, IN; Brickyard, IN; Muncie, IN; Flag City, OH; INT Flag City 079° and Dryer, OH, 240° radials; Dryer; Jefferson, OH; Erie, PA; Dunkirk, NY; Buffalo, NY; Geneseo, NY; Georgetown, NY; INT Georgetown 093° and Albany, NY, 270° radials; Albany; INT

Albany 084° and Gardner, MA, 284° radials; Gardner; to Norwich, CT.

Issued in Washington, DC, April 24, 2012. Paul Gallant,

Acting Manager, Airspace, Regulations and ATC Procedures Group. [FR Doc. 2012-10362 Filed 5-2-12; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF HEALTH AND HUMAN SERVICES

Food and Drug Administration

21 CFR Parts 522 and 558

[Docket No. FDA-2012-N-0002]

New Animal Drugs; Ceftiofur Crystalline Free Acid; Gamithromycin; Tylosin

AGENCY: Food and Drug Administration, HHS.

ACTION: Final rule.

SUMMARY: The Food and Drug Administration (FDA) is amending the animal drug regulations to reflect approval actions for new animal drug applications (NADAs) and abbreviated new animal drug applications (ANADAs) during February 2012. FDA is also informing the public of the availability of summaries of the basis of approval and of environmental review documents, where applicable. **DATES:** This rule is effective May 3, 2012.

FOR FURTHER INFORMATION CONTACT: George K. Haibel, Center for Veterinary Medicine (HFV-6), Food and Drug Administration, 7519 Standish Pl., Rockville, MD 20855, 240-276-9019, email:george.haibel@fda.hhs.gov.

SUPPLEMENTARY INFORMATION: FDA's Center for Veterinary Medicine is adopting the use of a monthly Federal **Register** document to codify approval actions for NADAs and ANADAs. CVM will no longer publish a separate rule for each action. This approach will allow a more efficient use of available resources.

In this document, FDA is amending the animal drug regulations to reflect the original and supplemental approval actions during February 2012, as listed in table 1 of this document. FDA is also informing the public of the availability of summaries of the basis of approval (FOI Summaries) under the Freedom of Information Act (FOIA) and of environmental review documents required under the National Environmental Policy Act (NEPA), where applicable.